

REPAIR ESTIMATE*

VEHICLE NO : SHD 3739S

DATE : 12.03.2019

MAKE :

MODEL : HYUNDAI IONIQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille ✓			\$ 1,227.50
	Front Bumper Cover ✓			\$ 418.30
	Front Bumper Sponge !			\$ 86.90
	Front Bumper Reinforcement ?			\$ 1,075.10
	Front Bumper Moulding Centre Upper ✓			\$ 108.50
	Front Bumper Lower Stiffner x rep/2			\$ 85.10
	Front Bumper Bracket Top (LH) ?			\$ 35.00
	Front Bumper Bracket (LH) ?			\$ 28.00
	Front Bumper Clips 10 pcs ✓			\$ 22.00
	Headlamp (LH) ✓			\$ 1,198.80
	Day Light, LH x			\$ 642.50
	Front Fender (LH) ✓			\$ 490.70
	Front Fender Shield (LH) x			\$ 114.70
	Emblem-Blue Drive (LH) ✓			\$ 26.60
	SUB TOTAL			\$ 5,559.70
	LESS 20%			\$ 1,111.94
	DISCOUNTED TOTAL			\$ 4,447.76
	Labour Charge			
	Panel Beating			\$ 400.00 200
	Spray Painting Charge			\$ 600.00 400
	Wiring Charge			\$ 30.00 20
	Tuff Kote			\$ 50.00 20
	TOTAL LABOUR			\$ 1,080.00
	ESTIMATE TOTAL			\$ 5,527.76

Link Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Kalin LKH

N

12/3/19 12504.

3 Dys

P/P

Before Paint photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.