

INS. CASE OWNER:

CC 4, LPC 1900 4460, K 332

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. : SLS 7771 U

Claim No. :

Name of Insured : LOH AI

Policy No. :

Insured Tel No. : HP:

Make / Model :

Excess Sec II : SS D.O.A : 9/3/19

Place of Accident :

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age :

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No. :

(V/L: YES / NO)

Insured Liability : %

Final ? Yes / No

INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time

1973
10/1

SLS 7771 U - X; SLS 7771 U - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

17/06/19

- OI CHANGED CASE
- LPC APPROVED MANDATE23/06/19
15/07/19- TP ACCEPTED OFFER.
- LPC RETURNED ORIG. BODS.
- ALL IN ORDER.
- TO CLOSE.

4-6-19

FOR MANDATE

PRELIMINARY ADVICE Date/Time: 15/06/19

Sent By: AS

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: L6 S\$ 3,800.00 (7 days) Reduction: 67 %

Email ☐ Call ☐

FINAL SETTLEMENT Date/Time: 09/07/19 Confirm with: SHAWN

Email ☒ Call ☐

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : 15

If NO or B 28, Ass. Lia :

Repair Cost: GST S\$ 4,066.00

Loss of Rental (LOR): S\$ 900 (9 days) 100

Loss of Use (LOU): S\$ (\$ x days)

Loss of Income (LOI): S\$ X (\$ x days)

LOR only ☒ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search S\$ 7.45

Medical: S\$ -

Disbursement: S\$ - (e.g. Tow/ Independent)

Legal Cost S\$ -

Total: S\$ 4,973.45 Global Sum S\$: -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee: \$450.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1: S\$ 4,973.45

Name 1: LEONG AUTO PTE LTD

Payee 2: (Strike if N.A.) S\$ -

Name 2: -

Payee 3: (Strike if N.A.) S\$ -

Name 3: -

COPY SENT
15/7/19

ASS. REC. BY:

REF:

LPC

ASSIGNMENT

From:

Date:

12/3/2019

Veh No:

SJG 20824

Yr Regn:

06, C8

Estimated Cost:

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

Truck / Trailer or

To Inspect Vehicle No:

SJG 20824

Make:

Honda Fit

c.c.

1339

at Workshop m/s

Leong Auto

Colour:

M. Black

A/C:

Insured / Std / NI / NA

of

160 Siming Drive # 02-13

Sp. Reading

222.897

T/Radio:

Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

GEB - 1053988

Claims No.

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Sum Insured:

Excess:

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

(Client's Record)

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Make of Veh:

Mod: ☒ Nil / ☐ STD A/Rim or

Tyre Size:

F:

205/45R16

R:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

824k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

6/23

'wp'

Vehicle: IN / OUT

Date:

Person Contacted:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

9/13/19

D.O.I.

12/13/19

Survey held at

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

O/S Acc

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

25-3-19 L/S \$3,800/-

Gross: 67,840.12 (67%)

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format:

Lump Sum / LBJ: (\$



Auto
Consultants
Pte Ltd

Company Registration No. 199607195R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 18/19/19/VP05/021505
Our ref: CC4/LPC19004460/Kja3

Date: 15/03/2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SJG 2082U

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 12/03/2019 at the premises of ML Tjong Auto Pte Ltd - Sin Ming and have the following to report:-

Workshop Estimate Amount	: S\$	11,640.12
Revised Estimate Amount	: S\$	4,332.64
"Check" Items Amount	: S\$	2,617.04
Total (Including Check Items)	: S\$	6,949.68

Market Value	: S\$	-	(est.)
LTA Reimbursement Value	: S\$	-	(est.)
Nett Value	: S\$	-	(est.)

Description of Damage:

The vehicle sustains damages at the
O/S Rear Portion



Comments/Present Findings:

Damages: Consistent

Estimated normal period for repairs: 7.0 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8177883C



Name

SUN HE

孙 鹤

Race

CHINESE

Date of birth

13-06-1981

Sex

F

Country of birth

CHINA



S8177883C

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8082824A



Name

ZHENG SHUAI

郑 帅

Race

CHINESE

Date of birth

30-03-1980

Sex

M

Country of birth

CHINA



S8082824A

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number S8177883C

Name

SUN HE

Birth Date 13 Jun 1981

Issue Date 03 Nov 2010



001908233A

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number S8082824A

Name

ZHENG SHUAI

Birth Date 30 Mar 1980


Issue Date 20 Aug 2010



001885409C



NRIC No. S8177883C



Date of issue

14-05-2009

APT BLK 393 BUKIT BATOK WEST AVENUE 5 #21-460
SINGAPORE 650393

NRIC No. S8177883C

Date: 24/02/2010


No: 6465924

4402128

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg 03 Nov 2010



Licence No: S8177883C

NP 429A



NRIC No. S8082824A



Nationality

CHINESE

Date of issue

13-06-2007

APT BLK 393 BUKIT BATOK WEST AVENUE 5 #21-460
SINGAPORE 650393

NRIC No. S8082824A

Date: 24/02/2010

No: 6465923

8884648

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg 20 Aug 2010



Licence No: S8082824A

NP 429A



CERTIFICATE OF INSURANCE

AUTOPLUS PRIVATE VEHICLE

Name of Policyholder : Sun He
 Period of Insurance : 24 Jun 2018 To 23 Jun 2019
 Engine No. : L13A4059682
 Chassis No. : GE61053968

Vehicle No. : sjg2082u
 Policy No. : 2100304512-06
 Endorsement No. :
 Issued Date : 14 May 2018

ABOUT THE COVER

Make/Model : HONDA FIT 1.3G
 Engine Capacity/Tonnage : 1,339.00 CC
 Driver Restriction : NA
 Sum Insured : Market Value
 Off Peak Car : No
 First Year of Registration : 2008
 Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*

- a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 30 years old and above

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc Optional

* Limitations rendered inoperative by Section 6 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Sun He - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Approved Reporting Centres/ AIG Authorised Repairers (For claims related repairs)

Any accident repairs to the Vehicle must be carried out by one of our Authorised Repairers. Within the first 3 years of the first registration of the Vehicle in Singapore, You have the option of having the accident repairs carried out at the Sole Agent's workshop.
 For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, You may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0502820000

TAN CHENG HOCK ERIC

180C RIVERVALE CRESCENT #16-375

SINGAPORE 543180 SP-ET-CHANHY

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

M. Anik

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

DDP478

LEONG AUTO PTE LTD

160 Sin Ming Drive, Sin Ming AutoCity, #02-13, Singapore 575722
 Tel: 62666448 Fax: 62666358 Email: Sales@leongauto.com.sg
 Business Registration No. 201312846W
 GST Registration No. 201312846W

Not Authorized
L1/Py D?
Resony After Paint

ESTIMATE

Date: 11/3/2019

DOA: 9/3/2019

Vehicle No: SJG2082U

Make & Model: Honda Fit 1.3 A

7 days

S/N	Qty	Item Description	Parts	Price	Surveyor
1	1	Rear Right Tail Lamp	<i>Sm</i>	\$ 455.70	X
2	1	Rear Right Tail Lamp Retainer	<i>Sm</i>	\$ 41.20	X
3	1	Rear Bumper	<i>nd/h</i>	\$ 614.70	X
4	1	Rear R/H Bumper Retainer	<i>Sm</i>	\$ 50.00	X
5	1	Rear R/H Bumper Bracket	<i>n</i>	\$ 51.40	X
6	1	Rear Right Fender	<i>B</i>	\$ 812.80	X
7	1	Rear Right Fender Wheel House	<i>\$ n</i>	\$ 306.60	X
8	1	Rear Right Fender Inner Garnish	<i>Sm</i>	\$ 354.40	X
9	1	Rear Right Fender Quarter Glass	<i>me</i>	\$ 126.10	X
10	1	Rear Right Fender MudFlap		\$ 130.20	X
11	1	Rear Right Door	<i>B</i>	\$ 937.70	X
12	1	Rear Right Door Lock Mechanism	<i>\$ n</i>	\$ 163.30	X
13	1	Rear Right Door Lock Catch	<i>\$ n</i>	\$ 67.50	X
14	1	Rear Right Door Hinges	<i>\$ n</i>	\$ 41.90	X
15	1	Rear Right Door Weatherstrip	<i>\$ n</i>	\$ 144.30	X
16	1	Rear Right Door Inner Trim Board	<i>\$ Sm</i>	\$ 467.50	X
17	1	Rear Right Door Window Glass Moulding		\$ 164.50	X
18	1	Rear R/H Air Duct Ventilator		\$ 71.10	X
19	1	Rear Axle Beam		\$ 1,284.00	X
20	1	Rear R/H Wheel Hub		\$ 214.00	X
21	1	Rear R/H Bearing		\$ 158.10	X
22	1	Rear R/H Shock Absorber		\$ 211.90	X
				\$ 6,868.90	
Less 20%				\$ 1,373.78	
				\$ 5,495.12	
<u>Special Nett Items</u>					
1		Sundries		\$ 50.00	X
2	1	Rear Right Tail Lamp Sealant	<i>na</i>	\$ 35.00	X
3	1 set	Rear Tail Lamp Clips	<i>na</i>	\$ 30.00	X
4	1 set	Rear Bumper Clips	<i>\$ na</i>	\$ 50.00	X
5	1	Rear Right Fender Sealant	<i>me</i>	\$ 80.00	<i>305n</i>
6	1 set	Rear Right Fender Inner Garnish Clips	<i>me</i>	\$ 30.00	X
7	1	Rear End Panel Sealant	<i>na</i>	\$ 80.00	X
8	2	Rear Bumper Reverse Sensor	<i>Sm</i>	\$ 250.00	X
9	1	Rear R/H Tyre		\$ 400.00	X
10	1	Rear R/H Rim	<i>nd</i>	\$ 300.00	<i>250n</i>

			\$ 1,305.00	
		Total parts	\$ 6,800.12	
S/N	Labour Description	Amount	Amount	
1	Labour for panel beating, cut, weld, straighten rear fender and replace rear damaged parts.	\$ 1,800.00	9001	
2	To putty and spray painting rear portion.	\$ 1,400.00	7201	
3	To check rear lighting and wiring.	\$ 60.00	201	
4	To remove and install, inner garnish and trim to facilitate the repair.	\$ 350.00	1001	
5	To apply anti rust proofing to rear affected area.	\$ 250.00	601	
6	To remove and install rear reverse sensor.	\$ 150.00	501	
7	To perform 4 wheel alignment and balancing.	\$ 150.00	602	
8	To remove and install quarter glass.	\$ 180.00	501	
9	To remove front & rear undercarriage to facilitate repairs	\$ 380.00	?	
10	To remove & refit rear fender component to replace rear fender, check & re-adjust the close gap and alignment and water seepage	\$ 120.00	201	
	Total labour :	\$ 4,840.00		
	Total parts :	\$ 6,800.12		
	Total labour :	\$ 4,840.00		
	Total repair cost : (Before GST)	\$ 11,640.12		

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after any lifting
- To display damaged parts during survey
- Parts prices are valid at the time of survey
- Third party survey "LKK's Mitigate Prejudice" basis
- No illegal modification is allowed
- Supplementary items purchased on order and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Kj

LEONG AUTO PTE LTD

160 Sin Ming Drive, Sin Ming AutoCity, #02-13, Singapore 575722
 Tel: 62666448 Fax: 62666358 Email: Sales@leongauto.com.sg
 Business Registration No. 201312846W
 GST Registration No. 201312846W

Not Authorised
11/12/2018
Resony After Paint

ESTIMATE

Date: 11/3/2019
 DOA: 9/3/2019

Vehicle No: SJG2082U
 Make & Model: Honda Fit 1.3 A

7 days

S/N	Qty	Item Description	Parts	Price	Surveyor
1	1	Rear Right Tail Lamp <i>206.50</i>	<i>Sm</i>	\$ 455.70	X
2	1	Rear Right Tail Lamp Retainer	<i>Sm</i>	\$ 41.20	X
3	1	Rear Bumper <i>493.70</i>	<i>Net/br</i>	\$ 614.70	X
4	1	Rear R/H Bumper Retainer	<i>Sm</i>	\$ 50.00	X
5	1	Rear R/H Bumper Bracket	<i>R</i>	\$ 51.40	X
6	1	Rear Right Fender <i>688.20</i>	<i>R</i>	\$ 812.80	X
7	1	Rear Right Fender Wheel House	<i>\$ R</i>	\$ 306.60	X
8	1	Rear Right Fender Inner Garnish	<i>Sm</i>	\$ 354.40	X
9	1	Rear Right Fender Quarter Glass <i>Midy Midy</i>	<i>Sm</i>	\$ 126.10	X
10	1	Rear Right Fender MudFlap	<i>CM</i>	\$ 130.20	X
11	1	Rear Right Door <i>765.30</i>	<i>R</i>	\$ 937.70	X
12	1	Rear Right Door Lock Mechanism	<i>\$ R</i>	\$ 163.30	X
13	1	Rear Right Door Lock Catch	<i>\$ R</i>	\$ 67.50	X
14	1	Rear Right Door Hinges	<i>\$ R</i>	\$ 41.90	X
15	1	Rear Right Door Weatherstrip	<i>\$ R</i>	\$ 144.30	X
16	1	Rear Right Door Inner Trim Board	<i>\$ Sm</i>	\$ 467.50	X
17	1	Rear Right Door Window Glass Moulding	<i>R/H</i>	\$ 164.50	X
18	1	Rear R/H Air Duct Ventilator	<i>\$ R</i>	\$ 71.10	X
19	1	Rear Axle Beam	<i>Sm</i>	\$ 1,284.00	X
20	1	Rear R/H Wheel Hub <i>Sm</i>		\$ 214.00	X
21	1	Rear R/H Bearing	<i>Sm</i>	\$ 158.10	X
22	1	Rear R/H Shock Absorber <i>R/H Sm</i>		\$ 211.90	X
				\$ 6,868.90	
Less 20%				\$ 1,373.78	
				\$ 5,495.12	
<u>Special Nett Items</u>					
1		Sundries	<i>\$ R</i>	\$ 50.00	X
2	1	Rear Right Tail Lamp Sealant	<i>R</i>	\$ 35.00	X
3	1 set	Rear Tail Lamp Clips	<i>R</i>	\$ 30.00	X
4	1 set	Rear Bumper Clips	<i>\$ R</i>	\$ 50.00	X
5	1	Rear Right Fender Sealant	<i>R</i>	\$ 80.00	X
6	1 set	Rear Right Fender Inner Garnish Clips	<i>R</i>	\$ 30.00	X
7	1	Rear End Panel Sealant	<i>R</i>	\$ 80.00	X
8	2	Rear Bumper Reverse Sensor	<i>R</i>	\$ 250.00	X
9	1	Rear R/H Tyre	<i>Sm</i>	\$ 400.00	X
10	1	Rear R/H Rim	<i>R</i>	\$ 300.00	X

		\$ 1,305.00	
	Total parts	\$ 6,800.12	
S/N	Labour Description	Amount	Amount
1	Labour for panel beating, cut, weld, straighten rear fender and replace rear damaged parts.	\$ 1,800.00	9001
2	To putty and spray painting rear portion.	\$ 1,400.00	7201
3	To check rear lighting and wiring.	\$ 60.00	201
4	To remove and install, inner garnish and trim to facilitate the repair.	\$ 350.00	1001
5	To apply anti rust proofing to rear affected area.	\$ 250.00	601
6	To remove and install rear reverse sensor.	\$ 150.00	501
7	To perform 4 wheel alignment and balancing.	\$ 150.00	602
8	To remove and install quarter glass.	\$ 180.00	501
9	To remove front & rear undercarriage to facilitate repairs	\$ 380.00	801
10	To remove & refit rear fender component to replace rear fender, check & re-adjust the close gap and alignment and water seepage	\$ 120.00	201
	Total labour :	\$ 4,840.00	
	Total parts :	\$ 6,800.12	
	Total labour :	\$ 4,840.00	
	Total repair cost : (Before GST)	\$ 11,640.12	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications are allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Work Order: R052843
 License: SJG2082U
 Year: 09
 Date: 11.3.19 10:06

Honda : Fit/Jazz : 2009-15 (GE/GG/GH) : except KY 1.5LXE, 1.5EXE Models and KE, KG Models

Front : Left

Actual	Before	Specified Range
-0°15'	-0°15'	-1°00' 1°00'
4°02'	4°02'	2°20' 4°20'
0°06'	0°05'	-0°07' 0°07'
13°24'	13°24'	
13°09'	13°09'	

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
0°01'	0°01'	-1°00' 1°00'
4°26'	4°26'	2°20' 4°20'
-0°08'	-0°07'	-0°07' 0°07'
13°17'	13°17'	
13°19'	13°19'	

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
-0°16'	-0°16'	-0°45' 0°45'
-0°23'	-0°23'	
0°07'	0°07'	
-0°02'	-0°02'	-0°14' 0°14'

Rear : Left

Actual	Before	Specified Range
-0°42'	-0°42'	-2°00' 0°00'
0°31'	0°31'	0°00' 0°12'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-2°32'	-2°31'	-2°00' 0°00'
-0°13'	-0°15'	0°00' 0°12'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
1°50'	1°49'	-0°45' 0°45'
0°18'	0°16'	0°00' 0°24'
0°22'	0°23'	

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Monday, 11 March 2019 11:45 AM
To: assignments
Subject: FW: Request for Pre-Repair Inspection – SJG2082U [External Confidential]

3:24pm @ 11/3/19
shawn
vehicle in
9692 4113

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Monday, 11 March 2019 11:11 AM
To: Admin A <admin-a@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: FW: Request for Pre-Repair Inspection – SJG2082U [External Confidential]

Lonpac External - Confidential

Our Ref: 18/19/19/VP05/021505

Dear Nivitha,

Kindly proceed accordingly with the survey.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: EMELLENE TENG [<mailto:tjh@leongauto.com.sg>]
Sent: Monday, 11 March, 2019 10:38 AM
To: GERALD POH WEE BIN
Cc: Leong Auto Ops; Leong Auto Trading; MT_Claim_SG
Subject: Re: Request for Pre-Repair Inspection – SJG2082U [External Confidential]

Dear Mr Poh,

Please arrange for LKK to survey this vehicle.

Best Regards,
Emellene Teng
Leong Auto Pte Ltd
Office : 6266-6448 Fax : 6266-6358

Please like our Facebook page at: <https://www.facebook.com/leongautogroup>

On Mon, 11 Mar 2019 at 10:16, Leong Auto Trading <sales@leongauto.com.sg> wrote:

----- Forwarded message -----

From: **GERALD POH WEE BIN** <geraldpoh@lonpac.com>

Date: Mon, Mar 11, 2019 at 9:16 AM

Subject: RE: Request for Pre-Repair Inspection – SJG2082U [External Confidential]

To: Leong Auto Trading <sales@leongauto.com.sg>

Cc: MT_Claim_SG <mt_claim@lonpac.com>

Lonpac External - Confidential

WITHOUT PREJUDICE

Our Ref : 18/19/19/VP05/021505

Dear Cady,

Please see attached and revert.


For your information, our insured has yet to lodge the accident report.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555



Lonpac External - Confidential data is for use by authorised external parties only.

From: Leong Auto Trading [mailto:sales@leongauto.com.sg]
Sent: Saturday, 9 March, 2019 3:06 PM
To: MT_Claim_SG; GERALD POH WEE BIN; ONG LI LI
Cc: EMELLENE TENG; Leong Auto Ops
Subject: Request for Pre-Repair Inspection – SJG2082U

Our Ref: SJG2082U

To: The owner and/or driver of SLS7771U 3rd party

c/o Lonpac Insurance Bhd

cc: Lonpac Insurance Bhd

Dear Sir/Madam,

Accident Involving SJG2082U & SLS7771U on 9/3/2019 along Bt Batok West Avenue 5 towards Bt Batok Central

With reference to the above, we hereby give Lonpac Insurance Bhd 2 days' notice to conduct a pre-repair inspection of vehicle SJG2082U at our premise.

Please arrange your surveyor to inspect the vehicle at:

160 Sin Ming Drive, #02-13 Sin Ming AutoCity

Singapore 575722

Mobile No.: 97370733

If we do not receive any reply from you within the stipulated timeline, we shall proceed to repair the vehicle without any further reference to you.

Please advise on liability for this case & let us have a list of surveyors to choose from to appoint as Single Joint Expert.

Regards,

Leong Auto Pte Ltd

Cady Lee

Office : 6266-6448 Fax : 6266-6358

Facebook page at: <https://www.facebook.com/leongautogroup>

Mei Kwan (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Monday, 18 March, 2019 9:14 AM
To: Mei Kwan (LKKAUTO)
Cc: MT_Claim_SG
Subject: RE: Request for Pre-Repair Inspection - SJG2082U [External Confidential]
Attachments: 18032019091010.pdf

Categories: HMK

Lonpac External - Confidential

Dear Mei Kwan,

Attached copy of insured's GIA report for your attention.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-01/02 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 7706



Lonpac External - Confidential data is for use by authorised external parties only.

From: Mei Kwan (LKKAUTO) [mailto:MeiKwan@lkkauto.com]
Sent: Monday, 18 March 2019 9:14 AM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG
Subject: RE: Request for Pre-Repair Inspection - SJG2082U [External Confidential]

*WITHOUT PREJUDICE
SAVED TO: 000000*

LPC ref: 18/19/19/MP05/021505
LKK REF: CC4/LPC19004460/kja3

Dear Sir / Madam,

We refer to the above matter.

Enclosed for your reference:

- TP GIA report
- Wheel alignment report

We have not authorized repairs.

Gerald Poh

Senior Claims Executive | Lionpac Insurance Ptd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6796 8888



Lionpac External - Confidential data is for use by authorised external parties only.

From: EMELIENE TENG [mailto:emeliene@leongauto.com.sg]

Sent: Monday, 11 March 2019, 11:16 AM

To: GERALD POH [mailto:gerald.poh@lionpac.com.sg]

Cc: Leong Auto [mailto:leongauto@leongauto.com.sg]

Subject: Re: [External Confidential] [External Confidential]

Dear Mr Poh,

Please arrange for LKK to survey this vehicle.

Best Regards,

Emelene Teng

Leong Auto Pte Ltd

Office : (65) 6250 7388

Please like our Facebook page [Leong Auto Group](#)

On Mon, 11 Mar 2019 at 11:16, Leong Auto Trading & Sales <leongauto.com.sg> wrote:

----- Forwarded message -----

From: GERALD POH [mailto:gerald.poh@lionpac.com.sg]

Date: Mon, Mar 11, 2019, 11:16 AM

Subject: RE: [External Confidential] Fair Inspection - S1170811 [External Confidential]

To: Leong Auto [mailto:leongauto@leongauto.com.sg]

Content: [External Confidential]

Lionpac External - Confidential

WITHOUT PREJUDICE

Our Ref: [External Confidential]

Dear Cady,

With reference to the above, we hereby give Leong Auto Pte Ltd 3 days' notice to conduct a pre-repair inspection of vehicle SJG2115411.

Please arrange your visit

160 Sin Ming Drive, #02-12, Sin Ming Centre

Singapore 575722

Mobile No.: 97477777

If we do not receive any response from you by 12 noon on 12/05/2011, we shall proceed to repair the vehicle without any further reference to you.

Please advise on liability for this case & let us have a list of surveyors to choose from to appoint as Single Joint Expert.

Regards,

Leong Auto Pte Ltd

Cady Lee

Office: 67664610/67664611

Facebook page at: <http://www.facebook.com/leongauto>



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC19004460/Kha3n2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 17-07-2019		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLS 7771U	Veh. Inspected	SJG 2082U	
Policy No.	Z18VP05020273	Coverage (\$)	0.00	
Claim No.	18/19/19/VP05/021505	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	12/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FIT (A)	c.c	1339	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	GE61053988	Colour	METALLIC BLACK	
Odometer	222897	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/45 R16	YOKOHAMA	9 mm	
L/H Front Tyre	205/45 R16	YOKOHAMA	9 mm	
R/H Rear Tyre	205/45 R16	YOKOHAMA	9 mm	
L/H Rear Tyre	205/45 R16	YOKOHAMA	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/03/2019	Inspection Date	12/03/2019	
Survey held at	LEONG AUTO PTE LTD 160 SIN MING DRIVE #02-13 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJG 2082U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR RIGHT TAIL LAMP	SERVICEABLE	455.70	-
1	REAR RIGHT TAIL LAMP RETAINER	SERVICEABLE	41.20	-
1	REAR BUMPER	DENTED / CUT	614.70	493.70
1	REAR R/H BUMPER RETAINER	SERVICEABLE	50.00	-
1	REAR R/H BUMPER BRACKET	TO REPAIR SEE LABOUR	51.40	-
1	REAR RIGHT FENDER	BENT	812.80	688.20
1	REAR RIGHT FENDER WHEEL HOUSE	TO REPAIR SEE LABOUR	306.60	-
1	REAR RIGHT FENDER INNER GARNISH	SERVICEABLE	354.40	-
1	REAR RIGHT FENDER QUARTER GLASS	MLDG NECESSARY	126.10	126.10
1	REAR RIGHT FENDER MUDFLAP	CRACKED	130.20	130.20
1	REAR RIGHT DOOR	BENT	937.70	765.30
1	REAR RIGHT DOOR LOCK MECHANISM	TO REPAIR SEE LABOUR	163.30	-
1	REAR RIGHT DOOR LOCK CATCH	TO REPAIR SEE LABOUR	67.50	-
1	REAR RIGHT DOOR HINGES	TO REPAIR SEE LABOUR	41.90	-
1	REAR RIGHT DOOR WEATHERSTRIP	SERVICEABLE	144.30	-
1	REAR RIGHT DOOR INNER TRIM BOARD	SERVICEABLE	467.50	-
1	REAR RIGHT DOOR WINDOW GLASS MOULDING	DISTORTED	164.50	164.50
1	REAR R/H AIR DUCT VENTILATOR	DENTED	71.10	71.10
1	REAR AXLE BEAM	SERVICEABLE	1,284.00	-
1	REAR R/H WHEEL HUB	SERVICEABLE	214.00	-
1	REAR R/H BEARING	NECESSARY	158.10	158.10
1	REAR R/H SHOCK ABSORBER	BENT / PUNCTURE	211.90	211.90
	LESS 20% DISCOUNT		-1,373.78	-561.82
			5,495.12	2,247.28
SPECIAL NETT ITEMS				
1	SUNDRIES (SN)	NOT NECESSARY	50.00	-
1	REAR RIGHT TAIL LAMP SEALANT (SN)	NOT NECESSARY	35.00	-

Report Ref No. CC4/LPC19004460/Kha3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR TAIL LAMP CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	REAR RIGHT FENDER SEALANT (SN)	NECESSARY	80.00	30.00
1	SET REAR RIGHT FENDER INNER GARNISH CLIPS (SN)	NECESSARY	30.00	30.00
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	80.00	-
2	REAR BUMPER REVERSE SENSOR (SN)	SERVICEABLE	250.00	-
1	REAR R/H TYRE (SN)	SERVICEABLE	400.00	-
1	REAR R/H RIM (SN)	DENTED	300.00	250.00
			1,305.00	360.00
	LABOUR			
	LABOUR FOR PANEL BEATING ,CUT ,WELD, STRAIGHTEN REAR FENDER AND REPLACE REAR DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF REAR R/H BUMPER BRACKET,REAR RIGHT FENDER WHEEL HOUSE,REAR RIGHT DOOR LOCK MECHANISM,REAR RIGHT DOOR LOCK CATCH AND REAR RIGHT DOOR HINGES.		1,800.00	900.00
	TO PUTTY AND SPRAY PAINTING REAR PORTION .		1,400.00	720.00
	TO CHECK REAR LIGHTING AND WIRING.		60.00	20.00
	TO REMOVE AND INSTALL ,INNER GARNISH AND TRIM TO FACILITATE THE REPAIR.		350.00	100.00
	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA.		250.00	60.00
	TO REMOVE AND INSTALL REAR REVERSE SENSOR.		150.00	50.00
	TO PERFORM 4 WHEEL ALIGNMENT AND BALANCING.		150.00	60.00
	TO REMOVE AND INSTALL QUARTER GLASS.		180.00	50.00
	TO REMOVE FRONT & REAR UNDERCARRIAGE TO FACILITATE REPAIRS.		380.00	80.00
	TO REMOVE & REFIT REAR FENDER COMPONENT TO REPLACE REAR FENDER ,CHECK & RE-ADJUST THE CLOSE GAP AND ALIGNMENT AND WATER SEEPAGE.		120.00	20.00
			4,840.00	2,060.00
	GRAND TOTAL		11,640.12	4,667.28
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,800.00

Report Ref No. CC4/LPC19004460/Kha3n2



Report Ref No. CC4/LPC19004460/Kha3n2

A handwritten signature in black ink, appearing to read 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.