

Registration No. TP 113L

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR RATE (\$)	MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP		
1	MATERIALS						
1.1	FRONT CRASH BAR	1	BENT	\$ 530.00	\$ 530.00		
1.2	FRONT FOOTREST ASSEMBLY - LH AND RH	1	MISSING	\$ 70.00	\$ 70.00		
1.3	WINDSHIELD	1	CRACKED	\$ 696.00	\$ 696.00		
1.4	FRONT COWLING PROTECTOR - LH	1	CRACKED	\$ 284.00	\$ 284.00		
1.5	FRONT INNER PANEL - LH	1	CRACKED	\$ 343.00	\$ 343.00		
1.6	METER COWLING	1	CRACKED	\$ 60.00	\$ 60.00		
1.7	METER LENS	1	CRACKED	\$ 55.00	\$ 55.00		
1.8	FRONT BLINKER LIGHT - RH	1	MISSING	\$ 380.00	\$ 380.00		
1.9	SIDE MIRROR - LH	1	CRACKED	\$ 140.00	\$ 140.00		
1.10	REAR CRASH BAR - LH	1	DENTED	\$ 145.00	\$ 145.00		
1.11	SIDE BOX COVER - LH	1	SCRATCHED	\$ 480.00	\$ 480.00		
	TO SUPPLY LABOUR & MATERIAL TO REPLACE BAR LIGHT COVER	1		\$ 3,183.00	\$ 3,183.00		
1	SCOPE OF REPAIRS						
1.1	TO REMOVE AND REPLACE FRONT CRASH BAR						1
1.2	TO REMOVE AND REPLACE FRONT FOOTREST - LH AND RH						0.5
1.3	TO REPLACE WINDSHIELD						0.5
1.4	TO REMOVE AND REPLACE FRONT COWLING PROTECTOR AND INNER PANEL - LH						0.5
1.5	TO REMOVE AND REPLACE METER COWLING METER LENS						1
1.6	TO REMOVE AND REPLACE FRONT BLINKER LIGHT - RH						0.5
1.7	TO REMOVE AND REPLACE SIDE MIRROR - LH						0.5
1.8	TO REMOVE AND REPLACE REAR CRASH BAR - LH						0.5
1.9	TO REMOVE AND REPLACE SIDE BOX COVER - LH						0.5
1.10	TO REPAIR AND RESPRAY PAINT FOR FRONT COWLING						2
1.11	TO SPRAY PAINT FRONT COWLING PROTECTOR - LH						1
1.12	TO REMOVE AND INSTALL CYLINDER BLOCK						10
2	ADDITIONAL SERVICES						
2.1	TOWING FROM STN - WKSP (SOR 10)					81.6	1
2.2	TOWING FROM WKSP - STN (SOR 10)					81.6	1

COSTING	TOTAL PARTS COST	\$3,183.00		
	TOTAL MAN-HOUR			20.5