

ASS. REC. BY

Stat/Ven/pt

REP

CS/SPF 19004461 / Jsd362

rel Instruction

ASSIGNMENT (Office)

From (Person) **Wei Yea Kim**

of **SPF**

Date/Time: **11/3/19 @ 3:31pm**

Estimate / Cost

Bill to:

OD TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

TP113L

Insured

at Workshop n/s

SMRT

Tel.

98576861

of

60 woodlands Ind-park E4

Policy No.

Claim No.

HOMSPFETQ 16000399

Sum Insured

Excess:

Make of Veh

(Client's Record)

D.O.A.

CA (REV) REP / REV 24 HRS

Date/Time: **11/3/19 @ 4:41pm**

Person Contacted

Mr. Kong

H.O.D. Endorsement:

Vehicle: **INT/OUT**

Date/Time	Action/Instruction (✓) Estimate
	TP113L - x
16/04/19	Veron tele - conversation with Kim Pang, Can direct submit the report.

REF: SPR

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: TBA

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No TP113L Yr Regn: _____ /

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Yamaha XJ900 C.C. _____

Colour White A/C: Insured / Std / NI / NA

Sp. Reading 43016 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/70 R17

R: 150/70 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. - mm L/Bal. - mm

D.O.A. _____ D.O.I. 20/3/19

Survey held at Smart

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 16 APR 2019

Date/Time. File Pass to?

16/04/19

1) Type 4

Date/Time. File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) _____

☐ : Preli. Report

☒ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

) \$ + PS. \$ _____

) Photos _____

) Others _____

TOTAL

180

180

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 8 April 2019 4:53 PM
To: 'Kim Pang CHAY (SPF)'
Cc: 'SUR'; 'Perry HE (SPF)'
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (TP113L)

Dear Kim Pang,

Can we submit our report?

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Perry HE (SPF) [mailto:Perry_HE@spf.gov.sg]
Sent: Wednesday, 3 April 2019 9:02 AM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (TP113L)

Hi Shirley,

Wei Yea has left SPF already.

Moving forward pls look for Mr Chay.

CC: Mr Chay, for your heads up pls, thanks.

Perry He Junyun
Contract Management Engineer
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4869 | HP: (65) 9191 5725



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 2 April 2019 4:36 PM
To: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>

Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Perry HE (SPF) <Perry_HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard_SEAH@spf.gov.sg>; Peng Seng NG (SPF) <NG_Peng_Seng@spf.gov.sg>; Rashid ABU HASAN (SPF) <Rashid_Abu_Hasan@spf.gov.sg>; assignments <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (TP113L)

Dear Wei Yea,

Can we submit our report?

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]

Sent: Thursday, 21 March 2019 2:34 PM

To: 'Wei Yea LIM (SPF)' <LIM_Wei_Yea@spf.gov.sg>

Cc: 'Kim Pang CHAY (SPF)' <CHAY_Kim_Pang@spf.gov.sg>; 'Kwee Huat TAN (SPF)' <TAN_Kwee_Huat@spf.gov.sg>; 'Perry HE (SPF)' <Perry_HE@spf.gov.sg>; 'Bernard SEAH (SPF)' <Bernard_SEAH@spf.gov.sg>; 'Peng Seng NG (SPF)' <NG_Peng_Seng@spf.gov.sg>; 'Rashid ABU HASAN (SPF)' <Rashid_Abu_Hasan@spf.gov.sg>; 'assignments' <assignments@lkkauto.com>; 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>; 'SUR' <sur@lkkauto.com>

Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (TP113L)

Dear Wei Yea,

Please refer attached.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wei Yea LIM (SPF) [mailto:LIM_Wei_Yea@spf.gov.sg]

Sent: Monday, 11 March 2019 3:31 PM

To: assignments <assignments@lkkauto.com>

Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Perry HE (SPF) <Perry_HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard_SEAH@spf.gov.sg>; Peng Seng NG (SPF)

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 21 March 2019 2:35 PM
To: 'Wei Yea LIM (SPF)'
Cc: 'Kim Pang CHAY (SPF)'; 'Kwee Huat TAN (SPF)'; 'Perry HE (SPF)'; 'Bernard SEAH (SPF)'; 'Peng Seng NG (SPF)'; 'Rashid ABU HASAN (SPF)'; assignments; Admin-D (LKKAuto); SUR
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (TP113L)
Attachments: TP 113L (SPF) .pdf; LKK SURVEYOR PHOTO.pdf

Dear Wei Yea,

Please refer attached.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wei Yea LIM (SPF) [mailto:LIM_Wei_Yea@spf.gov.sg]
Sent: Monday, 11 March 2019 3:31 PM
To: assignments <assignments@lkkauto.com>
Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Perry HE (SPF) <Perry_HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard_SEAH@spf.gov.sg>; Peng Seng NG (SPF) <NG_Peng_Seng@spf.gov.sg>; Rashid ABU HASAN (SPF) <Rashid_Abu_Hasan@spf.gov.sg>; 'Ai Phing (LKKAuto)' <aiphing@lkkauto.com>; 'Shiau Chan (LKKAuto)' <siewsc@lkkauto.com>
Subject: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (TP113L)

Hi Catherine,

Please provide Appraisal Services for the following SPF vehicles at SMRT Automotive Services:

- **TP113L**

In attached, please find the recommended Parts and Labour required for the repair of this vehicle.

Kindly contact the following SMRT personnel for viewing of the damaged vehicle:

- Mr Kong Sew Kui
- Mr Jason Yeo

Thank you and best regards,

Nivitha (LKK Auto)

From: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>
Sent: Monday, 11 March 2019 3:31 PM
To: assignments
Cc: Kim Pang CHAY (SPF); Kwee Huat TAN (SPF); Perry HE (SPF); Bernard SEAH (SPF); Peng Seng NG (SPF); Rashid ABU HASAN (SPF); 'Ai Phing (LKKAuto'; 'Shiau Chan (LKKAuto'
Subject: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (TP113L)
Attachments: TP113L.xlsx

Hi Catherine,

Please provide Appraisal Services for the following SPF vehicles at SMRT Automotive Services:

- **TP113L**

In attached, please find the recommended Parts and Labour required for the repair of this vehicle.

Kindly contact the following SMRT personnel for viewing of the damaged vehicle:

- Mr Kong Sew Kui
- Mr Jason Yeo

Thank you and best regards,

WeiYea LIM
Contract Management
AEMD, Police Logistics Department
Singapore Police Force
DID: (65) 6478 4844



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR RATE (\$)	MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP		
1	MATERIALS						
1.1	FRONT CRASH BAR	1	BENT	\$ 530.00	\$ 530.00		
1.2	FRONT FOOTREST ASSEMBLY - LH AND RH	1	MISSING	\$ 70.00	\$ 70.00		
1.3	WINDSHIELD	1	CRACKED	\$ 696.00	\$ 696.00		
1.4	FRONT COWLING PROTECTOR - LH	1	CRACKED	\$ 284.00	\$ 284.00		
1.5	FRONT INNER PANEL - LH	1	CRACKED	\$ 343.00	\$ 343.00		
1.6	METER COWLING	1	CRACKED	\$ 60.00	\$ 60.00		
1.7	METER LENS	1	CRACKED	\$ 55.00	\$ 55.00		
1.8	FRONT BLINKER LIGHT - RH	1	MISSING	\$ 380.00	\$ 380.00		
1.9	SIDE MIRROR - LH	1	CRACKED	\$ 140.00	\$ 140.00		
1.10	REAR CRASH BAR - LH	1	DENTED	\$ 145.00	\$ 145.00		
1.11	SIDE BOX COVER - LH	1	SCRATCHED	\$ 480.00	\$ 480.00		
	TO SUPPLY LABOUR & MATERIAL TO REPLACE BAR LIGHT COVER	1		\$ 3,183.00	\$ 3,183.00		
1	SCOPE OF REPAIRS						
1.1	TO REMOVE AND REPLACE FRONT CRASH BAR						1
1.2	TO REMOVE AND REPLACE FRONT FOOTREST - LH AND RH						0.5
1.3	TO REPLACE WINDSHIELD						0.5
1.4	TO REMOVE AND REPLACE FRONT COWLING PROTECTOR AND INNER PANEL - LH						0.5
1.5	TO REMOVE AND REPLACE METER COWLING METER LENS						1
1.6	TO REMOVE AND REPLACE FRONT BLINKER LIGHT - RH						0.5
1.7	TO REMOVE AND REPLACE SIDE MIRROR - LH						0.5
1.8	TO REMOVE AND REPLACE REAR CRASH BAR - LH						0.5
1.9	TO REMOVE AND REPLACE SIDE BOX COVER - LH						0.5
1.10	TO REPAIR AND RESPRAY PAINT FOR FRONT COWLING						2
1.11	TO SPRAY PAINT FRONT COWLING PROTECTOR - LH						1
1.12	TO REMOVE AND INSTALL CYLINDER BLOCK						10
2	ADDITIONAL SERVICES						
2.1	TOWING FROM STN - WKSP (SOR 10)					81.6	1
2.2	TOWING FROM WKSP - STN (SOR 10)					81.6	1

COSTING	TOTAL PARTS COST	\$3,183.00		
	TOTAL MAN-HOUR			20.5



Scope Of Work
Home Team Agency

SCOPE OF WORK

1 To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

CONTRACTOR	SMRT	VEH TYPE :	E9	UNIT	PDS
VEH NO :	TP113L	REPAIR TYPE:	ACCIDENT		
VEH MAKE/MODEL	YAMAHA XJ900		43016 km		

Reference No. 0113/SPF/2W/19/03/01

iLMS No. 1100019963

S/N	PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark	Total Parts Cost Per Unit After Mark Up (\$)
1	Scope Of Repairs					
1.1	Front Crash Bar BT ✓	\$530.00				
1.2	Front Footrest Assembly - LH and RH MIS ✓	\$70.00				
1.3	Windshield CRA ✓	\$696.00				
1.4	Front Cowling Protector - LH CRA ✓	\$284.00				
1.5	Front Inner Panel - LH CRA ✓	\$343.00				
1.6	Meter Cowling CRA ✓	\$60.00				
1.7	Meter Lens CRA ✓	\$55.00				
1.8	Front Blinker Light - RH MIS ✓	\$380.00				
1.9	Side Mirror - LH CRA ✓	\$140.00				
1.10	Rear Crash Bar - LH DD ✓	\$145.00				
1.11	Side Box Cover - LH SC ✓	\$480.00				
1.12	Cylinder Block SVC X	\$950.00				
2	Additional Services					
2.1	NA	\$0.00	0	0%	0.00	0.00
Remarks:					Parts Total:	

S/N	LABOUR DESCRIPTION	Man-Hour Rate (\$)	Man-Hour Qty	Total Man-Hour Cost (\$)
1	Scope Of Repairs			
1.1	To Remove and Replace Front Crash Bar		1	
1.2	To Remove and Replace Front Footrest - LH and RH		10.5	
1.3	To Replace Windshield		0.5	
1.4	To Remove and Replace Front Cowling Protector and Inner Panel - LH		0.5	
1.5	To Remove and Replace Meter Cowling and Meter Lens		1	
1.6	To Remove and Replace Front Blinker Light - RH		10.5	
1.7	To Remove and Replace Side Mirror - LH		0.5	
1.8	To Remove and Replace Rear Crash Bar - LH		0.5	
1.9	To Remove and Replace Side Box Cover - LH		0.5	
1.10	To Repair and Respray Paint for Front Cowling		2	
1.11	To Spray Paint Front Cowling Protector - LH		1	
1.12	To Remove and Install Cylinder Block		10	
2	Additional Services			
2.1	Towing from STN - WKSP (SOR 10)	81.60	1	
2.2	Towing from WKSP - STN (SOR10)	81.60	1	
		Labour Total:		
GRAND TOTAL :				
Total sum billed under SOR only :				
Total sum billed under CVR only :				
Contractor shall complete the entire repair within <u>60</u> working days upon quotation approved date. (Include parts awaiting time)				

Verification of Scope of Work					
Contractor QC		Verified By		Approved By	
Name	KONG SEW KUI	Name		Name	
Date	8.3.2019	Date		Date	
Sign:		Sign:		Sign:	
Verification of Completed Repairs					
Contractor QC		Home Team QC / Fleet Manager / Appointed Surveyor		Home Team Contract / Fleet Manager	
Name		Name		Name	
Date		Date		Date	
Sign:		Sign:		Sign:	

25/3/19
Hwee Jie - LK1
20/3/19
P/P 4 days.
Not Authorise



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF19004461/Jsd3e2		
ACCIDENT CLAIM SECTION (SPORE POLICE FORCE)1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333 ATTN : WEI YEA LIM		Date : 24-04-2019		
		Code : SPF		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.	Veh. Inspected		TP 113L	
Policy No.	Coverage (\$)		0.00	
Claim No.	HOMSPFETQ16000399	Excess (\$)	0.00	
Assign From	WEI YEA LIM	Assign Date	11/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA XJ900P	c.c	892	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JYA4KM00000127612	Colour	WHITE	
Odometer	43016	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	120/70 R17	BRIDGESTONE	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	150/70 R17	BRIDGESTONE	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	Inspection Date		20/03/2019	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				



Registration No. TP 113L

S/N	ITEM DESCRIPTION	PARTS					
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	MAN-HOUR RATE (S)	MAN-HOUR QTY
1	MATERIALS						
1.1	FRONT CRASH BAR	1	BENT	\$ 530.00	\$ 530.00		
1.2	FRONT FOOTREST ASSEMBLY - LH AND RH	1	MISSING	\$ 70.00	\$ 70.00		
1.3	WINDSHIELD	1	CRACKED	\$ 696.00	\$ 696.00		
1.4	FRONT COWLING PROTECTOR - LH	1	CRACKED	\$ 284.00	\$ 284.00		
1.5	FRONT INNER PANEL - LH	1	CRACKED	\$ 343.00	\$ 343.00		
1.6	METER COWLING	1	CRACKED	\$ 60.00	\$ 60.00		
1.7	METER LENS	1	CRACKED	\$ 55.00	\$ 55.00		
1.8	FRONT BLINKER LIGHT - RH	1	MISSING	\$ 380.00	\$ 380.00		
1.9	SIDE MIRROR - LH	1	CRACKED	\$ 140.00	\$ 140.00		
1.10	REAR CRASH BAR - LH	1	DENTED	\$ 145.00	\$ 145.00		
1.11	SIDE BOX COVER - LH	1	SCRATCHED	\$ 480.00	\$ 480.00		
1.12	CYLINDER BLOCK	1	SERVICEABLE	\$ 950.00			
1	SCOPE OF REPAIRS						
1.1	TO REMOVE AND REPLACE FRONT CRASH BAR						1
1.2	TO REMOVE AND REPLACE FRONT FOOTREST - LH AND RH						0.5
1.3	TO REPLACE WINDSHIELD						0.5
1.4	TO REMOVE AND REPLACE FRONT COWLING PROTECTOR AND INNER PANEL - LH						0.5

1.5	TO REMOVE AND REPLACE METER COWLING METER LENS						1
1.6	TO REMOVE AND REPLACE FRONT BLINKER LIGHT - RH						0.5
1.7	TO REMOVE AND REPLACE SIDE MIRROR - LH						0.5
1.8	TO REMOVE AND REPLACE REAR CRASH BAR - LH						0.5
1.9	TO REMOVE AND REPLACE SIDE BOX COVER - LH						0.5
1.10	TO REPAIR AND RESPRAY PAINT FOR FRONT COWLING						2
1.11	TO SPRAY PAINT FRONT COWLING PROTECTOR - LH						1
1.12	TO REMOVE AND INSTALL CYLINDER BLOCK						10
2	ADDITIONAL SERVICES						
2.1	TOWING FROM STN - WKSP (SOR 10)					81.6	1
2.2	TOWING FROM WKSP - STN (SOR 10)					81.6	1
COSTING		TOTAL PARTS COST			\$3,183.00		
		TOTAL MAN-HOUR					20.5

Registration No. TP 113L

Vehicle Inspected By

ONG HWEE JIE
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.