

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III19004463/GPA3Q2

**Date:** 18/08/2020

#### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SLP76E	<b>Insured Vehicle No :</b>	SHA3834R
Date of Loss: 05/03/2019	Nature of Claim: TP	Claim No: MCT19030146

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP76E		
Make & Model:	HONDA VEZEL, 1.5 (A)	Engine No:	LEB5944547
Reg. Date:	27/06/2017 (Man. Year: 2017)	Chassis No:	RU31244529
Colour:	Black	Odometer:	57970 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	245/40ZR18	Rear Tyre Size:	245/40ZR18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,549.00	1,791.07	757.93	29.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,070.00	1,070.00	2,000.00	65.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,619.00</b>	<b>2,861.07</b>	<b>2,757.93</b>	<b>49.08</b>
<b>+ GST 7.00/7.00% (S\$)</b>	393.33	200.27	193.06	49.08
<b>Nett Amount (S\$)</b>	<b>6,012.33</b>	<b>3,061.34</b>	<b>2,950.99</b>	<b>49.08</b>
<b>+ Car Rental (6.0 x S\$100.00/day + 7.00% GST) (S\$)</b>		642.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>3,710.79</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,700.00</b>		

#### INSPECTION

Date of Assignment:	11/03/2019	
Date Inspected:	12/03/2019 Inspected At:	Jack Cars Enterprise Pte Ltd - Ubi (HQ) BLK 3007 UBI ROAD 1 #01-450 Singapore 408701
Estimated Period of Repair:	4.0 days	

**Adjuster:** XING GUO QIANG

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 27 Jul 2020)
<b>Parts:</b> M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLP76E)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Buckled	1,200.00 FL	*1,100.00 FL
2	1		*REAR BUMPER	Deformed	980.00 FL	*751.34 FL
3	1		*REVERSE SENSOR	Not Necessary	200.00 FS	*- FS
4	1		*RELAY SENSOR	Damaged	180.00 FS	*96.00 FS
5	1		*SILICON SEALANT	Necessary	100.00 FS	*50.00 FS
6	1		*CLIPS	Necessary	100.00 FS	*40.00 FS
7	1		*HONDA EMBLEM	Not Necessary	95.00 FS	*- FS
8	1		*VEZEL EMBLEM	Necessary	75.00 FS	*69.00 FS
9	1		*HYBRID EMBLEM	Necessary	55.00 FS	*55.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>2,985.00</b>	<b>2,161.34</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	436.00	370.27
<b>Total Parts (S\$)</b>	<b>2,549.00</b>	<b>1,791.07</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	New	1,200.00	400.00
2	TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	New	900.00	400.00
3	TO CHECK WIRING & REWIRE	New	100.00	30.00
4	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY }	New	150.00	60.00
5	TO REMOVE AND REINSTALL TAILGATE COMPONENTS }	New	120.00	0.00
6	TO REMOVE AND REINSTALL REAR WINDSCREEN	New	200.00	100.00
7	TO REMOVE & REINSTALL REVERSE & RELAY SENSOR	New	150.00	40.00
8	TO CHECK LIGHTING SYSTEM	New	130.00	0.00
9	ANTI RUST TREATMENT	New	120.00	40.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,070.00</b>	<b>1,070.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >