

# ESTIMATE

<b>DATE OF ACCIDENT :</b> 05/03/2019
<b>VEHICLE :</b> SLP76E
<b>MAKE &amp; MODEL :</b> HONDA VEZEL
<b>INSURANCE :</b> INDIA INTERNATIONAL INSURANCE
<b>SURVEYOR :</b> LKK AUTO

PARTS		CONDITION	AMOUNT
1.	REAR BOOT / <i>Blue</i>		\$ 1200
2.	REAR BUMPER / <i>re.</i>		\$ 980
<b>SPECIAL NETT</b>			
1.	REVERSE SENSOR X <i>NN</i>		\$ 200
2.	RELAY SENSOR ?		\$ 180
3.	SILICON SEALANT / <i>5ml</i>	<i>50.</i>	\$ 100
4.	CLIPS / <i>5ml</i>	<i>40</i>	\$ 100
5.	"HONDA" EMBLEM X <i>NN</i>		\$ 95
6.	"VEZEL" EMBLEM / <i>5ml</i>		\$ 75
7.	"HYBRID" EMBLEM / <i>5ml</i>		\$ 55
<b>LABOUR</b>			
1.	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	<i>400</i>	\$ 1200
2.	TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	<i>400</i>	\$ 900
3.	TO CHECK WIRING & REWIRE	<i>30</i>	\$ 100
4.	TO REMOVE AND REINSTALL TAILGATE COMPONENTS	<i>60</i>	\$ 120
5.	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY		\$ 150
6.	TO REMOVE AND REINSTALL REAR WINDSCREEN	<i>100.</i>	\$ 200

7.	TO REMOVE & REINSTALL REVERSE & RELAY SENSOR	40	\$ 150
8.	TO CHECK LIGHTING SYSTEM	NN X	\$ 130
9.	ANTI RUST TREATMENT	40.	\$ 120
		<b>PARTS - 20% :</b>	\$ 1,744
		<b>SPECIAL NETT :</b>	\$ 805
		<b>LABOUR :</b>	\$ 3,070
		<b>TOTAL :</b>	\$ 5,619
		<b>7% GST :</b>	\$ 393.33
		<b>GRAND TOTAL :</b>	\$ 6,012.33

4 Days .

Part by part .

before paint photos .

Guo Cai ap - 82880282

12/3/19 .

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: