

ASSIGNMENT (REV)

REF: CS/CTI/19004468/Est 3

Report Instruction

Client Name

Steve

ASSIGNMENT (Office)

Insured Person

Chong Buon & n

CTI

Estimated Cost

Date/Time: 11/3/19 @ 3:32pm

OD / TP / AW / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No.

SCU 97132

Insured

PC4347T

at Workshop no.

Triple-T Automobile

Tel

98535175

of

25 Kuki Bkt Rd & # 05-66

413550

Policy No.

Claim No.

Sum Insured

Room

Make of Veh

(Client's Record)

D.O.A. 7/3/19

CA / REV / REP. / REV 24 HRS lwp

Date/Time

5:17pm @ 12/3/19

Person Contacted

Irene

H.O.D. Endorsement

Vehicle

IN OUT

Date/Time

Action/Instruction (✓) Estimate

SCU 97132 - VBA / INC 15002291 / R1

D.O.A - 06/02/2015

PC 4347T - CC3 / CTI / 19002577 / AP9 3

D.O.A - 08/02/2019

ASS. REC. BY:

Steve

REF: CTF

Call her once Reach -

ASSIGNMENT

30/05/07

29/05/19

From:

Date:

12/3/19

Estimated Cost:

OD TP/WS/TP RES/OD RES/EVA/INV/MVTo Inspect Vehicle No: SGU 9713 Zat Workshop n/s Triple - Tof 25 Kaki Bukit Rd 4 # 05-66

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

Irene @ 9853 5175

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

564 97132

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Altis

c.c

1.6

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

250527

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR 0532EC 107149350

Gen. Cond: Good (Fair) / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185 / 70R14

R:

1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

NEXEN

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

7/3/19

D.O.I.

12/3/19

Survey held at:

Triple - T

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV - 20,999

*Repairs agreed 4k repair limit.

PV - 16,275

NV - 3725

RECEIVED 3 5 APR 2019

Steve

Do Not finalized CAR with
repairer due to repair limit.05/04/19 Confirmed LIS & H.000/- @ 12 days with Steve
(\$ 8,358 - 88 Res - 68%)

Date/Time, File Page to?

05/04/19



: Prel. Report



: Final Report

1) Type

Date/Time, File Return to?

2)

Days Of Repair: 12

Resurvey No. of Trip: 2

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Phone:

Other:

TOTAL

Report Format:

Lump Sum / LBJ: \$ 4,000/- 45



From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Monday, 11 March 2019 3:32 PM
To: Irene
Cc: candy@iaconsultingsg.com; assignments
Subject: RE: ACCIDENT INVOLVING SGU9713Z AND PC4347T ALONG PIE TWDS CHANGI BEFORE ENG NEO AVE EXIT 17 ON 07.03.2019

WITHOUT PREJUDICE

SAVE AS TO COSTS

Dear Irene,

We refer to your email.

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Regards,
Chong Boon Sen
Claims Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E

Steve Chen (LKK Auto)

From: Irene <motor@iaconsultingsg.com>
Sent: Thursday, April 04, 2019 9:36 AM
To: Steve Chen (LKK Auto)
Cc: candy@iaconsultingsg.com
Subject: RE: SGU9713Z Finalize

Dear Steve,

We refer to your email below.

We confirm COR @ lump sum \$4,000.00 at 12 working days.

We shall submit LOD to the third party insurer within the next 2 days.

Thank you.

Regards,
Irene Tan

From: Steve Chen (LKK Auto) [<mailto:SteveChen@lkkauto.com>]
Sent: Wednesday, 3 April 2019 6:05 PM
To: motor@iaconsultingsg.com
Subject: SGU9713Z Finalize

Dear Irene,

The above vehicle finalize \$4k. And 12 days.

Kindly confirm.

Thanks

Best Regards,
Steve Chen | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8625Z
Vehicle Details	
Vehicle No.:	SGU9713Z
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	3ZZ4665009
Chassis No.:	MR053ZEC107149350
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$14,924.00
Original Registration Date:	30 May 2007
First Registration Date:	30 May 2007
Transfer Count:	1
Actual ARF Paid:	\$16,417.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 May 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$25,333.00
COE Rebate Amount:	\$16,275.00
Total Rebate Amount:	\$16,275.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 12 Mar 2019

OK



DON'T FALL FOR HER ONLINE PURCHASE SCAM

CLICK TO FIND OUT MORE AT www.scamalert.sg



toyota altis

Price Range ▼

Depreciation ▼

> 10 year(s) ▼

Vehicle Type ▼

Advanced
Search

Home » Used Cars » Car Search » Toyota Corolla Altis 1.6A (COE till 06/2022)

Toyota Corolla Altis 1.6A (COE till 06/2022)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

CONSIGNMENT



Car Search
We Represent You

Price	\$20,800		
Depreciation ⓘ	\$6,310 /yr	Reg Date	28-Jun-2007 (3yrs 3mths 15days COE left)
Mileage	137,648 km (11.8k /yr)	Manufactured ⓘ	2007
Road Tax ⓘ	\$890 /yr	Transmission	Auto
Dereg Value ⓘ	\$16,686 as of today (change)	OMV ⓘ	\$15,245
COE ⓘ	\$25,313	ARF ⓘ	\$16,770
Engine Cap	1,598 cc	Power	81.0 kW (108 bhp)
Curb Weight ⓘ	1,115 kg	No. of Owners ⓘ	4
Type of Vehicle	Mid-Sized Sedan		

Features

Fuel Efficient, Powerful 1.6L 16 Valves DOHC VVT-i Engine, Smooth Auto Transmission With ECT, Dual SRS Airbags, ABS, Digital Climate Aircon Controls. View specs of the Toyota Corolla Altis (2000-2007)

Accessories

Upholstery Beige Leather Interior, Factory Audio CD System With Steering Audio Control, Reverse Sensors, Electrical Retractable Side Mirror.

Description

Most Popular Sedan Among Its Class, Powerful, Comfort And Spacious. Owned By A Careful Owner, Well Maintained Condition. Trade In Welcome, Flexible Loan Scheme Available, Consignment Unit, Call Us Now! Viewing Strictly By Appointment Only.

Category

COE Car, Consignment Car

Status

Avi [Compare](#)

Owner Consignment Car

This car is for sale by direct owner via a consignment agent. Consignment agents help to market, sell and handle all documentation on the car seller's behalf.

- List of owner consignment cars
- List of consignment agents



Location Map

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company

Car Search

- dealer's pricelist
- 70 vehs sold | 153 vehs avail

Address

18 Sin Ming Lane #04-02
Search cars nearby this location

Location

Midview City

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?



toyota altis

Price Range

Depreciation

> 10 year(s)

Vehicle Type

Advanced Search

Home » Used Cars » Fei Yang Auto » Toyota Corolla Altis 1.6A (COE till 10/2022)

Toyota Corolla Altis 1.6A (COE till 10/2022)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price	\$22,600		
Depreciation ⓘ	\$6,290 /yr	Reg Date	15-Oct-2007 (3yrs 7mths 2days COE left)
Mileage	120,000 km (10.5k /yr)	Manufactured ⓘ	2007
Road Tax ⓘ	\$890 /yr	Transmission	Auto
Dereg Value ⓘ	\$15,300 as of today (change)	OMV ⓘ	\$15,245
COE ⓘ	\$21,282	ARF ⓘ	\$16,770
Engine Cap	1,598 cc	Power	81.0 kW (108 bhp)
Curb Weight ⓘ	1,115 kg	No. of Owners ⓘ	1
Type of Vehicle	Mid-Sized Sedan		

Features

View specs of the Toyota Corolla Altis (2000-2007)

Description

1 Owner, Leather Seats, Sport Rim, Reverse Sensor, Fuel Efficient, Well Maintained, Call Before Coming.

Category

COE Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Location Map

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company

Fei Yang Auto

» dealer's pricelist

» 17 vehs sold | 11 vehs availab

Address

3 Ang Mo Kio Street 62 #08-27

Search cars nearby this location

Location

Link @ AMK

Office No

65561611

Contact Person(s)

Jackson

869901

Jeffrey Lim

902551

Posted on: 08-Mar-2019 | Last Updated on: 12-Mar-2019

Up! →
Compare

» more Financial info

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/03/2019 10:40
Date Of Accident	07/03/2019 07:30
Exact Location Of Accident	PIE TOWARDS CHANGI BEFORE ENG NEO AVE EXIT 17
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGU9713Z
Insured/Policyholder	
Name Of Registered Owner	SEAN LIM YEONG KIAT
NRIC No	S6908625Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96931601
Alternative Phone No	OFFICE-96931601

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS 1.6 AUTO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5051987444-07
Cover Note Number	

Driver

Name of Driver	SEAN LIM YEONG KIAT
NRIC No	S6908625Z
Date Of Birth	16/03/1989
Occupation	INDOOR
Date Of Driving Pass	17/04/1993
Driving Experience	25 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96931601
Fax Number	
Contact Number	OFFICE-96931601
Email Address	NOEMAIL

Address	29 FERNVALE CLOSE #15-22
Postcode	797464
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC4347T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	DINIE HAZIQ BIN NORDIN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. The Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law or administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, contesting or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
(Name)
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



Ⓐ SGU 9713Z

Ⓑ PC 4347T.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along PIE. The traffic was heavy and the vehicles in front were moving slowly. When the vehicle in front slowed down, I reduced my speed to slow down too. Suddenly, vehicle B collided onto my car's rear portion without slowing down at all.

DECLARATION

(We declare the foregoing particulars are true in every respect.)



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/IN No.:

TRIPLE-T AUTOMOBILE

BLK 5 DEFU LANE 10 #01-574 SINGAPORE 539186

TEL: 6280 8927 FAX: 6280 4205

Vehicle No: SGU9713Z

Model No. Toyota Altis

Chassis no. *

Accident Date: 7/3/2019

Owner: Sean Lim Yeong Kiat

Date of Estimate: 11/3/2019

Estimate for Accident Vehicle No. SGU9713Z

List Items:	Qty	Unit Price	Total Amount
1 Bootlid ✓ DD	1	\$788.90	\$788.90 /
2 Bootlid lock ✓ BT	1	\$102.40	\$102.40 /
3 Bootlid lock striker ✓ BT	1	\$85.00	\$85.00 /
4 Bootlid inner garnish × NF	1	\$185.70	\$185.70 X
5 Bootlid lock sensor × NS	1	\$396.50	\$396.50 X
6 Bootlid logo ✓ NEC	1	\$90.80	\$90.80 /
7 Bootlid emblem - COROLLA ✓ NEC	1	\$55.20	\$55.20 /
8 Bootlid emblem - ALTIS ✓ NEC	1	\$45.80	\$45.80 /
9 Bootlid emblem - 1.6E ✓ NEC	1	\$55.00	\$55.00 /
10 Bootlid emblem - VVT-i ✓ NEC	1	\$58.90	\$58.90 /
11 Bootlid weatherstrip ✓ CRU	1	\$140.50	\$140.50 /
12 Bootlid hinge ✓ RH LH ✓ BT	2	\$110.80	\$221.60 /
13 Bootlid outer garnish ✓ DR	1	\$198.70	\$198.70 /
14 Bootlid reflector RH ✓ LH ✓ DR	2	\$205.00	\$205.00 /
15 Rear bumper reinforcement × NS NS	1	\$352.20	\$352.20 X
16 Rear bumper ✓ DD	1	\$458.70	\$458.70 /
17 Rear bumper bracket RH ✓ LH ✓ DD	2	\$85.50	\$171.00 /
18 Rear bumper side retainer RH ✓ LH ✓ DR	2	\$35.40	\$70.80 /
19 Rear end panel ✓ DD	1	\$700.80	\$700.80 / 580.60
20 Rear end panel top garnish ✓ CRU	1	\$112.00	\$112.00 /
21 Rear door lh - warped-repair × R	1	\$952.30	\$0.00 X
22 Fuel tank cover lh × NN	1	\$98.50	\$98.50 X
23 Taillamp RH ✓ LH ✓ DR	2	\$325.80	\$651.60 /
24 Taillamp lower panel RH ✓ LH ✓ DD	2	\$102.30	\$204.60 /
25 Rear floor panel ✓ DD	1	\$658.00	\$658.00 /
26 Rear floor side panel ? LH ✓ DD REPX	2	\$187.80	\$375.60 187.80 /
27 Rear floor panel top board ✓ TN	1	\$155.70	\$155.70 /
28 Rear fender RH ✓ LH ✓ DD	2	\$812.40	\$1,624.80 /
29 Rear fender inner cowling LH × RH × NN	2	\$88.50	\$177.00 X
30 Rear fender inner garnish LH ? RH ? NN	2	\$201.30	\$402.60 X
31 Exhaust silencer ? × NN	1	\$612.30	\$612.30 X

32 Exhaust heat shield ? X NN

1	\$110.00	\$110.00 X
Sub-Total Amount =		\$9,438.50 6923.40
Less parts-discount = 25%		\$2,359.63 -75%
Sub-Total =		\$7,078.88 5192.55

Special Nett Items

	Qty	Unit Price	Total Amount
1 Rear bumper clips NEC	1set	\$50.00	\$50.00 30 ✓
2 Rear number plate 00	1	\$50.00	\$50.00 30 ✓
3 Rear end panel top garnish clips NEC	4	\$5.00	\$20.00 ✓
4 Rear reverse sensor DR	1set	\$280.00	\$280.00 1280
5 Bootlid inner garnish clips NN	6	\$5.00	\$30.00 X
6 Taillamp clips NEC	6	\$5.00	\$30.00 20 ✓
7 Rear windscreen sealant NEC	1	\$60.00	\$60.00 ✓
8 Rear floor panel insulation NN	1	\$150.00	\$150.00 ? X
9 Rear fender inner shield clips NN	2sets	\$50.00	\$50.00 X
Sub-Total =			\$720.00 360
Total cost for parts =			\$7,798.88

Labour charges

1	Panel beating for replace and repair affected parts	\$1,900.00	1400
2	Spray painting	\$1,600.00	1400
3	Apply putty and anti-corrosion to affected parts.	\$250.00	50
4	Wiring / bulb checking	\$50.00	30
5	R/R rear exhaust pipe	\$100.00	50
6	Towing	\$60.00	/
7	Rear chassis alignment charges	\$250.00	? X
8	R/R rear windscreen glass	\$150.00	100
9	R/R rear upholstery to facilitate repair	\$120.00	30
10	R/R reverse sensor	\$80.00	20
		<hr/>	
		\$4,560.00	3140

P - 5,192.55
 NI - 360
 L - 3140
 8692.55
 L/S - 6954.04
 = 6950

* Reparer agreed 4K repair

Total parts = \$7,798.88

Total labour = \$4,560.00

Total Amount = \$12,358.88

Total Amount

Let Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____




































...CLAIM SUBFOLDER...(Pending for Survey Report)













































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Mar 2019		14 Mar 2019 15:44 Edit Adj Rpt	S\$4,000.00 Edit Estimates	S\$4,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured: -, ID: -									
Main Claimant: SEAN LIM YEONG KIAT									
Vehicle Reg. No.:	SGU9713Z	Date of Loss:	07/03/2019 00:00 - :59 [141 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D201089C02/7	Policy/Cover Note No.:	DMB1SN1810901800 (Comprehensive)						
Vehicle Reg. No. (Insured):	PC4347T	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Triple-t Automotive (HQ) NO.10 KAKI BUKIT ROAD 2 #03-07 FIRST EAST CENTRE, 417868 Kaki Bukit - Tel: 81856692								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 25/03/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGU9713Z (SNM19D201089C02/7)
[PC4347T]
TP
SEAN LIM YEONG KIAT
Mar 7 2019 12:00AM
[-]
Triple-t Automotive

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail					Print	
1	28/03/19 18:57	General View			Load JPG				<input checked="" type="checkbox"/>	
2	28/03/19 18:57	General View			Load JPG				<input checked="" type="checkbox"/>	
3	28/03/19 18:57	General View			Load JPG				<input checked="" type="checkbox"/>	
4	28/03/19 18:57	General View			Load JPG				<input checked="" type="checkbox"/>	
5	28/03/19 18:57	General View			Load JPG				<input checked="" type="checkbox"/>	
6	28/03/19 18:57	General View			Load JPG				<input checked="" type="checkbox"/>	
7	28/03/19 18:57	General View			Load JPG				<input checked="" type="checkbox"/>	
8	28/03/19 18:57	General View			Load JPG				<input checked="" type="checkbox"/>	
9	28/03/19 18:57	General View			Load JPG				<input checked="" type="checkbox"/>	
10	28/03/19 18:57	General View			Load JPG				<input checked="" type="checkbox"/>	
11	28/03/19 18:57	General View			Load JPG				<input checked="" type="checkbox"/>	
12	28/03/19 18:57	General View			Load JPG				<input checked="" type="checkbox"/>	
13	28/03/19 18:57	General View			Load JPG				<input checked="" type="checkbox"/>	
14	28/03/19 18:57	General View			Load JPG				<input checked="" type="checkbox"/>	
15	28/03/19 18:57	General View			Load JPG				<input checked="" type="checkbox"/>	
16	28/03/19 18:57	General View			Load JPG				<input checked="" type="checkbox"/>	
17	28/03/19 18:57	General View			Load JPG				<input checked="" type="checkbox"/>	
18	28/03/19 18:57	General View			Load JPG				<input checked="" type="checkbox"/>	
19	28/03/19 18:57	General View			Load JPG				<input checked="" type="checkbox"/>	
20	28/03/19 18:57	General View			Load JPG				<input checked="" type="checkbox"/>	
21	28/03/19 18:57	General View			Load JPG				<input checked="" type="checkbox"/>	
22	28/03/19 18:57	General View			Load JPG				<input checked="" type="checkbox"/>	
23	28/03/19 18:57	General View			Load JPG				<input checked="" type="checkbox"/>	
24	28/03/19 18:57	General View			Load JPG				<input checked="" type="checkbox"/>	
25	28/03/19 18:57	General View			Load JPG				<input checked="" type="checkbox"/>	
26	28/03/19 18:57	General View			Load JPG				<input checked="" type="checkbox"/>	
27	28/03/19 18:57	General View			Load JPG				<input checked="" type="checkbox"/>	
28	28/03/19 18:57	General View			Load JPG				<input checked="" type="checkbox"/>	
29	28/03/19 18:57	General View			Load JPG				<input checked="" type="checkbox"/>	
30	28/03/19 18:57	General View			Load JPG				<input checked="" type="checkbox"/>	
31	28/03/19 18:57	General View			Load JPG				<input checked="" type="checkbox"/>	
32	28/03/19 18:57	General View			Load JPG				<input checked="" type="checkbox"/>	
33	28/03/19 18:57	General View			Load JPG				<input checked="" type="checkbox"/>	
34	28/03/19 18:57	Odometer Reading			Load JPG				<input checked="" type="checkbox"/>	
35	28/03/19 18:57	Chassis Number			Load JPG				<input checked="" type="checkbox"/>	
36	28/03/19 18:57	General View			Load JPG				<input checked="" type="checkbox"/>	
37	28/03/19 18:57	General View			Load JPG				<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	28/03/19 18:57	General View	 Load JPG	<input checked="" type="checkbox"/>
39	28/03/19 18:57	General View	 Load JPG	<input checked="" type="checkbox"/>
40	28/03/19 18:57	General View	 Load JPG	<input checked="" type="checkbox"/>
41	28/03/19 18:57	General View	 Load JPG	<input checked="" type="checkbox"/>
42	28/03/19 18:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	28/03/19 18:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	28/03/19 18:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	28/03/19 18:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	28/03/19 18:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	28/03/19 18:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	28/03/19 18:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	28/03/19 18:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	28/03/19 18:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	28/03/19 18:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	28/03/19 18:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	28/03/19 18:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	28/03/19 18:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	28/03/19 18:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	28/03/19 18:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	28/03/19 18:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	28/03/19 18:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	28/03/19 18:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	28/03/19 18:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	28/03/19 18:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	28/03/19 18:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	28/03/19 18:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	28/03/19 18:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	28/03/19 18:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	28/03/19 18:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	28/03/19 18:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	28/03/19 18:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	28/03/19 18:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	28/03/19 18:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	28/03/19 18:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	28/03/19 18:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	28/03/19 18:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	28/03/19 18:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	28/03/19 18:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	28/03/19 18:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	28/03/19 18:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	28/03/19 18:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	28/03/19 18:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	14/03/19 15:45	PRI CONTACT	 Load PDF	
2	26/03/19 16:59	Singapore Accident Statement	 Load PDF	
3	26/03/19 17:04	REPORT OF SGU97132	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119004468/ESD3Q2

Date: 10/04/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SN1810901800
Claimant Vehicle No:	SGU9713Z	Insured Vehicle No:	PC4347T
Date of Loss:	07/03/2019	Nature of Claim:	TP
		Claim No:	SNM19D201089C02/7

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGU9713Z	Engine No:	3ZZ4665009
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEC107149350
Reg. Date:	30/05/2007 (Man. Year: 2007)	Odometer:	250527 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/70 R14	Rear Tyre Size:	185/70 R14
Front Left Side:	Nexen 7 mm	Rear Left Side:	Nexen 7 mm
Front Right Side:	Nexen 7 mm	Rear Right Side:	Nexen 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,054.82	5,552.55	3,502.27	38.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,560.00	3,140.00	1,420.00	31.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,614.82	8,692.55	4,922.27	36.15
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	13,614.82	4,000.00	9,614.82	70.62

INSPECTION

Date of Assignment:	14/03/2019	
Date Inspected:	12/03/2019 Inspected At:	Triple-t Automotive (HQ) NO.10 KAKI BUKIT ROAD 2 #03-07 FIRST EAST CENTRE Singapore 417868
Estimated Period of Repair:	12.0 days	

Adjuster: CHEN TSUE YEE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Apr 2019)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGU9713Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	788.90 FL	*788.90 FL
2	1		*BOOTLID LOCK	Bent	102.40 FL	*102.40 FL
3	1		*BOOTLID LOCK STRIKER	Bent	85.00 FL	*85.00 FL
4	1		*BOOTLID INNER GARNISH	Not fitted	780.30 FL	*- FL
5	1		*BOOTLID LOCK SENSOR	No such part	396.50 FL	*- FL
6	1		*BOOTLID LOGO	Necessary	90.80 FL	*90.80 FL
7	1		*BOOTLID EMBLEM -COROLLA	Necessary	55.20 FL	*55.20 FL
8	1		*BOOTLID EMBLEM -ALTIS	Necessary	45.80 FL	*45.80 FL
9	1		*BOOTLID EMBLEM -1.6E	Necessary	55.00 FL	*55.00 FL
10	1		*BOOTLID EMBLEM -VVT-I	Necessary	58.90 FL	*58.90 FL
11	1		*BOOTLID WEATHERSTRIP	Cracked	140.50 FL	*140.50 FL
12	2		*BOOTLID HINGE	Bent	221.60 FL	*221.60 FL
13	1		*BOOTLID OUTER GARNISH	Broken	198.70 FL	*198.70 FL
14	2		*BOOTLID REFLECTOR	Broken	205.00 FL	*205.00 FL
15	1		*REAR BUMPER REINFORCEMENT	No such part	352.20 FL	*- FL
16	1		*REAR BUMPER	Dented	458.70 FL	*458.70 FL
17	2		*REAR BUMPER BRACKET	Dented	171.00 FL	*171.00 FL
18	2		*REAR BUMPER SIDE RETAINER	Broken	70.80 FL	*70.80 FL
19	1		*REAR END PANEL	Dented	700.80 FL	*580.60 FL
20	1		*REAR END PANEL TOP GARNISH	Cracked	112.00 FL	*112.00 FL
21	1		*REAR DOOR LH-WARPED -REPAIR	Repair	952.30 FL	*- FL
22	1		*FUEL TANK COVER LH	Not Necessary	98.50 FL	*- FL
23	2		*TAILLAMP	Broken	651.60 FL	*651.60 FL
24	2		*TAILLAMP LOWER PANEL	Dented	204.60 FL	*204.60 FL
25	1		*REAR FLOOR PANEL	Dented	658.00 FL	*658.00 FL
26	1		*REAR FLOOR SIDE PANEL	N/S Dented	375.60 FL	*187.80 FL
27	1		*REAR FLOOR PANEL TOP BOARD	Torn	155.70 FL	*155.70 FL
28	2		*REAR FENDER	Deformed	1,624.80 FL	*1,624.80 FL
29	2		*REAR FENDER INNER COWLING	Not Necessary	177.00 FL	*- FL
30	2		*REAR FENDER INNER GARNISH	Not Necessary	402.60 FL	*- FL
31	1		*EXHAUST SILENCER	Not Necessary	612.30 FL	*- FL
32	1		*EXHAUST HEAT SHIELD	Not Necessary	110.00 FL	*- FL
33	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
34	1		*REAR NUMBER PLATE	Dented	50.00 FS	*30.00 FS
35	4		*REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
36	1		*SET REAR REVERSE SENSOR	Broken	280.00 FS	*200.00 FS
37	6		*BOOTLID INNER GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
38	1		*TAILLAMP CLIPS (6 PCS)	Necessary	30.00 FS	*20.00 FS
39	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REAR FLOOR PANEL INSULATION	Not Necessary	150.00 FS	*- FS
41	2		*SETS REAR FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
				Sub Total (\$\$)	11,833.10	7,283.40
				- List Item Discount on L Items 25.00/25.00% (\$\$)	2,778.28	1,730.85
				Total Parts (\$\$)	9,054.82	5,552.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING FOR REPLACE AND REPAIR AFFECTED PARTS	New	1,900.00	1,400.00
2	SPRAY PAINTING	New	1,600.00	1,400.00
3	APPLY PUTTY AND ANTI-CORROSION TO AFFECTED PARTS	New	250.00	50.00
4	WIRING/BULB CHECKING	New	50.00	30.00
5	R/R REAR EXHAUST PIPE	New	100.00	50.00
6	TOWING	New	60.00	60.00
7	REAR CHASSIS ALIGNMENT CHARGES	New	250.00	0.00
8	R/R REAR WINDSCREEN GLASS	New	150.00	100.00
9	R/R REAR UPHOLSTERY TO FACILITATE REPAIR	New	120.00	30.00
10	R/R REVERSE SENSOR	New	80.00	20.00
Gross Labour Cost (\$\$)			4,560.00	3,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >