

khan chng



LKK
Steve

VEHICLE NO : SMA3559B

MODEL : KIA/FORTE K3 1.6 AL

WIP : 42832

Material	: \$	<u>1,059.00</u>
Labour	: \$	<u>1,775.00</u>
Sub-Total	: \$	<u>2,834.00</u>
Less 2% Disc	: \$	<u>-</u>
Less Excess	: \$	<u>-</u>
Total	: \$	<u>2,834.00</u>
GST 7%	: \$	<u>198.38</u>
Grand Total	: \$	<u>3,032.38</u>
Finalise By/Date : <u>Larry ON 12/06/19</u>		

- ☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING
- ☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 4 WORKING DAYS + 2 days (wk end)

- * TP vehicle no: YN7949Y (ER60)
- * claim GIA search fee \$ 2.00
- * claim loss of RENTAL.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
NG BOON HSI, SARAH (HUANG WENSHI)	Cust No/Name LCV05743/NG BOON HSI, SARAH (HUANG WENSHI)
76 JALAN LIM TAI SEE	Reg No/Reg Date SMA3559B / 04/06/2018
SINGAPORE 268412	Date In/Mileage 23/04/2019/ 15802
Contact No *Mobile: 90128954	Chassis/Package KNAFJ411MJ5767032 /FS215N
23/04/	Engine No G4FGJH697091
	Make/Model KIA/FORTE K3 1.6 A L 189
	Colour/Trim MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CTP00080	Cash	17/06/2019/ 09:40	TLD	884 / Lauro Songcuan	42832		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							825.00
RENEW DAMAGED PARTS ON REAR BUMPER FACE							
E PNT88000							60.00
REMOVE AND INSTALL PARKING ASSIST							
E PNT98000							420.00
SPRAY PAINT REAR BUMPER FACE AND AFFECTED PORTIONS							
A 54900099							30.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM							
A 10028901							200.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
USING HI-SCAN PRO TEST							
M SUNDRY							20.00
SUNDRIES							
S SPECIALISTJOB							220.00
SUPPLY REVERSE SENSOR (KIA K3 / MST)							
X GROMMET ASSY-SCREW ✓				2.00	2.00	00.00	4.00
X RETAINER ✓				10.00	2.00	00.00	20.00
X COVER-RR BUMPER ✓				1.00	688.00	00.00	688.00
X COVER-RR BUMPER,CTR ✓				1.00	347.00	00.00	347.00
Z TEXT							
TP ERGO - YN7949Y							
DOA: 14.01.2019							
SURVEYOR: STEVE (LKK) 23.4.19							
Cycle & Carriage celebrates 120 years. Visit www.cyclecarriage.com/120 for more info!							
Parts	1,059.00				Nett		2,834.00
Labour	1,535.00				7% GST on	2834.00	198.38
Standard Menu	0.00						
Specialist Job	220.00				Total Payable		3,032.38
Diagnostics Job	0.00						
Sundry/Others	20.00						
Total(w/o GST)	2,834.00						

This is not an official tax invoice.
This is a computer generated document, no signature is required.

65684501



209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
NG BOON HSI, SARAH (HUANG WENSHI)	Cust No/Name LCV05743/NG BOON HSI, SARAH (HUANG WENSHI)
76 JALAN LIM TAI SEE	Reg No/Reg Date SMA3559B / 04/06/201
SINGAPORE 268412	Date In/Mileage / 0
Contact No	Chassis No KNAFJ411MJ5767032
	Engine No G4FGJH697091
	Make/Model KIA/FORTE K3 1.6 A L 189
	Colour/Trim MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LCV05743	CRDVCH	24/01/2019/ 16:38		465 / Tay Jian Ye	42832		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							815 1650.00
RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER FACE, REAR BEAM, REPAIR REAR END PANEL							
E PNT88000							60 80.00
REMOVE AND INSTALL PARKING ASSIST							
E PNT88000							430 1260.00
PAINT WORK SPRAY REAR END PANEL, REAR BUMPER FACE AND AFFECTED PORTION							
M SUNDRY							220.00
SUPPLY PARKING SENSOR UNIT							
A 54900099							30.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM							
M SUNDRY							80.00
PERFORM RUST PREVENTION							
A 10028901							200.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							
M SUNDRY							20.00
SUNDRIES							
M	BEAM-RR BUMPER	1.00	318.00	00.00			318.00
M	STAY-RR BUMPER LH	1.00	120.00	00.00			120.00
M	STAY-RR BUMPER RH	1.00	120.00	00.00			120.00
M	BRACKET-RR BEAM UPR MTG	1.00	3.00	00.00			3.00
M	BRACKET-RR BEAM UPR MTG, RH	1.00	3.00	00.00			3.00
M	BRACKET-RR BEAM LWR MTG	1.00	5.00	00.00			5.00
M	BRACKET-RR BEAM LWR MTG	1.00	5.00	00.00			5.00
M	BRACKET-RR BUMPER SIDE MTG, LH	1.00	29.00	00.00			29.00
M	BRACKET-RR BUMPER SIDE MTG, RH	1.00	29.00	00.00			29.00
M	GROMMET ASSY-SCREW	2.00	2.00	00.00			4.00
M	RETAINER	10.00	2.00	00.00			20.00
M	COVER-RR BUMPER	1.00	688.00	00.00			688.00
M	COVER-RR BUMPER, CTR	1.00	347.00	00.00			347.00
Confirm & accepted by							

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of removing the rubber seal or other repair requiring the removal of the windscreen.