



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged parts during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	Cust No/Name LCV05743/NG BOON HSI, SARAH (HUANG WENSHI) Reg No/Reg Date SMA3559B / 04/06/201 Date In/Mileage / 0 Chassis No KNAFJ411MJ5767032 Engine No G4FGJH697091 Make/Model KIA/FORTE K3 1.6 A L 189 Colour/Trim MST METAL STREAM / WK SATURN BLACK

Acknowledged by Repairer

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV05743	Date: CRDVCH	24/01/2019/ 16:38		465 / Tay Jian Ye	42832

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER FACE, REAR BEAM, REPAIR REAR END PANEL				815 1650.00
E PNT88000 REMOVE AND INSTALL PARKING ASSIST				60 80.00
E PNT98000 PAINT WORK SPRAY REAR END PANEL, REAR BUMPER FACE AND AFFECTED PORTION				420 1260.00
M SUNDRY SUPPLY PARKING SENSOR UNIT				✓ 220.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				✓ 30.00
M SUNDRY PERFORM RUST PREVENTION				50 X 80.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				✓ 200.00
M SUNDRY SUNDRIES				✓ 20.00
M BEAM-RR BUMPER	1.00	318.00	00.00	318.00
M STAY-RR BUMPER LH	1.00	120.00	00.00	120.00
M STAY-RR BUMPER RH	1.00	120.00	00.00	120.00
M BRACKET-RR BEAM UPR MTG	1.00	3.00	00.00	3.00
M BRACKET-RR BEAM UPR MTG, RH	1.00	3.00	00.00	3.00
M BRACKET-RR BEAM LWR MTG	1.00	5.00	00.00	5.00
M BRACKET-RR BEAM LWR MTG	1.00	5.00	00.00	5.00
M BRACKET-RR BUMPER SIDE MTG, LH	1.00	29.00	00.00	29.00
M BRACKET-RR BUMPER SIDE MTG, RH	1.00	29.00	00.00	29.00
P GROMMET ASSY-SCREW	2.00	2.00	00.00	4.00
M RETAINER	10.00	2.00	00.00	20.00
M COVER-RR BUMPER	1.00	688.00	00.00	688.00
M COVER-RR BUMPER, CTR	1.00	347.00	00.00	347.00

Confirm & accepted by

3-4 day

7% GST on **Nett** 5,231.00
366.17

Total Payable 5,597.17

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.