

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.
TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

11, MAR 2019

India International Insurance PL
64 Cecil Street #04-#05/#06-02
IOB Building S 049711

Attn: Motor claim dept-3rd party claim

Claiming against your insured vehicle no: SHD3675S

Accident involving vehicle no: SKC4253P/SHD3675S/SLP4833K

DOA: 08/03/2019 AT CTE Tunnel before Exit Outram

Dear officer incharge

Re: Estimate cost of repair for vehicle no: SKC4253P

To supply---

Description	Qty	Amount	
Rear bumper	1	482.00	✓
Rear bumper retainer @72.70	2	145.40	✓
Rear bumper sponge	1	117.50	✓
Rear bumper foglamp @37.20	2	74.40	✓
Rear fender, Rh	1	1,029.70	✓
Air duct	1	124.70	✓
Lid	1	754.30	✓
Lid lock	1	96.50	✓
Lid reflector @116.60	2	233.20	✓
Lid chrome handle	1	332.98	X
Lid-1.6 emblem	1	32.10	✓
Lid-VVTi emblem	1	38.40	✓
Lid Altis emblem	1	42.35	✓
Lid-corolla emblem	1	45.00	✓
Lid elegance emblem	1	44.10	✓
Boot weather strip	1	175.35	50% ✓
Spare tyre panel	1	702.90	X
End panel	1	581.20	?
End panel top garnish	1	185.20	?
Taillamp @281.90	2	563.80	✓
Fender cowl	1	156.00	?
Cowling clip		38.00	?
Parts		5,995.08	
Parts less 25%		1,498.77	
		4,496.31	

LIKKA Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

*Not Notarized
11 Day @?
Resurvey After Paint
9 days*

Reverse sensor	220.00	X
To remove/reinstall rear windscreen glass	180.00	1201
To remove rear seater cushion, rear speckerboard, inner garnish enable repair job		
Carryout, reinstall after job done.	250.00	1201
To remove damaged parts and attachments.		
Cut n weld damaged fender, panel.		
To Straighten rear chassis where necessary.		
To repair/reshape dented areas.		
To replace/align all parts into position.	1,300.00	12001
To spray paint.	1,200.00	10001
	7,646.31	