

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5323A**AAD1903-054***Not Authorized*
1/ Sep @ 79506

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC 5323A

VF1ABL15AUC276868

RENAULT

LATITUDE

8.3.2019

III

21/3/2014

PART**LIST**

1	1 BUMPER COVER REAR	\$	<i>RT/CM</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>RT</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>DIT</i> 113.47	✓
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>SL</i> 135.97	X
5	1 BUMEP R RETAINER RH REAR	\$	<i>SL</i> 44.99	X
6	1 BUMPER REFLECTOR RH	\$	<i>SL</i> 43.61	X
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>SL</i> 135.97	X
8	1 BUMEP R RETAINER LH REAR	\$	<i>SL</i> 44.99	X
9	1 BUMPER REFLECTOR LH	\$	<i>CM</i> 43.61	✓
10	1 BUMPER BEAM REAR	\$	<i>R</i> 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95	✓
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95	✓
13	1 BOOT REAR	\$	<i>R</i> 2,872.68	✓
14	1 BOOT FINISHER	\$	<i>SL</i> 470.06	} X
15	1 BOOT WHEATERSTRIP	\$	<i>SL</i> 323.05	
16	1 BOOT REFLECTOR LAMP LH	\$	<i>SL</i> 493.35	
17	1 BOOT REFLECTOR LAMP RH	\$	<i>SL</i> 493.35	
18	1 BOOT BADGE 'RENAULT'	\$	<i>SL</i> 225.36	
19	1 BOOT BADGE	\$	<i>SL</i> 225.36	
20	1 BOOT STRUT LH	\$	<i>SL</i> 276.08	
21	1 BOOT STRUT RH	\$	<i>SL</i> 276.08	
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84	
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84	
24	1 BOOT INNER TRIM	\$	<i>SL</i> 586.45	
25	1 BOOT SWITCH	\$	<i>SL</i> 168.13	
26	1 BOOT LOCK	\$	<i>R</i> 202.67	
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40	
28	2 LICENCE PLATE LAMP	\$	<i>SL</i> 50.52	
29	2 BOOT RUBBER PLUG	\$	<i>SL</i> 221.81	

Trans-cab Auto Services Pte Ltd**AAD1903-054**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5323A

30	1 FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13	} X
31	1 WHEELARCH REAR RH	\$	<i>Sn</i> 543.47	
32	1 FENDER PANEL REAR LH	\$	<i>R</i> 3,299.13	
33	1 WHEELARCH REAR LH	\$	<i>Sn</i> 543.47	
34	1 TAILLAMP LH	\$	<i>Sn</i> 552.55	
35	1 TAILLAMP PANEL LH	\$	<i>R</i> 986.70	
36	1 TAILLAMP RH	\$	<i>Sn</i> 552.55	
37	1 TAILLAMP PANEL RH	\$	<i>R</i> 986.70	
38	1 OUTER PANEL REAR (End Panel)	\$	<i>R</i> 1,471.77	✓
39	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>CM</i> 404.56	✓
40	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>R</i> 2,189.88	X
41	1 SPARE WHEEL PANEL TRIM	\$	<i>Sn</i> 612.21	X
42	1 EXHAUST REAR	\$	<i>R</i> 7,489.05	X
43	1 EXHAUST CAP REAR	\$	<i>R</i> 230.49	X

TOTAL	\$	34,526.04
10%	\$	3,452.60
	\$	31,073.44

Specical Nett

1	1SET PARKING AID	\$	<i>Short</i> 700.00 <i>Goosa</i>
2	1SET REAR BUMPER CLIP	\$	<i>na</i> 66.00 ✓
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>na</i> 33.00 ✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i> 10.00 X
5	1SET BUMPR RETAINER RH CLIP RR	\$	<i>na</i> 20.00 X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	<i>na</i> 10.00 X
7	1SET BUMPR RETAINER CLIP LH RR	\$	<i>na</i> 20.00 X
8	1SET BUMPER LOWER REAR RIVET	\$	<i>na</i> 22.00 X
9	1SET BUMPER LOWER REAR CLIP	\$	<i>na</i> 66.00 ✓
10	1 EXHAUST MOUNTING REAR	\$	<i>Sn</i> 17.82 X
11	1SET BOOT FINISHER CLIP	\$	<i>na</i> 24.20 X
12	1 REAR BOOT STICKER 'TRANS-CAB'	\$	<i>na</i> 80.00 <i>30JN</i>
13	1 REAR BOOT STICKER '6555-3333'	\$	<i>na</i> 80.00 <i>30JN</i>

Trans-cab Auto Services Pte Ltd**AAD1903-054**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5323A

14 1SET FENDER WHEELARCH REAR RH CLIP	\$	nn	35.00	}	X
15 1SET FENDER WHEELARCH REAR LH CLIP	\$	nn	35.00		
16 1 FENDER INNER TRIM CLIP LH	\$	nn	28.00		
17 1 FENDER INNER TRIM CLIP LH	\$	nn	28.00		
18 1 TAILLAMP CLIP RH	\$	nn	5.00		
19 1 TAILLAMP CLIP LH	\$	nn	5.00		
20 2 REAR WINDSCREEN SELANT	\$	nn	80.00		
21 1 WINDSCREEN MOULDING	\$	nn	100.00		
22 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00		
23 1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sn	385.00	}	
24 1 SPARE TYRE	\$	sn	330.00		

TOTAL \$ 2,280.02**TOTAL PARTS \$ 33,353.46****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	8801
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	8001
To Rust-Proofing Of The Affected Areas.	\$	170.00	601
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X

Trans-cab Auto Services Pte Ltd**AAD1903-054**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5323A

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 601
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To supply and re-do rear luggage floor panel insulation padding.	\$	nn 380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	↪ 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	↪ 170.00	X
To check steering geometry and computer wheel alignment	\$	↪ 220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	↪ 380.00	X
TOTAL	\$	14,340.00	

Over All Total \$ 47,693.46**(LUMP SUM)****Repair Days****20 DAYS****5 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: