



PROGRESSIVE
CAR CARE PTE LTD

Progressive Car Care P
(Co. Reg. No. 201006)
Blk 3022A Ubi Road 1 #01-45/ 46 S4
T: +65 6741 5336 | F: +65 674
E: claims@procarcare.com
W: www.procarcare.com

(SUPPLEMENTARY)

INSURER: **FWD Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD 0319-6916
Policy No:	PNPV2018-00001110-01	Date of Loss:	14/02/2019
Vehicle Reg. No.:	SKK7988R	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TAN DING YUAN		
Make/Model:	MERCEDES-BENZ A200, 1.6 W176 (A)	Vehicle Reg. Date:	24/07/2013
Vehicle Colour:	WHITE		
Engine No:	27091030188823	Chassis No:	WDD1760432J119394
Odometer:	134221 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	PROGRESSIVE CAR CARE PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	400.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	400.00
+ GST 7.00% (\$)	28.00
Nett Amount (\$)	428.00
+ Previous Estimates (\$)	7,114.43
Claim Total (\$)	7,542.43

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Mar 2019)
Parts: 144 MERCEDES-BENZ A200 1.6 W176 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKK7988R)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

*Supp.***Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*L/F HEADLAMP CONTROL UNIT <i>✓ Bank 420</i>	0.00	0.00	*400.00 F
Total Parts (S\$)						400.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Emile af
26/3/19

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO DIAGNOSE & TROUBLESHOOT, PERFORM SCN CODING ON LH HEADLAMP MODELU AND RESET FAULT MEMORT.	New	450.00
AIEC ✓ Gross Labour Cost (\$\$)			450.00

Progressive Car Care Pte Ltd/SKK7988R/04/04/2019 17:12. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.