



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
ERGO Insurance Pte Ltd 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 Attn: Motor Claims Contact No 68299194	Cust No/Name	/Mr Li Caihong (loy Chyehong)
	Reg No/Reg Date	SLH9494P*1F / 24/11/2016
	Date In/Mileage	11/03/2019/ 0
	Chassis No	MMBSTA13AHH003825
	Engine No	3A92UDP2515
	Make/Model	MIT/17MY Attrage 1.2 CVT
	Colour/Trim	U01 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
F0000082	Credit	12/03/2019/ 10:51		303 / Renemer	20429			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
S	MIPNT88088							250.00
	DIAGNOSTIC/SCANNING							
S	MIPNT88088							80 ✓ 100.00
	TO CHECK LIGHTING/WIRING SYSTEM ON RHS AFFECTED AREAS							
S	MIPNT88088							600 ✓ 1200.00
	TO REMOVE & RE-INSTALL ALL CARPETS/TRIMMING TO GIVE WAY ACCESS REPAIR ON RHS ACCIDENT AFFECTED AREAS							
S	MIPNT88088							600 ✓ 1200.00
	TO TRANSFER FRONT & REAR DOOR COMPONENTS/MECHANISM							
S	MIPNT88088							✓ 300.00
	TO REPLACE REAR WINDSCREEN							
S	MIPNT88088							✓ 100.00
	TO APPLY SEALANT KIT ON NEW REAR WINDSCREEN							
S	MIPNT88088							✓ 220.00
	TO INSTALL RIKECOOL SOLAR FILM ON REAR WINDSCREEN			* Solar Agreement				
S	MIPNT88088							✓ 300.00
	TO APPLY SEALANT KIT ON NEW & REPAIR PANELS							
S	MIPNT88088							✓ 180.00
	WHEEL ALIGNMENT							
S	MIPNT88088							8000 4200.00
	TO REPLACE FRONT & REAR RH DOOR, RHR OUTER FENDER, ETC.							
	TO REPAIR RH CENTER PILLAR POST			610				
	STRAIGHTEN, REFORM, ALIGN ON RHS ACCIDENT AFFECTED AREAS			470				
S	MIPNT98088							1260 2100.00
	SPRAY PAINTING ON RHS ACCIDENT AFFECTED AREAS							
S	MIPNT88088							✓ 50.00
	WHEEL BALANCING							
M	JJ5301F968	PANEL, QTR, OTR RH	✓ 00		1.00	756.00	0.00	756.00
M	JJ5730B792	RH, RR DOOR PANEL ASS	✓ 00		1.00	791.00	0.00	791.00
M	JJ5755A280	OTR, RH RR WEATHERSTR	?		1.00	135.00	0.00	135.00
M	JJ5700B682	RH, FR DOOR PANEL ASS	✓ 00		1.00	986.00	0.00	986.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info														
ERGO Insurance Pte Ltd 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 Attn: Motor Claims Contact No 68299194	<table> <tr> <td>Cust No/Name</td><td>/Mr Li Caihong (loy Chyehong)</td></tr> <tr> <td>Reg No/Reg Date</td><td>SLH9494P*1F / 24/11/2016</td></tr> <tr> <td>Date In/Mileage</td><td>11/03/2019/ 0</td></tr> <tr> <td>Chassis No</td><td>MMBSTA13AHH003825</td></tr> <tr> <td>Engine No</td><td>3A92UDP2515</td></tr> <tr> <td>Make/Model</td><td>MIT/17MY Attrage 1.2 CVT</td></tr> <tr> <td>Colour/Trim</td><td>U01 / BK</td></tr> </table>	Cust No/Name	/Mr Li Caihong (loy Chyehong)	Reg No/Reg Date	SLH9494P*1F / 24/11/2016	Date In/Mileage	11/03/2019/ 0	Chassis No	MMBSTA13AHH003825	Engine No	3A92UDP2515	Make/Model	MIT/17MY Attrage 1.2 CVT	Colour/Trim	U01 / BK
Cust No/Name	/Mr Li Caihong (loy Chyehong)														
Reg No/Reg Date	SLH9494P*1F / 24/11/2016														
Date In/Mileage	11/03/2019/ 0														
Chassis No	MMBSTA13AHH003825														
Engine No	3A92UDP2515														
Make/Model	MIT/17MY Attrage 1.2 CVT														
Colour/Trim	U01 / BK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000082	Credit	12/03/2019/ 10:51		303 / Renemer	20429
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M JJ5725A212	OTR,RH FR WEATHERSTR ?	1.00	143.00	0.00	143.00
M JJ7410A944XA	RH,TAPE, RR DOOR SAS / NEC	1.00	29.00	0.00	29.00
M JJ7410A940XA	RH,TAPE,FR DOOR SASH / NEC	1.00	29.00	0.00	29.00
M JJ5716A474RA	HANDLE,RR DOOR OUTSI X NN	1.00	101.00	0.00	101.00
M JJ5715A910	RH,LATCH FR DOOR X NN	1.00	303.00	0.00	303.00
M JJ5927A033WA	SW,KEYLESS OPERATION / CUT	1.00	87.00	0.00	87.00
M JJ5370B296	SHIELD,RR WHEELHOUSE X NN	1.00	35.00	0.00	35.00
M JJ5702A162	RH,UPR HINGE,FR DOOR ?	1.00	54.00	0.00	54.00
M JJ5702A154	RH,LWR HINGE,FR DOOR ?	1.00	54.00	0.00	54.00
M JJ5732A110	RH,UPR HINGE,RR DOOR X NN	1.00	54.00	0.00	54.00
M JJ5702A161	RH,LWR HINGE,FR DOOR X NN	1.00	54.00	0.00	54.00
M JJ6131A233	GLASS,RR WINDOW X NN	1.00	599.00	0.00	599.00
M JJMR462285	STOPPER,WINDSHIELD G / NEC	2.00	3.00	0.00	6.00
M JJ6102A405	SPACER,RR WINDOW / NEC	3.00	9.00	0.00	27.00
M JJ5702A137	CHECK,FR DOOR ?	1.00	48.00	0.00	48.00
M JJ5757A312	RH,MOULDING, RR DOOR X NN	1.00	66.00	0.00	66.00
M JJ5727A268	RH,MLDG,F/DR WDO BEL X NN	1.00	74.00	0.00	74.00
M JJMR200300	CLIP, BUMPER / NEC	10.00	2.00	0.00	20.00
M JJ4250D688	WHEEL,DISC Rem RM / CUT	1.00	850.00	0.00	850.00
M WYK1955015	YOKOHAMA 195/50/15 E X NN	1.00	113.00	0.00	113.00
Z NOTES	<p>ACCIDENT ON 11/03/2019 ALONG KAMPONG BAHRU ROAD TOWARDS SENTOSA OWNER CALIMING THIRD PARTY REQUIRED REPLACEMENT CAR TP#: XD7294S TP INS: ERGO</p> <p><i>Stew (CLKK) wil Raju/la 8322 8813 14/3/19 11:45am 7 days P/P Recy before spray</i></p>				

Confirm & accepted by

Parts	5,414.00
Labour	0.00
Standard Menu	0.00
Specialist Job	10,200.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	15,614.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.