

03/2017

ASS. REC. BY:

REF:

CS/SPF 19004493/Jtd362

Special Instruction:

Surveyor

Three Five

ASSIGNMENT (Office)

From (Person):

Wei Yea Lim

of

SPF

Date/Time:

12/3/19 @ 2:49pm

Estimated Cost:

Bill to:

☒ OT / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

QX 550B

Insured:

at Workshop m/s

SMRT

Tel:

9857 6861

of

60 wooden ds Ind. park e

Policy No:

Claim No:

MHASPF300000113

Sum Insured:

Excess:

75K

Make of Veh.

(Client's Record)

D.O.A.

CA / REV / REP. / REV 24 HRS

13/3/2019 @ morning

H.O.D. Endorsement:

Date/Time:

3:53pm @ 12/3/19

Person Contacted:

Mr Kong

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

QX 550R-X

14/3 @ - 4:26pm revert to Wei Yea.

Part S: 3405

check: 3090

man hour: 25:

Director Hwee Jie

REF: 8PF

ASSIGNMENT

From: Date: 13/3/19

Estimated Cost:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: QX 550B

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

TBA

(Client's Record)

Make of Veh: PLS call Mr. Kong @ 9857 6861
once reach

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: QX 550B Yr Regn: /

Type: ☒ M. Car / ☐ M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai C.C

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: 185/65 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 13/3/19

Survey held at smrt

Des. of Damages: Frt / Rear / O/S / N/S / ☒ U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 16 APR 2019

Date/Time, File Pass to?

1) 16/4 Typist

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I.: (\$)

☐ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

180

180

Nivitha (LKK Auto)

From: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>
Sent: Tuesday, 12 March 2019 2:49 PM
To: assignments; Admin-D (LKKAuto)
Cc: Kim Pang CHAY (SPF); Kwee Huat TAN (SPF); Perry HE (SPF); Bernard SEAH (SPF); Peng Seng NG (SPF); Rashid ABU HASAN (SPF); 'Ai Phing (LKKAuto'; 'Shiau Chan (LKKAuto'
Subject: Appraisal Services for SPF vehicles at SMRT Automotive Services - MHASPF0300000113 (QX550B)
Attachments: QX550B.xlsx

Hi,

Please provide Appraisal Services for the following SPF vehicles at SMRT Automotive Services:

- QX550B

In attached, please find the recommended Parts and Labour required for the repair of this vehicle.

Kindly contact the following SMRT personnel for viewing of the damaged vehicle:

- Mr Kong Sew Kui
- Mr Jason Yeo

Thank you and best regards,

WeiYea LIM
Contract Management
AEMD, Police Logistics Department
Singapore Police Force
DID: (65) 6478 4844



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Thursday, 14 March 2019 4:26 PM
To: Wei Yea LIM (SPF)
Cc: Kim Pang CHAY (SPF; Kwee Huat TAN (SPF; Perry HE (SPF; Bernard SEAH (SPF; Peng Seng NG (SPF; Rashid ABU HASAN (SPF; SUR
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - MHASPF0300000113 (QX550B)
Attachments: QX 550B photo.pdf; QX 550B.xls

Dear Wei Yea,

Please refer to the attachment of QX 550B.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wei Yea LIM (SPF) [mailto:LIM_Wei_Yea@spf.gov.sg]
Sent: Tuesday, 12 March 2019 2:49 PM
To: assignments <assignments@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Perry HE (SPF) <Perry_HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard_SEAH@spf.gov.sg>; Peng Seng NG (SPF) <NG_Peng_Seng@spf.gov.sg>; Rashid ABU HASAN (SPF) <Rashid_Abu_Hasan@spf.gov.sg>; 'Ai Phing (LKKAUTO)' <aiphing@lkkauto.com>; 'Shiau Chan (LKKAUTO)' <siewsc@lkkauto.com>
Subject: Appraisal Services for SPF vehicles at SMRT Automotive Services - MHASPF0300000113 (QX550B)

Hi,

Please provide Appraisal Services for the following SPF vehicles at SMRT Automotive Services:

- QX550B

In attached, please find the recommended Parts and Labour required for the repair of this vehicle.

Kindly contact the following SMRT personnel for viewing of the damaged vehicle:

- Mr Kong Sew Kui
- Mr Jason Yeo

Thank you and best regards,

WeiYea LIM

Contract Management

AEMD, Police Logistics Department

Singapore Police Force

DID: (65) 6478 4844



Scope Of Work
Home Team Agency

SCOPE OF WORK

1 To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

CONTRACTOR:	SMRT	VEH TYPE:	FRC	UNIT:	YISHUN NORTH NPC	Reference No.	0550/SPF/4W/19/03/01
VEH NO:	QX550B	REPAIR TYPE:	ACCIDENT				
VEH MAKE/MODEL:	HYUNDAI AVANTE	ODOMETER:	213325			iLMS No.	1100019535

S/N	PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mark Up (\$)
1	Scope Of Repairs					
1.1	Rear Bumper / CRA	\$270.00	1			
1.2	Spare Tyre Compartment / BUC	\$650.00	1			
1.3	Rear Cross Member / BT	\$575.00	1			
1.4	Rear LH Lower Arm / DD	\$240.00	1			
1.5	Rear RH Lower Arm / DD	\$240.00	1			
1.6	Rear LH Upper Arm / CRA	\$230.00	1			
1.7	Rear RH Upper Arm / CRA	\$230.00	1			
1.8	Rear LH Trailing Arm / CRA	\$185.00	1			
1.9	Rear RH Trailing Arm / CRA	\$185.00	1			
1.10	Front Cross Member / CRA	\$3,090.00	1			
1.11	Front LH Lower Arm / CRA	\$300.00	1			
1.12	Front RH Lower Arm / CRA	\$300.00	1			
1.13	To replace & supply new cushion covers (Driver / Front Passenger / Rear Passengers) SOR 6 Item 9 X NC	\$1,346.40	1			
2	Additional Services					
2.1	NA	\$0.00	0	0%	0.00	0.00
Remarks:					Parts Total:	

S/N	LABOUR DESCRIPTION	Man-Hour Rate (\$)	Man-Hour Qty	Total Man-Hour Cost (\$)
1	Scope Of Repairs			
1.1	Rear Bumper:		5	
	Remove & Replace Rear Bumper			
	Putty & Spray Paint for Rear Complete Bumper (2 colors)			
1.2	Rear Cross Member:		14	
	Remove & Replace Rear Cross Member			
1.3	Rear Lower Arm, Upper Arm & Trailing Arm:		16	
	Remove & Replace Rear RH Lower Arm			
	Remove & Replace Rear LH Lower Arm			
	Remove & Replace Rear RH Upper Arm			
	Remove & Replace Rear LH Upper Arm			
	Remove & Replace Rear RH Trailing Arm			
	Remove & Replace Rear LH Trailing Arm			
1.4	Front Cross Member:		13	
	Remove & Replace Front Cross Member			
1.5	Front Lower Arm:		13	
	Remove & Replace Front RH Lower Arm			
	Remove & Replace Front LH Lower Arm			
1.6	Wheel Alignment Test		2	
	SUB-TOTAL		31	
2	Additional Services			
2.1	Towing Service From Station to Workshop (SOR 10)	176.80	1	176.80
2.2	Return Service From Workshop to Station (SOR 9)	61.20	1	61.20
	SUB-TOTAL		2	238.00
			Labour Total:	
			GRAND TOTAL :	
			Total sum billed under SOR only :	
			Total sum billed under CVR only :	
Contractor shall complete the entire repair within <u>20</u> working days upon approval date . (Include parts awaiting time)				

Verification of Scope of Work					
Contractor QC		Vetted By		Approved By	
Name:	KONG SEW KUI	Name:		Name:	

Registration No. QX 550B

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	Rear Bumper	1	Cracked	\$270.00	\$270.00	
1.2	Spare Tyre Compartment	1	Buckled	\$650.00	\$650.00	
1.3	Rear Cross Member	1	Bent	\$575.00	\$575.00	
1.4	Rear LH Lower Arm	1	Damage	\$240.00	\$240.00	
1.5	Rear RH Lower Arm	1	Damage	\$240.00	\$240.00	
1.6	Rear LH upper Arm	1	Cracked	\$230.00	\$230.00	
1.7	Rear RH upper Arm	1	Cracked	\$230.00	\$230.00	
1.8	Rear LH Trailing Arm	1	Cracked	\$185.00	\$185.00	
1.9	Rear RH Trailing Arm	1	Cracked	\$185.00	\$185.00	
1.10	Front Cross Member	1	unconfirm	\$3,090.00	\$3,090.00	
1.11	Front LH Lower Arm	1	Cracked	\$300.00	\$300.00	
1.12	Front RH Lower Arm	1	Cracked	\$300.00	\$300.00	
1.13	To replace & supply new cushion covers (Driver/Front passenger / Rear Passengers) SOR 6 Item 9	1	unconfirm	\$1,346.40	\$1,346.40	
3	LABOUR					

[illegible]

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF19004493/Jtd3e2		
ACCIDENT CLAIM SECTION (SPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333		Date : 24-04-2019		
		Code : SPF		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.	Veh. Inspected		QX 550B	
Policy No.	Coverage (\$)		0.00	
Claim No. MHASPF0300000113	Excess (\$)		0.00	
Assign From WEI YEA LIM	Assign Date		12/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI AVANTE	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	KMHDU41BMAU021360	Colour	WHITE	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	FALKEN	6 mm	
L/H Front Tyre	185/65 R15	FALKEN	6 mm	
R/H Rear Tyre	185/65 R15	FALKEN	6 mm	
L/H Rear Tyre	185/65 R15	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE UNDERCARRIAGE PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	Inspection Date		13/03/2019	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				



Registration No. QX 550B

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	Rear Bumper	1	Cracked	\$270.00	\$270.00	
1.2	Spare Tyre Compartment	1	Buckled	\$650.00	\$650.00	
1.3	Rear Cross Member	1	Bent	\$575.00	\$575.00	
1.4	Rear LH Lower Arm	1	Dented	\$240.00	\$240.00	
1.5	Rear RH Lower Arm	1	Dented	\$240.00	\$240.00	
1.6	Rear LH upper Arm	1	Cracked	\$230.00	\$230.00	
1.7	Rear RH upper Arm	1	Cracked	\$230.00	\$230.00	
1.8	Rear LH Trailing Arm	1	Cracked	\$185.00	\$185.00	
1.9	Rear RH Trailing Arm	1	Cracked	\$185.00	\$185.00	
1.10	Front Cross Member	1	unconfirm	\$3,090.00	\$3,090.00	
1.11	Front LH Lower Arm	1	Cracked	\$300.00	\$300.00	
1.12	Front RH Lower Arm	1	Cracked	\$300.00	\$300.00	
1.13	To replace & supply new cushion covers (Driver/Front passenger / Rear Passengers) SOR 6 Item 9	1	Not Consistent With The Impact	\$1,346.40		
3	LABOUR					
1.1	Rear Bumper:					5
	Remove & Replace Rear Bumper					
	Putty & Spray Paint for rear complete bumper(2 color)					
1.2	Rear Cross Member:					4
	Remove & Replace Rear Cross Member					

1.3	Rear Lower Arm, Upper Arm & Trailing Arm:					6
	Remove & Replace RH Lower Arm					
	Remove & Replace LH Lower Arm					
	Remove & Replace RH Upper Arm					
	Remove & Replace LH Upper Arm					
	Remove & Replace RH Trailing Arm					
	Remove & Replace LH Trailing Arm					
1.4	Front Cross Member:					5
	Remove & Replace Front Cross Member					
1.5	Front Lower Arm:					3
	Remove & Replace Front RH lower Arm					
	Remove & Replace Front LH lower Arm					
1.5	Wheel Alignment Test:					2
COSTING		TOTAL PARTS COST			\$6,495.00	
		TOTAL MAN-HOUR				25

Registration No. QX 550B

Vehicle Inspected By

ONG HWEE JIE
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.