

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 1864S

DATE 11/3/2019 15:51

MAKE :

Like

PbyP

MODEL : HYUNDAI IONIQ

AXA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper ✓			\$ 459.40
	Rear Bumper Reinforcement ?			\$ 294.80
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 138.10	\$ 276.20
	Rear Bumper Centre Moulding Assy ✓			\$ 451.25
	Rear Bumper Lower Centre Moulding Assy X <i>repair</i>			\$ 47.50
	Rear Bumper Side Bracket (LH/RH) ?		\$ 33.10	\$ 66.20
	Rear Bumper Cover Clips ✓			\$ 22.00
	Rear Bumper Reflector Lamp (LH/RH) X		\$ 31.90	\$ 63.80
	Boot Lid Lamp (RH) ✓			\$ 794.40
	<i>Rear Fender (RH) X repair</i>			
	<i>Rear Bootlid X repair</i>			
	<i>Emblem</i>			
	SUB TOTAL			\$ 2,475.55
	LESS 20%			\$ 495.11
	DISCOUNTED TOTAL			\$ 1,980.44
	Rear No.Plate ✓			\$ 25.00
	Rear Bumper Rubber Mat ✓			\$ 50.00
	<i>corner struts</i> ✓			
	<i>Reverse sensor</i> ✓			
				\$ 75.00
	Labour Charge			
	Panel Beating			\$ 400.00
	Spray Painting Charge-Fender/Bumper			\$ 200 <i>200</i>
	Wiring Charge			\$ 30.00 <i>20</i>
	Tuff Kote			\$ 50.00 <i>20</i>
	Remove/Refix Reverse Sensor			\$ 120.00 <i>20</i>
				\$ 1,200.00
	TOTAL LABOUR			\$ 1,200.00
	ESTIMATE TOTAL			\$ 3,255.44

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____

Ka li (LKK)
12/3/19
3 days
PRP
Before part p/Lt

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.