

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G7463
27/3 1000

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SJW14X

Chassis No : JHMRU1810GX200466

Model : HRV DX-SIN CVT YM 2016

Owner's Name : JOANNE NICOLE WEE GEOK BAY

Ins Policy No. :

Date of Accident : 8/3/2019

Document No. : SQT19001205
Date : 14. Mar 2019
Customer No. : WZA006
Svc Advisor :
Engine No : L15B4530466
Date | Time : 14. Mar 2019 7:36:48 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
71501-T7B-000	FACE RR.BUMPER	1	777.90 <i>del</i>	25	583.42	40.84	624.26
91505-TM8-003	CLIP,BUMPER	14	2.30 <i>net</i>	25	24.15	1.69	25.84
04718-T7A-000ZZ	FACEL.RR.BUMPER CORNER	1	94.10 <i>X</i>	25	70.57	4.94	75.51
71593-T7A-000	SPACERR.RR.BUMPER SIDE	1	11.50 <i>net</i>	25	8.62	0.60	9.22
71598-T7A-000	SPACERL.RR.BUMPER SIDE	1	11.50 <i>net</i>	25	8.62	0.60	9.22
75722-T7W-A01	EMBLEMRR.	1	13.30 <i>net</i>	25	9.97	0.70	10.67
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	14.50 <i>net</i>	25	10.87	0.76	11.63
66100-T7A-300ZZ	PANEL COMPR. - <i>plus to #</i>	1	373.10 <i>bt</i>	25	279.82	19.59	299.41
68100-T7A-J20ZZ	TAIL GATE COMP	1	855.70 <i>bt</i>	25	641.77	44.92	686.69
74440-T7A-003	WEATHERSTRIPTAILGATE	1	98.70 <i>net</i>	25	74.02	5.18	79.20
74800-T7A-J02	LOCK ASSYTAILGATE	1	78.90 <i>bt</i>	25	59.17	4.14	63.31
34150-T7A-J01	LIGHT ASSY,R.LID	1	269.90 <i>X</i>	25	202.42	14.17	216.59
34155-T7A-J01	LIGHT ASSYL.LID	1	269.90 <i>X</i>	25	202.42	14.17	216.59
33502-T7A-J01	LAMP UNTR.	1	441.50 <i>X</i>	25	331.12	23.18	354.30
33552-T7A-J01	LAMP UNITL.	1	441.50 <i>X</i>	25	331.12	23.18	354.30
74890-T7A-J12ZC	GARNISH ASSYRR.LICENSE	1	193.60 <i>X</i>	25	145.20	10.16	155.36
38387-TZ5-A01	ANTENNA ASSYL.F.	1	59.30 <i>?</i>	25	44.47	3.11	47.58
74940-TZ5-A01	BUZZER ASSYSMART	1	60.40 <i>?</i>	25	45.30	3.17	48.47
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	19.30 <i>net</i>	25	14.47	1.01	15.48

Printed on 14/3/2019 7:44:18 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SJW14X

Chassis No : JHMRU1810GX200466

Model : HRV DX-SIN CVT YM 2016

Owner's Name : JOANNE NICOLE WEE GEOK BAY

Ins Policy No. :

Date of Accident : 8/3/2019

Document No. : SQT19001205

Date : 14. Mar 2019

Customer No. : WZA006

Svc Advisor :

Engine No : L15B4530466

Date | Time : 14. Mar 2019 7:36:48 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
73226-SZW-000	DAMPERSTD 5X5	1	8.50 <i>net</i>	25	6.37	0.45	6.82
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30 <i>net</i>	25	14.47	1.01	15.48
76711-T6A-003	CAPPIVOT	1	4.80 <i>net</i>	25	3.60	0.25	3.85
91501-S70-003	FASTENER BW/SHIELD	4	5.30 <i>net</i>	25	15.90	1.11	17.01
91502-S70-003	FASTENER B	2	5.30 <i>net</i>	25	7.95	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80 <i>net</i>	25	5.70	0.40	6.10
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00 <i>net</i>		120.00	8.40	128.40
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00 ?		320.00	22.40	342.40
Sum Item					3581.51	250.69	3,832.20
BOSUN	SUNDRIES	1	100.00 <i>30.</i>		100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	450.00 <i>X</i>		450.00	31.50	481.50
BOJSE	SEALANT FOR TAILGATE	1	80.00 <i>✓</i>		80.00	5.60	85.60
BOJSE	SEALANT FOR REAR END PANEL	1	<i>7</i> 80.00 <i>✓</i>		80.00	5.60	85.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00 <i>✓</i>		180.00	12.60	192.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00 <i>✓</i>		180.00	12.60	192.60
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	450.00 <i>X</i>		450.00	31.50	481.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	560.00 <i>✓</i>		560.00	39.20	599.20
BODAMKIT	WINDSCREEN DAM KIT.	1	100.00 <i>✓</i>		100.00	7.00	107.00
BOMISC1	REMOVE & INSTALL REVERSE CAMERA & CALIBRATION	1	380.00 <i>✓</i>		380.00	26.60	406.60
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	560.00 <i>✓</i>		560.00	39.20	599.20
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	560.00 <i>X</i>		560.00	39.20	599.20
BOMISC1	RESET VEHICLE SMART KEY ACCESS/ENTRY SYSTEM	1	380.00 <i>✓</i>		380.00	26.60	406.60
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	560.00 <i>✓</i>		560.00	39.20	599.20
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3000.00 <i>2700.</i>		3000.00	210.00	3210.00
BKRP21M	CUT OFF & RENEW RR PANEL RR L FENDER. STRAIGHTEN	1	5000.00 <i>2240.</i>		5000.00	350.00	5350.00
Sum Labor					12620.00	883.40	13,503.40

Printed on 14/3/2019 7:44:18 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SJW14X

Chassis No : JHMRU1810GX200466

Model : HRV DX-SIN CVT YM 2016

Owner's Name : JOANNE NICOLE WEE GEOK BAY

Ins Policy No. :

Date of Accident : 8/3/2019

Document No. : SQT19001205

Date : 14. Mar 2019

Customer No. : WZA006

Svc Advisor :

Engine No : L15B4530466


Date | Time : 14. Mar 2019 7:36:48 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 3

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Survey By	Tan Jiah 97495749						
Date & Time	27/5/19 @ 12pm.						
Excess							
Status	WP						
Signature							

Total Amount 16,201.51 1,134.09 17,335.60

Total (Inclusive of GST) 17,335.60

Resurvey before paint
sent @ lkkauto.com.
07days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 14/3/2019 7:44:18 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.