



Section A - Accident Details

Registration Number	SHC4256S
Case Reference Number	TAX/03/19/2049
Registration Date	19/3/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	JAU MENG JUAM
Type of Accident	Side Swipe
Accident Date and Time	11/3/2019 11:20 AM
Accident Reported Date and Time	11/3/2019 2:12 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24100534
Special Instruction to ARC, if any	TP VEHICLE NUMBER YK5721R - AXA OUR VEHICLE DAMAGED FRONT LEFT SIDE
Prepared Date and Time	12/3/2019 1:54 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$400.00
Total Spray Cost	\$1,674.00	\$500.00
Total Spare Part Cost	\$7,850.56	\$1,795.60
Total Other Cost	\$1,020.00	\$80.00
TOTAL COST	\$11,558.56	\$2,775.60
Lump Sum Total	\$11,550.00	\$2,800.00 (L/S)
Number of Repair Days	7.0	4.0
Prepared / Adjusted By	Tuck Foo Kok	Taufikh (LKK) / AXA
ARC / Surveyor Sign Off Date	12/03/2019 4:12 PM	12/03/2019 3:57 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1904-0385	Invoice Number	
Quotation Date	27.04.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$1,014.00	\$400.00
Total Labour	\$1,014.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO SPRAY FRONT BUMPER LOWER SUB GRILLE	\$180.00	\$100.00
TO REPSRAY FRONT HOOD	\$378.00	\$0.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,674.00	\$500.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$0.00
TO TOP UP A/C GAS	\$120.00	\$0.00
TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$1,020.00	\$80.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace
		52611-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$78.80	0.00	\$0.00	Replace	Check X
		52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Check X
		57014-47030	ARM SUB-ASSY, FR BUMPER LH	1.00	\$250.40	25.00	\$187.80	Replace	Replace
		52116-47040	BUMPER SUPPORT F/LH	1.00	\$76.40	25.00	\$57.30	Replace	Replace
		53102-47020	BUMPER GRILLE SUB-ASSY, LOWER	0.00	\$311.10	0.00	\$0.00	Replace	Check X



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757706
FAX Number : 83865582
Estimator Telephone Number: 88662623
Accident Reporting Number : 68862672

Date Generated : 27/04/2019
User ID : PohSuan

81220-12230	FOG LAMP LH	0.00	\$280.10	25.00	\$0.00	Replace	Check	X
81529-47060	BRACKET, FR TURN CENTER LH	0.00	\$58.20	0.00	\$0.00	Replace	Check	X
81529-47050	BRACKET, FR TURN LOWER LH	0.00	\$26.00	0.00	\$0.00	Replace	Check	X
81529-47040	BRACKET, FR TURN UPPER LH	0.00	\$24.40	0.00	\$0.00	Replace	Check	X
81521-47050	LENS & BODY, FR TURN LH	0.00	\$511.80	0.00	\$0.00	Replace	Check	X
53113-47040	GRILLE RADIATOR LOWER NO.2	0.00	\$94.60	0.00	\$0.00	Replace	Check	X
53111-47040	GRILLE, RADIATOR	0.00	\$310.60	0.00	\$0.00	Replace	Check	X
75310-47010	EMBLEM FRONT	1.00	\$86.50	25.00	\$64.88	Replace	Replace	X
52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Check	X
82113-47180	WIRE, ENGINE ROOM, NO.3	0.00	\$242.00	0.00	\$0.00	Replace	Check	X
53301-47060	HOOD PANEL	1.00	\$748.10	100.00	\$0.00	Replace	Check	X
53395-47020	HOOD END PANEL SEAL	0.00	\$35.50	0.00	\$0.00	Replace	Not Given	X
53420-47070	HOOD HINGE LH	0.00	\$55.90	0.00	\$0.00	Replace	Not Given	X
53201-47902	SUPPORT SUB-ASSY	1.00	\$1,460.40	100.00	\$0.00	Replace	Check	X
53289-47032	COVER, RADIATOR	0.00	\$122.80	0.00	\$0.00	Replace	Check	X
81170-47500	HEAD LAMP LH	1.00	\$945.20	10.00	\$850.68	Replace	Replace	X
	COOLANT	0.00	\$12.32	0.00	\$0.00	Replace	Not Given	X
88460-47150	A/C CONDENSER	0.00	\$1,181.90	0.00	\$0.00	Replace	Not Given	X
G9010-47031	RADIATOR ASSY, UPPER	0.00	\$679.60	0.00	\$0.00	Replace	Not Given	X
16400-37230	RADIATOR ASSY	0.00	\$1,496.90	25.00	\$0.00	Replace	Not Given	X
53802-47050	FENDER FRT/LH	1.00	\$723.40	25.00	\$542.55	Replace	Replace	X
75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	X
53876-47030	FENDER LINER FRT/LH	1.00	\$171.70	25.00	\$128.78	Replace	Replace	X
53852-47020	FENDER LINER PAD, FR WHEEL LH	0.00	\$49.30	0.00	\$0.00	Replace	Check	X
53826-47010	FENDER PROTECTOR FRT/LH UPPER	0.00	\$46.10	0.00	\$0.00	Replace	Check	X
42611-47140 (Frt)	WHEEL DISC. FRONT	0.00	\$1,484.20	0.00	\$0.00	Replace	Not Given	X
Total			\$12,725.83		\$2,244.50			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

2244.50
- 202
1795.60
+ 400.00
+ 580.00
2775.60

4/5 \$2800/-