

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	


Date Generated : 13/03/2019

User ID : ZhiYangPhua

Section A - Accident Details

Registration Number	SHD6014E
Case Reference Number	TAX/03/19/2028
Registration Date	2/12/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	TIO SENG SING
Type of Accident	Head to Rear
Accident Date and Time	7/3/2019 7:05 AM
Accident Reported Date and Time	7/3/2019 3:24 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24100527
Special Instruction to ARC, if any	TP/AXA
Prepared Date and Time	12/3/2019 2:45 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates


Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$338.00	\$0.00
Total Spray Cost	\$558.00	\$0.00
Total Spare Part Cost	\$915.96	\$0.00
Total Other Cost	\$260.00	\$0.00
TOTAL COST	\$2,071.96	\$0.00
Lump Sum Total	\$2,050.00	\$0.00
Number of Repair Days	3.0	
Prepared / Adjusted By	Tuck Foo Kok	
ARC / Surveyor Sign Off Date	12/03/2019 2:58 PM	
Signature		<input checked="" type="checkbox"/>
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Quotation Amount		Prepared Date	

Right / Driver Side

Front



Rear

Left / Passenger Side

Toyota Prius

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 13/03/2019

User ID : ZhiYangPhua

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION	\$338.00 200	
Total Labour	\$338.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY BUMPER BEAM	\$180.00 0 X	
TO RESPRAY REAR BUMPER	\$378.00 2.00	
Total Spray Painting & Panel Beating	\$558.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00 X	
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00 30	
TO WASH AND VACUUM	\$60.00 X	
Total Other Costs	\$260.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52015- 47050	ARM SUB-ASSY, RR BUMPER RH	1.00	\$139.60	25.00	\$104.70	Replace ?	
		52161- 16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace /	nee
		76088- 47020	BUMPER LIP COVER RR/LH	1.00	\$72.20	25.00	\$54.15	Replace ?	
		52563- 47010	TAIL LAMP BRACKET, LH	1.00	\$30.70	25.00	\$23.02	Replace ?	
		52016- 47030	ARM SUB-ASSY, RR BUMPER LH	1.00	\$139.60	25.00	\$104.70	Replace ?	
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace X	nee
		52159- 47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace /	DEF
		52023- 12240	BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.27	Replace ?	
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace /	nee
		52576- 47020	BUMPER SIDE RETAINER RR/LH	1.00	\$94.80	25.00	\$71.10	Replace ?	
Total					\$1,382.81		\$1,167.97		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Hwee die - LKK

13/3/19

C/S 2days.

Photo after paint