

INS CASE OWNER

CC 6/ 01 1900 4520, Eka3n2

LKK:
IDAC:

Supplier

Store

DCI

ASSIGNMENT

11/3/19

Date / Time

11/3/19

Registered in Merimon

12/3/19

Pre-assign / CCU / FTE



Insured Vehicle No.

SLT 4841R

Name of Insured

PNG MARIA THERESA

Insured Tel No.

HP:

Excess Sec II :SS

D.O.A:

2/3/19

Is driver the owner?

(YES) NO

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES NO ; TP GIA REPORT: YES NO

Insured Liability: % Final ? Yes / No

56450964



INSRS:
WSP:
Tel:
Liability:
RMKS:

PrimeAuto



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

56450964 - CUB 111 1650 78 26 / 109 392; 014: 26/4/16

SLT 4841R - X

- PINAUGRO

- TO LOD IN BT BURL/ORIGINAL COPY IN

INFORMED OF TP CLAIM AND AWARE NEW ISSUES

14/6/19

- File pass to type mandate

22/7/19

FILE PASS TO MEI KWAN TO CLOSE

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

17/5/19

MEI K

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time: 03/04/19

Sent By: ab

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

4/9

SS 3,600.00 (5 days) Reduction: 1,828.39 % 34%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

12/7/19

Confirm with:

Alice

Email ☒ Call ☐

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

9

If NO or B 28, Ass. Lin:

Repair Cost:

4/9 (GST)

SS 3,852.00

(OI FROM WILCO 2016)

Loss of Rental (LOR):

SS

224

(5 days)

x 544.80

Loss of Use (LOU):

SS

-

(5 - x - days)

Loss of Income (LOI):

SS

-

(5 - x - days)

LOR only ☒

LOU only

☐

LOR + LOU

☐

LOR + LOI

☐

[Tick only one]

GIA/LTA Search

SS

2.00

Medical:

SS

-

Disbursement:

SS

-

Legal Cost

SS

-

(e.g. Tow/ Independent)

1) Claim status: (Normal/Reject/Private Settle)

2) Report Format:

3) Survey fee:

24/7/19

Total:

SS

4,078.00

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS

4,078.00

Name 1:

PRIME AUTO CLAIMS SERVICE PTE LTD

Payee 2: (Str & 1/2, 2, 3)

SS

Name 2:

Payee 3: (Str & 1/2, 2, 3)

SS

Name 3:

24/7/19

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OO / TP / WS / TP RES / OO RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop n/s: _____
 at: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time : Action / Instruction

MV - 31,900
 PV - 16,117
 NV - 4,888

CL/S \$3-600 / Ret \$1,828.39/34%)

Veh No: 504 5096Y Yt Regn: 17/05/2007
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Toyota NOS CC: 1497
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 237013 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: MR 053 HY 9305006-163

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Locked / Burnt orBrake: In order / Jammed / Locked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65R15
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Westlake

Front

Rear

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 7/3/19 D.O.I. 11/3/19Survey held at Prime Auto

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
o/s front

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time: File Pass to?

☐ : Prelim. Report

Date/Time: File Return to?

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation

) 2 + R% \$

) Photos

) Copies

TOTAL

Report Format

Lump Sum / I.B. \$



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC6/CTI19004520/Eha3

Date: 03/04/2019

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SGU 5096Y

We refer to the above matter.


Please be informed that we had conducted the inspection of the above mentioned vehicle on 11/03/2019 at the premises of M/s Prime Auto Claims Service Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	5,428.39
Revised Estimate Amount	: S\$	3,600.00
"Check" Items Amount	: S\$	-
Total (Including Check Items)	: S\$	3,600.00

Market Value	: S\$	-	(est.)
LTA Reimbursement Value	: S\$	-	(est.)
Nett Value	: S\$	-	(est.)

Description of Damage:

The vehicle sustained damages at the
O/S front portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5 days

Yours faithfully,

STEVE CHEN
Licensed Appraiser



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

FOR US ONLY



Toyota Vios

Price Range

Depreciation

> 10 years

Vehicle Type

Advanced Search

Home > Used Cars > Direct Owners > Toyota Vios 1.5A E (COE 98/03/2022)

Toyota Vios 1.5A E (COE till 03/2022)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Direct Owners

Price \$20,888

Depreciation \$6,540 /yr

Reg Date

11-Apr-2007
(Dns 20days COE wft)

Mileage 113,000 km (9.5k /yr)

Manufactured

2006

Road Tax

\$821 /yr

Transmission

Auto

Derog Value

\$15,113 as of today (Change)

OHV

\$12,337

COE

\$24,713

ARF

\$10,461

Engine Cap

1,497 cc

Power

80.0 kW (107 bhp)

Curb Weight

1,520 kg

No. of Owners

2

Type of Vehicle

Mid-Size Sedan

Features

Stock Condition, No Modifications, White Color. View specs of the Toyota Vios (2003-2007)

Description

Car In Excellent Condition, New Leather Upholstery, Low Mileage, No Dents Please, Only One 1 Transfer.

Category

COE Car, Direct Owner Sale, Low Mileage Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

Find out the market value of your existing car for free. Get started

100% FREE
PAPERWORK
SUPPORT FOR
BUYER & SELLER

Related Listings

Toyota

CarMart

Add Auto

Toyota Ertiga

More Autos

Seller Information

Contact Person(s)

Charlie

Contact No.

90627341

Enquiry

Contact Seller

ESSENTIAL TRANSACTION FORMS

• Indemnity form

• Sales agreement

• Receipt

• Hand-over form

• Ownership Transfer

GET HELP WITH
PAPERWORKSGCARMART
CONNECT

sgCarMart Connect handles your transaction paperwork - send us your completed Sales Agreement, and we'll help with Car Loans, Insurance, Payments & Ownership Transfer, FREE for all sgCarMart Advertised Vehicles.

Upload your Sales Agreement

Read our 8 Step Guide for Direct Buyers & Sellers

Posted on: 13-Feb-2018 | Last updated on: 11-Mar-2018

Upfront Payment

www.sgcarMart.com

Transfer Fee

\$25

Down Payment

\$6,000 (change)

Maximum 10% Loan

1st Installment

\$433

Based on 5.75% interest rate

Insurance

\$1,104 onwards

Not at fault? No upfront payment required! (Get a quote)



Total Upfront Payment

\$7,562

Check with seller for exact figure

Products and Services

View All



Any New For Grab: Click to find out



Grab New Steering Wheel



Door View



Parts Guide (With Cover)



Based Condition for Sale

Check out the specialist workshop for Toyota cars: [Toyota Automobiles Pte Ltd](#)

Tags: Toyota Vios, Toyota Vios, 2007 Toyota Vios, 2007 Toyota Vios, Toyota Vios, Vios, Used Toyota

Recommended for you

1/6 of 18

Copyright

SUPREME


 CLICK HERE OR CALL FOR A TEST DRIVE
6479 6280

Toyota Vios

Price Range

Depreciation

> 10 years

Vehicle Type

Advanced Search

Home > Used Cars > Starline Auto Pte Ltd > Toyota Vios 1.5A E (COE till 01/2022)

Toyota Vios 1.5A E (COE till 01/2022)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price \$19,500

Depreciation \$6,790 /yr

Reg Date 23-Jan-2007
(2yrs 10mths 11days COE left)

Mileage 130,000 km (12.4k /yr)

Manufactured 2006

Road Tax \$821 /yr

Transmission Auto

Derog Value \$14,542 as of today (1 change)

DMV \$12,237

COE \$25,323

ARF \$9,368

Engine Cap 1,497 cc

Power 85.0 KW (107 hp)

Curb Weight 1,020 kg

No. of Owners 2

Type of Vehicle Mid-Size Sedan

Features

Smooth Gearbox, Quiet Engine And No Rattling Sound At All. Solid Undercarriage Like A Few Years Old Condition. Very Cold Aircon. Reliable Plus Durable View areas of the Toyota Vios (2003-2007)

Accessories

Leather Upholstery, 15" Sports Rims, Amcrest, Fog Lamps, Bottle, Crystal Clear Headlamps (No Damage By Sunlight), Etc.

Description

Starline Auto, Your Automotive Partner Since 1997! Genuine Deal, Cheapest In Town! 1 Owner Only, Previously OPC Car, Agent Maintained, Immaculate Condition, Must View To Believe. Cash Buyer Welcome With Immediate Transfer. Call For More Enquiries!



Category

COE Car

Status

Available

Resources

Car Valuation - Free
Find out the market value of your existing car for free. Get startedVehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more

Posted on 05-Mar-2019 | Last updated on 10-Mar-2019

Upfront Payments

Transfer Fee \$25

Down Payment \$1,800 (change)

Maximum 10% Loan

1st Instalment \$444

Based on 3.75% interest rate

Insurance \$1,204 onwards

Not at fault? No upfront payment required! (Get it sorted)

Total Upfront Payment \$7,423

Check with seller for exact figure



Products and Services

View All



The largest Car Buy/Sell market in SG



Carbon Fiber Steering Wheel



Door View



Black GR86 (With Camaro)



Selling Camaro for Sale

Check out the specialist workshop for Toyota cars: [Starline Auto Pte Ltd](#)

Tag: Complete 3,400, 2007 Toyota Vios, 2007 Toyota Vios, Toyota Vios, Vios, Used Toyota

Enquire Transfer Fee

Vehicle Details

Vehicle No.	SGU5096Y
Vehicle Type	Z10 - Private Hire (Chauffeur) Motor Car
Vehicle Attachment 1	No Attachment
Vehicle Scheme	Normal
Vehicle Make	TOYOTA
Vehicle Model	VIOS G AUTO
Chassis No.	MR053HY9305006163
Propellant	Petrol
Engine No.	1N2X558979
Engine Capacity	1497 cc
Maximum Power Output	80.0 kW (107 bhp)
Maximum Laden Weight	1520 kg
Unladen Weight	1110 kg
Year Of Manufacture	2007
Original Registration Date	17 May 2007
Lifespan Expiry Date	-
COE Category	E - Open Category
PQP Paid	\$25,333.00
COE Expiry Date	16 May 2022
Road Tax Expiry Date	16 May 2018
Inspection Due Date	16 May 2018
Intended Transfer Date	03 Apr 2018
CO2 Emission	-
CO Emission	-
HC Emission	-
NOx Emission	-
PM Emission	-

The current road tax expiry is 16 May 2018. You may renew the road tax from 17 Feb 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 16 May 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 17 May 2018 to 16 Nov 2018)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment)	411.00	-	411.00
Total Amount Payable:			436.00

Amount Payable (From 17 May 2018 to 16 May 2019)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment)	821.00	-	821.00
Total Amount Payable:			846.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

You may print this page for reference.

OK

Print

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3381N
Vehicle Details	
Vehicle No.:	SGU5096Y
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS G AUTO
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	1NZX558979
Chassis No.:	MR053HY9305006163
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$14,039.00
Original Registration Date:	17 May 2007
First Registration Date:	17 May 2007
Transfer Count:	2
Actual ARF Paid:	\$15,443.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	16 May 2022
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$25,333.00
COE Rebate Amount:	\$16,112.00
Total Rebate Amount:	\$16,112.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 11 Mar 2019

OK



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M

6 Benoi Place Singapore 629927

Tel: 6861 0908 Fax: 6515 2948

Steve (LKK) wil provide 11/3/19 4:10pm
8322 8813 L/S
Re AF spray
S chgs

Date: 11.03.2019

China Taiping Insurance (S) Pte Ltd

2 Anson Road #16-00

Springleaf Tower

Singapore 079909

Attn: Motor Claims Dept

RE: COST OF REPAIR TO VEHICLE SGU5096Y TOYOTA VIOS G (2007)

To Supply

1)	1pc	Front bumper ✓	\$	689.10
2)	1set	Front bumper clip ✓	\$ 20	30.00
3)	1pc	Front bumper right side retainer ✓	\$	77.50
4)	1pc	Right front fender ✓	\$	524.10
5)	1pc	Right front fender cowling ✓	\$	125.80
6)	1set	Right front fender cowling clip ✓	\$ 20	40.00
7)	1pc	Right head lamp ✓	\$	595.10
8)	1pc	Right front shock absorber ?	\$	623.50
9)	1pc	Right front wheel nuckle ?	\$	523.08
10)	1pc	Right lower arm ?	\$	624.10
11)	1pc	Right side mirror assy ✓	\$	1,142.80
12)	1pc	Right side mirror cover ✓	\$	96.10

Sub total parts	\$	5,091.18
Less: 25% discount	\$	1,272.79
	\$	3,818.39

To Supply S.Nett Parts

1)	1pc	Right front tyre rim	\$	180.00 ✓
Sub total S.Nett Parts			\$	180.00

L/charge

1)	To tuff kote	\$	50.00 20
2)	To remove right front tyre, tyre rim, balance tyre & replace rim	\$	50.00 40
3)	To computerise wheel alignment	\$	80.00 60

- | | | | |
|-----|--|-----------|-----|
| 4) | To remove right front wheel nuckle, shock absorber & lower arm.
Replace the above parts. | \$ 200.00 | 150 |
| 5) | To focus right head lamp. Check wiring | \$ 50.00 | 70 |
| 6) | To remove right front fender, front bumper & right side mirror.
Replace front bumper, right front fender & right side mirror. Align &
adjust front bumper & fender | \$ 500.00 | 300 |
| 7) | To putty, respray painting front bumper, right front fender & right
side mirror cover. To polish | \$ 500.00 | 450 |

Sub total L/charges	\$ 1,430.00
Estimated Grand Total	\$ 5,428.39

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Mr ROSSHY
Steve (LKK) wil paymte 11/3/19 4.10pm
8322 8813 L/S
Rm AF spg
S chji

Date: 11.03.2019

China Taiping Insurance (S) Pte Ltd
2 Anson Road #16-00
Springleaf Tower
Singapore 079909

Attn: Motor Claims Dept

RE: COST OF REPAIR TO VEHICLE SGU5096Y TOYOTA VIOS G (2007)

To Supply

- 1) 1pc Front bumper *NEC 00*
- 2) 1set Front bumper clip *NEC*
- 3) 1pc Front bumper right side retainer *BR*
- 4) 1pc Right front fender *00*
- 5) 1pc Right front fender cowling *CRU*
- 6) 1set Right front fender cowling clip *NEC*
- 7) 1pc Right head lamp *CUT*
- 8) 1pc Right front shock absorber *BT*
- 9) 1pc Right front wheel nuckle *BT*
- 10) 1pc Right lower arm *BT*
- 11) 1pc Right side mirror assy *BR*
- 12) 1pc Right side mirror cover *MIS*

\$	689.10	<i>482.10 / ✓</i>
\$	30.00	<i>✓ / ✓</i>
\$	77.50	<i>✓ / ✓</i>
\$	524.10	<i>✓ / ✓</i>
\$	125.80	<i>✓ / ✓</i>
\$	40.00	<i>30 / ✓</i>
\$	595.10	<i>427.80 / ✓</i>
\$	623.50	<i>393.70 / ✓</i>
\$	523.08	<i>465.90 / ✓</i>
\$	624.10	<i>495.10 / ✓</i>
\$	1,142.80	<i>980.10 / ✓</i>
\$	96.10	<i>✓</i>

Sub total parts	\$	5,091.18	<i>4127.50</i>
Less: 25% discount	\$	1,272.79	<i>-75%</i>
	\$	3,818.39	<i>3095.62</i>

To Supply S.Nett Parts

- 1) 1pc Right front tyre rim *CUT*

\$	180.00	<i>✓</i>
Sub total S.Nett Parts	\$	180.00 <i>180</i>

L/charge

- 1) To tuff kote *NEC*
- 2) To remove right front tyre, tyre rim, balance tyre & replace rim
- 3) To computerise wheel alignment

\$	50.00	<i>20 ✓</i>
\$	50.00	<i>40 ✓</i>
\$	80.00	<i>60 ✓</i>

- | | | | | |
|-----|--|----|--------|----------------------|
| 4) | To remove right front wheel nuckle, shock absorber & lower arm.
Replace the above parts. | \$ | 200.00 | 180 200 ✓ |
| 5) | To focus right head lamp. Check wiring | \$ | 50.00 | 70 ✓ |
| 6) | To remove right front fender, front bumper & right side mirror.
Replace front bumper, right front fender & right side mirror. Align &
adjust front bumper & fender | \$ | 500.00 | 500 400 ✓ |
| 7) | To putty, respray painting front bumper, right front fender & right
side mirror cover. To polish | \$ | 500.00 | 450 ✓ |

Sub total L/charges	\$	1,430.00	1700
Estimated Grand Total	\$	5,428.39	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

4475-62
L/S - 3580-49
= 3600

Steve Chen (LKK Auto)

From: Alice Leong <aliceleong@primeautoclaims.com>
Sent: Tuesday, March 19, 2019 5:27 PM
To: Steve Chen (LKK Auto)
Subject: RE: SGU5096Y Finalize

Hi Steve,

confirmed

Thank you

Alice Leong
Manager, Motor Claims

Prime Auto Claims Service Pte Ltd
6 Benoi Place Singapore 629927
T (65): 6861 0908 | F (65) 6515 2948
HP (65) 9818 4304

A member of the Prime Group

Disclaimer

This e-mail (including all attachment) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intend recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: Steve Chen (LKK Auto) [<mailto:SteveChen@lkkauto.com>]
Sent: 19 March, 2019 5:25 PM
To: Alice Leong <aliceleong@primeautoclaims.com>
Subject: SGU5096Y Finalize

Dear Alice,

The finalize \$3600. 5 days.

Kindly confirm.

Thanks

Best Regards,
Steve Chen | Assistant Automotive Assessor
LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Khanchna (LKK Auto)

From: Alice Leong <aliceleong@primeautoclaims.com>
Sent: Friday, 12 July 2019 4:55 PM
To: Khanchna (LKK Auto)
Cc: Hsiao Tong (LKKAuto); Admin A
Subject: RE: ACCIDENT ON 07.03.2019 INVOLVING VEHICLES SGU5096Y & SLT4841R LKK REF CC6/CTI19004520/Eka3

Importance: High

Hi Khanchna,

We accepted your below offer. Please let us have your offer.

Thank you

Alice Leong
Manager, Motor Claims

Prime Auto Claims Service Pte Ltd
6 Benoi Place Singapore 629927
T (65): 6861 0908 | F (65) 6515 2948
HP (65) 9818 4304

A member of the Prime Group

Disclaimer

This e-mail (including all attachment) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intend recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: Khanchna (LKK Auto) [mailto:khanchna@lkkauto.com]
Sent: 12 July, 2019 4:28 PM
To: aliceleong@primeautoclaims.com
Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: ACCIDENT ON 07.03.2019 INVOLVING VEHICLES SGU5096Y & SLT4841R LKK REF CC6/CTI19004520/Eka3

Without Prejudice
(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair	\$ 3,852.00
2. Loss of Rental (5days x \$44.80)	\$ 224.00 (5days x \$44.80)
3. LTA/GIA Search Fee	\$ 2.00
TOTAL	\$ 4,078.00

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Friday, 12 July 2019 4:28 PM
To: aliceleong@primeautoclaims.com
Cc: Hsiao Tong (LKKAuto); Admin A
Subject: RE: ACCIDENT ON 07.03.2019 INVOLVING VEHICLES SGU5096Y & SLT4841R LKK REF CC6/CTI19004520/Eka3

Without Prejudice
(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair	\$ 3,852.00
2. Loss of Rental (5days x \$44.80)	\$ 224.00 (5days x \$44.80)
3. LTA/GIA Search Fee	\$ 2.00
TOTAL	\$ 4,078.00

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Alice Leong <aliceleong@primeautoclaims.com>

Sent: Friday, 12 July 2019 2:51 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: FW: ACCIDENT ON 07.03.2019 INVOLVING VEHICLES SGU5096Y & SLT4841R LKK REF CC6/CTI19004520/Eka3

Importance: High

Hi Hsiao Tong,

Refer to our earlier conversation on the even date.



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 15.07.2019

Our ref: SGU5096Y
Your Ref: DMPCSN3065671800

LKK Auto Consultants Pte Ltd
51, Ubi Ave 1, #01-25
Paya Ubi Industrial Park,
Singapore 408933

without prejudice

Attn: Ms. Khanchna / Ms. Hsiao Tong -Motor Claims Dept

Dear Madam,

ACCIDENT ON 07.03.2019 INVOLVING VEHICLES SGU5096Y & SLT4841R

See enclosed our client's signed Discharge Voucher for your payment processing. Please let us have your payment of \$4,078.00 make **payable to Prime Auto claims Service Pte Ltd.**

Thank you

Yours faithfully,

Ms. Alice Leong
e-mail: aliceleong@primeautoclaims.com

Encl.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC6/CTI19004520/Eka3n2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 29-07-2019	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLT 4841R	Veh. Inspected	SGU 5096Y	
Policy No.	DMPCSN3065671800	Coverage (\$)	0.00	
Claim No.	SNM19D201125C02/1	Excess (\$)	0.00	
Assign From		Assign Date	11/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	MR053HY9305006163	Colour	SILVER	
Odometer	237013	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	WEST LAKE	5 mm	
L/H Front Tyre	185/65 R15	WEST LAKE	5 mm	
R/H Rear Tyre	185/65 R15	WEST LAKE	5 mm	
L/H Rear Tyre	185/65 R15	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/03/2019	Inspection Date	11/03/2019	
Survey held at	PRIME AUTO CLAIMS SERVICE PTE LTD 6 BENOI PLACE SINGAPORE 629927			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGU 5096Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DENTED	689.10	482.10
1	SET FRONT BUMPER CLIP	NECESSARY	30.00	30.00
1	FRONT BUMPER RIGHT SIDE RETAINER	BROKEN	77.50	77.50
1	RIGHT FRONT FENDER	DENTED	524.10	524.10
1	RIGHT FRONT FENDER COWLING	CRUSHED	125.80	125.80
1	SET RIGHT FRONT FENDER COWLING CLIP	NECESSARY	40.00	30.00
1	RIGHT HEAD LAMP	CUT	595.10	427.80
1	RIGHT FRONT SHOCK ABSORBER	BENT	623.50	393.70
1	RIGHT FRONT WHEEL NUCKLE	BENT	523.08	465.20
1	RIGHT LOWER ARM	BENT	624.10	495.10
1	RIGHT SIDE MIRROR ASSY	BROKEN	1,142.80	980.10
1	RIGHT SIDE MIRROR COVER	MISSING	96.10	96.10
	LESS 25% DISCOUNT		-1,272.80	-1,031.88
			3,818.38	3,095.62
SPECIAL NETT ITEMS				
1	RIGHT FRONT TYRE RIM (SN)	CUT	180.00	180.00
			180.00	180.00
LABOUR				
	TO TUFF KOTE.		50.00	20.00
	TO REMOVE RIGHT FRONT TYRE ,TYRE RIM ,BALANCE TYRE & REPLACE RIM .		50.00	40.00
	TO COMPUTERISE WHEEL ALIGNMENT.		80.00	60.00
	TO REMOVE RIGHT FRONT WHEEL NUCKLE ,SHOCK ABSORBER & LOWER ARM ,REPLACE THE ABOVE PARTS.		200.00	200.00
	TO FOCUS RIGHT HEAD LAMP .CHECK WIRING.		50.00	30.00
	TO REMOVE RIGHT FRONT FENDER ,FRONT BUMPER & RIGHT SIDE MIRROR .REPLACE FRONT BUMPER ,RIGHT FRONT FENDER & RIGHT SIDE MIRROR .ALIGN & ADJUST FRONT BUMPER & FENDER.		500.00	400.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY,RESPRAY PAINTING FRONT BUMPER ,RIGHT FRONT FENDER & RIGHT SIDE MIRROR COVER .TO POLISH.		500.00	450.00
			1,430.00	1,200.00
GRAND TOTAL			5,428.38	4,475.62
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,600.00

Report Ref No. CC6/CTI19004520/Eka3n2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.