

ASSIGNED BY
Salvador
merimen
From (Person)

Marcus

Melvin Ye

REF: CS/SM019004522 / Urd3 / 12

per Instruction

ASSIGNMENT (Office)

SMO

Date/Time 12/31/19 @ 2:35pm

Estimated Cost

Bill to

OD (1) WS / IT RES / OD RES / EVA / INV / MYTCS

To Inspect Vehicle For

SGN 97P

Insured

SJD 4654Y

at Workshop on

Fusteeh Auto

Tel

67465405

of

1kaki Bkt Ave 6 # 01-46

Policy No

D18M7PV01016003

Claim No

CTD1901304

Sum Insured

Excess

Make of Veh

D.O.A

10/03/2019

(Client's Record)

CA / REV / REP / REV 24 HRS

H.O.D. Endorsement

Date/Time

9:58pm @ 12/31/19

Person Contacted

Nancy

Vehicle

IN / OUT

Date/Time

Action/Instruction

(✓)

Estimate

SGN 97P-X

SJD 4654Y-X

14/3/19

Informed Melvin pending workshop est by merimen

25/3/19

Send preli revised via merimen

(08/11/13) wef

REF:

5mo

ASS. REC. BY: *MACUS*

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

L7A56962

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SGN97P

Yr Regn:

11/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

is /

Make:

Honda ODYSSEY

c.c

2356

Colour

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

6018

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHMR-1890JC206044

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55-217

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

10/3/19

D.O.I.

12/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

20/3/19 L/S \$5000 confirmed with Aler. (Red 16,061.50, 767)

RECEIVED 25 MAR 2019

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

25/3- typist

Report Format :

metimen

Lump Sum / I.B.I: (\$

5000/2

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

450
10

460

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Melvin Ye

Date: 25 Mar 2019

Preliminary Advice

Insured Vehicle No	: SJD4654Y	Accident Date	: 10/03/2019
TP Vehicle No	: SGN97P	Assignment Date	: 12/03/2019
Make	: HONDA ODYSSEY	Est. Duration of Repair	: 0.00
Date of Inspection	: 12/03/2019		
Inspection At	: FASTECH AUTO PTE LTD (HQ) 1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	21,061.50
Revised Amount (EST)	:S\$	5,000.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,000.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

☐ The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

☐ The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

☒ Other comments :The above survey was conducted on a 'Without Prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Mar 2019		12 Mar 2019 14:35 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS
[Created by insurer]

Insured:	OH CHOON KIAT (HU JUNJIE), ID: S1768398E		
Main Claimant:	LIM RONGJUN, KEN, ID: S8831229E		
Vehicle Reg. No.:	SGN97P	Date of Loss:	10/03/2019 20:00 - :59
Claim Type:	TP / CMTD1901304	Policy/Cover Note No.:	D18MTPV01016003 (Comprehensive)
Vehicle Reg. No. (Insured):	SJD4654Y	Policy No. (Claimant):	
		Excess:	
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Melvin Ye - 6322 4667]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/03/2019]		
Driver/Custodian (Insured):	OH CHING TAT (), NRIC: S9216627I, Tel: +6581398776 Email:		

ASSOCIATED MAIL RECEIVED
[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS ▾
[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

***SGN97P (CMTD1901304)**
[SJD4654Y]

TP
LIM RONGJUN, KEN
Mar 10 2019 8:00PM
[OH CHOON KIAT (HU JUNJIE)]
Fastech Auto Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **14/03/2019 08:41 AM**.

To MelvinYe

Subject TP SURVEY SGN 97P

Dear Melvin,

Please be informed that we have inspected the vehicle SGN 97P on 12/3/2019.

We are pending estimate from repairer.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1229E
Vehicle Details	
Vehicle No.:	SGN97P
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Mar 2019
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4 EXV-S CVT SR
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	K24W72402481
Chassis No.:	JHMRC1890JC206044
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$31,195.00
Original Registration Date:	07 Nov 2018
First Registration Date:	07 Nov 2018
Transfer Count:	0
Actual ARF Paid:	\$35,673.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Nov 2028
PARF Rebate Amount:	\$26,754.00
Intended COE Rebate Details	
COE Expiry Date:	06 Nov 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$32,552.00
COE Rebate Amount:	\$30,208.00
Total Rebate Amount:	\$56,962.00

The information contained herein is correct as at 12 Mar 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/03/2019 17:33
Date Of Accident	10/03/2019 20:05
Exact Location Of Accident	JURONG GATEWAY RD TOWARDS TOH GUAN RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGN97P
Insured/Policyholder	
Name Of Registered Owner	LIM RONGJUN, KEN
NRIC No	S8831229E
Email Address	KENUEE@GMAIL.COM
Mobile Phone No	(LOCAL) +65-81004321
Alternative Phone No	OFFICE-81004321

Vehicle Particulars

Manufacturer	HONDA
Model	ODYSSEY-2.4 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	LIM RONGJUN, KEN
NRIC No	S8831229E
Date Of Birth	29/08/1988
Occupation	INDOOR
Date Of Driving Pass	18/02/2014
Driving Experience	5 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81004321
Fax Number	
Contact Number	OFFICE-81004321
Email Address	KENUEE@GMAIL.COM

Address

BLK 656 CHIA CHU KANG CRESCENT #11-31

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle

-

-

-

Insurance Company of Driver's Own Vehicle

-

-

-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 6

Passenger 1
NAME: : LIM BENG JUN LOUIS
GENDER: : MALE

Passenger 2
NAME: : GAY TENG YONG
GENDER: : FEMALE

Passenger 3
NAME: : BU YUAN YU
GENDER: : FEMALE

Passenger 4
NAME: : JENNY TAN
GENDER: : FEMALE

Passenger 5
NAME: : TAN GUAT ENG
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJD4654Y

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Vehicle Number: _____

SKETCH PLAN

A = SGN 97P.
B = STD 4654Y

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Car stop at junction. Car from behind bang on to my car

NO ONE INJURED

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 14.58 11/3/15

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Tax Reg No : 20-0006262-D

SGN 97P

not Allowed
OK
1/5 \$5000
Hwy
11/3/19

(207)

TO DISMANTLE & REFIX REAR EXHAUST

✓✓ \$100.00 ✕

505230

TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTREY
TO MOUNT VEHICLE ON CAR-LINER
TO SPRAY RUST PROOFING
LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTENED
& REPLACING PARTS
TO PUTTY & SPRAY PAINTING

\$120.00 80
11 \$380.00 X
\$100.00 60
\$1,500.00 600
\$1,500.00 1000
TO \$21,061.50

6261.54

21011.50

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19004522/UVD3N2

Date: 26/03/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01016003
Claimant Vehicle No :	SGN97P	Insured Vehicle No :	SJD4654Y
Date of Loss:	10/03/2019	Nature of Claim:	TP
		Claim No:	CMTD1901304

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGN97P	Engine No:	K24W72402481
Make & Model:	HONDA ODYSSEY, 2.4 (A)	Chassis No:	JHMRC1890JC206044
Reg. Date:	07/11/2018 (Man. Year: 2018)	Odometer:	6018 km
Colour:	Blue		
Engine Capacity:	2356 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55R17	Rear Tyre Size:	215/55R17
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	16,901.50	4,241.84	12,659.66	74.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,110.00	2,020.00	2,090.00	50.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,011.50	6,261.84	14,749.66	70.20
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	21,011.50	5,000.00	16,011.50	76.20
+ GST 7.00/7.00% (S\$)	1,470.81	350.00	1,120.81	76.20
Nett Amount (S\$)	22,482.31	5,350.00	17,132.31	76.20

INSPECTION

Date of Assignment: 12/03/2019
Date Inspected: 12/03/2019 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50
Autobay
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Mar 2019)
Parts: M1-MPV	HONDA ODYSSEY 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SGN97P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR WINDSCREEN	Not Necessary	1,105.10 F	*- FL
2	1	*REAR WINDSCREEN MOULDING	Necessary	122.80 F	*122.80 FL
3	1	*TAILGATE	Badly Dented	1,485.30 F	*1,285.30 FL
4	1	*TAILGATE H LOGO	Necessary	45.80 F	*45.80 FL
5	1	*TAILGATE ODYSSEY EMBLEM	Necessary	45.20 F	*45.20 FL
6	1	*TAILGATE REFLECTORS	N/s Cracked	1,360.00 F	*680.00 FL
7	1	*TAILGATE INNER LOCK	Dented/Shorted	299.20 F	*299.20 FL
8	1	*TAILGATE INNER LOCK STRIKER	Not Necessary	68.20 F	*- FL
9	1	*TAILGATE INNER TRIM BOARD	Deformed/Cracked	745.30 F	*485.30 FL
10	1	*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	35.00 F	*35.00 FL
11	1	*TAILGATE WEATHERSTRIP	Twisted	166.20 F	*117.30 FL
12	1	*TAILGATE OUTER HANDLE	Not Necessary	299.30 F	*- FL
13	1	*TAILGATE OUTER CHROME MOULDING LOWER	Cracked	295.40 F	*295.40 FL
14	1	*TAILGATE LOCK SENSOR	Cracked	210.00 F	*210.00 FL
15	2	*TAILGATE LICENCE LAMPS	Not Necessary	130.00 F	*- FL
16	1	*REAR BUMPER	Dented/Torn	915.30 F	*665.40 FL
17	2	*REAR BUMPER SIDE HOLDERS	Not Necessary	133.00 F	*- FL
18	1	*SET REAR BUMPER CLIPS	Necessary	39.00 F	*39.00 FL
19	2	*REAR BUMPER REFLECTORS	Not Necessary	210.00 F	*- FL
20	2	*REAR BUMPER CHROMES	Not Necessary	330.00 F	*- FL
21	1	*REAR END PANEL	Dented/Bent	691.20 F	*460.80 FL
22	1	*REAR END PANEL TOP GARNISH	Twisted	315.40 F	*165.80 FL
23	1	*TAILLAMP HOUSING PANEL N/S	Repair	458.20 F	*- FL
24	2	*TAILLAMPS	Not Necessary	1,500.00 F	*- FL
25	2	*REAR FENDERS	Not Necessary	1,942.00 F	*- FL
26	2	*REAR FENDER INNER TRIM BOARDS	Not Necessary	1,640.00 F	*- FL
27	1	*TAILLAMP LOWER GARNISH N/S	Not Necessary	318.20 F	*- FL
28	1	*REAR FLOOR PANEL	Not Necessary	866.40 F	*- FL
29	1	*REAR REVERSE CAMERA	Not Necessary	650.00 F	*- FL
30	1	*REAR END PANEL SEALANT	Necessary	50.00 F	*50.00 FL
31	1	*REAR WINDSCREEN SEALANT	Necessary	50.00 F	*50.00 FL
32	1	*SET REAR BUMPER SENSOR	Shorted	380.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,901.50	5,252.30
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	1,010.46
Total Parts (\$\$)	16,901.50	4,241.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REAR REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX TAILGATE MECHANISM	New	100.00	80.00
4	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
5	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
6	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY	New	120.00	80.00
7	TO MOUNT VEHICLE ON CAR-LINER	New	380.00	0.00
8	TO SPRAY RUST PROOFING	New	100.00	60.00
9	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTENED & REPLACING PARTS	New	1,500.00	600.00
10	TO PUTTY & SPRAY PAINTING	New	1,500.00	1,000.00
Gross Labour Cost (S\$)			4,110.00	2,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >