

ASSIGNMENT

CTI 19004523/Kqd302

12/3/19 @ 2:16pm

Münster Kenneth
Chong Boon Sen

ASSIGNMENT (OHIO)

CTI

Date/Time 12/3/19 @ 2:16pm

Estimated Cost

Bill to

OWS / TP RES / OD RES / EVA / INV / MVCS

To Impact Vehicle No.

SLA 8564P

Insured

GBA 5363R

at Workshop no.

Jeri Hout (Meng Kee)

Tel

64538110

of

160 Sin Ming Drive # 04-01

Policy No.

DMCVSN30559618083

Claim No.

SNM19D201105C02

Name Insured

Excess

Make of Veh.

D.O.A

9/13/2019

(Client's Record)

CA / REV / REP / REV 24 HRS

lup

H.O.D. Employment

Date/Time

3:10pm 12/3/19

Person Contacted

Jenny

Vehicle

IN/OUP

Date/Time

Action/Instruction

Estimate

SLA 8564P-x

GBA 5363R-NA/CTI 1602018/23

DOB: 22/10/16

Final Fig \$6842.56, 6 days (red \$344.40, 5%.)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Mar 2019 Sendback Est	11 Mar 2019 16:53 S\$6,472.96	12 Mar 2019 14:16 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	-, ID: -								
Main Claimant:	EE LEE KUAN DEBORAH , ID: S1764912D								
Vehicle Reg. No.:	SLA8564P	Date of Loss:	09/03/2019 13:00 - :59 [35 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D201105C02	Policy/Cover Note No.:	DMCVSN30559818033						
Vehicle Reg. No. (Insured):	GBA5363R	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	United Overseas Insurance Ltd (HQ) - Tel: 64909318								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/03/2019]								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 4912D

Vehicle Details

Vehicle No.: SLA8564P

Vehicle to be Exported: No

Intended Deregistration Date: 09 Mar 2019

Vehicle Make: AUDI

Vehicle Model: A1 SB 1.0 TFSI (PI)

Primary Colour: Red

Manufacturing Year: 2015

Engine No.: CHZ061849

Chassis No.: WAUZZZ8X8GB064320

Maximum Power Output: 70.0 kW (93 bhp)

Open Market Value: \$21,163.00

Original Registration Date: 18 Mar 2016

First Registration Date: 18 Mar 2016

Transfer Count: 0

Actual ARF Paid: \$6,629.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 17 Mar 2026

PARF Rebate Amount: \$4,971.00

Intended COE Rebate Details

COE Expiry Date: 17 Mar 2026

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$45,000.00

COE Rebate Amount: \$31,596.00

Total Rebate Amount: \$36,567.00

The information contained herein is correct as at 09 Mar 2019

OK



THANK YOU

Lai Mei Ling Deborah has successfully logged out.

Your last login date and time was 09 Mar 2019, 15:16:35.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S.No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type
1	Vehicle	GBA5363R	-	18.32 Insurance Enquiry (GIRO Payment)
2	Vehicle	GBA5363R	-	18.32 Insurance Enquiry (GIRO Payment)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/03/2019 15:21
Date Of Accident	09/03/2019 13:30
Exact Location Of Accident	CTE TOWARDS PIE CHANGI
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLA8564P
Insured/Policyholder	
Name Of Registered Owner	EE LEE KUAN DEBORAH
NRIC No	S1764912D
Email Address	DEBBIE.EE@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90012898
Alternative Phone No	OTHERS-90012898
Vehicle Particulars	
Manufacturer	AUDI
Model	A1 SB 1.0 TFSI (PI)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	UNITED OVERSEAS INSURANCE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	
Driver	
Name of Driver	EE LEE KUAN DEBORAH
NRIC No	S1764912D
Date Of Birth	09/09/1966
Occupation	OUTDOOR
Date Of Driving Pass	24/09/1992
Driving Experience	26 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-90012898
Fax Number	
Contact Number	OTHERS-90012898
Email Address	DEBBIE.EE@GMAIL.COM

Address	BLK 217 SERANGOON AVENUE 4 #12-156
Postcode	550217
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Traffic along CTE towards PIE Changi was heavy. My car SLA 8564P was on brake mode when a lorry GBA 5363R suddenly hit my car. It was along CTE along the Australian School area moving towards PIE Changi.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBA5363R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	LU YANG
NRIC/Passport Number	G6195461P
Contact Number	97937085
Address	C/O CLX BUILDERS PTE LTD 18 KAKI BUKIT ROAD 3 #03-11
Postcode	415978
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: - 9 MAR 2019

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: Deborah Lai
NRIC/FIN No.: S7332811Z

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Traffic along CTE towards PIE changi was heavy. my car SLA8564P was on brake mode when a lorry GBA5363R suddenly hit my car. It was along CTE along the Australian School area moving towards PIE changi. Estimated time 9 March about 1.30 pm

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Deborah Lai
 Policyholder's signature
 Date & Time: -9 MAR 2019

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Deborah Lai
 Reporting Centre/Personnel's Signature
 Name: Deborah Lai
 NRIC/FIN No.: S7332811Z

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence No. **S1764912D**
EE LEE KUAN DEBORAH
 Birth Date: 09 Sep 1966
 Issue Date: 24 May 2003

000505966J

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S1764912D**



Name: **EE LEE KUAN DEBORAH**
 余丽娟
 Race: **CHINESE**
 Date of Birth: 09-09-1966 Sex: F
 Country of Birth: **SINGAPORE**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class	Description	Pass Date
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	24 Feb 1992

NP-428A

Licence No. S1764912D

0282728

Barcode: S1764912D

NRIC No. **S1764912D**
 Blood Group: **O+** Date of Issue: **26-03-1992**

APT. BLK 217 SERANGOON AVENUE 4 #12-15G
 SINGAPORE 550217
 NRIC No. **S1764912D** Date: **22-12-2004** No: **5089021**

Certificate of Insurance

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
 Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
 Road Transport Act, 1987 (Malaysia)
 Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

ORIGINAL

CERTIFICATE NO.	DHOM120027541701	Excess:	\$500/- NAMED DRIVERS \$1500/- OTHERS
Type of Cover	COMPREHENSIVE		\$3000/- APPL TO <25 YRS & OR <3YRS EXP
Vehicle Number	SLA8564P		\$100/- WINDSCREEN DAMAGE CLAIM
Name of Insured	EE LEE KUAN DEBORAH		
Restricted Driver(s)	NOT APPLICABLE		

Period of Insurance 18 March 2018 to 17 March 2019
Hire Purchase UNITED OVERSEAS BANK LIMITED

Engine# CHZ061849
Chassis# WAUZZZ8X8GB064320

PRIVATE CAR - INDIVIDUAL OWNERSHIP [MX 1]
 AUTHORISED DRIVER

- (1) The Insured
- (2) Any other person who is driving on the Insured's order or with his permission
- (3) In the event of the death of the Insured
 - (a) any member of the Insured's family or a paid driver who has been driving the car during the lifetime of the Insured and permission to drive had not been withdrawn prior to the death of Insured and
 - (b) any other person who has been given permission to drive the vehicle prior to the death and such permission had not been withdrawn by the Insured

LIMITATIONS AS TO USE

Use only for social domestic and pleasure purposes and for the Insured's business

THE POLICY DOES NOT COVER

Use for hire or reward or racing pace-making reliability trial or speed-testing or the carriage of goods (other than samples) in connection with any trade or business or use for any purposes in connection with the Motor Trade

The carriage of passengers pursuant to car pooling arrangements and payments or any of them made by the passengers thereunder towards the running expenses of any vehicle described in the Schedule shall not be deemed to constitute use for hire or reward

Provided that the person is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

*Limitation rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles(Third-Party Risks and Compensation) Act (Chapter 189) and part IV of the Road Transport Act, 1987 (Malaysia).

UNITED OVERSEAS INSURANCE LTD



For the Company

FCTTS Date : 21/02/2018

Lai Huat (Meng Kee) Motor Pte Ltd
Sin Ming Industrial Estate, Sector A, Blk 21 #01-58
575679

Claim Reference: TP-GBA 5363R
 Assessment number: 70310
 Version: 1810
 Date calculated: 03/11/2019 04:40 PM

Full Report
Registration: SLA 8564P
Printed: 11/03/2019 4:41 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:	TP-GBA 5363R	Date of Incident:	2019-03-09
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer: AUDI
 Model: A1 (8X)
 Sub Model: DESIGN
 Model Sheet Number: 00 83 51
 Registration: SLA 8564P
 VIN number: WAUZZZ8X8GB064320
 Odometer:

Model Specs

FROM 11/2015	STOP-START SYSTEM	DR-MIRROR BODY COLOR	WHEELS 7J X 16 ALLOY
AUTO AIR CON	FR SCREEN/SHADE BAND	REAR PARKING SYSTEM	WITHOUT SAFETY DEV
VOICE CONTROL SYSTEM	8 SPEAKER	RADIO MEDIA CENTER	XENON HEADLAMPS
LED TAILLAMP	HEADLAMP WASHERS	RAIN SENSOR	CLOTH TRIM
SPORT SEATS	TRIM PART LEATHER	SPORT S-WHEEL LEATH	HEIGHT ADJ PASS SEAT
MULTI FUNC DISPLAY	REAR BATTERY	LUMBAR SUPPORT	ALTERNATOR 140A
HD COOLING	S-TRONIC	TYRES 215/45 VR 16	TRIM PACK ALUMINIUM
AIR VENTS COLOURED	PHONE SYS BLUETOOTH	1.0 LTR 70KW	5-DOOR
TWO COAT PEARL/MICA			

Not Authorized
Resurvey B4paint
6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal modifications is allowed
- Supplementary items will be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

**Lai Huat (Meng Kee) Motor Pte
Ltd
Sin Ming Industrial Estate, Sector
A, Blk 21 #01-58
575679**

Claim Reference: TP-GBA 5363R
Assessment number: 70310
Version: 1810
Date calculated: 03/11/2019 04:40 PM

Full Report
Registration: SLA 8564P
Printed: 11/03/2019 4:41 PM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All
Underbody



Labour

Code	Description	Time Base 10 WU/h	Price = 48.00 SGD/h	
			WU	Price SGD
55 70 19 00	R + R TAILGATE SEAL		3.0	14.40
55 59 19 00)	R + R TAILGATE (INNER TAILLAMPS REMOVED) INCLUDES: TAILGATE TRIM REMOVE + REFIT. ADJUST TAILGATE.		9.0	43.20
55 59 55 50	RENEW TAILGATE (TAILGATE REMOVED) (2C-MATERIAL) INCLUDES: R + R ALL PARTS		22.0	105.60
94 31 19 01	R + R LEFT INNER TAILLAMP		2.0	9.60
94 31 19 01	R + R RIGHT INNER TAILLAMP		2.0	9.60
63 69 55 54	RENEW REAR BUMPER COVER (COVER REMOVED) INCLUDES: R + R LOWER SPOILER AND SENSORS		4.0	19.20

**Lai Huat (Meng Kee) Motor Pte
Ltd
Sin Ming Industrial Estate, Sector
A, Blk 21 #01-58
575679**

Claim Reference: TP-GBA 5363R
Assessment number: 70310
Version: 1810
Date calculated: 03/11/2019 04:40 PM

Full Report
Registration: SLA 8564P
Printed: 11/03/2019 4:41 PM

Code	Description	WU	Price SGD
53 16 53 00	REMOVE PARTS REAR END CROSSMEMBER INCLUDES: REMOVE TAILLAMPS, BUMPER (IMPACT CARRIER), BUMPER COVER, LOCK CARRIER COVER, BOOT TRIMS, TAILGATE SEAL AND LOWER LOCK	9.0	43.20
53 16 55 00	RENEW REAR END CROSSMEMBER	25.0	120.00
53 05 55 50	RENEW REAR END PANEL (COMPOSITE WORK) (REAR END CROSSMEMBER REMOVED)	42.0	201.60
53 16 59 00	FIT PARTS REAR END CROSSMEMBER INCLUDES: FIT REMOVED PARTS, RENEW IF NECESSARY DOES NOT INCLUDE: RENEW BUMPER COVER	11.0	52.80
68 05 19 00	R + R R/INNER SILL TRIM	2.0	9.60
70 67 19 10)	R + R R/LOWER B-PILLAR TRIM	1.0	4.80
70 67 19 20)	R + R R/UPPER B-PILLAR TRIM	2.0	9.60
70 68 19 70)	R + R R/LOWER C-PILLAR TRIM	2.0	9.60
70 39 19 00	R + R REAR LOCK CARRIER COVER	2.0	9.60
69 11 19 10)	R + R RIGHT FRONT THREE POINT SEAT BELT (B-PILLAR TRIM REMOVED)	2.0	9.60
91 76 19 51	R + R REAR PARKING SYSTEM WARNING SENSOR	1.0	4.80
NN	REAR PARKING SENSOR R&R / NEW PARTS	2.0*	9.60
3583	L/R SIDE PANEL REINF REPAIR	10.0*	48.00
3584	R/R SIDE PANEL REINF REPAIR	10.0*	48.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		16.30	163.0
Total of Labour			782.40

Paint

Code	Description - TWO COAT PEARL/MICA	WU	Price SGD
Paint Work	SYSTEM AZT	Time Basis 10WU/h	
	REAR PANEL NEW PART PAINTING	20.0	
	TAILGATE/BOOTLID NEW PART PAINTING	18.0	
	REAR BUMPER NEW PART PAINT K1R	11.0	
	L/R SIDE PANEL REINF REPAIR PAINTING <50%	7.0	
	R/R SIDE PANEL REINF REPAIR PAINTING <50%	7.0	

**Lai Huat (Meng Kee) Motor Pte
Ltd
Sin Ming Industrial Estate, Sector
A, Blk 21 #01-58
575679**

Claim Reference: TP-GBA 5363R
Assessment number: 70310
Version: 1810
Date calculated: 03/11/2019 04:40 PM

Full Report
Registration: SLA 8564P
Printed: 11/03/2019 4:41 PM

Paint Material Per Part

Code	Description	Price SGD
2711	REAR PANEL NEW PART PAINTING	23.10
2931	TAILGATE/BOOTLID NEW PART PAINTING	53.15
2581	REAR BUMPER NEW PART PAINT K1R	48.71
3583	L/R SIDE PANEL REINF REPAIR PAINTING <50%	0.65
3584	R/R SIDE PANEL REINF REPAIR PAINTING <50%	0.65

Labour Cost - Paint

Factor	48.00 SGD/h	Hrs	WU	Price SGD
Time Paint			63.0	
Preparation Main Work Metal		2.10	21.0	100.80
Preparation Comp. Work Plastic		0.50	5.0	24.00
Total	10 WU/h	8.90	89.0	427.20

Material Cost - Paint

Description	Price SGD
New Part Painting	76.25
New Part Painting - Plastic K1R	48.71
Repair Painting	1.30
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	153.36

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-09-02/23	Price SGD
2581	REAR BUMPER	8XA 807 067 A GRU		B1 ✓	450.00
2605	REAR BUMPER SPOILER	8XA 807 421 B 9B9		Dilling Di ✓	160.00
2640	REAR BUMPER SUPPORT	8X0 807 309		B1 ✓	200.00
2711	REAR PANEL	8X0 813 301 TB	B1	430 ✓	165.00
2719	REAR PANEL C-MEMBER	8X0 813 309	B1		430.00
2786	REAR PARKING SENSOR	INNER RIGHT			110.00
2931	TAILGATE/BOOTLID	8X4 827 023 B	✓	B1 ✓	750.00
2944	BOOT/TAILGATE SEAL	8X4 827 705	✓	Me ✓	85.00
2952	BOOT/T.GATE MNTG SET	8X0 098 617 A	Me	6.00 ✓	0.00
2975	BOOT/TAILGATE LOCK	8R0 827 505 A	Me		75.00
2985	BOOT/TAILGATE SENSOR	5J0 827 566 E	Me		75.00

**Lai Huat (Meng Kee) Motor Pte
Ltd
Sin Ming Industrial Estate, Sector
A, Blk 21 #01-58
575679**

Claim Reference: TP-GBA 5363R

Assessment number: 70310

Version: 1810

Date calculated: 03/11/2019 04:40 PM

Full Report

Registration: SLA 8564P

Printed: 11/03/2019 4:41 PM

Code	Description	Part Number	Supplier	Price SGD
3013	L/R BADGE	8X0 853 741	2ZZ	<i>na</i> ✓ 50.00
3019	R/R BADGE	8X0 853 737 A		<i>na</i> ✓ 50.00
3020	REAR BADGE	8X0 853 742 A		<i>na</i> ✓ 50.00
3281	L/R LAMP	8XA 945 093 A		<i>CM</i> ✓ 450.00
3282	R/R LAMP	8XA 945 094 A		<i>CM</i> ✓ 450.00
4662	R/F SEAT BELT	8X3 857 706 E		<i>400</i> <i>JA</i> ✓ 420.00
4978	REAR BOOT COVERING	8X0 861 475 A		<i>R</i> 210.00
4985	END PANEL TRIM	8X0 863 459 C		<i>na</i> 110.00
9665	CENTRAL FUSING	8X0 915 459		<i>CM</i> ? 180.00
1005	REAR PARKING SENSOR	INNER LEFT		<i>R</i> 210.00
f: OEM Parts				Savings 0.00
n: Non-OEM Parts				Subtotal 4,680.00
u: Used parts				Total 4,680.00

Extras

Code	Description	Price SGD
1000	ANTI RUST CHEMICAL	<i>60l.</i> 120.00*
1001	CHECK/ERASE FAULT CODES	? 120.00*
1002	RECODING SRS MODULE	<i>na</i> ✓ 120.00*
1003	RR WINDSCREEN SEALANT	<i>na</i> ✓ 40.00*
1004	RR WINDSCREEN SEAL	<i>na</i> ✓ 30.00*
2786	[E]: REAR PARKING SE NSOR: INNER RIG	0.00*
2786	HT	0.00*
Total Extras		430.00

**Lai Huat (Meng Kee) Motor Pte
Ltd
Sin Ming Industrial Estate, Sector
A, Blk 21 #01-58
575679**

Claim Reference: TP-GBA 5363R
Assessment number: 70310
Version: 1810
Date calculated: 03/11/2019 04:40 PM

Full Report
Registration: SLA 8564P
Printed: 11/03/2019 4:41 PM

Final Calculation

	SGD	SGD
Parts	4,680.00	
Total Parts		4,680.00
Labour Time Base 10 WU/h		
Total 163.0 WU X 48.00 SGD/h	782.40	
Total of Labour		782.40
Total Of Extras		430.00
Paint Work Time Base 10 WU/h		
Labour Cost 89.0 WU X 48.00 SGD/h	427.20	
Material Cost	153.36	
Total Paint Including Material		580.56
Repair Cost Excludes GST		6,472.96
GST (+7.0%)		453.11
Repair Cost Included GST		6,926.07

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01,
#04-02 & #07-03, Sin Ming
Autocity
575722

Claim Reference: TP-GBA 5363R
Assessment number: 70310
Version: 1810
Date calculated: 31/05/2019 5:58 PM

Full Report
Registration: SLA 8564P
Printed: 31/05/2019 5:58 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:	TP-GBA 5363R	Date of Incident:	09/03/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	AUDI
Model:	A1 (8X)
Sub Model:	DESIGN
Model Sheet Number:	00 83 51
Registration:	SLA 8564P
VIN number:	WAUZZZ8X8GB064320
Odometer:	

Model Specs

FROM 11/2015	STOP-START SYSTEM	DR-MIRROR BODY COLOR	WHEELS 7J X 16 ALLOY
AUTO AIR CON	FR SCREEN/SHADE BAND	REAR PARKING SYSTEM	WITHOUT SAFETY DEV
VOICE CONTROL SYSTEM	8 SPEAKER	RADIO MEDIA CENTER	XENON HEADLAMPS
LED TAILLAMP	HEADLAMP WASHERS	RAIN SENSOR	CLOTH TRIM
SPORT SEATS	TRIM PART LEATHER	SPORT S-WHEEL LEATH	HEIGHT ADJ PASS SEAT
MULTI FUNC DISPLAY	REAR BATTERY	LUMBAR SUPPORT	ALTERNATOR 140A
HD COOLING	S-TRONIC	TYRES 215/45 VR 16	TRIM PACK ALUMINIUM
AIR VENTS COLOURED	PHONE SYS BLUETOOTH	1.0 LTR 70KW	5-DOOR
TWO COAT PEARL/MICA			

**Lai Huat (Meng Kee) Motor Pte
Ltd**
**160 Sin Ming Drive, #04-01,
 #04-02 & #07-03, Sin Ming
 Autocity**
575722

Claim Reference: TP-GBA 5363R
 Assessment number: 70310
 Version: 1810
 Date calculated: 31/05/2019 5:58 PM
Vehicle Condition


Full Report
Registration: SLA 8564P
Printed: 31/05/2019 5:58 PM

Vehicle Status

Pre-Accident Damage:
 Date of Inspection:

Damage Areas

All
 Underbody



Labour

Code	Description	Time Base 10 WU/h	Price = 48.00 SGD/h	
			WU	Price SGD
55 70 19 00	R + R TAILGATE SEAL		3.0	14.40
55 59 19 00)	R + R TAILGATE (INNER TAILLAMPS REMOVED) INCLUDES: TAILGATE TRIM REMOVE + REFIT, ADJUST TAILGATE.		9.0	43.20
55 59 55 50	RENEW TAILGATE (TAILGATE REMOVED) (2C-MATERIAL) INCLUDES: R + R ALL PARTS		22.0	105.60
94 31 19 01	R + R LEFT INNER TAILLAMP		2.0	9.60
94 31 19 01	R + R RIGHT INNER TAILLAMP		2.0	9.60
63 69 55 54	RENEW REAR BUMPER COVER (COVER REMOVED) INCLUDES: R + R LOWER SPOILER AND SENSORS		4.0	19.20

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01,
#04-02 & #07-03, Sin Ming
Autocity
575722

Claim Reference: TP-GBA 5363R
 Assessment number: 70310
 Version: 1810

Full Report
 Registration: SLA 8564P
 Printed: 31/05/2019 5:58 PM

Date calculated: 31/05/2019 5:58 PM

		WU	Price SGD
53 16 53 00	REMOVE PARTS REAR END CROSSMEMBER INCLUDES: REMOVE TAILLAMPS, BUMPER (IMPACT CARRIER), BUMPER COVER, LOCK CARRIER COVER, BOOT TRIMS, TAILGATE SEAL AND LOWER LOCK	9.0	43.20
53 16 55 00	RENEW REAR END CROSSMEMBER	25.0	120.00
53 05 55 50	RENEW REAR END PANEL (COMPOSITE WORK) (REAR END CROSSMEMBER REMOVED)	42.0	201.60
53 16 59 00	FIT PARTS REAR END CROSSMEMBER INCLUDES: FIT REMOVED PARTS, RENEW IF NECESSARY DOES NOT INCLUDE: RENEW BUMPER COVER	11.0	52.80
68 05 19 00	R + R L/INNER SILL TRIM	2.0	9.60
70 67 19 10)	R + R LEFT B-PILLAR LOWER TRIM	1.0	4.80
70 67 19 20)	R + R L/UPPER B-PILLAR TRIM	2.0	9.60
68 05 19 00	R + R R/INNER SILL TRIM	2.0	9.60
70 67 19 10)	R + R R/LOWER B-PILLAR TRIM	1.0	4.80
70 67 19 20)	R + R R/UPPER B-PILLAR TRIM	2.0	9.60
70 68 19 70)	R + R R/LOWER C-PILLAR TRIM	2.0	9.60
70 39 19 00	R + R REAR LOCK CARRIER COVER	2.0	9.60
69 11 19 10)	R + R LEFT FRONT THREE POINT SEAT BELT (B-PILLAR TRIM REMOVED)	2.0	9.60
69 11 19 10)	R + R RIGHT FRONT THREE POINT SEAT BELT (B-PILLAR TRIM REMOVED)	2.0	9.60
NN	RR W/S NOZZLE JET R&R / NEW PARTS	1.0*	4.80
NN	SRS BATTERY FUSE R&R / NEW PARTS	10.0*	48.00
3571	L/R REARLAMP SUPP REPAIR	10.0*	48.00
3572	R/R REARLAMP SUPP REPAIR	10.0*	48.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		17.80	178.0
Total of Labour			854.40

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h	
Code	Description - TWO COAT PEARL/MICA	WU	Price SGD
	REAR PANEL NEW PART PAINTING	20.0	
	TAILGATE/BOOTLID NEW PART PAINTING	18.0	
	L/R SIDE PANEL REINF NEW PART PAINTING	8.0	

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01,
#04-02 & #07-03, Sin Ming
Autocity
575722

Claim Reference: TP-GBA 5363R
 Assessment number: 70310
 Version: 1810

Full Report
 Registration: SLA 8564P
 Printed: 31/05/2019 5:58 PM
 Time Basis 10WU/h

Date calculated: 31/05/2019 5:58 PM SYSTEM AZT

Code	Description - TWO COAT PEARL/MICA	WU	Price SGD
	R/R SIDE PANEL REINF NEW PART PAINTING	8.0	
	REAR BUMPER NEW PART PAINT K1R	11.0	
	REAR BOOT FLOOR SURFACE PAINT	9.0	

Paint Material Per Part

Code	Description	Price SGD
2711	REAR PANEL NEW PART PAINTING	23.10
2931	TAILGATE/BOOTLID NEW PART PAINTING	53.15
3583	L/R SIDE PANEL REINF NEW PART PAINTING	1.10
3584	R/R SIDE PANEL REINF NEW PART PAINTING	1.10
2581	REAR BUMPER NEW PART PAINT K1R	48.71
3901	REAR BOOT FLOOR SURFACE PAINT	24.90

Labour Cost - Paint

	Factor	Hrs	WU	Price SGD
	48.00 SGD/h			
	Time Paint		74.0	
	Preparation Main Work Metal	2.10	21.0	100.80
	Preparation Comp. Work Plastic	0.50	5.0	24.00
Total	10 WU/h	10.00	100.0	480.00

Material Cost - Paint

	Price SGD
New Part Painting	78.45
New Part Painting - Plastic K1R	48.71
Surface-/Blend Paint	24.90
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	179.16

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-09-02/23	Price SGD
2581	REAR BUMPER	8XA 807 067 A			450.00
		GRU			
2605	REAR BUMPER SPOILER	8XA 807 421 B			160.00
		9B9			
2640	REAR BUMPER SUPPORT	8X0 807 309			200.00

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01,
#04-02 & #07-03, Sin Ming
Autocity
575722

Claim Reference: TP-GBA 5363R
 Assessment number: 70310
 Version: 1810

Full Report
 Registration: SLA 8564P
 Printed: 31/05/2019 5:58 PM

Date calculated: 31/05/2019 5:58 PM	Part Number	Supplier	Price SGD
2703	REAR NO PLATE REINF KNPL0		14.00
2711	REAR PANEL 8X0 813 301 TB		430.00
2719	REAR PANEL C-MEMBER 8X0 813 309		165.00
2931	TAILGATE/BOOTLID 8X4 827 023 B		750.00
2944	BOOT/TAILGATE SEAL 8X4 827 705		85.00
2952	BOOT/T.GATE MNTG SET 8X0 098 617 A		6.00
2975	BOOT/TAILGATE LOCK 8R0 827 505 A		75.00
3013	L/R BADGE 8X0 853 741 2ZZ		50.00
3019	R/R BADGE 8X0 853 737 A		50.00
3020	REAR BADGE 8X0 853 742 A 2ZZ		50.00
3281	L/R LAMP 8XA 945 093 A		450.00
3282	R/R LAMP 8XA 945 094 A		450.00
3313	L/INN REARLAMP SEAL 8X0 945 191	<i>me</i>	17.00
3314	R/INN REARLAMP SEAL 8X0 945 191	<i>me</i>	17.00
3583	L/R SIDE PANEL REINF 8X0 809 449	<i>me</i>	70.00
3584	R/R SIDE PANEL REINF 8X0 809 450	<i>me</i>	70.00
4661	L/F SEAT BELT 8X3 857 705 E V04	<i>me</i>	400.00
4662	R/F SEAT BELT 8X3 857 706 E V04	<i>me</i>	400.00
4985	END PANEL TRIM 8X0 863 459 C 6PS	<i>me</i>	110.00
9665	CENTRAL FUSING 8X0 915 459		180.00
1006	L/R END PNL VENT RENEW	<i>me</i>	35.00
1007	R/R END PNL VENT RENEW	<i>me</i>	35.00
1010	RR W/S NOZZLE JET RENEW	<i>me</i>	15.00
1011	SRS BATTERY FUSE 4F0915519	<i>me</i>	55.00
f: OEM Parts	Savings		0.00
n: Non-OEM Parts	Subtotal		4,789.00
u: Used parts	Fixed Sundry Parts Price		100.00
	Total		4,889.00

Extras

Code	Description	Price SGD
1000	ANTI RUST CHEMICAL SN	<i>60l</i> 120.00*
1001	CHK/ERASE FAULT CODE SN	120.00*
1002	RECODE SRS MODULE SN	120.00*
1003	RR W/S SEALANT SN	40.00*

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01,
#04-02 & #07-03, Sin Ming
Autocity
575722

Claim Reference: TP-GBA 5363R
 Assessment number: 70310
 Version: 1810

Full Report
 Registration: SLA 8564P
 Printed: 31/05/2019 5:58 PM

Date calculated: 31/05/2019 5:58 PM

		Price SGD
1004	RR W/S SEAL SN	30.00*
1009	TOWING FEE SN	70.00* ?
4661	[E]: L/F SEAT BELT: NO STOCK LOCAL	0.00*
4661	Y. NEED TO ORDER FRO M GERMANY.	0.00*
4662	[E]: R/F SEAT BELT: NO STOCK LOCAL	0.00*
4662	Y. NEED TO ORDER FRO M GERMANY.	0.00*
Total Extras		500.00

Final Calculation

	SGD	SGD
Parts	4,789.00	
Fixed Sundry Parts Price	100.00	
Total Parts		4,889.00
Labour Time Base 10 WU/h		
Total 178.0 WU X 48.00 SGD/h	854.40	
Total of Labour		854.40
Total Of Extras		500.00
Paint Work Time Base 10 WU/h		
Labour Cost 100.0 WU X 48.00 SGD/h	480.00	
Material Cost	179.16	
Total Paint Including Material		659.16
Repair Cost Excludes GST		6,902.56
GST (+7.0%)		483.18
Repair Cost Included GST		7,385.74

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS



24 HOURS TOWING SERVICES

KAOLIN MOTOR TRADING CO

Thomson Road Post Office, P.O. Box 95, Singapore 915704

Tel: 6452 0716, 6458 4013

Registration No. 21645200K

**CASH SALE
JOB ORDER**

Messrs LH M/K

No. 7012019

Date 9/3/19

Vehicle No.	<u>SLA 8564P</u>	Model	<u>AYD1 A1</u>
Destination	<u>B1213 TOA PAYON LOH8 TO W/S</u>		
Time In		Time Out	
Remarks	<u>YL8963J</u>	Amount \$	<u>707</u>

- Change Spare Tyre / Jumpstart
- Basement / Multi Carpark
- Accident
- Using King Dolly (Extra Trailer)
- Lowered Bodykit / Suspension

- Loaded With Goods
- Dismantle Shaft / Brake / Equipment
- Open Door
- Crane up / Winch out

Driver

Received By

bizSAFE

來發(明記)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722
Tel: 64538110 Fax: 64596267 Email: info@laihuat.com.sg
UEN: 199407592C

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

Singapore

Claimant Insurer: United Overseas Insurance Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	70310
Policy No:		Date of Loss:	09/03/2019
Vehicle Reg. No.:	SLA8564P	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	EE LEE KUAN DEBORAH		
Make/Model:	AUDI A1, 999CC SB 1.0 TFSI (PI) (A)	Vehicle Reg. Date:	18/03/2016
Vehicle Colour:	RED		
Engine No:	CHZ061849	Chassis No:	WAUZZZ8X8GB064320
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	TRAFFIC ALONG CTE TOWARDS PIE CHANGI WAS HEAVY. MY CAR SLA 8564P WAS ON BRAKE MODE WHEN A LORRY GBA 5363R SUDDENLY HIT MY CAR. IT WAS ALONG CTE ALONG THE AUSTRALIAN SCHOOL AREA MOVING TOWARDS PIE CHANGI.		
Present Location:	LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING)		

COST OF CLAIMS	Amount
Parts	4,680.00
Miscellaneous Items	430.00
Labour	782.40
Paintwork Labour	580.56
Towing	0.00
Gross Total (S\$)	7,186.96
+ GST 7.00% (S\$)	453.11
Nett Amount (S\$)	6,926.07

This claim is handled by: JENNY LIM LAI FOONG

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Mar 2019)

Parts: 144 AUDI A1 999cc SB 1.0 TFSI (PI) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Lai Huat (Meng Kee) Motor Pte Ltd/SLA8564P/11/03/2019 16:53

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Spare Parts	0.00	0.00	4,680.00 F
Total Parts (S\$)						4,680.00

F=Franchise part.

Lai Huat (Meng Kee) Motor Pte Ltd/SLA8564P/11/03/2019 16:53. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	Miscellaneous Items	440 430.00
Sub Total (S\$)			430.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	Total Paint including Material	New	659.16 580.56
<u>Labour Items</u>			
2	Total of Labour	New	854.40 782.40
Gross Labour Cost (S\$)			1,362.96

Lai Huat (Meng Kee) Motor Pte Ltd/SLA8564P/11/03/2019 16:53. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

來發(明記)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722
Tel: 64538110 Fax: 64596267 Email: info@laihuat.com.sg
UEN: 199407592C

(SUPPLEMENTARY)

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

Singapore

Claimant Insurer: United Overseas Insurance Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	70310
Policy No:	DMCVSN30559818033	Date of Loss:	09/03/2019
Vehicle Reg. No.:	SLA8564P	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	EE LEE KUAN DEBORAH		
Make/Model:	AUDI A1, 999CC SB 1.0 TFSI (PI) (A)	Vehicle Reg. Date:	18/03/2016
Vehicle Colour:	RED		
Engine No:	CHZ061849	Chassis No:	WAUZZZ8X8GB064320
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	TRAFFIC ALONG CTE TOWARDS PIE CHANGI WAS HEAVY. MY CAR SLA 8564P WAS ON BRAKE MODE WHEN A LORRY GBA 5363R SUDDENLY HIT MY CAR. IT WAS ALONG CTE ALONG THE AUSTRALIAN SCHOOL AREA MOVING TOWARDS PIE CHANGI.		
Present Location:	LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING)		

COST OF CLAIMS	Amount
Parts	714.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	714.00
+ GST 7.00% (S\$)	49.98
Nett Amount (S\$)	763.98
+ Previous Estimates (S\$)	6,926.07

Claim Total (S\$)

7,690.05

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 31 May 2019)**Parts:** 144 AUDI A1 999cc SB 1.0 TFSI (PI) (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Lai Huat (Meng Kee) Motor Pte Ltd/SLA8564P/31/05/2019 17:59**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*L/INN REAR LAMP SEAL	0.00	0.00	NEC *17.00 F
2	1		*R/INN REAR LAMP SEAL	0.00	0.00	NEC *17.00 F
3	1		*L/R SIDE PANEL REINF	0.00	0.00	42 *70.00 F
4	1		*R/R SIDE PANEL REINF	0.00	0.00	42 *70.00 F
5	1		*L/F SEAT BELT	0.00	0.00	JM *400.00 F
6	1		*L/R END PANEL VENT	0.00	0.00	170 *35.00 F
7	1		*R/R END PANEL VENT	0.00	0.00	170 *35.00 F
8	1		*RR W/S NOZZLE JET	0.00	0.00	NEC *15.00 F
9	1		*SRS BATTERY FUSE	0.00	0.00	NEC *55.00 F
Total Parts (S\$)						714.00

F=Franchise part.

Lai Huat (Meng Kee) Motor Pte Ltd/SLA8564P/31/05/2019 17:59. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Lai Huat (Meng Kee) Motor Pte Ltd/SLA8564P/31/05/2019 17:59. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: TP-GBA 5363R
Assessment number: 70310
Version: 1810
Date calculated: 14/06/2019 4:16 PM

Full Report
Registration: SLA 8564P
Printed: 14/06/2019 4:16 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:	TP-GBA 5363R	Date of Incident:	09/03/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle			
Manufacturer:	AUDI		
Model:	A1 (8X)		
Sub Model:	DESIGN		
Model Sheet Number:	00 83 51		
Registration:	SLA 8564P		
VIN number:	WAUZZZ8X8GB064320		
Odometer:			
Model Specs			
FROM 11/2015	STOP-START SYSTEM	DR-MIRROR BODY COLOR	WHEELS 7J X 16 ALLOY
AUTO AIR CON	FR SCREEN/SHADE BAND	REAR PARKING SYSTEM	WITHOUT SAFETY DEV
VOICE CONTROL SYSTEM	8 SPEAKER	RADIO MEDIA CENTER	XENON HEADLAMPS
LED TAILLAMP	HEADLAMP WASHERS	RAIN SENSOR	CLOTH TRIM
SPORT SEATS	TRIM PART LEATHER	SPORT S-WHEEL LEATH	HEIGHT ADJ PASS SEAT
MULTI FUNC DISPLAY	REAR BATTERY	LUMBAR SUPPORT	ALTERNATOR 140A
HD COOLING	S-TRONIC	TYRES 215/45 VR 16	TRIM PACK ALUMINIUM
AIR VENTS COLOURED	PHONE SYS BLUETOOTH	1.0 LTR 70KW	5-DOOR
TWO COAT PEARL/MICA			

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: TP-GBA 5363R
 Assessment number: 70310
 Version: 1810
 Date calculated: 14/06/2019 4:16 PM

Full Report
 Registration: SLA 8564P
 Printed: 14/06/2019 4:16 PM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
 Date of Inspection:

Damage Areas

- All
 Underbody



Labour

Code	Description	Time Base 10 WU/h	Price = 48.00 SGD/h	
			WU	Price SGD
55 70 19 00	R + R TAILGATE SEAL		3.0	14.40
55 59 19 00)	R + R TAILGATE (INNER TAILLAMPS REMOVED) INCLUDES: TAILGATE TRIM REMOVE + REFIT. ADJUST TAILGATE.		9.0	43.20
55 59 55 50	RENEW TAILGATE (TAILGATE REMOVED) (2C-MATERIAL) INCLUDES: R + R ALL PARTS		22.0	105.60
94 31 19 01	R + R LEFT INNER TAILLAMP		2.0	9.60
94 31 19 01	R + R RIGHT INNER TAILLAMP		2.0	9.60
63 69 55 54	RENEW REAR BUMPER COVER (COVER REMOVED) INCLUDES: R + R LOWER SPOILER AND SENSORS		4.0	19.20

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: TP-GBA 5363R
 Assessment number: 70310
 Version: 1810
 Date calculated: 14/06/2019 4:16 PM

Full Report
 Registration: SLA 8564P
 Printed: 14/06/2019 4:16 PM

Code	Description	WU	Price SGD
53 16 53 00	REMOVE PARTS REAR END CROSSMEMBER INCLUDES: REMOVE TAILLAMPS, BUMPER (IMPACT CARRIER), BUMPER COVER, LOCK CARRIER COVER, BOOT TRIMS, TAILGATE SEAL AND LOWER LOCK	9.0	43.20
53 16 55 00	RENEW REAR END CROSSMEMBER	25.0	120.00
53 05 55 50	RENEW REAR END PANEL (COMPOSITE WORK) (REAR END CROSSMEMBER REMOVED)	42.0	201.60
53 16 59 00	FIT PARTS REAR END CROSSMEMBER INCLUDES: FIT REMOVED PARTS, RENEW IF NECESSARY DOES NOT INCLUDE: RENEW BUMPER COVER	11.0	52.80
68 05 19 00	R + R L/INNER SILL TRIM	2.0	9.60
70 67 19 10)	R + R LEFT B-PILLAR LOWER TRIM	1.0	4.80
70 67 19 20)	R + R L/UPPER B-PILLAR TRIM	2.0	9.60
68 05 19 00	R + R R/INNER SILL TRIM	2.0	9.60
70 67 19 10)	R + R R/LOWER B-PILLAR TRIM	1.0	4.80
70 67 19 20)	R + R R/UPPER B-PILLAR TRIM	2.0	9.60
70 68 19 70)	R + R R/LOWER C-PILLAR TRIM	2.0	9.60
70 39 19 00	R + R REAR LOCK CARRIER COVER	2.0	9.60
69 11 19 10)	R + R LEFT FRONT THREE POINT SEAT BELT (B-PILLAR TRIM REMOVED)	2.0	9.60
69 11 19 10)	R + R RIGHT FRONT THREE POINT SEAT BELT (B-PILLAR TRIM REMOVED)	2.0	9.60
NN	RR W/S NOZZLE JET R&R / NEW PARTS	1.0*	4.80
NN	SRS BATTERY FUSE R&R / NEW PARTS	10.0*	48.00
3571	L/R REARLAMP SUPP REPAIR	10.0*	48.00
3572	R/R REARLAMP SUPP REPAIR	10.0*	48.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		17.80	178.0
Total of Labour			854.40

Paint

Code	Description - TWO COAT PEARL/MICA	WU	Price SGD
	REAR PANEL NEW PART PAINTING	20.0	
	TAILGATE/BOOTLID NEW PART PAINTING	18.0	
	L/R SIDE PANEL REINF NEW PART PAINTING	8.0	

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: TP-GBA 5363R
 Assessment number: 70310
 Version: 1810
 Date calculated: 14/06/2019 4:16 PM

Full Report
 Registration: SLA 8564P
 Printed: 14/06/2019 4:16 PM

Paint Work		SYSTEM AZT	Time Basis 10WU/h	
Code	Description - TWO COAT PEARL/MICA		WU	Price SGD
	R/R SIDE PANEL REINF NEW PART PAINTING		8.0	
	REAR BUMPER NEW PART PAINT K1R		11.0	
	REAR BOOT FLOOR SURFACE PAINT		9.0	

Paint Material Per Part

Code	Description	Price SGD
2711	REAR PANEL NEW PART PAINTING	23.10
2931	TAILGATE/BOOTLID NEW PART PAINTING	53.15
3583	L/R SIDE PANEL REINF NEW PART PAINTING	1.10
3584	R/R SIDE PANEL REINF NEW PART PAINTING	1.10
2581	REAR BUMPER NEW PART PAINT K1R	48.71
3901	REAR BOOT FLOOR SURFACE PAINT	24.90

Labour Cost - Paint

Factor	48.00 SGD/h	Hrs	WU	Price SGD
Time Paint			74.0	
Preparation Main Work Metal		2.10	21.0	100.80
Preparation Comp. Work Plastic		0.50	5.0	24.00
Total	10 WU/h	10.00	100.0	480.00

Material Cost - Paint

	Price SGD
New Part Painting	78.45
New Part Painting - Plastic K1R	48.71
Surface-/Blend Paint	24.90
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	179.16

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-09-02/23	Price SGD
2581	REAR BUMPER	8XA 807 067 A GRU			450.00
2605	REAR BUMPER SPOILER	8XA 807 421 B 9B9			160.00
2640	REAR BUMPER SUPPORT	8X0 807 309			200.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: TP-GBA 5363R
 Assessment number: 70310
 Version: 1810
 Date calculated: 14/06/2019 4:16 PM

Full Report
 Registration: SLA 8564P
 Printed: 14/06/2019 4:16 PM

Code	Description	Part Number	Supplier	Price SGD
2703	REAR NO PLATE REINF	KNPLO		14.00
2711	REAR PANEL	8X0 813 301 TB		430.00
2719	REAR PANEL C-MEMBER	8X0 813 309		165.00
2931	TAILGATE/BOOTLID	8X4 827 023 B		750.00
2944	BOOT/TAILGATE SEAL	8X4 827 705		85.00
2952	BOOT/T.GATE MNTG SET	8X0 098 617 A		6.00
2975	BOOT/TAILGATE LOCK	8R0 827 505 A		75.00
3013	L/R BADGE	8X0 853 741 2ZZ		50.00
3019	R/R BADGE	8X0 853 737 A 2ZZ		50.00
3020	REAR BADGE	8X0 853 742 A 2ZZ		50.00
3281	L/R LAMP	8XA 945 093 A		450.00
3282	R/R LAMP	8XA 945 094 A		450.00
3313	L/INN REARLAMP SEAL	8X0 945 191		17.00
3314	R/INN REARLAMP SEAL	8X0 945 191		17.00
3583	L/R SIDE PANEL REINF	8X0 809 449		70.00
3584	R/R SIDE PANEL REINF	8X0 809 450		70.00
4661	L/F SEAT BELT	8X3 857 705 E V04		400.00
4662	R/F SEAT BELT	8X3 857 706 E V04		400.00
4985	END PANEL TRIM	8X0 863 459 C 6PS		110.00
9665	CENTRAL FUSING	8X0 915 459		180.00
1006	L/R END PNL VENT	RENEW		35.00
1007	R/R END PNL VENT	RENEW		35.00
1010	RR W/S NOZZLE JET	RENEW		15.00
1011	SRS BATTERY FUSE	4F0915519		55.00

f: OEM Parts
 n: Non-OEM Parts
 u: Used parts

Savings	0.00
Subtotal	4,789.00
Fixed Sundry Parts Price	100.00
Total	4,889.00

Extras

Code	Description	Price SGD
1000	ANTI RUST CHEMICAL SN	60.00*
1001	CHK/ERASE FAULT CODE SN	120.00*
1002	RECODE SRS MODULE SN	120.00*
1003	RR W/S SEALANT SN	40.00*

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: TP-GBA 5363R
 Assessment number: 70310
 Version: 1810
 Date calculated: 14/06/2019 4:16 PM

Full Report
 Registration: SLA 8564P
 Printed: 14/06/2019 4:16 PM

Code	Description	Price SGD
1004	RR W/S SEAL SN	30.00*
1009	TOWING FEE SN	70.00*
4661	[E]; L/F SEAT BELT: NO STOCK LOCAL	0.00*
4661	Y. NEED TO ORDER FRO M GERMANY.	0.00*
4662	[E]; R/F SEAT BELT: NO STOCK LOCAL	0.00*
4662	Y. NEED TO ORDER FRO M GERMANY.	0.00*
Total Extras		440.00

Final Calculation

	SGD	SGD
Parts	4,789.00	
Fixed Sundry Parts Price	100.00	
Total Parts		4,889.00
Labour Time Base 10 WU/h		
Total 178.0 WU X 48.00 SGD/h	854.40	
Total of Labour		854.40
Total Of Extras		440.00
Paint Work Time Base 10 WU/h		
Labour Cost 100.0 WU X 48.00 SGD/h	480.00	
Material Cost	179.16	
Total Paint Including Material		659.16
Repair Cost Excludes GST		6,842.56
GST (+7.0%)		478.98
Repair Cost Included GST		7,321.54

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: TP-PC 4674Z
Assessment number: 70648
Version: 1810
Date calculated: 06/08/2019 9:42 AM

Full Report
Registration: SKZ 3402L
Printed: 06/08/2019 9:43 AM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:	TP-PC 4674Z	Date of Incident:	01/07/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle			
Manufacturer:	TOYOTA		
Model:	COROLLA		
Sub Model:	ALTIS CLASSIC		
Model Sheet Number:	70 EW 20		
Registration:	SKZ 3402L		
VIN number:			
Odometer:			
Model Specs			
FROM 01/2016	AUTO AIR CON	LED HEADLAMP	FOG LAMPS
LED TAILLAMP	REARVIEW CAMERA	1.6 LTR 90KW	CVT AUTO GEARBOX
TYRES 205/55 VR 16	KNEE AIRBAG	TWO COAT METALLIC	PREPARE OFF VEHICLE

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: TP-PC 4674Z
 Assessment number: 70648
 Version: 1810
 Date calculated: 06/08/2019 9:42 AM

Full Report
 Registration: SKZ 3402L
 Printed: 06/08/2019 9:43 AM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
 Date of Inspection:

Damage Areas

All
 Underbody



Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
B290	RENEW END PANEL (REAR BUMPER REMOVED) INCLUDES: BOOT COMPARTMENT FLOOR MAT AND ALL TRIMS IN REPAIR AREA REMOVE AND REFIT NOT INCLUDED: R + R REAR SEAT		44.0	184.80
B360	RENEW BOOTLID INCLUDES: BOOTLID, TRIM BOOTLID, BOTH INN TAILLAMPS, BOTH NUMBER PLATE LAMP, LOCK BOOTLID AND REQUIRED ATTACHED PARTS R + R		11.0	46.20
B420	RENEW REAR BUMPER INCLUDES: BUMPER AND ALL REQUIRED ATTACHED PARTS R + R		6.0	25.20
B410	R + R REAR BUMPER REINFORCEMENT		1.0	4.20

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: TP-PC 4674Z
 Assessment number: 70648
 Version: 1810
 Date calculated: 06/08/2019 9:42 AM

Full Report
 Registration: SKZ 3402L
 Printed: 06/08/2019 9:43 AM

Code	Description	WU	Price SGD
3481	L/R SIDE PANEL REPAIR	10.0*	42.00
3482	R/R SIDE PANEL REPAIR	10.0*	42.00
3571	L/TAILLAMP PANEL REPAIR	10.0*	42.00
3572	R/TAILLAMP PANEL REPAIR	6.0*	25.20
Labour Cost		Hrs	WU
Panel / Mechanical Labour		9.80	98.0
Total of Labour			411.60

Paint

Code	Description - TWO COAT METALLIC	WU	Price SGD
Paint Work		SYSTEM AZT	
		Time Basis 10WU/h	
	REAR PANEL NEW PART PAINTING	24.0	
	BOOTLID NEW PART PAINTING	17.0	
	REAR BUMPER NEW PART PAINT K1R	15.0	
	L/R SIDE PANEL REPAIR PAINTING <50%	16.0	
	R/R SIDE PANEL REPAIR PAINTING <50%	16.0	

Paint Material Per Part

Code	Description	Price SGD
2711	REAR PANEL NEW PART PAINTING	30.80
2931	BOOTLID NEW PART PAINTING	49.54
2581	REAR BUMPER NEW PART PAINT K1R	74.78
3481	L/R SIDE PANEL REPAIR PAINTING <50%	26.81
3482	R/R SIDE PANEL REPAIR PAINTING <50%	26.81

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor			42.00 SGD/h
Time Paint		88.0	
Preparation Main Work Metal	2.50	25.0	105.00
Preparation Comp. Work Plastic	0.50	5.0	21.00
Total	10 WU/h	118.0	495.60

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: TP-PC 4674Z
 Assessment number: 70648
 Version: 1810
 Date calculated: 06/08/2019 9:42 AM

Full Report
Registration: SKZ 3402L
Printed: 06/08/2019 9:43 AM

Material Cost - Paint	Price SGD
New Part Painting	80.34
New Part Painting - Plastic K1R	74.78
Repair Painting	53.62
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	246.34

Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
2581	REAR BUMPER	52159 0Z904		210.00
2640	REAR BUMPER REINF	52023 02190		100.00
2711	REAR PANEL	58307 02380		250.00
2931	BOOTLID	64401 02861		260.00
2981	BOOTLID MOULDING	76801 02D40		125.00
3013	MANUFACTURER BADGE	75441 02300		25.00
3017	BADGE MODEL	75442 02320		25.00
3022	VERSION BADGE	75442 02340		25.00
3289	L/R INNER LAMP	81591 02551		125.00
3290	R/R INNER LAMP	81581 02551		125.00
3362	R/NUMBER PLATE LAMP	81270 0D120		45.00
4985	INNER END PANEL TRIM	58387 02240		90.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			1,405.00
u: Used parts	Fixed Sundry Parts Price			100.00
	Total			1,505.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: TP-PC 4674Z
 Assessment number: 70648
 Version: 1810
 Date calculated: 06/08/2019 9:42 AM

Full Report
Registration: SKZ 3402L
Printed: 06/08/2019 9:43 AM

Final Calculation

	SGD	SGD
Parts	1,405.00	
Fixed Sundry Parts Price	100.00	
Total Parts		1,505.00
Labour Time Base 10 WU/h		
Total 98.0 WU X 42.00 SGD/h	411.60	
Total of Labour		411.60
Paint Work Time Base 10 WU/h		
Labour Cost 118.0 WU X 42.00 SGD/h	495.60	
Material Cost	246.34	
Total Paint Including Material		741.94
Repair Cost Excludes GST		2,658.54
GST (+7.0%)		186.10
Repair Cost Included GST		2,844.64

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Mar 2019 Sendback Est	11 Mar 2019 16:53 S\$6,472.96	12 Mar 2019 14:16 Edit Adj Rpt	S\$6,842.56 Edit Estimates	S\$6,842.56 View Rpt		Pending for Survey Report Cancel Case
Supp #1	31 May 2019 17:45	31 May 2019 17:59 S\$714.00	31 May 2019 17:59			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	-, ID: -								
Main Claimant:	EE LEE KUAN DEBORAH , ID: S1764912D								
Vehicle Reg. No.:	SLA8564P	Date of Loss:	09/03/2019 13:00 - :59 [35 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D201105C02	Policy/Cover Note No.:	DMCVSN30559818033						
Vehicle Reg. No. (Insured):	GBA5363R	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	United Overseas Insurance Ltd (HQ) - Tel: 64909318								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 21/03/2019]								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="text"/>									
			View All	Search Tasks					
			Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLA8564P (SNM19D201105C02)
[GBA5363R]
TP
EE LEE KUAN DEBORAH
Mar 9 2019 1:00PM
[-]
Lai Huat (Meng Kee) Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser
Assessment Reports									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print					
1	09/03/19 17:07	Accident Statement		Load HTM						
2	11/03/19 16:53	Repairer Estimates		Load HTM						
3	31/05/19 17:59	Repairer Estimates Suppl. #1		Load HTM						
Photos/Images									3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print					
1	09/03/19 17:07	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>					
2	09/03/19 17:07	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>					
3	09/03/19 17:07	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>					
4	09/03/19 17:07	Chassis Number <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>					
5	11/03/19 16:52	Rear View Left		Load JPG	<input checked="" type="checkbox"/>					
6	11/03/19 16:52	Rear View Right		Load JPG	<input checked="" type="checkbox"/>					
7	11/03/19 16:52	Rear View		Load JPG	<input checked="" type="checkbox"/>					
8	11/03/19 16:52	Chassis Number		Load JPG	<input checked="" type="checkbox"/>					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	16/08/19 15:02	General View		Load JPG	<input checked="" type="checkbox"/>					
2	16/08/19 15:02	General View		Load JPG	<input checked="" type="checkbox"/>					
3	16/08/19 15:02	General View		Load JPG	<input checked="" type="checkbox"/>					
4	16/08/19 15:02	General View		Load JPG	<input checked="" type="checkbox"/>					
5	16/08/19 15:02	General View		Load JPG	<input checked="" type="checkbox"/>					
6	16/08/19 15:02	General View		Load JPG	<input checked="" type="checkbox"/>					
7	16/08/19 15:02	General View		Load JPG	<input checked="" type="checkbox"/>					
8	16/08/19 15:02	General View		Load JPG	<input checked="" type="checkbox"/>					
9	16/08/19 15:02	General View		Load JPG	<input checked="" type="checkbox"/>					
10	16/08/19 15:02	General View		Load JPG	<input checked="" type="checkbox"/>					
11	16/08/19 15:02	General View		Load JPG	<input checked="" type="checkbox"/>					
12	16/08/19 15:02	General View		Load JPG	<input checked="" type="checkbox"/>					
13	16/08/19 15:02	General View		Load JPG	<input checked="" type="checkbox"/>					
14	16/08/19 15:02	General View		Load JPG	<input checked="" type="checkbox"/>					
15	16/08/19 15:02	General View		Load JPG	<input checked="" type="checkbox"/>					
16	16/08/19 15:02	General View		Load JPG	<input checked="" type="checkbox"/>					
17	16/08/19 15:02	General View		Load JPG	<input checked="" type="checkbox"/>					
18	16/08/19 15:02	General View		Load JPG	<input checked="" type="checkbox"/>					
19	16/08/19 15:02	General View		Load JPG	<input checked="" type="checkbox"/>					
20	16/08/19 15:02	General View		Load JPG	<input checked="" type="checkbox"/>					
21	16/08/19 15:02	General View		Load JPG	<input checked="" type="checkbox"/>					
22	16/08/19 15:02	General View		Load JPG	<input checked="" type="checkbox"/>					

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
23	16/08/19 15:02	General View	Load JPG	<input checked="" type="checkbox"/>
24	16/08/19 15:02	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
25	16/08/19 15:02	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
26	16/08/19 15:02	General View	Load JPG	<input checked="" type="checkbox"/>
27	16/08/19 15:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
28	16/08/19 15:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
29	16/08/19 15:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
30	16/08/19 15:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
31	16/08/19 15:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
32	16/08/19 15:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
33	16/08/19 15:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
34	16/08/19 15:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	09/03/19 17:06	Sketch Plan <small>[Linked Accident Report Documents]</small>	Load TIF	
2	09/03/19 17:06	Driver NRIC and Driving Licence <small>[Linked Accident Report Documents]</small>	Load TIF	
3	11/03/19 16:53	E-filed GIA report	Load PDF	
4	11/03/19 16:53	Driver NRIC & Driving Licence	Load PDF	
5	11/03/19 16:53	Certificate of Insurance	Load PDF	
6	11/03/19 16:53	Enquire PARF / COE Rebate for Registered Vehicle	Load PDF	
7	11/03/19 16:53	LTA Search	Load PDF	
8	11/03/19 16:53	Audatex Report	Load PDF	

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/08/19 10:13	Supplementary	Load PDF	

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	09/03/19 17:07	Accident Statement	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	09/03/19 17:07	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	09/03/19 17:07	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	09/03/19 17:07	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	09/03/19 17:07	Chassis Number	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	09/03/19 17:06	Sketch Plan	Load TIF	
2	09/03/19 17:06	Driver NRIC and Driving Licence	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Repairer Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT19004523/KQD3E2

Date: 21/08/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSN30559818033	
Claimant Vehicle No: SLA8564P	Insured Vehicle No: GBA5363R	
Date of Loss: 09/03/2019	Nature of Claim: TP	Claim No: SNM19D201105C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLA8564P		
Make & Model: AUDI A1, 999cc SB 1.0 TFSI (PI) (A)	Engine No: CHZ061849	
Reg. Date: 18/03/2016 (Man. Year: 2015)	Chassis No: WAUZZZ8X8GB064320	
Colour: Red	Odometer: 32488 km	
Engine Capacity: 999 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R16	Rear Tyre Size:	215/45 R16
Front Left Side:	Hankook 8 mm	Rear Left Side:	Hankook 7 mm
Front Right Side:	Hankook 8 mm	Rear Right Side:	Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,394.00	4,889.00	505.00	9.36
Miscellaneous Items	430.00	440.00	-10.00	-2.33
Labour	782.40	854.40	-72.00	-9.20
Paintwork Labour	580.56	659.16	-78.60	-13.54
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,186.96	6,842.56	344.40	4.79
+ GST 7.00/7.00% (S\$)	503.09	478.98	24.11	4.79
Nett Amount (S\$)	7,690.05	7,321.54	368.51	4.79

INSPECTION

Date of Assignment:	12/03/2019 Present Location:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
Date Inspected:	12/03/2019 Inspected At:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Aug 2019)
Parts: 144	AUDI A1 999cc SB 1.0 TFSI (PI) (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLA8564P)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Spare Parts		4,680.00 F	*4,175.00 F
Supplementary #1						
2	1		*L/INN REAR LAMP SEAL	Necessary	17.00 F	*17.00 F
3	1		*R/INN REAR LAMP SEAL	Necessary	17.00 F	*17.00 F
4	1		*L/R SIDE PANEL REINF	Bent	70.00 F	*70.00 F
5	1		*R/R SIDE PANEL REINF	Bent	70.00 F	*70.00 F
6	1		*L/F SEAT BELT	Jammed	400.00 F	*400.00 F
7	1		*L/R END PANEL VENT	Dented	35.00 F	*35.00 F
8	1		*R/R END PANEL VENT	Dented	35.00 F	*35.00 F
9	1		*RR W/S NOZZLE JET	Necessary	15.00 F	*15.00 F
10	1		*SRS BATTERY FUSE	Necessary	55.00 F	*55.00 F
Total Parts (S\$)					5,394.00	4,889.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	Miscellaneous Items	430.00	440.00
Sub Total (S\$)			430.00	440.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	Total Paint including Material	New	580.56	659.16
Labour Items				
2	Total of Labour	New	782.40	854.40
Gross Labour Cost (S\$)			1,362.96	1,513.56

Report was unsubmitted during this print-out.

< END OF ESTIMATES >