

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 31 May 2019)**Parts:** 144 AUDI A1 999cc SB 1.0 TFSI (PI) (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Lai Huat (Meng Kee) Motor Pte Ltd/SLA8564P/31/05/2019 17:59**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

| No. | Qty | Part No. | Particulars | %Disc | %Depr | Amount |
|--------------------------|-----|----------|-----------------------|-------|-------|---------------------|
| 1 | 1 | | *L/INN REAR LAMP SEAL | 0.00 | 0.00 | <i>REC</i> *17.00 F |
| 2 | 1 | | *R/INN REAR LAMP SEAL | 0.00 | 0.00 | <i>REC</i> *17.00 F |
| 3 | 1 | | *L/R SIDE PANEL REINF | 0.00 | 0.00 | <i>BT</i> *70.00 F |
| 4 | 1 | | *R/R SIDE PANEL REINF | 0.00 | 0.00 | <i>BT</i> *70.00 F |
| 5 | 1 | | *L/F SEAT BELT | 0.00 | 0.00 | <i>JM</i> *400.00 F |
| 6 | 1 | | *L/R END PANEL VENT | 0.00 | 0.00 | <i>DD</i> *35.00 F |
| 7 | 1 | | *R/R END PANEL VENT | 0.00 | 0.00 | <i>DD</i> *35.00 F |
| 8 | 1 | | *RR W/S NOZZLE JET | 0.00 | 0.00 | <i>REC</i> *15.00 F |
| 9 | 1 | | *SRS BATTERY FUSE | 0.00 | 0.00 | <i>REC</i> *55.00 F |
| Total Parts (S\$) | | | | | | 714.00 |

F=Franchise part.

Lai Huat (Meng Kee) Motor Pte Ltd/SLA8564P/31/05/2019 17:59. Not valid without Reference section.
Generated using Merimen e-Claims IEAS