

ASS. REC. BY:

REF:

CS/SM019004526/Ktd3^{m2}

Special Instruction:

Surveyor

Kennedy

ASSIGNMENT (Office)

From (Person):

Amoh paul bong

of

SMO

Date/Time: 12/3/190 2:57pm

Estimated Cost:

Bill to:

OD / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8HD 730K

Insured:

SKD 7147M

at Workshop m/s:

Trans-cab

Tel:

6287 6666

of

No 2 Amk St. 63

Policy No:

DIEMTPV01008608

Claim No:

CM101901297

Sum Insured:

Excess:

Make of Veh:

D.O.A.

10/3/2009

(Client's Record)

CA / REV / REP. / REV 24 HRS

1up

Date/Time:

901am 13/3/19

Person Contacted:

Cerndy

H.O.D. Endorsement:

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

() Estimate

REF: 8MO

ASSIGNMENT

From:

Date:

13/3/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SHD 730K

at Workshop m/s

Trans-cab

of

No. 2 Amk St-63

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

1/2

days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 730K

Yr Regn:

12 / 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius

C.C

1798

Colour

M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

32148

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3FU 803076975

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

10/3/19

D.O.I.

13/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

8494.45 (Red: 20803.31; 97%)

RECEIVED 18 MAR 2019

Date/Time, File Pass to?



: Preli. Report

1) 513 Typist



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

0.5

Resurvey No. of Trip:

-

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

450

10

460

Report Format :

Lump Sum / I.B.I. (\$

494.45

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: GNOH PAU LOONG

Date: 15 Mar 2019

Preliminary Advice

Insured Vehicle No	: SKD7147M	Accident Date	: 10/03/2019
TP Vehicle No	: SHD730K	Assignment Date	: 12/03/2019
Make	: TOYOTA PRIUS	Est. Duration of Repair	: 0.50
Date of Inspection	: 13/03/2019		
Inspection At	: TRANS-CAB AUTO SERVICES PTE LTD NO 2 ANG MO KIO STREET 63 SINGAPORE 569111		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	21,298.26
Revised Amount	:S\$	494.45
Check Items (Estimated)	:S\$	0.00
Total	:S\$	494.45

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Survey on "WP"

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Mar 2019		12 Mar 2019 14:57 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	KOH WEE KIANG, ID: S7810068J		
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHD730K	Date of Loss:	10/03/2019 12:00 - :59
Claim Type:	TP / CMTD1901297	Policy/Cover Note No.:	D18MTPV01008608 (Comprehensive)
Vehicle Reg. No. (Insured):	SKD7147M	Policy No. (Claimant):	
		Excess:	
Repairer:	Trans-cab Auto Services Pte Ltd () No 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/03/2019]		
Adj Asg. Remarks:	-PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHD730K
Vehicle to be Exported:	Yes
Intended Deregistration Date:	11 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2ZR2B76845
Chassis No.:	JTDKB3FU903076975
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	22 Nov 2018
First Registration Date:	22 Nov 2018
Transfer Count:	0
Actual ARF Paid:	\$14,247.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Nov 2026
PARF Rebate Amount:	\$10,685.00

Intended COE Rebate Details

COE Expiry Date:	21 Nov 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$23,736.00
COE Rebate Amount:	\$18,988.00
Total Rebate Amount:	\$29,673.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 11 Mar 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/03/2019 09:45
Date Of Accident	10/03/2019 12:45
Exact Location Of Accident	THOMSOM ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD730K
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS-1.8 HYBRID CVT (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	LEE CHYE HUAT
NRIC No	S1715187H
Date Of Birth	06/06/1965
Occupation	OUTDOOR
Date Of Driving Pass	12/06/1985
Driving Experience	33 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97551395
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 274D PUNGGOL PLACE #04-842
Postcode	824274
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 10.03.2019 at about 1245hours, I was travelling straight on the extreme left lane along Thomson Road, suddenly I felt an impact. Vehicle B (SKD7147M) hit onto my taxi rear portion.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKD7147M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KOH WEE KIANG
NRIC/Passport Number	S7810068J
Contact Number	90666106
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

P/S see attach AIA Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHD 730K**AAD1903-063***Not Authorised**Resunny Bkpaint**8494.45*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

SHD 730K

JTDKB3FU903076975

TOYOTA

PRIUS

10.3.2019

SOMPO

22/11/2018

PART**LIST**

1	1 REAR BUMPER	\$	<i>R</i>	458.60	X
2	1 REAR BUMPER RE-INFORCEMENT	\$	<i>R</i>	318.80	X
3	1 REAR BUMPER TOWING COVER	\$	<i>Sm</i>	14.70	X
4	1 REAR BUMPER UNDER COVER (BLACK)	\$	<i>nd/w</i>	552.60	✓
5	1 REAR BUMPER SIDE RETAINER LH	\$	<i>Sm</i>	112.70	} X
6	1 REAR BUMPER SIDE RETAINER RH	\$	<i>Sm</i>	112.70	
7	1 REAR TAILGATE	\$	<i>R</i>	1,547.27	
8	1 REAR TAILGATE OUTER GARNISH	\$	<i>Sm</i>	905.10	
9	1 COVER, REAR COMBINATION LAMP, RH	\$	<i>Sm</i>	54.70	
10	1 COVER, REAR COMBINATION LAMP, RH	\$	<i>Sm</i>	54.70	
11	1 GARNISH, BACK DOOR SIDE, LH	\$	<i>Sm</i>	93.60	
12	1 GARNISH, BACK DOOR SIDE, RH	\$	<i>Sm</i>	93.60	
13	1 BOARD ASSY, BACK DOOR TRIM	\$	<i>Sm</i>	254.40	
14	1 PANEL ASSY, BACK DOOR TRIM, UPPER	\$	<i>Sm</i>	51.20	
15	1 REAR TAILGATE WEATHERSTRIP	\$	<i>Sm</i>	365.20	
16	1 REAR END PANEL	\$	<i>R</i>	602.10	
17	1 TAILLAMP LOWER RH	\$	<i>Sm</i>	548.40	
18	1 TAILLAMP UPPER RH	\$	<i>Sm</i>	557.90	
19	1 REAR BUMPER SIDE RH	\$	<i>Sm</i>	232.00	
20	1 REAR BUMPER SIDE LH	\$	<i>Sm</i>	232.00	
21	1 TAILLAMP LOWER LH	\$	<i>Sm</i>	548.40	
22	1 TAILLAMP UPPER LH	\$	<i>Sm</i>	557.90	
		\$		8,268.57	
		25% \$		2,067.14	
		\$		6,201.43	

Specical Nett

1 1SET PARKING AID

\$ *Sm* 700.00 X

Trans-cab Auto Services Pte Ltd**AAD1903-063**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 730K

2 1SET REAR BUMPER CLIP	\$	na	22.00	}
3 2 REAR WINDSCREEN SELANT	\$	na	80.00	
4 1 WINDSCREEN MOULDING	\$	na	100.00	
5 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
6 1 REAR TAILGATE TOYOTA LOGO	\$	na	47.00	
7 1 REAR TAILGATE WORDING 'PRIUS'	\$	na	52.90	
8 1 REAR TAILGATE WORDING 'HYBRID'	\$	na	53.50	
9 1 REAR TAILGATE STICKER 'TRANS-CAB'	\$	na	80.00	
10 1 REAR TAILGATE STICKER '6555-3333'	\$	na	80.00	
11 1 REAR BUMPER PROTECTOR	\$	na	100.00	X

TOTAL \$ 1,315.40**TOTAL PARTS \$ 7,516.83****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	na	3,000.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		3,000.00	801
To Rust-Proofing Of The Affected Areas.	\$	na	170.00	X
To reinstall rear bumper parking sensor.	\$	na	170.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	na	170.00	X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	na	170.00	X
To repair and realign rear exhaust pipe.	\$	na	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na	170.00	X

Trans-cab Auto Services Pte Ltd**AAD1903-063**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 730K

To transfer of rear end panel fittings, attachment and
perform water seepage test.

\$ *nn* 170.00 *X*

To transfer of rear windscreen fittings and conduct
water seepage test.

\$ *nn* 170.00 *Y*

To check steering geometry and computer wheel
alignment

\$ *nn* 220.00 *X***TOTAL \$ 7,580.00****Over All Total \$ -21,298.26**

15196.83

(PART-BY-PART) Repair Days**10 DAYS***1/2 day*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Repair must be re-surveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19004526/KTD3N2

Date: 18/03/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01008608
Claimant Vehicle No :	SHD730K	Insured Vehicle No :	SKD7147M
Date of Loss:	10/03/2019	Nature of Claim:	TP
		Claim No:	CMTD1901297

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD730K	Engine No:	2ZR2B76845
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU903076975
Reg. Date:	22/11/2018 (Man. Year: 2018)	Odometer:	32148 km
Colour:	Metallic White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,616.83	414.45	7,202.38	94.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,580.00	80.00	7,500.00	98.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	15,196.83	494.45	14,702.38	96.75
+ GST 7.00/7.00% (\$\$)	1,063.78	34.61	1,029.17	96.75
Nett Amount (\$\$)	16,260.61	529.06	15,731.55	96.75

INSPECTION

Date of Assignment:	12/03/2019	
Date Inspected:	13/03/2019	Inspected At:
		Trans-cab Auto Services Pte Ltd
		No 2 Ang Mo Kio Street 63
		Singapore 569111
Estimated Period of Repair:	0.5 days	

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 Mar 2019)
Parts: 144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHD730K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	458.60 FL	*- FL
2	1		*REAR BUMPER RE-INFORCEMENT	Repair	318.80 FL	*- FL
3	1		*REAR BUMPER TOWING COVER	Serviceable	14.70 FL	*- FL
4	1		*REAR BUMPER UNDER COVER (BLACK)	Dented/Cut	552.60 FL	*552.60 FL
5	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	112.70 FL	*- FL
6	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	112.70 FL	*- FL
7	1		*REAR TAILGATE	Repair	1,547.27 FL	*- FL
8	1		*REAR TAILGATE OUTER GARNISH	Serviceable	905.10 FL	*- FL
9	1		*COVER,REAR COMBINATION LAMP,RH	Serviceable	54.70 FL	*- FL
10	1		*COVER,REAR COMBINATION LAMP,RH	Serviceable	54.70 FL	*- FL
11	1		*GARNISH,BACK DOOR SIDE,LH	Serviceable	93.60 FL	*- FL
12	1		*GARNISH,BACK DOOR SIDE,RH	Serviceable	93.60 FL	*- FL
13	1		*BOARD ASSY,BACK DOOR TRIM	Serviceable	254.40 FL	*- FL
14	1		*PANEL ASSY,BACK DOOR TRIM,UPPER	Serviceable	51.20 FL	*- FL
15	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	365.20 FL	*- FL
16	1		*REAR END PANEL	Repair	602.10 FL	*- FL
17	1		*TAILLAMP LOWER RH	Serviceable	548.40 FL	*- FL
18	1		*TAILLAMP UPPER RH	Serviceable	557.90 FL	*- FL
19	1		*REAR BUMPER SIDE RH	Serviceable	232.00 FL	*- FL
20	1		*REAR BUMPER SIDE LH	Serviceable	232.00 FL	*- FL
21	1		*TAILLAMP LOWER LH	Serviceable	548.40 FL	*- FL
22	1		*TAILLAMP UPPER LH	Serviceable	557.90 FL	*- FL
23	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
24	1		*SET REAR BUMPER CLIP	Not Necessary	22.00 FS	*- FS
25	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
26	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
27	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
28	1		*REAR TAILGATE TOYOTA LOGO	Not Necessary	47.00 FS	*- FS
29	1		*REAR TAILGATE WORDING PRIUS	Not Necessary	52.90 FS	*- FS
30	1		*REAR TAILGATE WORDING HYBRID	Not Necessary	53.50 FS	*- FS
31	1		*REAR TAILGATE STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
32	1		*REAR TAILGATE STICKER 6555-3333	Not Necessary	80.00 FS	*- FS
33	1		*REAR BUMPER PROTECTOR	Serviceable	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,683.97	552.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,067.14	138.15
Total Parts (\$\$)	7,616.83	414.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	0.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	3,000.00	80.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
5	TO TRANSFER OF TAILGATE FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
6	TO TRANSFER OF REAR BUMPER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
7	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
8	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
9	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
10	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
11	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
Gross Labour Cost (S\$)			7,580.00	80.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >