

ASS. REC. BY:

REF:

CS/FCI 19004527/Ktd3n2

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

AWS

George Jar

of

FCI

Date/Time:

7:49pm 12/3/19

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 58314

Insured:

SHA 15694

at Workshop n/s

Tune-Cab

Tel:

62876666

of

No 2 mk st-63

Policy No:

Claim No:

D19001726MP84

Sum Insured:

Excess:

Make of Veh.
(Client's Record)

D.O.A.

10/03/2019

CA / REV / REP. / REV 24 HRS

'DS'

H.O.D. Enforcement:

Date/Time:

9:04am 12/3/19

Person Contacted:

Candy

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHD 58314 - CC3/EOI 18021414 / Kjb3

DUA: 23/11/2018

SHA 15694 - CC3/TM 17003079 / Hlvbn2

DUA: 12/2/17

12/3-

Revised w/a preli advise.

REF: FCF

ASSIGNMENT

From:

Date:

13/03/2019

Veh No:

S140 58314 Yr Regn: 11 18

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

8HD 58314

Make:

Toy Prit

c.c.

1788

at Workshop m/s

Trans-cab

Colour

M.P. White / Red

A/C: Insured / Std / NI / NA

of

No. 2 Amie St. 63

Sp. Reading

38546

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

7

Policy No.

C/No:

J70KB 31-460 305072

Claims No.

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: ☒ In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: ☒ In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)


Tyre Size:

F:

195/85R15

R:

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

Front

Rear

IDAC Accident Report:

Consistent? : Yes or No

R/Bal.

mm

R/Bal.

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

mm

L/Bal.

mm

Est. Repairs:

1 1/2 days

Res.: Yes or No

D.O.A.

10/3/19

D.O.I.

14/3/19

Lum Sum:

1-B.1 %

3 Val.: Yes or No

Survey held at

CA / REV / REP. / 24 HRS 'DS'

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

8 756.45 (Red: 20541.31, 96%)

RECEIVED 18 MAR 2019.

Date/Time, File Pass to?



Preli. Report

Days Of Repair: 1.5

1) 8/3 Typist



Final Report

Resurvey No. of Trip: -

Date/Time, File Return to?

2)

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Report Format: TP

Lump Sum / I/B: (\$ 756.45)

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

350



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19001726MFSH

Date: 18/3/2019

Our Ref: CS/FCI19004527/Ktd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 5831U

Please be informed that we had conducted the inspection of the abovementioned vehicle
14/3/2019 at the premises of M/s Trans-Cab have the following to report: -

Workshop Estimate Amount	: S\$ <u>21,298.26</u>
Revised Estimate Amount	: S\$ <u>756.45</u>
"Check" Items Amount	: S\$ <u>0.00</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the
Rear n/s portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Kenneth

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	12-03-2019	Our Ref No. D19001726MFSH
Accident Date	10-03-2019	Claim Type. Third Party
Insured Vehicle	SHA1569U	Third Party Vehicle. SHD5831U
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	CANDY KONG	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE: EST. COR \$21,298.26 (QUANTUM TO BE AGREED)	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Monday, 18 March 2019 11:09 AM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'Serene Ler'; SUR
Subject: RE: SURVEY ASSESSMENT - D19001726MFSH/1
Attachments: PRELI ADVISED SHD 5831U.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHD 5831U**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 13 March 2019 8:29 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <Sereneler@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001726MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 12 March 2019 7:49 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Sereneler@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19001726MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

[Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHD5831U
Vehicle to be Exported:	Yes
Intended Deregistration Date:	11 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2ZR2B59850
Chassis No.:	JTDKB3FU603075072
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	01 Nov 2018
First Registration Date:	01 Nov 2018
Transfer Count:	0
Actual ARF Paid:	\$14,247.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Oct 2026
PARF Rebate Amount:	\$10,685.00

Intended COE Rebate Details

COE Expiry Date:	31 Oct 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$23,736.00
COE Rebate Amount:	\$18,988.00
Total Rebate Amount:	\$29,673.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 11 Mar 2019

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5831U

AAD1903-C

*Not Notified**Running B4 paint**Direct Settle**8756.45*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 5831U

JTDKB3FU603075072

TOYOTA

PRIUS

10.3.2019

FCIL

1/11/2018

PART**LIST**

1	1 REAR BUMPER	\$	<i>M</i>	458.60	X
2	1 REAR BUMPER RE-INFORCEMENT	\$	<i>M</i>	318.80	X
3	1 REAR BUMPER TOWING COVER	\$	<i>Sm</i>	14.70	X
4	1 REAR BUMPER UNDER COVER (BLACK)	\$	<i>Red/Sm</i>	552.60	
5	1 REAR BUMPER SIDE RETAINER LH	\$	<i>Sm</i>	112.70	} X
6	1 REAR BUMPER SIDE RETAINER RH	\$	<i>Sm</i>	112.70	
7	1 REAR TAILGATE	\$	<i>M</i>	1,547.27	
8	1 REAR TAILGATE OUTER GARNISH	\$	<i>Sm</i>	905.10	
9	1 COVER, REAR COMBINATION LAMP, RH	\$	<i>Sm</i>	54.70	
10	1 COVER, REAR COMBINATION LAMP, RH	\$	<i>Sm</i>	54.70	
11	1 GARNISH, BACK DOOR SIDE, LH	\$	<i>Sm</i>	93.60	
12	1 GARNISH, BACK DOOR SIDE, RH	\$	<i>Sm</i>	93.60	
13	1 BOARD ASSY, BACK DOOR TRIM	\$	<i>Sm</i>	254.40	
14	1 PANEL ASSY, BACK DOOR TRIM, UPPER	\$	<i>Sm</i>	51.20	
15	1 REAR TAILGATE WEATHERSTRIP	\$	<i>Sm</i>	365.20	
16	1 REAR END PANEL	\$	<i>M</i>	602.10	
17	1 TAILLAMP LOWER RH	\$	<i>Sm</i>	548.40	
18	1 TAILLAMP UPPER RH	\$	<i>Sm</i>	557.90	
19	1 REAR BUMPER SIDE RH	\$	<i>Sm</i>	232.00	
20	1 REAR BUMPER SIDE LH	\$	<i>Sm</i>	232.00	
21	1 TAILLAMP LOWER LH	\$	<i>Sm</i>	548.40	
22	1 TAILLAMP UPPER LH	\$	<i>Sm</i>	557.90	
		\$		8,268.57	
		25% \$		2,067.14	
		\$		6,201.43	

Special Nett

1 1SET PARKING AID

\$ *Sm* 700.00 X

Trans-cab Auto Services Pte Ltd

AAD1903-066

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5831U

2 1SET REAR BUMPER CLIP	\$	na	22.00	✓
3 2 REAR WINDSCREEN SELANT	\$	na	80.00	} X
4 1 WINDSCREEN MOULDING	\$	na	100.00	
5 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
6 1 REAR TAILGATE TOYOTA LOGO	\$	na	47.00	
7 1 REAR TAILGATE WORDING 'PRIUS'	\$	na	52.90	
8 1 REAR TAILGATE WORDING 'HYBRID'	\$	na	53.50	
9 1 REAR TAILGATE STICKER 'TRANS-CAB'	\$	na	80.00	}
10 1 REAR TAILGATE STICKER '6555-3333'	\$	na	80.00	
11 1 REAR BUMPER PROTECTOR	\$	na	100.00	

TOTAL \$ 1,315.40**TOTAL PARTS \$ 7,516.83****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	2201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	1001
To Rust-Proofing Of The Affected Areas.	\$	170.00	X
To reinstall rear bumper parking sensor.	\$	na 170.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	na 170.00	X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	na 170.00	X
To repair and realign rear exhaust pipe.	\$	na 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na 170.00	X

Trans-cab Auto Services Pte Ltd**AAD1903-066**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5831U

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ *nn* 170.00 X

To transfer of rear windscreen fittings and conduct water seepage test.

\$ *nn* 170.00 X

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 X**TOTAL \$ 7,580.00****Over All Total \$ 21,298.26****(PART-BY-PART) Repair Days**~~10 DAYS~~*1 1/2 days**15196.83*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19004527/Ktd3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 18-03-2019



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 1569U	Veh. Inspected	SHD 5831U
Policy No.		Coverage (\$)	0.00
Claim No.	D19001726MFSH	Excess (\$)	0.00
Assign From	SERENE	Assign Date	12/03/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS (A)	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JTDKB3FU603075072	Colour	M.PEARL WHITE / RED
Odometer	38546	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	8 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	8 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	9 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	10/03/2019	Inspection Date	14/03/2019
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	1.500 Working Days
-------------------------------------	---------------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 5831U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	TO REPAIR SEE LABOUR	458.60	-
1	REAR BUMPER RE-INFORCEMENT	TO REPAIR SEE LABOUR	318.80	-
1	REAR BUMPER TOWING COVER	SERVICEABLE	14.70	-
1	REAR BUMPER UNDER COVER (BLACK)	DENTED / CUT	552.60	552.60
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	112.70	-
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	112.70	-
1	REAR TAILGATE	TO REPAIR SEE LABOUR	1,547.27	-
1	REAR TAILGATE OUTER GARNISH	SERVICEABLE	905.10	-
1	COVER,REAR COMBINATION LAMP,RH	SERVICEABLE	54.70	-
1	COVER,REAR COMBINATION LAMP,RH	SERVICEABLE	54.70	-
1	GARNISH,BACK DOOR SIDE,LH	SERVICEABLE	93.60	-
1	GARNISH,BACK DOOR SIDE,RH	SERVICEABLE	93.60	-
1	BOARD ASSY,BACK DOOR TRIM	SERVICEABLE	254.40	-
1	PANEL ASSY,BACK DOOR TRIM,UPPER	SERVICEABLE	51.20	-
1	REAR TAILGATE WEATHERSTRIP	SERVICEABLE	365.20	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	602.10	-
1	TAILLAMP LOWER RH	SERVICEABLE	548.40	-
1	TAILLAMP UPPER RH	SERVICEABLE	557.90	-
1	REAR BUMPER SIDE RH	SERVICEABLE	232.00	-
1	REAR BUMPER SIDE LH	SERVICEABLE	232.00	-
1	TAILLAMP LOWER LH	SERVICEABLE	548.40	-
1	TAILLAMP UPPER LH	SERVICEABLE	557.90	-
	LESS 25% DISCOUNT		-2,067.14	-138.15
			6,201.43	414.45
<u>SPECIAL NETT ITEMS</u>				
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	22.00	22.00
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-

Report Ref No. CS/FCI19004527/Ktd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	REAR TAILGATE TOYOTA LOGO (SN)	NOT NECESSARY	47.00	-
1	REAR TAILGATE WORDING "PRIUS" (SN)	NOT NECESSARY	52.90	-
1	REAR TAILGATE WORDING "HYBRID" (SN)	NOT NECESSARY	53.50	-
1	REAR TAILGATE STICKER "TRANS-CAB" (SN)	NOT NECESSARY	80.00	-
1	REAR TAILGATE STICKER "6555-3333" (SN)	NOT NECESSARY	80.00	-
1	REAR BUMPER PROTECTOR (SN)	NOT NECESSARY	100.00	-
			1,415.40	22.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	220.00
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF REAR BUMPER,REAR BUMPER RE-INFORCEMENT,REAR TAILGATE AND REAR END PANEL.		3,000.00	100.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR.	NOT NECESSARY	170.00	-
	TO TRANSFER OF TAILGATE FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR BUMPER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
			7,580.00	320.00
	GRAND TOTAL		15,196.83	756.45

Report Ref No. CS/FCI19004527/Ktd3n2



RECOMMENDED COST OF REPAIRS			756.45
-----------------------------	--	--	--------

Report Ref No. CS/FCI19004527/Ktd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.