

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST 63 SINGAPORE 569111
 TEL NO.6287 6666 FAX NO.6257 1330
 CO/GST REG NO.201019626G
SHD 9920U - AXA

Not Authorised
1-B.1

RIZA

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHD 9920U - RIZA
 VF1ABL15AUC277504
 RENAULT
 LATITUDE
 06.02.16
AXA

PART			LIST	
1	1	BUMPER COVER FRT	\$	<i>R</i> 968.78 X
2	1	BUMPER RETAINER FRT LH	\$	<i>Sn</i> 116.47 X
3	1	BUMPER BRACKET FRT LH	\$	<i>R</i> 139.81 X
4	1	HEADLAMP LH	\$	<i>Sn</i> 911.10 X
5	1	AIR CLEANER LOWER	\$	<i>Sn</i> 271.26 X
6	1	AIR CLEANER HOSE	\$	<i>Sn</i> 58.57 X
7	1	LOWER ARM LH	\$	527.51 ?
8	1	KUNCKLE ARM LH	\$	651.53 ?
9	1	ABSORBER FRT LH	\$	277.34 ?
10	1	FENDER PANEL FRT LH	\$	<i>R</i> 602.95 ✓
11	1	FENDER WHEELARCH FRT LH (Linner)	\$	<i>Sn</i> 107.33 X
12	1	DOOR FRT LH	\$	<i>R</i> 2,188.20 X
13	1	DOOR HANDLE OUTER FRT LH	\$	<i>Sn</i> 198.55 X
14	1	DOOR HANDLE COVER FRT LH	\$	<i>Sn</i> 10.17 X
15	1	DOOR MIRROR LH	\$	<i>Sn</i> 1,141.08 X
16	1	DOOR SEAL FRT LH	\$	<i>Sn</i> 52.83 X
17	1	ROCKER PANEL OUTER LH	\$	<i>R</i> 759.61 X
18	1	DOOR REAR LH	\$	<i>B</i> 2,188.20 ✓
19	1	DOOR HANDLE OUTER REAR LH	\$	<i>Sn</i> 97.31 X
20	1	FENDER PANEL REAR LH	\$	<i>R</i> 2,537.80 X
21	1	FENDER WHEELARCH REAR LH (Linner)	\$	<i>Sn</i> 418.06 X
22	1	BUMPER COVER REAR	\$	<i>R</i> 852.66 X
23	1	BUMPER BRACKET SIDE LH REAR(Taillamp loc)	\$	<i>Sn</i> 104.59 X
24	1	BUMPER RETAINER LH REAR	\$	<i>Sn</i> 34.61 X

TOTAL	\$	15,216.32
10%	\$	1,521.63
	\$	13,694.68

Special Nett

1	1SET	FRONT BUMPER CLIP	\$	<i>na</i> 66.00 X
2	1SET	WHEELARCH CLIP FRT LH	\$	<i>na</i> 66.00 X
3	1	CAP HUB LH RR	\$	<i>M</i> 35.00 ✓
4	1	RIM LH RR	\$	<i>Sn</i> 385.00 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 9920U - AXA**RIZA**

5	1	TYRE LH RR	\$	sn 330.00 X
6	1	DOOR CASING FRT CLIP LH (door inner trim)	\$	nn 45.00 X
7	1	DOOR STICKER "Trans-cab"	\$	nn 80.00 60sn
8	1	DOOR STICKER "Classic"	\$	nn 30.00 15sn
9	1	DOOR STICKER "6555-3333"	\$	nn 80.00 60sn
10	2	Rear Windscreen Sealant	\$	nn 100.00 40sn
11	1	Rear Windscreen Inner Sponge Seal	\$	nn 150.00 30sn
12	1	CAP HUB LH RR	\$	nn 35.00 —
13	1	RIM LH RR (spare change)	\$	sn 385.00 X
14	1	TYRE LH RR (spare change)	\$	sn 330.00 X
15	1SET	WHEELARCH CLIP RR LH	\$	nn 66.00 X
16	1SET	REAR BUMPER CLIP	\$	nn 66.00 X
17	1SET	BUMPER RETAINER LH CLIP RR	\$	nn 20.00 X
18	1	FENDER ADVERTISEMENT STICKER FRT LH	\$	nn 250.00 150sn
19	1	DOOR ADVERTISEMENT STICKER FRT LH	\$	nn 250.00 150sn
20	1	DOOR ADVERTISEMENT STICKER RR LH	\$	nn 250.00 150sn
21	1	FENDER ADVERTISEMENT STICKER RR LH	\$	nn 250.00 150sn
22	1	BUMPER ADVERTISEMENT STICKER RR	\$	nn 150.00 100sn

TOTAL	\$	3,419.00
TOTAL PARTS	\$	17,113.68

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 5,400.00

To Check Electrical Lighting Concerned.

\$ 170.00 401

Putty and spray painting of the affected portion.

\$ 6,000.00 13201

To dismantle and refit front end suspension, undercarriage parts, final checking and testing.

\$ 380.00 ?

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ 380.00 X

To check steering geometry and computer wheel alignment

\$ 220.00 601

To transfer of tire, rim and on wheel balancing.

\$ 170.00 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 9920U - AXA**RIZA**

To remove and replace corporate sticker	\$	330.00 1200
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00 1000
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00 1200
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00 X
To rust-proofing of the affected areas.	\$	170.00 600

TOTAL	\$	13,730.00
Over All Total	\$	30,843.68

(PARTS BY PARTS) Repair Days**20 Days**
7 days**LKK Auto Consultants** hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: