

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

|                   |   |                    |
|-------------------|---|--------------------|
| <b>Estimate</b>   | : | Accident Repairs   |
| <b>Workshop</b>   | : | Ubi Road 1         |
| <b>Contact No</b> | : | 6366 2323          |
| <b>Fax No</b>     | : | 6841 1183          |
| <b>Reference</b>  | : | PA/OD/0314/2019/KK |
| <b>Date</b>       | : | 9-Mar-19           |

**Vehicle not in workshop. Kindly arrange for survey.**

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

|                          |   |                            |
|--------------------------|---|----------------------------|
| <b>Owner's Name</b>      | : | Mr. Fong Yu Jun            |
| <b>Address</b>           | : | 675 Choa Chu Kang Crescent |
|                          | : | #08-443                    |
|                          | : | Singapore 680675           |
| <b>Telephone</b>         | : | HP +65 92972834            |
| <b>Type of Claim</b>     | : | Own Damage Claims          |
| <b>Policy No.</b>        | : | 1800104565                 |
| <b>Vehicle No</b>        | : | <b>SMD 7509 D</b>          |
| <b>Model Code</b>        | : | Q2 1.0 TFSI S TRONIC       |
| <b>Model / Year</b>      | : | 31/8/2018                  |
| <b>Engine No</b>         | : | CHZ 461193                 |
| <b>Chassis No</b>        | : | WAUZZZGA6JA089386          |
| <b>Mileage</b>           | : |                            |
| <b>Date In</b>           | : |                            |
| <b>Liability</b>         | : | -                          |
| <b>Excess Cost</b>       | : | -                          |
| <b>Estimated By</b>      | : | Johnny Boo / Allan Wu      |
| <b>Accident Date</b>     | : | 1-Mar-19                   |
| <b>Place of Accident</b> | : | Along Choa Chu Kang Way    |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SMD 7509 D

| S/n                  | Nature of Jobs                                                                                                                                                                              | Estimated Charges            | Surveyor's Recommendation |
|----------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------|---------------------------|
| 1                    | To remove, check and reinstall front wire harness for healights, horns, outside temperature sensor and headlight washer assy.                                                               | S/N \$ 360.00 ✓              |                           |
| 2                    | To dismantle and renew front bumper, bonnet, rhs front fender and rhs headlight. To inspect front lock carrier. Re-organise front crash management components. Reinstall all parts removed. | \$ <del>3,150.00</del> 250 . |                           |
| 3                    | To respray front bumper, rhs front fender, hinges and bonnet. ✓ X                                                                                                                           | \$ <del>2,500.00</del> 1100  |                           |
| 4                    | To carry out diagnostic check.                                                                                                                                                              | S/N \$ 192.00 ✓              |                           |
| TOTAL LABOUR CHARGES |                                                                                                                                                                                             | : \$ <u>6,202.00</u>         |                           |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SMD 7509 D

| S/N                                  | Parts Description                        | Damaged Parts & Prices |        |
|--------------------------------------|------------------------------------------|------------------------|--------|
|                                      |                                          | S/Nett                 | Remark |
| 1                                    | FRONT BUMPER <i>deland</i>               | \$ 1,706.00            | ✓      |
| 2                                    | FRONT BUMPER FIXING PARTS <i>new</i>     | \$ 314.00              | ✗      |
| 3                                    | ANTHRACITE GRILLE - CENTER <i>new</i>    | \$ 179.00              | ✗      |
| 4                                    | AIR GUIDE GRILLE - RH <i>new</i>         | \$ 154.00              | ✓      |
| 5                                    | FRONT BUMPER END CAP - RH ?              | \$ 31.00               | ?      |
| 6                                    | FRONT BUMPER SPOILER <i>deland</i>       | \$ 273.00              | ✓      |
| 7                                    | FRONT BUMPER CLOSING ELEMENT <i>new</i>  | \$ 142.00              | ✗      |
| 8                                    | WHEEL SPOILER - RH <i>new</i>            | \$ 31.00               | ✗      |
| 9                                    | ADAPTER - RH <i>new</i>                  | \$ 38.00               | ✗      |
| 10                                   | RADIATOR GRILLE <i>new</i>               | \$ 1,301.00            | ✓      |
| 11                                   | STRIKER PLATE <i>new</i>                 | \$ 114.00              | ✗      |
| 12                                   | FRONT BUMPER CARRIER ?                   | \$ 625.00              | ?      |
| 13                                   | FOAM FILLER PIECE ?                      | \$ 71.00               | ?      |
| 14                                   | BUMPER COVER ?                           | \$ 91.00               | ?      |
| 15                                   | GUIDE SECTION - RH <i>new</i>            | \$ 32.00               | ✗      |
| 16                                   | FRONT FENDER - RH <i>new</i>             | \$ 1,047.00            | ✗      |
| 17                                   | FRONT FENDER ATTACHMENT PARTS <i>new</i> | \$ 36.00               | ✗      |
| 18                                   | BRACKET - RH ?                           | \$ 43.00               | ✗      |
| 19                                   | BRACE - RH <i>new</i>                    | \$ 29.00               | ✗      |
| 20                                   | BRACKET <i>new</i>                       | \$ 21.00               | ✗      |
| <b>SUB-TOTAL SPARE PARTS CHARGES</b> |                                          | <b>\$ 6,278.00</b>     |        |

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SMD 7509 D

| S/N                       | Parts Description                    | Damaged Parts & Prices |              |
|---------------------------|--------------------------------------|------------------------|--------------|
|                           |                                      | S/Nett                 | Remark       |
| 21                        | WHEEL HOUSING LINER - RH             | \$ 183.00              | X            |
| 22                        | WHEEL HOUSING LINER ATTACHMENT PARTS | \$ 52.00               | X            |
| 23                        | FRONT BONNET                         | \$ 2,549.00            | X            |
| 24                        | FRONT BONNET ATTACHMENT PARTS        | \$ 149.00              | X            |
| 25                        | LID HINGE - LH                       | \$ 56.00               | X            |
| 26                        | LID HINGE - RH                       | \$ 56.00               | X            |
| 27                        | GAS FILLED STRUT                     | \$ 93.00               | X            |
| 28                        | GAS FILLED STRUT BRACKET - RH        | \$ 31.00               | X            |
| 29                        | STRIKER - RH                         | \$ 100.00              | X            |
| 30                        | ENGINE BONNET SOUND ABS              | \$ 201.00              | X            |
| 31                        | IMPACT PROTECTION - CENTER           | \$ 27.00               | X            |
| 32                        | IMPACT PROTENTION - LH               | \$ 28.00               | X            |
| 33                        | IMPACT PROTENTION - RH               | \$ 27.00               | X            |
| 34                        | BOWDEN CABLE - RH                    | \$ 53.00               | X            |
| 35                        | MOUNTING BEAM HEADLIGHT              | \$ 107.00              | X ?          |
| 36                        | LED HEADLIGHT - RH                   | \$ 4,491.00            | -            |
| 37                        | LIFT CYLINDER - RH                   | \$ 128.00              | ?            |
| 38                        | FRONT WHEEL COVER - LH               | \$ 294.00              | ✓            |
| 39                        | FRONT WHEEL COVER - RH               | \$ 294.00              | ✓            |
| 40                        | FRONT NO PLATE                       | S/N \$ 25.00           | ✓            |
| 41                        | SUNDRIES                             | \$ 800.00              | ?            |
| TOTAL SPARE PARTS CHARGES |                                      | :                      | \$ 16,022.00 |
| TOTAL LABOUR CHARGES      |                                      | :                      | \$ 6,202.00  |
| GRAND TOTAL               |                                      | :                      | \$ 22,224.00 |

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : *Adrian King*  
Surveyed Date : *12/03/19*  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : *Not Authorised, 04 days.*

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the  
progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant