

REPAIR ESTIMATE*

VEHICLE NO : SHC8519H
 MAKE : HYUNDAI
 MODEL : i40

DATE: 12. Mar. 2019

DOA: 5. Mar. 2019

EQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Rear Bumper ✓			\$553.00
10	Rear Bumper Clips ✓		\$2.20	\$22.00
1	Rear Bumper Sponge ?			\$103.50
2	Rear Bumper Reinforcement Brackets – RH/LH ?		\$80.00	\$160.60
1	Rear Bumper Reinforcement ?			\$428.40
1	Rear Bumper Undercover ✗			\$228.00
SUB TOTAL				\$1,495.50
LESS 20%				\$299.10
DISCOUNTED TOTAL				\$1,196.40
1	Reverse Sensor ✗			\$135.70
1	Rear Bumper Rubber Mat ✓			\$50.00
				\$185.70
Labour Charge				
1	Panel Beating			\$300.00 ²⁰⁰
1	Spray Painting Charge			\$300.00 ²⁰⁰
1	Remove/refix Reverse Sensor			\$120.00 ³⁰
TOTAL LABOUR				\$720.00
ESTIMATE TOTAL				\$2,102.10

Nett
Nett

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

Larry Ng

Kalvin 10/10/19
 12/3/19
 2 Apr
 4/5
 12/3/19
 Alla Repair p 4/4

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.