

23/03/2019

ASS. REC. BY:

REF:

CS3/SMD19002256/Jed302-1

CS3/SMD19002256/Jed302

Special Instruction

Surveyor

menmen

ASSIGNMENT (Office)

From (Person):

Huang Shiang Yi

of

SMD

Date/Time: 8/2/19 @ 8:57am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YP 38753

Insured:

YP 87269

at Workshop m/s

Megastore Holdings

Tel:

9237 6951

of

25E Sungai Kerkut Street 1

Policy No:

DIEMTPCVC 001573

Claim No:

CMTD1900679

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 30/01/2019

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

9:25am 8/2/19

Person Contacted:

Mr. Chong

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate
	YP 38753 - X
	YP 87269 - CS3/SMD19002256/Jed3 DUA: 30/01/2019
	Waiting for workshop email changed parts before proceed with finalization.
23/02/19	confirmed Ls \$4,450/- @ 6 days

(B 4,668.00 Rel - 51%)

Resurvey No. of Trip - 1

RECEIVED 29 JUL 2019

250-100 = 150

Shirley Hiew (LKK Auto)

From: Donald Jesus Molina Go <donald.go@samwoh.com.sg>
Sent: Friday, 26 July 2019 1:36 PM
To: Shirley Hiew (LKK Auto)
Cc: Insurance Dept; SUR
Subject: Re: Liability Claim : Vehicle No. XB9541B & YP3875A Accident on 30 January 2019

Dear Shirley Hiew,

This to inform you that we accept the lump sum settlement.

We will prepare our repair invoice and submit to Sompo Insurance Singapore Pte Ltd

Best regards,
Donald
DID 63652639

On Thu, Jul 25, 2019 at 4:35 PM Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> wrote:

Dear Donald,

As spoken, please re-confirm L/S \$ 4,450.00/6 days before gst.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto) [<mailto:denisetay@lkkauto.com>]
Sent: Tuesday, 23 July 2019 10:29 AM
To: Donald Jesus Molina Go <donald.go@samwoh.com.sg>

MEGASTONE

HOLDINGS PTE LTD

Head Office: 25E Sungei Kadut Street 1 Singapore 729333
Tel: (65) 6269 7288 Fax: (65) 6368 2886
Sales Office: 42A Sungei Kadut Street 1 Singapore 729347
Tel: (65) 6365 2066 Fax: (65) 6368 5997
Email: info@samwoh.com.sg website: www.renewcrete.sg
Co. Reg. No. 199504015N GST No. 19-9504015-N

bizSAFE
Partner



18th Feb 2019

Sompo Insurance Singapore Pte Ltd
50 Raffles Place, #05-01/06
Singapore Land Tower,
Singapore 048623
Attention: Motor Claims Department.

Dear Sir/ Madam,

Quotation to supply labour, parts, necessary equipment and tools for the repair of YP3875S.

Description	Qty	U/Price	Total Price
Rear bumper <i>NN X</i>	1 pc	\$580.00	\$580.00
Side gate support bracket <i>DEF ✓</i>	1 pc	\$320.00	\$320.00
RH side door <i>BVC ✓</i>	1 pc	\$750.00	\$750.00
RH door panel <i>DD ✓</i>	1 pc	\$1,455.00	\$1,455.00
Step panel RH <i>CR A ✓</i>	1 pc	\$374.00	\$374.00
Tail lamp LH (3 colour) <i>NN X</i>	1 pc	\$48.00	\$48.00
Rear wheel mudguard <i>NN X</i>	1 pc	\$108.00	\$108.00
Front wheel mudguard <i>SCR ✓</i>	1 pc	\$198.00	\$198.00
Pillar front door rear <i>BVC ✓</i>	1 pc	\$1,900.00	\$1,900.00
U bolt sub frame <i>NN X</i>	1 pc	\$115.00	\$115.00
Big wood <i>NN X</i>	1 pc	\$750.00	\$750.00
Protector front door <i>NEC ✓</i>	1 pc	\$120.00	\$120.00
		Total Parts	\$6,718.00
Labour Charge			<i>1500</i>
To remove & replace damage parts, spray paint	1 job	\$2,400.00	\$2,400.00
		Total Labour:	\$2,400.00
		Sub-Total:	\$9,118.00
		7% GST	\$638.26
		Grand Total	\$ 9,756.26

Thanks,

Jou Chung Fat
Workshop In-charge

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total - \$3400

Huan Jie - LKK

27/2/19

L/S 6days

15/3/19

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Jan 2019		08 Feb 2019 08:57 Edit Adj Rpt	S\$4,450.00 Edit Estimates	S\$4,450.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	LIM SIANG HUAT PTE LTD , Co. Reg. No.: 199803003N								
Main Claimant:	MEGASTONE HOLDINGS PTE LTD , Co. Reg. No.: 199504015N								
Vehicle Reg. No.:	YP3875S	Date of Loss:	30/01/2019 16:00 - :59 [29 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1900679	Policy/Cover Note No.:	D18MTPCVE001573 (Comprehensive)						
Vehicle Reg. No. (Insured):	YP8726G	Policy No. (Claimant):							
		Excess:							
Repairer:	MEGASTONE HOLDINGS PTE LTD (HQ) 25E Sungei Kadut Street 1, 729333 Sungei Kadut - Tel: 63652066								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 25/07/2019]								
Driver/Custodian (Insured):	ZHANG KAI (), NRIC: G2243806P, Tel: +6584512066 Email:								
Adj Asg. Remarks:	PIC: MR CHONG CHEE KONG / 92376951 DID 63652639								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
SOMPO_SG (23/07/2019): Report Send Back Alerts - YP3875S (TP)									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***YP3875S (CMTD1900679)**
[YP8726G]
TP
MEGASTONE HOLDINGS PTE LTD
Jan 30 2019 4:00PM
[LIM SIANG HUAT PTE LTD]
MEGASTONE HOLDINGS PTE LTD

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/02/19 09:50	General View	 Load JPG	☒
2	11/02/19 09:50	General View	 Load JPG	☒
3	11/02/19 09:50	General View	 Load JPG	☒
4	11/02/19 09:50	General View	 Load JPG	☒
5	11/02/19 09:50	General View	 Load JPG	☒
6	11/02/19 09:50	General View	 Load JPG	☒
7	11/02/19 09:50	General View	 Load JPG	☒
8	11/02/19 09:50	General View	 Load JPG	☒
9	11/02/19 09:50	General View	 Load JPG	☒
10	11/02/19 09:50	General View	 Load JPG	☒
11	11/02/19 09:50	General View	 Load JPG	☒
12	11/02/19 09:50	General View	 Load JPG	☒
13	11/02/19 09:50	General View	 Load JPG	☒
14	11/02/19 09:50	General View	 Load JPG	☒
15	11/02/19 09:50	General View	 Load JPG	☒
16	11/02/19 09:50	General View	 Load JPG	☒
17	11/02/19 09:50	General View	 Load JPG	☒
18	11/02/19 09:50	General View	 Load JPG	☒
19	11/02/19 09:50	General View	 Load JPG	☒
20	11/02/19 09:50	General View	 Load JPG	☒
21	11/02/19 09:50	General View	 Load JPG	☒
22	11/02/19 09:50	General View	 Load JPG	☒
23	11/02/19 09:50	General View	 Load JPG	☒
24	11/02/19 09:50	General View	 Load JPG	☒
25	11/02/19 09:50	General View	 Load JPG	☒
26	11/02/19 09:50	General View	 Load JPG	☒
27	11/02/19 09:50	General View	 Load JPG	☒
28	11/02/19 09:50	General View	 Load JPG	☒
29	11/02/19 09:50	General View	 Load JPG	☒
30	11/02/19 09:50	General View	 Load JPG	☒
31	11/02/19 09:50	General View	 Load JPG	☒
32	11/02/19 09:50	General View	 Load JPG	☒
33	11/02/19 09:50	General View	 Load JPG	☒
34	11/02/19 09:50	General View	 Load JPG	☒
35	11/02/19 09:50	General View	 Load JPG	☒
36	11/02/19 09:50	General View	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	☒
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	07/02/19 15:51	PRI FR MEGASTONE HOLDINGS - YP3875S	 Load PDF	
2	07/02/19 16:15	Third Party E-filed GIA report(M)	 Load PDF	
3	08/02/19 08:55	TP - ASSIGN LKK	 Load PDF	
4	26/02/19 17:57	ESTIMATE	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/07/19 08:43	PRS Invoice	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19002256/ESD3E2-1

Date: 30/07/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPCVE001573
Claimant Vehicle No :	YP3875S	Insured Vehicle No :	YP8726G
Date of Loss:	30/01/2019	Nature of Claim:	TP
		Claim No:	CMTD1900679

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP3875S	Engine No:	N04CUS28627
Make & Model:	HINO XZU710R-HKFMS3, 4.0 D (M)	Chassis No:	JHHUCS3H40K017987
Reg. Date:	24/08/2016 (Man. Year: 2016)	Odometer:	0 km
Colour:	Yellow		
Engine Capacity:	4009 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	7.00 R16	Rear Tyre Size:	7.00 R16
Front Left Side:	OHTSU 7 mm	Rear Left Side:	OHTSU 7 mm
Front Right Side:	OHTSU 7 mm	Rear Right Side:	OHTSU 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,718.00	4,065.30	2,652.70	39.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	1,500.00	900.00	37.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,118.00	5,565.30	3,552.70	38.96
Approved Total (Overridden) (S\$)		4,450.00		
(S\$)	9,118.00	4,450.00	4,668.00	51.20
+ GST 7.00/7.00% (S\$)	638.26	311.50	326.76	51.20
Nett Amount (S\$)	9,756.26	4,761.50	4,994.76	51.20

INSPECTION

Date of Assignment:	08/02/2019	
Date Inspected:	08/02/2019 Inspected At:	MEGASTONE HOLDINGS PTE LTD (HQ) 25E Sungei Kadut Street 1 Singapore 729333
Estimated Period of Repair:	6.0 days	

Adjuster: ONG HWEE JIE**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Jul 2019)	
Parts:	N/A	HINO XZU710R-HKFMS3 4.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP3875S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Not Necessary	580.00 F	*- FL
2	1		*SIDE GATE SUPPORT BRACKET	Deformed	320.00 F	*320.00 FL
3	1		*RH SIDE DOOR	Buckled	750.00 F	*750.00 FL
4	1		*RH DOOR PANEL	Dented	1,455.00 F	*1,455.00 FL
5	1		*STEP PANEL RH	Cracked	374.00 F	*374.00 FL
6	1		*TAIL LAMP LH (3 COLOUR)	Not Necessary	48.00 F	*- FL
7	1		*REAR WHEEL MUDGUARD	Not Necessary	108.00 F	*- FL
8	1		*FRONT WHEEL MUDGUARD	Scratched	198.00 F	*198.00 FL
9	1		*PILLAR FRONT DOOR REAR	Buckled	1,900.00 F	*1,300.00 FL
10	1		*U BOLT SUB FRAME	Not Necessary	115.00 F	*- FL
11	1		*BIG WOOD	Not Necessary	750.00 F	*- FL
12	1		*PROTECTOR FRONT DOOR	Necessary	120.00 F	*120.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	6,718.00	4,517.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	451.70
Total Parts (S\$)	6,718.00	4,065.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REPLACE DAMAGE PARTS, SPRAY PAINT	New	2,400.00	1,500.00
Gross Labour Cost (S\$)			2,400.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >