

REPAIR ESTIMATE*

VEHICLE NO : SHC 3969A

MAKE :

MODEL : HYUNDAI i40

DATE 12/3/2019

Merimen
Tyre Han Kook

Tokio Marine - (L/S) TS

LKK - kalvin

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover /			\$ 544.50
	Front Bumper Bracket Top (LH) ?			\$ 22.40
	Front Bumper Bracket (LH) ?			\$ 24.60
	Front Wheel Hub Cap (LH) /			\$ 107.10
	Front Fender (LH) x repair			
	Front Door (LH) x repair			
	Rear Door (LH) x repair			
	SUB TOTAL			\$ 698.60
	LESS 20%			\$ 139.72
	DISCOUNTED TOTAL			\$ 558.88
	Front Door Comfort Logo (LH) /			\$ 75.00
	Rear Door Comfortdelgro & Apps Sticker (LH) /			\$ 80.00
				\$ 155.00
	Labour Charge			200
	Panel Beating			\$ 400.00
	Spray Painting Charge-Bumper/Fender/Door x2			\$ 1,000.00
	Tuff Kote			\$ 50.00
	FRT Wheel Alignment			\$ 80.00
	TOTAL LABOUR			\$ 1,530.00
	ESTIMATE TOTAL			\$ 2,243.88

Nett

Nett

800

x

x

K/Calvin 11/11/19

12/3/19 1110 hrs

3 Pgs

L/S

After Repair y Lh

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "What you see is what you get" basis
- No liability for consequential damage
- Survey is only for the purpose of estimating repair costs and is not a guarantee of the quality of the repair work

Acknowledged by:

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.