

NS/INC19004544/11v0302

Taufkh

INC

Vehicle: **FE 5980R**
 Policy No: **5082382072-10 (1/3/19-29/2/20)**
 Claim No: **MT/1035653-002**
 Date: **1/3/19**
 Person Contacted: **FE 5980R**
 Action/Instruction: **FE 5980R-X**
 Insured vehicle number is **FE 5980R**.



Vehicle: **SHB5819S**
 Policy No: **2017 Dec**
 Type: **Motorcycle**
 Make: **Typh Piro**
 Model: **1798**
 Year: **128983**
 Engine: **1798**
 Gen. Cond. Code: **Good**
 Steering: **Insider**
 Brake: **Insider**
 Mod: **Nil**
 Tyre Size: **175/65R15**
 BS/DUH/EXHOVA/GY/ES/LIZA/MIC/GHTSU/PIR/334ML
 TOYO/YORO or **Fallen**
 Front: **6** mm
 Rear: **6** mm
 D.O.A. **9/3/19**
 Survey held at **SMRT**
 Desc. of Damages: **Front / Rear / ORS / MS / DIC / Rooftop or**
Rear o/s
 The DIC / Chassis frame / Body Structure affected due to collision

3/5/19 Final fig \$ 3002.51 confirmed by email (Recd 3359.89, 5319)

RECEIVED 3 3 2019

Vehicle File Number: **35- typst**
 Preli. Report
 Final Report

Days Of Repair: **3**
 Resurvey No. of Trip: **1**

Survey Fee: **160**
 Transportation: **160**

Add Fee: **35- typst**
 Date In p: **35**
 In p: **35**
 In p: **35**
 In p: **35**

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident
1	MT/1042643-001	COMFORT TRANSPORTATION PTE LTD	SHD 6530G	GBD 5668X	27/4/2019
2	MT/1042160-002	COMFORT TRANSPORTATION PTE LTD	SHD 3134L	SLS 2664D	26/4/2019
3	MT/1035653-002	SMRT TAXIS	SHB 5819S	FE 5980R	9/3/2019
4	MT/1042102-002	COMFORT TRANSPORTATION PTE LTD	SH 8788R	SHB 8608P	27/4/2019
5	MT/1041880-002	COMFORT TRANSPORTATION PTE LTD	SH 7218B	YP 251L	25/4/2019
6	MT/1041969-002	COMFORT TRANSPORTATION PTE LTD	SHA 1749S	SKS 3400D	26/4/2019
7	MT/1042207-002	COMFORT TRANSPORTATION PTE LTD	SH 7982C	SFF 9629A	26/4/2019

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident
Vehicle No.(For Motor) Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5032382072-10		KOH THAI SAN	S0961922D	GMC	Third Party	FE5980R	FE5980R	01/03/2019	29/02/2020

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/03/2019 09:53
Date Of Accident	09/03/2019 17:50
Exact Location Of Accident	AMK ST 22 TOWARDS AMK AVE 3 (OPP BLK 202)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5819S
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	AHMAD BIN SALLEH
NRIC No	S0192223H
Date Of Birth	12/11/1952
Occupation	OUTDOOR
Date Of Driving Pass	24/12/1979
Driving Experience	39 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	YISHUN NORTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 31 YISHUN CENTRAL , POSTCODE: 768827 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8529999 - FAX NO: 68522299
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20190309/2158

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBH5980R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

* No. Of Passenger (Including Driver)


DETAILS OF INJURED PERSON 1

Name	AHMAD BIN SALLEH
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SHB5819S
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

DETAILS OF INJURED PERSON 2

Name	UNKNOWN
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FBH5980R
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

Sketch Plan Pg. 1



DECLARATION
I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Chuk 11/3/2019
Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature] 11/3/2019
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time

 11-3-2019
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

 11/3/2019
 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999



T/20190309/2158

1 of 3

Report No. T/20190309/2158

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:
09/03/2019 23:08

Vide Report No.:
F/20190309/0177

Station Diary No.:
199

Informant's Particulars

Name of Informant:
AHMAD BIN SALLEH

Address:
APT BLK 408 YISHUN AVENUE 6 #04-1254 SINGAPORE
760408

ID Type / ID No.:
NRIC NO / S0192223H

Contact No.:
Home/Office: Mobile: 81125962

Nationality:
SINGAPORE CITIZEN

Email:

Sex: Male Age: 66 Date of Birth: 12/11/1952

Type of Informant:
Driver

Race:
Malay

Language:
English

Institution / School Name:

Occupation:
Taxi driver

Driving Licence Information:
Class: 3

Date of Expiry:

General Information of the Accident

Type of
Accident:

Injury
Attended by Police

Drink
Drive:
No

Date/Time of
Accident:
09/03/2019 17:50

Type of Location:
Straight Road

Location:
Along Road 1
ANG MO KIO STREET 22

Along Ang Mo Kio Street 22 towards Ang Mo Kio Ave 3 opposite Blk 202

Weather:
Clear

Road Surface:
Dry

Road Speed Limit:

Traffic Flow:
Two Way

Traffic Control:
Not Controlled

Traffic Volume:
No Traffic

Type of Collision:
Between Moving Vehicles - Head To Rear

Anyone conveyed by
ambulance:
Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
FE5980R	Motorcycle					0
SHB5819S	Car				Seriously Damaged	0

Details of Person Involved

Any Pedestrian Involved: No

No. of Pedestrians Injured: NIL

Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190309/2158

2 of 3

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

Report No. T/20190309/2158

CONTINUATION OF REPORT

Driver			
Name	AHMAD BIN SALLEH		ID No. S0192223H
Related Vehicle	SHB5819S (Car)		Contact No. 81125962
Hospital/Clinic	TAN TOCK SENG HOSPITAL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	09/03/2019	Date Discharge	NIL
No. of Days granted Medical Leave	01	Degree of Injury	Slight

Brief Details.

On 09/03/2019 at about 1750hrs, I was driving my taxi bearing registration number SHB5819S and exiting from the carpark of Blk 202 Ang Mo Kio. I had turned to the right after exiting the carpark as there was a passenger waving to hail a taxi. Upon turning right to Ang Mo Kio Street 22 (to the direction of Ang Mo Kio Ave 3), I had turned on the hazard lights and stopped to pick up the passenger. However, before the passenger entered my taxi, there was a sudden collision impact to the rear of my taxi.

Thereafter I had alighted from my taxi to check for any injuries and damages. A motorcycle bearing registration number FE5980R had collided to the right rear side of my taxi, the impact of the collision caused the rear right bumper to crack and fell off, the rear right lights were also damaged and rear right portion (above the bumper) was dented. The rider of FE5980R was on the road and I had helped him to carry him to the side of the road; the motorcycle was pushed to the side of the road.

My son-in-law had assisted to call for the Police to report the accident. Subsequently the Traffic Police and the ambulance arrived at scene. The rider and myself was later conveyed to the hospital (TTSH) for medical attention. As the rider was injured, I did not ask for his particulars and contact numbers. My son-in-law namely Alim (Tel: 96460008) arrived at the accident scene and liaised with the Traffic Police officer who had later took over the memory card from the dashcam in my taxi and I was instructed to lodge a Police report on the accident.

I am lodging this report for my company's actions, insurance claimant and under the instruction of the Traffic Police.



**SINGAPORE
POLICE FORCE**



T/20190309/2158

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

3 of 3




Report No. T/20190309/2158

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: L / Staff Sgt YAP YHEE HOE 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 09/03/2019 23:08
Officer In Charge Of Case: TP / GIT / Sgt 3 MARIAH BINTE ZAKARIA Contact No.: 65476433	Classification Of Case: 
Authentication Stamp NP168	

Case Details

Case Reference Number :

TAX/03/19/2043

Type of Repair : Accident Repair

Vehicle Registration Number :

SHB5819S

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-6054-ID

Assigned By : Taxi Claims Manager
Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd

Accident Date and Time : 09/03/2019 09:50 AM

Vehicle Age(In Months) : 15

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	317.92	Replace ▾	de✓
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 1	2	3.80	7.60	25.00	5.70	Replace	0	0	Check ▾	?
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 2	2	3.80	7.60	25.00	5.70	Replace	0	0	Check ▾	?
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 3	2	3.80	7.60	25.00	5.70	Replace	0	0	Check ▾	?
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.00	22.00	25.00	16.50	Replace	0	0	Check ▾	?
One Time Key In	Main			STOPPER, RR BUMPER, RH & LH	2	4.30	8.60	25.00	6.45	Replace	0	0	Check ▾	?
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	1	84.53	Replace ▾	nc✓
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	0	0	Not Give ▾	x
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	1	418.72	Replace ▾	de✓

Total Spare Part Cost 3,192.82

Surveyor Total 2,002.56

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 3,192.82

Final Sur Total 2,002.56

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	0	0	Check	?
One Time Key In	Main			FILLER, RR BUMPER , RH	1	119.90	119.90	25.00	89.93	Replace	0	0	Check	?
One Time Key In	Main			COVER, REAR FLOOR UNDER , RH	1	169.50	169.50	25.00	127.13	Replace	1	127.13	Replace	de
One Time Key In	Main			COVER, REAR FLOOR UNDER CENTER	1	222.60	222.60	25.00	166.95	Replace	0	0	Not Give	ding
One Time Key In	Main			PANEL SUB-ASSY, FENDER REAR RH	1	824.80	824.80	25.00	618.60	Replace	1	0	Repair	RV
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	na
One Time Key In	Main			LINER, REAR FENDER , RH	1	135.80	135.80	25.00	101.85	Replace	1	101.85	Replace	de
One Time Key In	Main			LENS & BODY ASSY , RR BUMPER , RH	1	486.80	486.80	10.00	438.12	Replace	1	438.12	Replace	One
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP , RH	1	438.10	438.10	10.00	394.29	Replace	1	394.29	Replace	One
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Check	xun
Total Spare Part Cost									3,192.82		Surveyor Total		2,002.56	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)		0	
Final Spare Part Cost									3,192.82		Final Sur Total		2,002.56	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION REAR	845.00	300	
Total:			845.00	300.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			936.00	500.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY FILLER RR BUMPER RH	180.00	100	
3	Main	TO RESPRAY REAR FENDER RH	378.00	200	
Total:			936.00	500.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	56.00	0	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30	
4	Main	TO REMOVE / REFIT SEAT	120.00	0	
5	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30	
6	Main	TO WASH AND VACUUM	60.00	0	
7	Main	TO REPLACE SUNDRY PARTS	100.00	20	
Total:			636.00	110.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	3,192.82	2,002.56
Total Labour Cost	845.00	300.00
Total Spray Painting	936.00	500.00
Other	636.00	110.00
Overall Total	5,609.82	2,912.56
Lump Sum Repair Option		
Lump Sum Total	0.00	2,912.56
Surveyor Approved Amount		2,912.56
No of Repair Days*	5	3

Estimator Assessment(\$)

Surveyor Assessment(\$)

Remarks

Resurvey before paint

Surveyor Name

Taufikh

Signature

R

+

14/3/19

Save

Clear

Survey Date

12/03/2019

LKK Auto Consultants hence notify
the Repairer of the following:

- To **resurvey** before/after spray painting
- To **display** damaged part(s) during resurvey
- **Parts prices** are subject to confirmation
- **Third party** survey is on a "Without Prejudice" basis
- No **illegal** modification(s) is allowed
- **Supplementary** item(s) must be resurveyed **and** is **subject** to final approval from Insurance Company



Acknowledged by Repairer

Signature:

Date:

Section A - Accident Details

Registration Number	SHB5819S
Case Reference Number	TAX/03/19/2043
Registration Date	12/12/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	AHMAD B SALLEH
Type of Accident	Head to Rear
Accident Date and Time	9/3/2019 5:50 PM
Accident Reported Date and Time	11/3/2019 10:11 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	9/3/2019 7:26 PM
Replacement Vehicle issued?	No
Job Card Number	24100524
Special Instruction to ARC, if any	TOWED \$40/TP/ NTUC - LKK
Prepared Date and Time	12/3/2019 11:15 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Diagram

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$300.00
Total Spray Cost	\$936.00	\$500.00
Total Spare Part Cost	\$3,282.75	\$2,092.51
Total Other Cost	\$636.00	\$110.00
TOTAL COST	\$5,699.75 <i>6360.40</i>	\$3,002.51 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Zhi Yang Phua	Taufik (LKK) / NTUC
ARC / Surveyor Sign Off Date	12/03/2019 11:34 AM	12/03/2019 4:02 PM
Signature	<i>R</i>	<i>+</i>
Remarks		Resurvey before paint

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1904-0501	Invoice Number	
Quotation Date	30.04.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION REAR	\$845.00	\$300.00
Total Labour	\$845.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$100.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$936.00	\$500.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00
TO REMOVE / REFIT SEAT	\$120.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
Total Other Costs	\$636.00	\$110.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5215947913	COVER, RR BUMPER ASSY	1.00	\$423.90	25.00	\$317.93	Replace	Replace
		5246247030	PAD, RR BUMPER, RH & LH, 1	0.00	\$3.80	0.00	\$0.00	Replace	Check
		5246247020	PAD, RR BUMPER, RH & LH, 2	0.00	\$3.80	0.00	\$0.00	Replace	Check
		5246247010	PAD, RR BUMPER, RH & LH, 3	0.00	\$3.80	0.00	\$0.00	Replace	Check
		5219147030	SEAL, RR BUMPER ARM, RH & LH	0.00	\$11.00	0.00	\$0.00	Replace	Check
		5259968030	STOPPER, RR BUMPER, RH & LH	0.00	\$4.30	0.00	\$0.00	Replace	Check
		5257547040	RETAINER, RR BUMPER, RH	1.00	\$112.70	25.00	\$84.53	Replace	Replace
		5257647040	RETAINER, RR BUMPER, LH	0.00	\$111.50	0.00	\$0.00	Replace	Not Given
		5245347010	GUARD, RR BUMPER, LOWER	1.00	\$558.30	25.00	\$418.73	Replace	Replace
		5216947020	COVER, GUARD RR BUMPER LOWER	0.00	\$14.80	0.00	\$0.00	Replace	Check
		5256547900	FILLER, RR BUMPER, RH	0.00	\$119.90	0.00	\$0.00	Replace	Check
		5839847050	COVER, REAR FLOOR UNDER, RH	1.00	\$169.50	25.00	\$127.13	Replace	Replace

	66259470 10	COVER, REAR FLOOR UNDER CENTER	0.00	\$222.60	0.00	\$0.00	Replace	Not Given	X
	61601471 50	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$824.80	100.00	\$0.00	Replace	Repair	R
		PIXEL STICKER	2.00	\$50.00	0.00	\$120.00	Replace	Replace	
	65637470 60	LINER, REAR FENDER, RH	1.00	\$135.80	25.00	\$101.85	Replace	Replace	
	81581470 10	LENS & BODY ASSY, RR BUMPER, RH	1.00	\$486.80	10.00	\$438.12	Replace	Replace	
	81551472 81	LENS & BODY, REAR COMBINATION LAMP, RH	1.00	\$438.10	10.00	\$394.29	Replace	Replace	
		SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Check	X
Total				\$3,885.40		\$2,002.58			

na
R
nec
de
cra
cra
na

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		Stock Number	FILLER, RR BUMPER, RH	1.00	\$119.90	25.00	\$89.93	Replace	Replace
Total					119.90		89.93		

de

4065-20

2092.51
+ 300.00
+ 610.00

3002.51

6482-30

Veron Chen (LKKAUTO)

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) <YeoPohsuan@smrt.com.sg>
Sent: Friday, 3 May 2019 3:52 PM
To: Veron Chen (LKKAUTO); Taufikh (LKKAUTO)
Cc: SUR; CS A Team
Subject: RE: SHB5819S

Hi,

Amount confirmed as per your recommendation, thanks.

Regards
Poh Suan

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Friday, 3 May 2019 3:44 PM
To: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis); Taufikh (LKKAUTO)
Cc: SUR; CS A Team
Subject: RE: SHB5819S

Dear Poh Suan,

WITHOUT PREJUDICE

Amount confirm \$3,002.51 @ 3 working days

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) <YeoPohsuan@smrt.com.sg>
Sent: Tuesday, 30 April 2019 6:01 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: SHB5819S

Hi Taufikh,

Attached herewith the repair estimate of SHB 5819S having Case No: TAX/03/19/2043.

There is no change to the approved amount of \$3,002.51 @ 3 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)

Sent: Tuesday, 30 April 2019 1:36 PM

To: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)

Subject: Scan Data from FX-D421D6

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 3 May 2019 3:44 PM
To: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis); Taufikh (LKKAUTO)
Cc: SUR; CS A Team
Subject: RE: SHB5819S

Dear Poh Suan,

WITHOUT PREJUDICE

Amount confirm \$3,002.51 @ 3 working days

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) <YeoPohsuan@smrt.com.sg>
Sent: Tuesday, 30 April 2019 6:01 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: SHB5819S

Hi Taufikh,

Attached herewith the repair estimate of SHB 5819S having Case No: TAX/03/19/2043.

There is no change to the approved amount of \$3,002.51 @ 3 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)
Sent: Tuesday, 30 April 2019 1:36 PM
To: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)
Subject: Scan Data from FX-D421D6



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19004544/T1vd3e2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 08-05-2019	
Code: INC4				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FE 5980R	Veh. Inspected	SHB 5819S	
Policy No.	5032382072-10	Coverage (\$)	0.00	
Claim No.	MT/1035653-002	Excess (\$)	0.00	
Assign From		Assign Date	12/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU503575935	Colour	MAROON	
Odometer	128983	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	FALKEN	6 mm	
L/H Front Tyre	195/65 R15	FALKEN	6 mm	
R/H Rear Tyre	195/65 R15	FALKEN	6 mm	
L/H Rear Tyre	195/65 R15	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/03/2019	Inspection Date	12/03/2019	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5819S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	COVER, RR BUMPER ASSY (DISC 25%)	DEFORMED	423.90	317.93
1	RETAINER, RR BUMPER, RH (DISC 25%)	NECESSARY	112.70	84.53
1	GUARD, RR BUMPER, LOWER (DISC 25%)	DEFORMED	558.30	418.73
1	COVER, REAR FLOOR UNDER, RH (DISC 25%)	DEFORMED	169.50	127.13
1	LINER, REAR FENDER, RH (DISC 25%)	DEFORMED	135.80	101.85
1	FILLER, RR BUMPER, RH (DISC 25%)	DEFORMED	119.90	89.93
1	LENS & BODY ASSY, RR BUMPER, RH (DISC 10%)	CRACKED	486.80	438.12
1	LENS & BODY, REAR COMBINATION LAMP, RH (DISC 10%)	CRACKED	438.10	394.29
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	PAD, RR BUMPER, RH & LH, 1	NOT NECESSARY	3.80	-
1	PAD, RR BUMPER, RH & LH, 2	NOT NECESSARY	3.80	-
1	PAD, RR BUMPER, RH & LH, 3	NOT NECESSARY	3.80	-
1	SEAL, RR BUMPER ARM, RH & LH	NOT NECESSARY	11.00	-
1	STOPPER, RR BUMPER, RH & LH	NOT NECESSARY	4.30	-
1	RETAINER, RR BUMPER, LH	NOT NECESSARY	111.50	-
1	COVER, GUARD RR BUMPER LOWER	NOT NECESSARY	14.80	-
1	FILLER, RR BUMPER, RH	NOT NECESSARY	119.90	-
1	COVER, REAR FLOOR UNDER CENTER	NOT NECESSARY	222.60	-
1	SENSOR REVERSE	NOT NECESSARY	180.00	-
1	PANEL SUB-ASSY, FENDER REAR RH	TO REPAIR SEE LABOUR	824.80	-
			4,065.30	2,092.51
<u>LABOUR</u>				
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF PANEL SUB-ASSY, FENDER REAR RH.		845.00	300.00
	SPRAY PAINT.		936.00	500.00
	TOWING CHARGE.		56.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	30.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	30.00
	TO REMOVE / REFIT SEAT.	NOT NECESSARY	120.00	-

Report Ref No. NS/INC19004544/T1vd3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	NOT NECESSARY	120.00	30.00
	TO WASH AND VACUUM.		60.00	-
	TO REPLACE SUNDRY PARTS.		100.00	20.00
			2,417.00	910.00
GRAND TOTAL			6,482.30	3,002.51
RECOMMENDED COST OF REPAIRS (CONFIRMED)				3,002.51

Report Ref No. NS/INC19004544/T1vd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.