

Confirmed with Marcus
on 13/03/2019



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : SLT7053D p/p #3669-36
Date of Accident : 11 March 2019

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Not Approved
Lkh

Mr Peh Boon Cheng

the pls below party.
HJ.
13/3/19

Date : 11 March 2019

Lkh - Marcus
13/03/19 C0943h

Estimate To Repair SLM2056R - Honda VEZEL 1.5X CVT
Chassis No : RU11209341

S/No	Quantity	Description	Amount
LIST ITEMS			
01	1 pc	tailgate lid <i>30d/30d</i>	\$ 953.30
02	1 pc	tailgate lid vezel badge <i>net</i>	\$ 32.90
03	1 pc	tailgate lid lock <i>2ur</i>	\$ 76.60
04	1 pc	tailgate lid striker <i>11</i>	\$ 27.50
05	1 pc	tailgate lid weatherstrip <i>Torn</i>	\$ 96.80
06	1 pc	tailgate lid outer garnish <i>11</i>	\$ 220.00
07	1 pc	tailgate lid reflector left <i>11</i>	\$ 413.20
08	1 pc	tailgate lid inner trim board <i>11</i>	\$ 225.00
09	2 ps	tailgate lid rubber stoppers @ \$18.50 <i>11</i>	\$ 37.00
10	1 pc	rear windscreen glass weatherstrip <i>new/dy net</i>	\$ 120.00
11	1 pc	rear truck floorboard <i>11</i>	\$ 258.00
12	1 pc	rear end panel <i>2</i>	\$ 415.60
13	1 pc	rear end panel inner trim <i>11</i>	\$ 98.00
14	1 pc	rear luggage floor compartment tool foam <i>11</i>	\$ 230.00
15	1 pc	rear bumper centre <i>20</i>	\$ 762.70
16	1 pc	rear bumper centre screw spacer <i>net</i>	\$ 5.00
17	1 pc	rear bumper side left <i>Torn</i>	\$ 195.00
18	2 ps	rear bumper side retainers @ \$22.00 <i>11</i>	\$ 44.00
19	1 pc	rear bumper reflector left <i>11</i>	\$ 141.10
20	10 ps	rear bumper clips @ \$4.50 <i>net</i>	\$ 45.00
21	1 pc	rear lamp left <i>11</i>	\$ 474.60
22	2 ps	rear lamp clip holders @ \$4.50 <i>11</i>	\$ 9.00
Less 20 %			\$ 4,880.30
			\$ 976.06
			\$ 3,904.24
SPECIAL NETT ITEMS			
23	1 pc	rear bumper lower diffuser - accessory <i>2</i>	\$ 500.00
24	1 pc	rear bumper reflector chrome rim - accessory <i>net</i>	\$ 200.00
25	1 pc	rear bumper thread plate chrome <i>net</i>	\$ 250.00
26	1 pc	rear panel inner trim thread plate chrome <i>11</i>	\$ 250.00
27	1 pc	rear windscreen glass sealant <i>net</i>	\$ 80.00
28	1 pc	rear windscreen glass inner sponge seal <i>net</i>	\$ 120.00
29	1 set	rear bumper parking sensor <i>shud</i>	\$ 450.00
30	1 pc	rear licence plate <i>11</i>	\$ 80.00
			\$ 1,930.00
LABOUR & MISC. CHARGES			
01		To remove and refit rear windscreen glass	\$ 180.00

Handwritten marks and corrections on the right side of the table, including checkmarks, 'X' marks, and numerical values like '2287.3', '120', '40', '30', '200', and 'X'.



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SLT7053D

Date of Accident : 11 March 2019

Mr Peh Boon Cheng

Date : 11 March 2019

Estimate To Repair SLM2056R - Honda VEZEL 1.5X CVT
Chassis No : RU11209341

S/No	Quantity	Description	Amount
LABOUR & MISC. CHARGES			
02		To check electrical lighting concerned.	\$ 50.00
03		To remove and reinstall reverse camera	\$ 80.00
04		To rust-proofing of the affected areas.	\$ 180.00
05		To reinstall of rear bumper parking sensor.	\$ 120.00
06		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 180.00
07		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 150.00
08		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,000.00
09		Putty and spray painting of the affected portion.	\$ 1,200.00
			\$ 3,140.00
Total			\$ 8,974.24

20
50
30
50
60
60
400
500

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-2109-36
S.N-390
color-1170
3669-36
P-2636-7



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : SLT7053D

Date of Accident : 11 March 2019

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Mr Peh Boon Cheng

Date : 13 March 2019

Supplementary To Repair SLM2056R - Honda VEZEL 1.5X CVT

Chassis No : RU11209341

S/No	Quantity	Description	Amount
		<u>LABOUR & MISC. CHARGES</u>	
01	1 pc	rear fender wheel arch garnish LH	\$ <i>Total</i> 184.20
02	1 pc	rear buzzer assy	\$ <i>Car</i> 165.20
			\$ 349.40
		Less 20 %	\$ 69.88
			\$ 279.52
		Total	\$ 279.52