



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

FWD Singapore Pte Ltd 6 Temasek Boulevard, #18-01 Suntec Tower 4, Singapore 038986 ATTN. : MOTOR CLAIMS FAX :		NAME : Muhammed Jamil Bin Abdul Aziz ADDRESS : Blk 754 Pasir Ris St 71 02-124 Singapore 510754 TEL : 91182203		WIP : 37031 EXCESS : DATE: 12-Mar-19	
VEH NO :	SLX142E	DATE IN :		CONTACT PERSON :	Vion 63957877
CHASSIS NO :	JM6BN22A8H0166803	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3	DATE REG.:	13-Mar-18	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MBHN1-50-221ABB	de ✓	\$ 1,074.80
2	RETAINER LHS	1	MBHN1-50-2J1A	ne ✓	\$ 36.10
3	RETAINER RHS	1	MBHN1-50-2H1A	ne ✓	\$ 36.10
4	BRACKET LHS	1	MBHN9-51-077B	ne ✓	\$ 45.60
5	BRACKET RHS	1	MBHN9-51-067B	ne ✓	\$ 45.60
6	BRACKET CENTER	1	MKD53-50-251	?	\$ 5.10
7	REFLECTOR LHS	1	MD350-51-5L0E	ce ✓	\$ 50.40
8	TOWING COVER LHS	1	MBHN1-50-EL1 BB	ms ✓	\$ 15.70
9	TOWING COVER RHS	1	MBHN1-50-EK1 BB	ms ✓	\$ 16.20
10	REAR REINFORCMENT	1	MB45A-50-260	bt ✓	\$ 537.30
11	SHIELD SPLASH LHS	1	MBHN1-50-350B	X	\$ 79.20
12	SHIELD SPLASH RHS	1	MBHN1-50-340B	X	\$ 71.10
13	GROMMET, REAR BUMPER	4	MBHN1-50-0Z1A	ne ✓	\$ 10.00
14	GROMMET, REAR BUMPER	2	M9991-00-501	ne ✓	\$ 5.60
15	RIVET, REAR BUMPER	4	MBBM4-50-355	ne ✓	\$ 16.80
16	FASTENER, REAR BUMPER	4	MB45A-56-146A	ne ✓	\$ 11.20
17	REAR END PANEL	1	MB4YA-70-75Z	ht ✓	\$ 505.10
18	TRIM, END PANEL	1	MBHN1-68-89XA	de ✓	\$ 85.10
19	FASTENER, TRIM	10	MGJ21-68-885B02	ne ✓	\$ 28.00
20	INSULATOR, HEAT SHIELD	1	MB45A-56-451	bt ✓	\$ 53.10
22	RIVET, INSULATOR	4	MB25D-56-398	ne ✓	\$ 8.00
24	BOOTLID	1	MBHY2-52-61XB	ht ✓	\$ 957.40
25	HINGE LHS, BOOTLID	1	MB61T-52-720	?	\$ 145.30
26	HINGE RHS, BOOTLID	1	MB61T-52-710	?	\$ 145.30
27	WEATHERSTRIP, BOOTLID	1	MBHN1-56-951A	ne ✓	\$ 107.70
28	LOCK, BOOTLID	1	MGHK1-56-820A	bt ✓	\$ 153.00
29	STRIKER, BOOTLID	1	MGG2A-56-840	?	\$ 33.40
30	ORNAMENT, MAZDA	1	MBHN1-51-721	ne ✓	\$ 53.40
31	MASCOT, REAR	1	MBHN1-51-730	ne ✓	\$ 74.40
32	ORNAMENT, SKYACTIVE	1	MBHN1-51-771	ne ✓	\$ 63.60

33	FASTENER, BOOTLID	2	MEG21-51-146	✓	\$ 11.80
34	GROMMET, BOOTLID	2	MGA7B-51-146	✓	\$ 6.20
35	LAMP LHS, BOOTLID	1	MB45A-51-3G0	?	\$ 265.00
36	LAMP LHS, TAILLAMP	1	MB45A-51-160B	?	\$ 509.40
37	FASTENER, TAILLAMP	1	MKD53-51-146B	✓	\$ 3.90
38	FASTENER, TAILLAMP	1	MGJ6A-51-14Y	✓	\$ 14.90
39	GASKET LHS, BOOTLID LAMP	1	MB45A-51-3J8	✓	\$ 20.90
40	GASKET RHS, BOOTLID LAMP	1	MB45A-51-3H8	✓	\$ 20.90
41	GASKET LHS, TAILLAMP	1	MBHN1-51-163	✓	\$ 20.90
42	GASKET RHS, TAILLAMP	1	MBHN1-51-153	✓	\$ 20.90
43	GUARD STONE LHS	1	MBHS2-50-4R2	✓	\$ 16.50
44	GUARD STONE RHS	1	MBHS2-50-4P2	✓	\$ 17.30
45	LAMP LHS, LICENCE PLATE	1	MB45A-51-2L0A	?	\$ 71.10
TOTAL PARTS					\$ 5,469.30
LESS 10%					\$ 546.93
TOTAL PARTS COST					\$ 4,922.37

Labour Description				
1	MZ-BR-REAR06	TO REPLACE REAR BUMPER, REAR END PANEL AND BOOTLID. TO REPAIR REAR FENDER LH, REAR FENDER RH, REAR FLOOR PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.	4290.	\$ 4,950.00
2		TO RESPRAY REAR BUMPER, REAR END PANEL, BOOTLID, REAR FLOOR PANEL, REAR FENDER LH AND REAR FENDER RH x5	3150.	\$ 3,780.00
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS. (WITH REVERSE SENSOR)	✓ NETT	\$ 660.00
4	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	X NETT	\$ 330.00
5	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.	X NETT	\$ 70.00
6	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	630.	\$ 990.00
7	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	180.	\$ 350.00
8	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	150	\$ 250.00
9	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
10	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180.	\$ 350.00
11		TO SUPPLY BRILA PREMIUM COATING. => sales agreement ?	X NETT	\$ 400.00
12	MZ-BR-TOW-IN	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP. ? invoice	NETT	\$ 120.00

13	MZ-BR-SUNDRI	SUNDRIES.	30	NETT *	\$ 100.00
				TOTAL LABOUR	\$ - \$ 12,600.00
				TOTAL PARTS	\$ - \$ 4,922.37
				TOTAL	\$ - \$ 17,522.37
				LESS EXCESS	\$ - \$ -
				TOTAL AFTER EXCESS	\$ - \$ -
				GST 7%	\$ - \$ -
				GRAND TOTAL	\$ - \$ -

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

Tanfir 9749549
"up"
Resurvey before paint.
12-13 days
sure lkkauto.com
13/3/19 @ 3:10pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: