



Case Details

Case Reference Number :

TAX/03/19/2032

Type of Repair : Accident Repair

Vehicle Registration Number :

SHC4973E

Company Type : SMRT Taxis

Pte Ltd

Estimation ID : EST-6023-ID

Assigned By : Taxi Claims

Manager Team

Insurance Company Name : AIG Asia Pacific

Insurance Pte Ltd

Accident Date and Time : 08/03/2019 12:25 AM

Vehicle Age(In Months) : 16

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor	
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	317.9
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 1	2	3.80	7.60	25.00	5.70	Replace	2	5.70
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 2	2	3.80	7.60	25.00	5.70	Replace	2	5.70
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 3	2	3.80	7.60	25.00	5.70	Replace	2	5.70
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.00	22.00	25.00	16.50	Replace	2	16.50
Total Spare Part Cost									33,650.07		Surveyor Total	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)	
Final Spare Part Cost									33,650.07		Final Sur Total	

SMRT Recommendation											Survey	
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.0
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	0	0
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	0	0
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	0	0
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	1	418.7
One Time Key In	Main			COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	0	0
One Time Key In	Main			PAD, RR BUMPER, CTR	3	2.20	6.60	25.00	4.95	Replace	3	4.95
One Time Key In	Main			ANTENNA, ELECTRICAL KEY	1	60.30	60.30	10.00	54.27	Replace	0	0
One Time Key In	Main			WIRE, LUGGAGE ROOM	1	143.50	143.50	10.00	129.15	Replace	0	0
One Time Key In	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	371.6
One Time Key In	Main			COVER, FR BUMPER LH	1	28.10	28.10	25.00	21.08	Replace	1	21.08
Total Spare Part Cost									33,650.07		Surveyor Total	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)	
Final Spare Part Cost									33,650.07		Final Sur Total	

SMRT Recommendation											Survey	
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)
One Time Key In	Main			COVER, FR BUMPER RH	1	28.10	28.10	25.00	21.08	Replace	0	0
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25
One Time Key In	Main			GRILLE SUB-ASSY	1	335.60	335.60	25.00	251.70	Replace	1	251.7
One Time Key In	Main			EMBLEM ASSY FRONT	1	87.10	87.10	25.00	65.32	Replace	1	65.32
One Time Key In	Main			GRILLE, RADIATOR	1	165.00	165.00	25.00	123.75	Replace	1	123.7
One Time Key In	Main			BRACKET, FR BUMPER	1	99.80	99.80	25.00	74.85	Replace	1	74.85
One Time Key In	Main			NUMBER PLATE	1	35.00	35.00	0.00	35.00	Replace	1	35.00
One Time Key In	Main			NUMBER PLATE FRAME	1	25.00	25.00	0.00	25.00	Replace	1	25.00
One Time Key In	Main			SEAL, HOOD TO FR END	1	24.40	24.40	25.00	18.30	Replace	1	18.30
One Time Key In	Main			SUPPORT, FR BUMPER LH	1	82.30	82.30	25.00	61.72	Replace	1	61.72
One Time Key In	Main			SUPPORT, FR BUMPER RH	1	76.90	76.90	25.00	57.68	Replace	0	0
One Time Key In	Main			ABSORBER, FR BUMPER	1	70.30	70.30	25.00	52.72	Replace	0	0
Total Spare Part Cost									33,650.07		Surveyor Total	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)	
Final Spare Part Cost									33,650.07		Final Sur Total	

SMRT Recommendation												Surveyor
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)
One Time Key In	Main			REINFORCEMENT FRONT UPPER	1	691.10	691.10	25.00	518.33	Replace	0	0
One Time Key In	Main			ABSORBER, FR BUMPER LOWER	1	117.00	117.00	25.00	87.75	Replace	0	0
One Time Key In	Main			REINFORCEMENT FRONT LOWER	1	238.50	238.50	25.00	178.88	Replace	0	0
One Time Key In	Main			EXTENSION SUBASSY, LH	1	116.30	116.30	25.00	87.22	Replace	0	0
One Time Key In	Main			EXTENSION SUBASSY, RH	1	116.30	116.30	25.00	87.22	Replace	0	0
One Time Key In	Main			LAMP ASSY, FOG, LH	1	910.20	910.20	10.00	819.18	Replace	1	819.1
One Time Key In	Main			LAMP ASSY, FOG, RH	1	910.20	910.20	10.00	819.18	Replace	0	0
One Time Key In	Main			COVER ASSY, ENGINE	1	180.10	180.10	25.00	135.07	Replace	0	0
One Time Key In	Main			HOOD SUB-ASSY	1	938.40	938.40	25.00	703.80	Replace	1	703.8
One Time Key In	Main			INSULATOR, HOOD	1	393.90	393.90	25.00	295.42	Replace	0	0
One Time Key In	Main			HINGE ASSY, HOOD, LH	1	57.00	57.00	25.00	42.75	Replace	1	42.75
One Time Key In	Main			HINGE ASSY, HOOD, RH	1	57.00	57.00	25.00	42.75	Replace	1	42.75
Total Spare Part Cost									33,650.07		Surveyor Total	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)	
Final Spare Part Cost									33,650.07		Final Sur Total	

SMRT Recommendation											Survey	
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)
One Time Key In	Main			LOCK ASSY, HOOD	1	131.10	131.10	25.00	98.32	Replace	1	98.32
One Time Key In	Main			CABLE ASSY, HOOD	1	53.20	53.20	25.00	39.90	Replace	0	0
One Time Key In	Main			MOULDING LH	1	83.30	83.30	25.00	62.47	Replace	0	0
One Time Key In	Main			MOULDING RH	1	83.30	83.30	25.00	62.47	Replace	0	0
One Time Key In	Main			WIPER GARNISH LOUVER SUB-ASSY	1	666.90	666.90	25.00	500.17	Replace	0	0
One Time Key In	Main			WIPER GARNISH LOUVER SUB-ASSY , CLIP	6	3.20	19.20	25.00	14.40	Replace	0	0
One Time Key In	Main			WIPER GARNISH SHIELD, COWL WATER , LH	1	18.90	18.90	25.00	14.17	Replace	0	0
One Time Key In	Main			WIPER GARNISH SHIELD, COWL WATER , RH	1	18.90	18.90	25.00	14.17	Replace	0	0
One Time Key In	Main			COVER SUB-ASSY, FRONT PILLAR , UPR LH	1	96.90	96.90	25.00	72.68	Replace	0	0
One Time Key In	Main			THERMISTOR ASSY	1	68.00	68.00	10.00	61.20	Replace	0	0
One Time Key In	Main			COVER, RADIATOR	1	227.80	227.80	25.00	170.85	Replace	0	0
One Time Key In	Main			SUPPORT S/A UPPER	1	364.90	364.90	25.00	273.67	Replace	0	0
Total Spare Part Cost									33,650.07		Surveyor Total	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)	
Final Spare Part Cost									33,650.07		Final Sur Total	

SMRT Recommendation											Survey	
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)
One Time Key In	Main			SUPPORT SUB-ASSY LOWER	1	397.40	397.40	25.00	298.05	Replace	0	0
One Time Key In	Main			SUPPORT S/A LH	1	237.00	237.00	25.00	177.75	Replace	0	0
One Time Key In	Main			SUPPORT S/A RH	1	237.00	237.00	25.00	177.75	Replace	0	0
One Time Key In	Main			BRACE, HOOD LOCK SUPPORT	1	76.20	76.20	25.00	57.15	Replace	0	0
One Time Key In	Main			SUPPORT, RADIATOR UPPER LH	1	76.70	76.70	25.00	57.53	Replace	0	0
One Time Key In	Main			SUPPORT, RADIATOR UPPER RH	1	76.70	76.70	25.00	57.53	Replace	0	0
One Time Key In	Main			UNIT, HEADLAMP , LH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	1	2,303
One Time Key In	Main			UNIT, HEADLAMP , RH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	0	0
One Time Key In	Main			COMPUTER SUBASSY, HEADLAMP, LH NO.1	1	486.40	486.40	10.00	437.76	Replace	0	0
One Time Key In	Main			HORN ASSY, HIGH	1	112.80	112.80	10.00	101.52	Replace	0	0
One Time Key In	Main			HORN ASSY, LOW	1	112.80	112.80	10.00	101.52	Replace	0	0
One Time Key In	Main			AIR CON CONDENSER ASSY	1	1,317.70	1,317.70	25.00	988.28	Replace	0	0
Total Spare Part Cost									33,650.07		Surveyor Total	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)	
Final Spare Part Cost									33,650.07		Final Sur Total	

SMRT Recommendation											Survey	
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)
One Time Key In	Main			TUBE & ACCESSORY	1	574.40	574.40	25.00	430.80	Replace	0	0
One Time Key In	Main			HOSE SUB-ASSY, DISCHARGE	1	337.10	337.10	25.00	252.83	Replace	0	0
One Time Key In	Main			COOLANT	1	12.30	12.30	0.00	12.30	Replace	0	0
One Time Key In	Main			GUIDE, RADIATOR AIR,	1	93.90	93.90	25.00	70.43	Replace	0	0
One Time Key In	Main			GUIDE, RADIATOR AIR , UPPER	1	44.70	44.70	25.00	33.53	Replace	0	0
One Time Key In	Main			GUIDE, RADIATOR AIR , LH	1	58.80	58.80	25.00	44.10	Replace	0	0
One Time Key In	Main			GUIDE, RADIATOR AIR , RH	1	54.60	54.60	25.00	40.95	Replace	0	0
One Time Key In	Main			RADIATOR ASSY	1	1,841.10	1,841.10	25.00	1,380.82	Replace	0	0
One Time Key In	Main			GROMMET (FOR RADIATOR LOWER SUPPORT)	2	12.70	25.40	25.00	19.05	Replace	0	0
One Time Key In	Main			CUSHION, (FOR RADIATOR UPPER SUPPORT)	2	9.80	19.60	25.00	14.70	Replace	0	0
One Time Key In	Main			FAN RADIATOR , LH	1	181.80	181.80	25.00	136.35	Replace	0	0
One Time Key In	Main			FAN RADIATOR , RH	1	233.00	233.00	25.00	174.75	Replace	0	0
Total Spare Part Cost									33,650.07	Surveyor Total		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		
Final Spare Part Cost									33,650.07	Final Sur Total		

SMRT Recommendation											Survey	
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)
One Time Key In	Main			FAN SHROUD RADIATOR	1	219.30	219.30	25.00	164.48	Replace	0	0
One Time Key In	Main			MOTOR, COOLING FAN , LH	1	543.50	543.50	10.00	489.15	Replace	0	0
One Time Key In	Main			MOTOR, COOLING FAN , RH	1	443.40	443.40	10.00	399.06	Replace	0	0
One Time Key In	Main			HOSE, RADIATOR , NO.1	1	42.60	42.60	25.00	31.95	Replace	0	0
One Time Key In	Main			HOSE, RADIATOR , NO.2	1	40.20	40.20	25.00	30.15	Replace	0	0
One Time Key In	Main			HOSE, WATER BYPASS , NO.1	1	37.40	37.40	25.00	28.05	Replace	0	0
One Time Key In	Main			HOSE, WATER BYPASS , NO.2	1	37.40	37.40	25.00	28.05	Replace	0	0
One Time Key In	Main			HOSE, WATER BYPASS , NO.3	1	20.10	20.10	25.00	15.08	Replace	0	0
One Time Key In	Main			HOSE, WATER BYPASS , NO.4	1	13.20	13.20	25.00	9.90	Replace	0	0
One Time Key In	Main			HOSE, WATER BYPASS , NO.8	1	37.90	37.90	25.00	28.42	Replace	0	0
One Time Key In	Main			PIPE, WATER BYPASS , NO.1	1	11.00	11.00	25.00	8.25	Replace	0	0
One Time Key In	Main			PIPE, WATER BYPASS , NO.2	1	11.00	11.00	25.00	8.25	Replace	0	0
Total Spare Part Cost									33,650.07		Surveyor Total	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)	
Final Spare Part Cost									33,650.07		Final Sur Total	

SMRT Recommendation											Survey	
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)
One Time Key In	Main			PIPE, WATER BYPASS, NO.3	1	56.40	56.40	25.00	42.30	Replace	0	0
One Time Key In	Main			INVERTER WATER PUMP ASSY	1	432.00	432.00	10.00	388.80	Replace	0	0
One Time Key In	Main			HOSE, HV WATER PUMP INLET	1	37.90	37.90	25.00	28.42	Replace	0	0
One Time Key In	Main			HOSE, HV WATER PUMP OUTLET	1	29.60	29.60	25.00	22.20	Replace	0	0
One Time Key In	Main			TANK ASSY, INVERTER RESERVE	1	371.30	371.30	25.00	278.48	Replace	0	0
One Time Key In	Main			HOSE, INVERTER COOLING INLET	1	43.10	43.10	25.00	32.33	Replace	0	0
One Time Key In	Main			HOSE, INVERTER COOLING OUTLET	1	29.60	29.60	25.00	22.20	Replace	0	0
One Time Key In	Main			HOSE, INVERTER RADIATOR INLET	1	40.70	40.70	25.00	30.53	Replace	0	0
One Time Key In	Main			COOLER, MOTOR COOLING	1	249.10	249.10	25.00	186.82	Replace	0	0
One Time Key In	Main			WIRE, ENGINE ROOM MAIN	1	6,138.00	6,138.00	10.00	5,524.20	Replace	0	0
One Time Key In	Main			BATTERY	1	1,584.90	1,584.90	10.00	1,426.41	Replace	0	0
One Time Key In	Main			CLAMP SUB-ASSY, BATTERY	1	41.40	41.40	25.00	31.05	Replace	0	0
Total Spare Part Cost									33,650.07		Surveyor Total	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)	
Final Spare Part Cost									33,650.07		Final Sur Total	

SMRT Recommendation											Survey	
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)
One Time Key In	Main			CLAMP, BATTERY, NO.2	1	43.30	43.30	25.00	32.47	Replace	0	0
One Time Key In	Main			COVER, FUSIBLE LINK	1	28.30	28.30	25.00	21.23	Replace	0	0
One Time Key In	Main			BLOCK ASSY, FUSIBLE LINK	1	99.80	99.80	10.00	89.82	Replace	0	0
One Time Key In	Main			TERMINAL ASSY, BATTERY POSITIVE (+)	1	48.00	48.00	10.00	43.20	Replace	0	0
One Time Key In	Main			BLOCK, JUNCTION	1	15.80	15.80	10.00	14.22	Replace	0	0
One Time Key In	Main			SENSOR ASSY, BATTERY STATE	1	256.80	256.80	10.00	231.12	Replace	0	0
One Time Key In	Main			INLET, AIR CLEANER, NO 1	1	130.50	130.50	25.00	97.88	Replace	0	0
One Time Key In	Main			INLET, AIR CLEANER, NO 2	1	93.90	93.90	25.00	70.43	Replace	0	0
One Time Key In	Main			INLET, AIR CLEANER, NO 3	1	35.30	35.30	25.00	26.47	Replace	0	0
One Time Key In	Main			CLAMP (FOR AIR CLEANER HOSE , NO.2)	1	9.00	9.00	25.00	6.75	Replace	0	0
One Time Key In	Main			CLAMP (FOR AIR CLEANER INLET , NO.1)	1	7.10	7.10	25.00	5.32	Replace	0	0
One Time Key In	Main			HOSE, AIR CLEANER , NO.1	1	62.10	62.10	25.00	46.58	Replace	0	0
Total Spare Part Cost									33,650.07		Surveyor Total	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)	
Final Spare Part Cost									33,650.07		Final Sur Total	

SMRT Recommendation												Surveyor
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)
One Time Key In	Main			RESONATOR, INTAKE AIR	1	14.90	14.90	25.00	11.18	Replace	0	0
One Time Key In	Main			BRACKET, AIR CLEANER	1	26.90	26.90	25.00	20.17	Replace	0	0
One Time Key In	Main			AIR CLEANER ASSY	1	956.20	956.20	25.00	717.15	Replace	0	0
One Time Key In	Main			TUBE, UNION (FOR AIR CLEANER HOSE)	1	19.40	19.40	25.00	14.55	Replace	0	0
One Time Key In	Main			FENDER SUB-ASSY, FR , LH	1	933.10	933.10	25.00	699.83	Replace	1	699.8
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.67	Replace	1	39.67
One Time Key In	Main			PROTECTOR, FR FENDER LH	1	90.40	90.40	25.00	67.80	Replace	0	0
One Time Key In	Main			SEAL SUB-ASSY, LH	1	50.20	50.20	25.00	37.65	Replace	0	0
One Time Key In	Main			LINER, FR FENDER, LH	1	194.30	194.30	25.00	145.73	Replace	0	0
One Time Key In	Main			PAD, FR WHEEL LH	1	57.70	57.70	25.00	43.28	Replace	0	0
One Time Key In	Main			APRON SUB-ASSY, FRONT FENDER , LH	1	944.20	944.20	25.00	708.15	Replace	0	0
One Time Key In	Main			PANEL SUB-ASSY, FRONT DOOR LH	1	1,249.60	1,249.60	25.00	937.20	Replace	1	0
Total Spare Part Cost									33,650.07	Surveyor Total		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		
Final Spare Part Cost									33,650.07	Final Sur Total		

SMRT Recommendation											Survey	
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00
One Time Key In	Main			CHECK ASSY, FRONT DOOR	1	153.50	153.50	25.00	115.13	Replace	0	0
One Time Key In	Main			HINGE ASSY, FRONT DOOR , UPPER LH	1	82.10	82.10	25.00	61.57	Replace	0	0
One Time Key In	Main			HINGE ASSY, FRONT DOOR , LOWER LH	1	92.10	92.10	25.00	69.07	Replace	0	0
One Time Key In	Main			FENDER SUB-ASSY, FR , RH	1	933.10	933.10	25.00	699.83	Replace	0	0
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.67	Replace	0	0
One Time Key In	Main			MEMBER SUB-ASSY, FR LH	1	1,959.50	1,959.50	25.00	1,469.63	Replace	1	0
Total Spare Part Cost									33,650.07		Surveyor Total	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)	
Final Spare Part Cost									33,650.07		Final Sur Total	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT PORTION	1,690.00	800	
2	Main	TO REPAIR REAR PORTION	338.00	300	
Total:			2,028.00	1,100.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO REPSRAY FRONT HOOD	378.00	200	
3	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	100	
4	Main	TO RESPRAY RADIATOR SUPPORT LOWER	180.00	0	
5	Main	TO RESPRAY FRONT FENDER RH	378.00	0	
6	Main	TO RESPRAY FRONT FENDER LH	378.00	200	
7	Main	TO RESPRAY APRON PANEL LH	180.00	0	
8	Main	TO RESPRAY FRT MEMBER,LH	180.00	100	
9	Main	TO RESPRAY REAR BUMPER	378.00	200	
10	Main	TO RESPRAY BUMPER BEAM	180.00	0	
Total:			2,790.00	1,000.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	100	
3	Main	TO TOP UP A/C GAS	120.00	80	
4	Main	TO ALIGN CHASSIS	350.00	100	
5	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	60	
6	Main	TO REMOVE AND REFIT WIRE HARDESS	250.00	60	
Total:			1,400.00	510.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
7	Main	TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	120.00	80	
8	Main	TO REPLACE SUNDRY PARTS	100.00	0	
9	Main	TO WASH AND VACUUM	60.00	0	
Total:			1,400.00	510.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	33,650.07	6,775.35
Total Labour Cost	2,028.00	1,100.00
Total Spray Painting	2,790.00	1,000.00
Other	1,400.00	510.00
Overall Total	39,868.07	9,385.35
Lump Sum Repair Option	☐	☐
Lump Sum Total	0.00	9,385.35
Surveyor Approved Amount		9,385.35
No of Repair Days*	16	10
Remarks	-	RESURVEY BEFORE PAINT / PART BY PART
Surveyor Name		Rasul
Signature		
		Save Clear

Estimator Assesment(\$)		Surveyor Assesment(\$)
Survey Date	11/03/2019	