



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving 1 2012 FERRARI CALIFORNIA 4.3L FERXXX
(EZ489C)

Date of Loss 17 February 2019

Time of Loss 10.05

Loss Description EZ489C (INSD) C/W SLW6622C (TP)

Comment

Workshop Details

Total Rebate Amount 206745

Nett Loss Amount \$173,255.00

Assigned Workshop LKK AUTO CONSULTANTS PTE LTD (OD)

Days of work
completion * 82



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# EZ489C

Registration State

SINGAPORE

Mileage

39098

Purchase Date

dd/mm/yyyy



Registration Date *

26/05/2012



Age of Vehicle

6

CATEGORY

POLICY INFORMATION

ASSESSMENT
INFORMATIONManufacturing
Year

2012

2012

Make

FERRARI
CALIFORNIA 4.3L

FERRARI

Model

FERXXX

CALIFORNIA 4.3L A

Driver Details

CATEGORY

FNOL INFORMATION

POST SURVEY
INFORMATION

Driver Name

SOH PUAY HWEE

Date of Birth

15 February 1972

dd/mm/yyyy



Age

47

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		
Type of Paint		
Chassis No	ZFFTJ65C000187858	ZFFTJ65C000187858
Engine No	186705	186705
Engine Capacity		4297
Sum Insured	0	0
Market Value	0	380000

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	
Education Qualification	Other	
Driving Experience	0	
Driver License #		
License Type		
License Issue Date		dd/mm/yyyy 
License Expiration Date		dd/mm/yyyy 
Address	4 JALAN SAYANG, 418625, Singapore	
Address type	Residential	

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Male	
Marital status	Married	
Identification #	S7205403B	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

14/03/2019



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

10000

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

245/35R20

Rear Tyre Size

285/35R20

Front left side

MICHELIN6mm

Rear left side

MICHELIN6mm

Front right side

MICHELIN6mm

Rear right side

MICHELIN6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes No

Part Supplied by AXA

Yes No



SERVICE REQUESTS

MESSAGES

CLAIMS

<< Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

	EDIT	SR NO	QUAN TTY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTRN	DISC COUNT	SALV AGEN	PART PRICE(Net)	ACTION (PARTS)	REMOVE
		1	1			COMPL AIR DUCT			Cracked	4240.44				4240.44	Reviewing	
		2	1			WATER RADIATOR			Bent	1995				1995	Reviewing	
		3	1			RH LOWER BRACKET			Bent	333				333	Reviewing	
		4	4			RUBBER BUSHING			Necessary	17.59				70.36	Reviewing	
		5	4			BUSHING			Necessary	11.51				46.04	Reviewing	
		6	1			COMPL ELECTRIC FAN ASSEMBLY			Cracked	3600.11				3600.11	Reviewing	
		7	1			RH BRAKE AIR INTAKE FASTENER			Serviceable	0	0	0	0	0	Deny	
		8	1			COMPL LH FRONT FENDER			Cracked	10949.71				10949.71	Reviewing	
		9	1			CPL RH FRONT MOOGUARD			Bent	11569.9				11569.9	Reviewing	

	EDIT	SR NO	QUAN TTY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC COUNT%	SALV AGEN	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		10	1			LOWER CROSS-MEMBER			Bent	2533.61				2533.61	Reviewing	
		11	1			COMPL FRONT BUMPER CROSS-MEMBER			Bent	2132.57				2132.57	Reviewing	
		12	1			RH FRONT CRASH BOX UPRIGHT			Bent	1064.12				1064.12	Reviewing	
		13	1			FRONT SECTION OF FRONT FLAT UNDERFLOOR			Cracked	634.55				634.55	Reviewing	
		14	51			SCREW			Necessary	2.81				143.31	Reviewing	
		15	1			CENTRAL SECTION OF FRONT FLAT UNDERFLOOR			Cracked	634.55				634.55	Reviewing	
		16	1			FRONT GRAVEL GUARD FOR RH FRONT WHEELHOUSE LH			Damaged	705.07				705.07	Reviewing	
		17	1			COMPLETE FRONT BUMPER			Deformed	15055.53				15055.53	Reviewing	
		18	1			FRONT SPOILER			Cracked	2190.03				2190.03	Reviewing	
		19	1			FRONT BUMPER GRILL			Bent	5610.07				5610.07	Reviewing	
		20	1			CAVALLINO RAMPANTE BADGE			Bent	196.03				196.03	Reviewing	
		21	2			NUT			Necessary	1.36				2.72	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTRN	DSC COUNTN	SALV AGEN	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		22	1			R.H BRAKE AIR INTAKE			Cracked	214.49				214.49	Reviewing	
		23	1			FRONT LICENE PLATE INSTALLATION			Bent	86.28				86.28	Reviewing	
		24	1			BRACKET			Bent	46.91				46.91	Reviewing	
		25	1			FRONT PARKING SENSOR CABLE			Cracked	310.29				310.29	Reviewing	
		26	1			SENSOR N/S			Serviceable	0	0	0	0	0	Deny	
		27	1			SENSOR O/S			Missing	472.01				472.01	Reviewing	
		28	2			CLEAR SILICONE RING			Necessary	24.35				48.7	Reviewing	
		29	2			PARKING SENSOR			Missing	517.21				1034.42	Reviewing	
		30	2			GASKET			Necessary	25.57				51.14	Reviewing	
		31	1			INNER RH SENSOR BRACKET			Necessary	96.29				96.29	Reviewing	
		32	1			INNER LH SENSOR BRACKET			Necessary	91.42				91.42	Reviewing	
		33	25			CLIP			Necessary	2.95				73.75	Reviewing	
		34	1			GASKET			Necessary	750.06				750.06	Reviewing	
		35	1			R.H. FRONT HEADLIGHT			Damaged	14720.53				14720.53	Reviewing	

	EDIT	SR NO	QUAN TTY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALY AGES	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		36	1			CENTRAL ENGINE COMPARTMENT COVER			Cracked	277.35				277.35	Reviewing	
		37	1			CLAMP			Necessary	6.41				6.41	Reviewing	
		38	1			CENTRE MOUNTING BRACKET FOR RADIATOR			Bent	436.03				436.03	Reviewing	
		39	1			L.H. COVER FOR ENGINE COMPARTMENT			Cracked	437.89				437.89	Reviewing	
		40	5			LPGLYCOSHELL CONCENTRATE - 550010571 1X2			Necessary	19.55				97.75	Reviewing	

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		20 DAYS LABOUR - TO DO WELDING, REMOVE AND REPLACE FRONT DAMAGE PARTS	28800	0	0	Reviewing		
		2		TO RESPRAY PAINT FOR FRONT BUMPER, BONNET, FENDERS AND INTERNAL STRUCTURES	6000	0	0	Reviewing		
		3		TOWING FEE, NUMBER PLATE, AC GAS TOP UP	188	0	0	Reviewing		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

AMOUNT

COMMENT

REMOVE



1

DAYS
OF
REPAIR
: 15
DAYS

Reviewing





SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount

\$107,947.44

Claim Amount

\$107,947.44

CATEGORY

ESTIMATE

REVISED AMOUNT

Spare Parts

\$82,959.44

\$82,959.44

Labour

\$34,988.00

\$34,988.00

Excess

-\$10,000.00

-\$10,000.00

Submit for Review