Premium Automobiles

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183

Reference : PA/OD/0312/2019/GW (NK)

Date : 9-Mar-19

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Goh Si Feng,Chester

Address : Blk 102 Bukit Purmei Road

: #03-24

Singapore 090102

Telephone:HP +65 97548907Type of Claim:Own Damage Claims

Policy No. : 2100507390-01

Vehicle No : SLM 9929 B

 Model Code
 : A3 Sedan 1.0 TFSI

 Model / Year
 : 19/4/2017

 Engine No
 : CHZ 330303

Chassis No : WAUZZZ8VXH1060923

Mileage :

Date In :

Liability : Excess Cost :

Estimated By : Johnny Boo / Allan Wu

Accident Date : 7-Mar-19

Place of Accident : Rochor Rd (Near Rochor Flyover)

Premium Automobiles 55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLM 9929 B

S/n	Nature of Jobs		 Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for healights, horns, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise front crash management components. Reinstall all parts removed.		\$ 2,100.00	1250
3	To respray front bumper and rhs front fender.		\$ 1,500.00	1100
4	To carry out diagnostic check.	S/N	\$ 192.00	
	TOTAL LABOUR CHARGES	:	\$ 4,152.00	

Premium Automobiles 55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLM 9929 B

S/N	Parts Description	<u>Damaged Parts & Prices</u> S/Nett Remark		
				*
1	FRONT BUMPER Jeld	\$	1,830.00 —	
2	FRONT BUMPER FIXING PARTS Ale	\$	170.00 🛩	•
3	FRONT BUMPER GUIDE SECTION-RH Mu	\$	ىد 35.00	
4	FRONT BUMPER GRILLE-CENTER MEL CALL	\$	146.00	•
5	FRONT BUMPER CLOSING ELEMENT-LOWER CENTER	\$	488.00 🗶	
6	FRONT BUMPER CLOSING ELEMENT-RH	\$	270.00	
7	FRONT BUMPER COVER TRIM-RH	\$	148.00	•
8	FRONT ADAPTER WHEEL HOUSING LINER-RH	\$	34.00 	_
9	FRONT BUMPER AIR GUIDE GRILLE-RH	\$	171.00	
10	FRONT BUMPER REINFORCEMENT BEAM ?	\$	660.00 ?	
11	FOAM FILLER PIECE	\$	172.00 7	
12 ′	FRONT BUMPER COVER	\$	111.00 🛩	
13	FRONT BUMPER REINFORCEMENT BEAM COVER Run	\$	111.00 🗶	
. 14	FRONT FENDER-RH Dented	\$	778.00	
15	FRONT FENDER ATTACHMENT PARTS-RH ?	\$	65.00	
16	FRONT FENDER BRACKET-RH	\$	35.00 +	
17	FRONT FENDER BRACE-RH ALL A	\$	88.00 X	
18	FRONT WHEEL HOUSING LINER-RH	\$	158.00 +	
19	WHEEL HOUSING LINER ATTACHMENT PARTS-RH ALL n	\$	81.00 *.	
20	LED HEALIGHT-RH	\$	5,029.00	
	SUB-TOTAL SPARE PARTS CHARGES :	\$	10,580.00	

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLM 9929 B

			Damaged Parts & Prices		
Parts Description				S/Nett	Remark
	_			7	
LED HEALIGHT LIFT CYLINDER-RH			\$	128.00	
SUNDRIES 🏋			\$	500.00	•
TOTAL SPARE PARTS CHARGES		:	\$	11,208.00	
TOTAL LABOUR CHARGES		:	\$	4,152.00	
GRAND TOTAL		:	\$	15,360.00	
	LED HEALIGHT LIFT CYLINDER-RH SUNDRIES TOTAL SPARE PARTS CHARGES TOTAL LABOUR CHARGES	LED HEALIGHT LIFT CYLINDER-RH SUNDRIES TOTAL SPARE PARTS CHARGES TOTAL LABOUR CHARGES	LED HEALIGHT LIFT CYLINDER-RH SUNDRIES TOTAL SPARE PARTS CHARGES : TOTAL LABOUR CHARGES :	LED HEALIGHT LIFT CYLINDER-RH SUNDRIES TOTAL SPARE PARTS CHARGES TOTAL LABOUR CHARGES S **S **TOTAL LABOUR CHARGES **S **TOTAL LABOUR CHARGES **S **TOTAL LABOUR CHARGES **TOTAL LABOUR CHARGES **TOTAL LABOUR CHARGES	Parts Description LED HEALIGHT LIFT CYLINDER-RH SUNDRIES SUNDRIES TOTAL SPARE PARTS CHARGES TOTAL LABOUR CHARGES S/Nett 7 \$ 128.00 7 \$ 500.00 1 11,208.00 TOTAL LABOUR CHARGES S 4,152.00

Legend:

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Not Authorised, 04 Days

LKK Auto Consultants hence notify the Repairer of the following:

· To resurvey before/after spray painting • To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• No illegal modification(s) is allowed

Acknowledged by Repairer

Signature: Date:

• Third party survey is on a "Without Prejudice" basis

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Please Note

This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully. Premium Automobiles Pte Ltd

Johnny Boo **Body Repair Manager** Allan Wu Claims Consultant