



CYCLE & CARRIAGE

CYCLE & CARRIAGE FRANCE PTE. LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240



CITROËN

Company Reg No. 200609327M
GST Reg No. MR-8500111-X

ESTIMATE

Invoice Name & Address		Owner Name & Vehicle Info	
Mr Lim Hock Guan		Cust No/Name	/Mr Lim Hock Guan
14 Lor Pisang Emas		Reg No/Reg Date	SLL4835B / 28/02/2017
Singapore 597831		Date In/Mileage	/ 0
		Chassis No	VF73ABHZTGJ806555
		Engine No	10JBHD3064841
Contact No Mobile: 98711463		Make/Model	CIT/GC4P 1.6 BLUEHDI EAT6 INTENSIVE ML
		Colour/Trim	PYM ROUGE RUBI / IXF YATAGO GREY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	12/03/2019/ 11:11	TLC	442 / CocoLu	14192

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPAIR FRT BUMPER, FRT FENDER RH				✓ 600.00
E PNT98000 SPRAY PAINT FOR FRT BUMPER, FRT FENDER RH				420 700.00
A 54900099 CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM				✓ 300.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				✓ 50.00
M SUNDRY Sundry				✓ 20.00
M BUMPER MOULDING	1.00	196.00	0.00	cat 196.00
M BUMPER MOULDING	1.00	214.00	0.00	cat 214.00
M HEADLIGHT ASSY RH	1.00	582.00	0.00	? 582.00

Estimate

SURVEYOR NAME: Tayfun 97495949

SURVEYOR SIGNATURE: Tayfun

DATE: 4/4/19 @ 1230

REMARKS: Resing after repair
surv 1 h h auto con
0.3 days

LKK Auto Consultants hence notify

the Repairer of the following:

Confirm & accepted by:

- To resolve before/after spray painting
- To display damaged parts during repair
- Parts prices are subject to change
- Third party surveyor's advice
- No illegal modification

Authorized signatory and company stamp

Parts	992.00
Labour	1,650.00
Standard Menu	0.00
Specialist Job	0.00
Diagnostics Job	0.00
Sundry/Others	20.00
Total (w/o GST)	2,662.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you to be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.