

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5808T**AAD1903-061***Not Authorized
C/Smp B18501*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC 5808T

VF1ABL15AUC282209

RENAULT

LATITUDE

10.3.2019

AIG

3/8/2015

PART**LIST**

- | | |
|----|------------------------------------|
| 1 | 1 BUMPER COVER REAR |
| 2 | 1 BUMPER LOWER REAR |
| 3 | 1 BUMPER BRACKET CTR REAR |
| 4 | 1 BUMPR BRACKET SIDE RH REAR |
| 5 | 1 BUMPR RETAINER RH REAR |
| 6 | 1 BUMPER REFLECTOR RH |
| 7 | 1 BUMPR BRACKET SIDE LH REAR |
| 8 | 1 BUMPER RETAINER LH REAR |
| 9 | 1 BUMPER REFLECTOR LH |
| 10 | 1 BUMPER BEAM REAR |
| 11 | 1 BUMPER BEAM BRACKET LH REAR |
| 12 | 1 BUMPER BEAM BRACKET RH REAR |
| 13 | 1 OUTER PANEL REAR (End Panel) |
| 14 | 1 OUTER PANEL REAR (End Panel)TRIM |
| 15 | 1 BOOT REAR |
| 16 | 1 TAILLAMP RH |
| 17 | 1 TAILLAMP PANEL RH |
| 18 | 1 TAILLAMP LH |
| 19 | 1 TAILLAMP PANEL LH |

\$	<i>Buckley</i> 1,108.46	✓
\$	<i>Nelson</i> 768.84	✓
\$	<i>SL</i> 113.47	} X
\$	<i>SL</i> 135.97	
\$	<i>SL</i> 44.99	
\$	<i>SL</i> 43.61	
\$	<i>SL</i> 135.97	
\$	<i>SL</i> 44.99	
\$	<i>SL</i> 43.61	
\$	<i>N</i> 777.52	
\$	<i>N</i> 225.95	
\$	<i>N</i> 225.95	
\$	<i>N</i> 1,471.77	
\$	<i>SL</i> 404.56	
\$	<i>N</i> 2,872.68	
\$	<i>SL</i> 552.55	
\$	<i>N</i> 986.70	
\$	<i>SL</i> 552.55	
\$	<i>N</i> 986.70	

\$ **11,496.85**10% \$ **1,149.69**\$ **10,347.17****Specical Nett**

- | | |
|---|------------------------------|
| 1 | 1SET PARKING AID |
| 2 | 1SET REAR BUMPER CLIP |
| 3 | 1SET BUMPER BRACKET CTR CLIP |

\$	<i>SL</i> 700.00	X
\$	<i>N</i> 66.00	✓
\$	<i>N</i> 33.00	✓

Trans-cab Auto Services Pte Ltd**AAD1903-061**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5808T

4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na	66.00	
10	1 EXHAUST MOUNTING REAR	\$	Sh	17.82	} X
11	2 REAR WINDSCREEN SELANT	\$	na	80.00	
12	1 WINDSCREEN MOULDING	\$	na	100.00	
13	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
14	1 REAR BOOT STICKER 'Trans-cab'	\$	na	80.00	
15	1 REAR BOOT STICKER '6555-3333'	\$	na	80.00	
TOTAL		\$		605.82	
TOTAL PARTS		\$		10,952.99	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	2201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	2001
To Rust-Proofing Of The Affected Areas.	\$	na	170.00 X
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	na	170.00 X
To repair and realign rear exhaust pipe.	\$	na	170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na	170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	na	170.00 X

Trans-cab Auto Services Pte Ltd**AAD1903-061**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5808T

To transfer of rear windscreen fittings and conduct
water seepage test.

\$ *na* 170.00 *X*

To check steering geometry and computer wheel
alignment

\$ *na* 220.00 *X***TOTAL \$ 7,410.00****Over All Total \$ 28,710.15****(LUMP SUM)****Repair Days***10 DAYS*
2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: