

ASS. REC. BY:

REF: (S/INC 19004571 R1+d362

Special Instruction:

Surveyor: Rasul

ASSIGNMENT (Office)

From (Person): Daniel Koh

of

INCDate/Time: 13/3/19 09:22am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV/CS

To Inspect Vehicle No:

SL 507A

Insured:

SIQ 1078L

at Workshop m/s:

Bp Auto

Tel:

6266 0555

of

48 Joh Guan Rd East #01-121

Policy No:

Claim No:

MT-1035579-001

Sum Insured:

Excess:

Make of Veh:

D.O.A.

913/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:37am 13/3/19

Person Contacted:

Yunne

Vehicle:

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SL 507A - NA / INC 19004501 / 24

D.O.A - 09/03/2019

SIQ 1078L - NA / INC 19004501 / 24

D.O.A - 09/03/2019

lump sum 9150 finalize with Rasul k workshop
(Red: 5235.18, 36%)

Surveyor *Form*

REF: INC

0308C


(OPC)

ASSIGNMENT

From: _____ Date: 13/3/19
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SLL 507A
 at Workshop m/s BP Auto
 of 18-ton Guan Rd East #01-121
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 50K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLL 507A Yr Regn: 2011 / PAB
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Hyundai ELANTRA 1-6 c.c. 1591
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp.Reading: 6293 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: KMH0841CMH2333029

Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Kumho

Front		Rear
R/Bal. <u>6</u> mm		R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm		L/Bal. <u>6</u> mm
D.O.A. <u>07/03/19</u>		D.O.I. <u>13/03/19 0356pm</u>

Survey held at BP Auto
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>50K</u>
	<u>MV 46K</u>
	<u>LTA 38.5K</u>
	<u>HL 11K</u>
	<u>Repair limit 11K</u>
	RECEIVED 30 MAY 2019

Date/Time, File Pass to? ☐ : Preli. Report

1) 2015 Typist ☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 13

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

☐ S + RS, ☐ SI

☐ Photos

☐ Others

☐

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) 91501

290

290

Nivitha (LKK Auto)

From: Daniel Koh <daniel.koh@income.com.sg>
Sent: Wednesday, 13 March 2019 9:22 AM
To: 'assignments@lkkauto.com'
Cc: Toh Choon Hin; Thio Tse Kiat
Subject: FW: TP CASES FARMED OUT TO LKK ON 13/3/2019

Dear Veron / Nivitha

Please assist to survey the vehicles as per Mr Toh's instruction :-

S/NO	THIRD PARTY	OUR INSURED	WORKSHOP / CONTACT	DOA / REF / OFFICER
1	GBC7565B	YM5368S	SIN SHENG ENGINEERING / Susan 68639595	26-2-2019 / MT-1034078-002 / Jared Liu
2	SLL507A	SJQ1078L	BP AUTO / Yvonne 62660555	9-3-2019 / MT-1035579-001 / Eric Tang

Please contact workshops.

Please ack.

Thank You

Daniel Koh
Senior Admin Assistant, Motor Insurance
T +65 6430 7901
www.income.com.sg



Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the

recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/03/2019 14:52
Date Of Accident	09/03/2019 14:00
Exact Location Of Accident	CHOA CHU KANG RD TWDS BUKIT BATOK ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL507A
Insured/Policyholder	
Name Of Registered Owner	SAYZWANI ABDULLAH SIM @ SIM GUAN CHOON
NRIC No	S1250308C
Email Address	SUAZWANI.SIM03@YAHOO.COM
Mobile Phone No	(LOCAL) +65-98165824
Alternative Phone No	OFFICE-60000000

Vehicle Particulars

Manufacturer	HYUNDAI
Model	ELANTRA-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00597378
Cover Note Number	

Driver

Name of Driver	SAYZWANI ABDULLAH SIM @ SIM GUAN CHOON
NRIC No	S1250308C
Date Of Birth	03/12/1957
Occupation	INDOOR
Date Of Driving Pass	05/01/1987
Driving Experience	32 YEARS AND 2 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98165824
Fax Number	
Contact Number	OFFICE-60000000
Email Address	SUAZWANI.SIM03@YAHOO.COM

Address	475D UPPER SERANGOON CRESCENT #09-561
Postcode	537457
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : SELAMAT MOHD MED NOOR GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Report please refer to Sketch Plan

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJQ1078L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHEN RUIQUAN
NRIC/Passport Number	S8303883G
Contact Number	87762249
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mailed packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: 
NRIC/FIN No.: 87131809C

Sketch Plan #2

SKETCH PLAN

CHUA
CHU
KANG
ROAD



BUKIT
BATOK
ROAD

A - SLL 507 A
B - SLD 1078 L

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS DRIVING ALONG CHUA CHU KANG ROAD TOWARD BUKIT BATOK ROAD ON THE 2ND LANE OF A 3 LANE ROAD. VEHICLE IN FRONT OF ME SLOWED DOWN AND STOPPED DUE TO THE HEAVY TRAFFIC FLOW. AS SUCH, I ALSO APPLIED BRAKE AND MANAGE TO STOPPED COMPLETELY. OUT OF A SUDDEN, I FELT A STRONG IMPACT FROM THE REAR PORTION OF MY VEHICLE. AFTER THE ACCIDENT, I ALIGHTED AND REALISE THAT VEHICLE (B) DROVE FROM THE REAR AND COLLIDED DIRECTLY ONTO THE REAR PORTION OF MY VEHICLE.

A - SLL 507 A
B - SLD 1078 L

DECLARATION

(We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: *Renee 5731809E*

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0308C
Vehicle Details	
Vehicle No.:	SLL507A
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Mar 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	ELANTRA AD 1.6 GLS AT
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	G4FGGU014773
Chassis No.:	KMHD841CMHU333029
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$18,224.00
Original Registration Date:	11 Feb 2017
First Registration Date:	11 Feb 2017
Transfer Count:	0
Actual ARF Paid:	\$18,224.00
OPC Cash Rebate Details	
OPC Cash Rebate Eligibility:	No
OPC Cash Rebate Eligibility Expiry Date:	-
OPC Cash Rebate Amount:	-
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Feb 2027
PARF Rebate Amount:	\$13,668.00
Intended COE Rebate Details	
COE Expiry Date:	10 Feb 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$31,401.00
COE Rebate Amount:	\$24,834.00
Total Rebate Amount:	\$38,502.00

The information contained herein is correct as at 14 Mar 2019

OK

63k
 64k
 - 13.6k

 50k

BP Auto
(UEN No. 53378133K)
48 Toh Guan Road Esat #01-121
Enterprise Hub S(608586)
Tel: 6266 0555 Fax : 6266 3155

TO : NTUC INCOME INSURANCE	DATE : 12-Mar-19
ATTENTION : MOTOR CLAIMS DEPARTMENT	JOB TYPE : T/P CLAIMS
ESTIMATE REPORT :	
OWNER PARTICULAR	
NAME :	VEHICLE DETAILS
ADDRESS :	VEHICLE NO. : SLL507A
TEL. NO. :	MODEL / MAKE : HYUNDAI ELANTRA
OWNER INSURANCE : DIRECT ASIA	CHASSIS NO. : KMHD841CMHU333029
POLICY NO. : MT/00597378	ACCIDENT DETAIL
PERSON INCHARGE :	DATE : 9-Mar-19
	TIME : 14:00hrs

QUOTATION SUMMARY PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE	
1	REAR BOOT LID <i>PA</i>	1	\$ 1,690.67	\$ 1,690.67	1620
2	REAR BOOT LID LOGO EMBLEM <i>new</i>	1	\$ 82.14	\$ 82.14	50
3	REAR BOOT LID ELITE EMBLEM <i>new</i>	1	\$ 65.32	\$ 65.32	50
4	REAR BOOT LID ELANTRA EMBLEM <i>new</i>	1	\$ 78.42	\$ 78.42	68
5	REAR BOOT LID REFLECTOR LED LAMP LH <i>SCR</i>	1	\$ 664.90	\$ 664.90	
6	REAR BOOT LID OUTER LOCK HANDLE SWITCH WITH REVERSE CAMERA <i>X</i>	1	\$ 652.07	\$ 652.07	SVL
7	REAR BOOT LID NUMBER PLATE LAMP LH <i>X</i>	1	\$ 55.65	\$ 55.65	SVL
8	REAR BOOT LID HINGES LH/RH <i>X</i>	2	\$ 145.42	\$ 290.84	SVL
9	REAR BOOT LID INNER UPHOLSTERY TRIM <i>X</i>	1	\$ 358.31	\$ 358.31	SVL
10	REAR BOOT LID INNER HANDLE <i>X</i>	1	\$ 112.10	\$ 112.10	SVL
11	REAR BOOT LID RUBBER GUIDE STOPPER LH/RH <i>new</i>	2	\$ 40.29	\$ 80.58	
12	REAR BOOT LID MECHANISM LOCK <i>X</i>	1	\$ 208.70	\$ 208.70	SVL
13	REAR BOOT LID WEATHER STRIP <i>new</i>	1	\$ 92.50	\$ 92.50	
14	REAR BUMPER <i>new</i>	1	\$ 489.24	\$ 489.24	
15	REAR BUMPER REFLECTOR LH <i>new</i>	1	\$ 31.90	\$ 31.90	
16	REAR BUMPER SIDE RETAINER LH/RH <i>LH-new RH-X</i>	1 pc	\$ 44.30	\$ 44.30	44.30
17	REAR BUMPER INNER SIDE SHIELD RH <i>X</i>	1	\$ 145.65	\$ 145.65	SVL
18	REAR BUMPER LOWER UNDER COVER LH <i>X</i>	1	\$ 151.32	\$ 151.32	SVL
19	REAR BUMPER TOP BRACKET LH/RH <i>LH-new/RH-X</i>	2	\$ 25.71	\$ 51.42	25.71
20	REAR BUMPER REINFORCEMENT <i>PA</i>	1	\$ 548.42	\$ 548.42	328
21	REAR BUMPER INNER BOOT LID ANTENA SENSOR <i>X</i>	1	\$ 325.61	\$ 325.61	SVL
22	REAR BUMPER MADFLAP LH <i>SCR</i>	1	\$ 62.30	\$ 62.30	
23	REAR BUMPER INNER BOOT LID ANTENA SENSOR WIRE HARNESS <i>3 cut</i>	1	\$ 198.27	\$ 198.27	100
24	REAR TAILLAMP LED LH <i>CRA</i>	1	\$ 876.90	\$ 876.90	
25	REAR TAILLAMP INNER PANEL LH <i>new PA</i>	1	\$ 358.78	\$ 358.78	250
26	REAR END PANEL <i>PA</i>	1	\$ 480.72	\$ 480.72	
27	REAR END PANEL INNER TOP GARNISH <i>CRA</i>	1	\$ 159.80	\$ 159.80	105

5420.05

8215.95
20th
6572.76

2795.90

QUOTATION SUMMARY

PAGE 02

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE	
28	REAR END PANEL INNER BOOT LID ANTENA SENSOR X	1	\$ 325.61	\$ 325.61	SN
29	REAR END PANEL LOCK STRIKER X	1	\$ 43.70	\$ 43.70	SN
30	SPARE TYRE PANEL repair <i>One</i> /	1	\$ 789.48	\$ 789.48	775
31	SPARE TYRE PANEL INNER TOP UPHOLSTERY BOARD X	1	\$ 219.10	\$ 219.10	SN
32	SPARE TYRE RETAINER LOCK X <i>re</i> /	1	\$ 10.90	\$ 10.90	
33	SPARE TYRE SIDE PANEL LH repair <i>re</i> /	1	\$ 245.62	\$ 245.62	800
34	REAR SUB CHASSIS FRAME TOP PANEL LH repair <i>re</i> /	1	\$ 813.14	\$ 813.14	8
35	REAR FENDER LH repair <i>re</i> /	1	\$ 1,769.12	\$ 1,769.12	1560
36	REAR FENDER INNER UPHOLSTERY TRIM LH <i>cut</i> /	1	\$ 207.90	\$ 207.90	
37	REAR FENDER INNER SHIELD LH X <i>re</i> /	1	\$ 112.30	\$ 112.30	
38	REAR FENDER STONE PROTECTIVE STICKER LH X <i>re</i> /	1	\$ 27.02	\$ 27.02	WN
39	REAR WINDSCREEN MOULDING X <i>re</i> /	1	\$ 129.80	\$ 129.80	
* BLIND SPOT DETECTION SENSOR - <i>CRA</i>				TOTAL PRICE	\$ 13,095.72 \$9,050.37
* BLIND SPOT DETECTION SENSOR BRACKET <i>re</i> /				LESS -20%	\$ (2,619.14) \$(1,810.07)
* BLIND SPOT DETECTION SENSOR WIRE HARNESS re <i>cut</i> /				SUB TOTAL PRICE	\$ 10,476.58 \$7,240.30
* BLIND SPOT DETECTION SENSOR ABSORBER <i>re</i> /					

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BOOT LID REFLECTOR CLIPS SET LH/RH <i>re</i> /	1pc 2	\$ 10.00	\$ 10 20.00
2	REAR BOOT LID INNER UPHOLSTERY TRIM CLIPS SET <i>re</i> /	1	\$ 50.00	\$ 50.00
3	REAR BOOT LID NUMBER PLATE WITH CASING re <i>re</i> /	1	\$ 50.00	\$ 35 50.00
4	REAR BOOT LID NUMBER PLATE WEEK END SEAL <i>re</i> /	1	\$ 50.00	\$ 50.00
5	REAR BOOT LID SEALANT <i>re</i> /	1	\$ 60.00	\$ 40 60.00
6	REAR BUMPER REVERSE SENSOR SET <i>re</i> /	1	\$ 280.00	\$ 220 280.00
7	REAR BUMPER CLIPS SET <i>re</i> /	1	\$ 60.00	\$ 40 60.00
8	REAR TAILLAMP CLIPS SET LH/RH <i>re</i> / re <i>re</i> /	1pc 2	\$ 20.00	\$ 40.00
9	REAR TAILLAMP INNER PANEL SEALANT LH re <i>re</i> /	1	\$ 30.00	\$ 30.00
10	REAR END PANEL INNER TOP GARNISH CLIPS SET <i>re</i> /	1	\$ 30.00	\$ 30.00
11	REAR END PANEL SEALANT <i>re</i> /	1	\$ 80.00	\$ 40 80.00
12	SPARE TYRE PANEL SEALANT <i>re</i> /	1	\$ 100.00	\$ 60 100.00
13	REAR FENDER SEALANT LH <i>re</i> /	1	\$ 100.00	\$ 100.00
14	REAR FENDER INNER UPHOLSTERY TRIM CLIPS SET LH <i>re</i> /	1	\$ 50.00	\$ 30 50.00
15	REAR FENDER INNER SHIELD CLIPS SET LH <i>re</i> /	1	\$ 40.00	\$ 20 40.00
16	REAR WINDSCREEN SEALANT WITH PRIMER <i>re</i> /	1	\$ 120.00	\$ 40 120.00

TOTAL

\$ 1,160.00 \$815.00

QUOTATION SUMMARY

PAGE 03

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 1,800.00	1200 1400	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 1,400.00	1000	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 160.00	100	
TO PERFORM LIGHTING & WIRING CHECK	\$ 90.00	40 60	
TO CALIBRATE CHASSIS & CAR BODY BACK TO MANUFACTURING SPECIFICATION	\$ 380.00	100 photo? X no photo	
TO DISMANTLE & REINSTALL REAR PETROL TANK FOR FACILITATE REPAIR	\$ 250.00	80 X	
TO DISMANTLE & REINSTALL REAR WINDSCREEN PERFORM	\$ 150.00	120	
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE COMPONENT TO PERFORM FACILITATE REPAIRS	\$ 260.00	X	
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	\$ 80.00	60	
TO DISMANTLE & REPLACED REAR BOOT LID REVERSE CAMERA WITH SETTING	\$ 80.00	40	
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 280.00	60	
TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 80.00	30	

TOTAL

\$ 5,010.00 \$2,870.00

QUOTATION SUMMARY

PAGE 05

ESTIMATE REPORT

TOTAL PARTS COST	:	\$	11,636.58
TOTAL LABOUR COST	:	\$	5,010.00
TOTAL REPAIR COST	:	\$	16,646.58

APPROVED DETAILS

EXCESS :
 NO. OF REPAIR DAYS : 13 days
 RE-SURVEY :
 P/P OR L/S : P/P

DATE / TIME OF SURVEY : 13/03/15 @ 1620
 SURVEYED BY / FROM : RASHUK (LKK)
 CONTACT NUMBER : 90010068
 FAX NUMBER :
 EMAIL ADDRESS : Remy b8 paul

Parts	\$	9,050.37
Supplementary	\$	2,162.80
	\$	11,213.17
Less 25%	\$	2,242.63
	\$	8,970.54
SN	\$	815.00
	\$	9,785.54
Labour	\$	2,870.00
	\$	12,655.54

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

6572.76

815.00

2870.00

10,257.76

20%

8,206.20

45-8,200

13 days

BP Auto
(UEN No. 53378133K)
48 Toh Guan Road Esat #01-121
Enterprise Hub S(608586)
Tel: 6266 0555 Fax : 6266 3155

TO : NTUC INCOME INSURANCE	DATE : 12-Mar-19
ATTENTION : MOTOR CLAIMS DEPARTMENT	JOB TYPE : T/P CLAIMS
ESTIMATE REPORT :	
<u>OWNER PARTICULAR</u>	
NAME :	<u>VEHICLE DETAILS</u>
ADDRESS :	VEHICLE NO. : SLL507A
TEL. NO. :	MODEL / MAKE : HYUNDAI ELANTRA
OWNER INSURANCE : DIRECT ASIA	CHASSIS NO. : KMHD841CMHU333029
POLICY NO. : MT/00597378	<u>ACCIDENT DETAIL</u>
PERSON INCHARGE :	DATE : 9-Mar-19
	TIME : 14:00hrs

QUOTATION SUMMARY

PAGE 01

CLAIMS DETAIL : PARTS LIST

SUPPLEMENTARY ITEMS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BLIND SPOT DETECTION SENSOR LH	1	\$ 1,660.10	\$ 1,660.10
2	REAR BLIND SPOT DETECTION SENSOR BRACKET LH	1	\$ 186.20	\$ 186.20
3	REAR BLIND SPOT DETECTION SENSOR WIRE HARNESS LH	1	\$ 219.40	\$ 219.40
4	REAR BLIND SPOT DETECTION SENSOR ABSORBER LH	1	\$ 97.10	\$ 97.10
TOTAL PRICE				\$ 2,162.80
LESS -20%				\$ (432.56)
SUB TOTAL PRICE				\$ 1,730.24

APPROVED DETAILS

DATE / TIME OF RESURVEY :
SURVEYED BY / FROM :
CONTACT NUMBER :
FAX NUMBER :
EMAIL ADDRESS :

P - 6572.76
S/N - 815.00
L - 2870.00
Suppl - 1189.60
T - 11,447.36
20%
9157.88
L/S - 9,150

(comes with complete set)

13 days

BP Auto
(UEN No. 53378133K)
48 Toh Guan Road Esat #01-121
Enterprise Hub S(608586)
Tel: 6266 0555 Fax : 6266 3155

TO : NTUC INCOME INSURANCE ATTENTION : MOTOR CLAIMS DEPARTMENT ESTIMATE REPORT : OWNER PARTICULAR NAME : ADDRESS : TEL. NO. : OWNER INSURANCE : DIRECT ASIA POLICY NO. : MT/00597378 PERSON INCHARGE :	DATE : 12-Mar-19 JOB TYPE : T/P CLAIMS VEHICLE DETAILS VEHICLE NO. : SLL507A MODEL / MAKE : HYUNDAI ELANTRA CHASSIS NO. : KMHD841CMHU333029 ACCIDENT DETAIL DATE : 9-Mar-19 TIME : 14:00hrs
---	--

QUOTATION SUMMARY **PAGE 01**
CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BOOT LID <i>PA</i>	1	\$ 1,690.67	\$ 1,690.67
2	REAR BOOT LID LOGO EMBLEM <i>ne</i>	1	\$ 82.14	\$ 82.14
3	REAR BOOT LID ELITE EMBLEM <i>ne</i>	1	\$ 65.32	\$ 65.32
4	REAR BOOT LID ELANTRA EMBLEM <i>ne</i>	1	\$ 78.42	\$ 78.42
5	REAR BOOT LID REFLECTOR LED LAMP LH <i>sc</i>	1	\$ 664.90	\$ 664.90
6	REAR BOOT LID OUTER LOCK HANDLE SWITCH WITH REVERSE CAMERA <i>X su</i>	1	\$ 652.97	\$ 652.97
7	REAR BOOT LID NUMBER PLATE LAMP LH <i>X su</i>	1	\$ 55.65	\$ 55.65
8	REAR BOOT LID HINGES LH/RH <i>X su</i>	2	\$ 145.42	\$ 290.84
9	REAR BOOT LID INNER UPHOLSTERY TRIM <i>X su</i>	1	\$ 358.31	\$ 358.31
10	REAR BOOT LID INNER HANDLE <i>X su</i>	1	\$ 112.10	\$ 112.10
11	REAR BOOT LID RUBBER GUIDE STOPPER LH/RH <i>ne</i>	2	\$ 40.29	\$ 80.58
12	REAR BOOT LID MECHANISM LOCK <i>X su</i>	1	\$ 208.70	\$ 208.70
13	REAR BOOT LID WEATHER STRIP <i>ne</i>	1	\$ 92.50	\$ 92.50
14	REAR BUMPER <i>tu</i>	1	\$ 489.24	\$ 489.24
15	REAR BUMPER REFLECTOR LH <i>pro</i>	1	\$ 31.90	\$ 31.90
16	REAR BUMPER SIDE RETAINER LH/RH <i>LH-ne, RH-X</i>	1	\$ 44.30	\$ 88.60
17	REAR BUMPER INNER SIDE SHIELD RH <i>X su</i>	1	\$ 145.65	\$ 145.65
18	REAR BUMPER LOWER UNDER COVER LH <i>X su</i>	1	\$ 151.32	\$ 151.32
19	REAR BUMPER TOP BRACKET LH/RH <i>LH-ne/RH-X su</i>	2	\$ 25.71	\$ 51.42
20	REAR BUMPER REINFORCEMENT <i>PA</i>	1	\$ 548.42	\$ 548.42
21	REAR BUMPER INNER BOOT LID ANTENA SENSOR <i>X su</i>	1	\$ 325.61	\$ 325.61
22	REAR BUMPER MADFLAP LH <i>X su</i>	1	\$ 62.30	\$ 62.30
23	REAR BUMPER INNER BOOT LID ANTENA SENSOR WIRE HARNESS <i>scut</i>	1	\$ 198.27	\$ 198.27
24	REAR TAILLAMP LED LH <i>CR</i>	1	\$ 876.90	\$ 876.90
25	REAR TAILLAMP INNER PANEL LH <i>re fepet PA</i>	1	\$ 358.78	\$ 358.78
26	REAR END PANEL <i>PA</i>	1	\$ 480.72	\$ 480.72
27	REAR END PANEL INNER TOP GARNISH <i>CR</i>	1	\$ 159.80	\$ 159.80

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
28	REAR END PANEL INNER BOOT LID ANTENA SENSOR X <i>svl</i>	1	\$ 325.61	\$ 325.61
29	REAR END PANEL LOCK STRIKER X <i>svl</i>	1	\$ 43.70	\$ 43.70
30	SPARE TYRE PANEL Repair <i>Que</i> /	1	\$ 789.48	\$ 789.48
31	SPARE TYRE PANEL INNER TOP UPHOLSTERY BOARD X <i>svl</i>	1	\$ 219.10	\$ 219.10
32	SPARE TYRE RETAINER LOCK * <i>ne</i> /	1	\$ 10.90	\$ 10.90
33	SPARE TYRE SIDE PANEL LH <i>repair</i>	1	\$ 245.62	\$ 245.62
34	REAR SUB CHASSIS FRAME TOP PANEL LH <i>repair</i>	1	\$ 813.14	\$ 813.14
35	REAR FENDER LH Repair <i>Que</i> /	1	\$ 1,769.12	\$ 1,769.12
36	REAR FENDER INNER UPHOLSTERY TRIM LH <i>cut</i> /	1	\$ 207.90	\$ 207.90
37	REAR FENDER INNER SHIELD LH REA /	1	\$ 112.30	\$ 112.30
38	REAR FENDER STONE PROTECTIVE STICKER LH * <i>X</i> <i>ne</i>	1	\$ 27.02	\$ 27.02
39	REAR WINDSCREEN MOULDING * <i>ne</i> /	1	\$ 129.80	\$ 129.80

* BLIND SPOT DETECTION SENSOR - <i>CR</i> /	TOTAL PRICE	\$ 13,095.72
* BLIND SPOT DETECTION SENSOR BRACKET <i>TA</i> /	LESS -20%	\$ (2,619.14)
* BLIND SPOT DETECTION SENSOR WIRE HARNESS SET <i>Sub</i> /	SUB TOTAL PRICE	\$ 10,476.58
* BLIND SPOT DETECTION SENSOR ABSORBER <i>CR</i> /		

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BOOT LID REFLECTOR CLIPS SET LH/RH <i>ne</i> /	<i>1pc</i> 2	\$ 10.00	\$ <i>10</i> 20.00
2	REAR BOOT LID INNER UPHOLSTERY TRIM CLIPS SET <i>ne</i> /	1	\$ 50.00	\$ 50.00
3	REAR BOOT LID NUMBER PLATE WITH CASING * <i>ne</i> /	1	\$ 50.00	\$ <i>35</i> 50.00
4	REAR BOOT LID NUMBER PLATE WEEK END SEAL <i>ne</i> /	1	\$ 50.00	\$ 50.00
5	REAR BOOT LID SEALANT <i>ne</i> /	1	\$ 60.00	\$ <i>40</i> 60.00
6	REAR BUMPER REVERSE SENSOR SET <i>ne</i> /	1	\$ 280.00	\$ <i>220</i> 280.00
7	REAR BUMPER CLIPS SET <i>ne</i> /	1	\$ 60.00	\$ <i>40</i> 60.00
8	REAR TAILLAMP CLIPS SET LH/RH <i>LH-ne</i> / <i>RH-X</i> <i>TA</i> /	<i>1pc</i> 2	\$ <i>20.00</i> 40.00	\$ 40.00
9	REAR TAILLAMP INNER PANEL SEALANT LH * <i>ne</i> /	1	\$ 30.00	\$ 30.00
10	REAR END PANEL INNER TOP GARNISH CLIPS SET <i>ne</i> /	1	\$ 30.00	\$ 30.00
11	REAR END PANEL SEALANT <i>ne</i> /	1	\$ 80.00	\$ <i>40</i> 80.00
12	SPARE TYRE PANEL SEALANT <i>ne</i> /	1	\$ 100.00	\$ <i>60</i> 100.00
13	REAR FENDER SEALANT LH <i>ne</i> /	1	\$ 100.00	\$ 100.00
14	REAR FENDER INNER UPHOLSTERY TRIM CLIPS SET LH <i>ne</i> /	1	\$ 50.00	\$ <i>30</i> 50.00
15	REAR FENDER INNER SHIELD CLIPS SET LH <i>ne</i> /	1	\$ 40.00	\$ <i>20</i> 40.00
16	REAR WINDSCREEN SEALANT WITH PRIMER <i>ne</i> /	1	\$ 120.00	\$ <i>40</i> 120.00

TOTAL

\$ 1,160.00

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 1,800.00	1200 1400 ✓	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 1,400.00	1000 ✓	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 160.00	100 ✓	
TO PERFORM LIGHTING & WIRING CHECK	\$ 90.00	40 60 ✓	
TO CALIBRATE CHASSIS & CAR BODY BACK TO MANUFACTURING SPECIFICATION	\$ 380.00	100 photo? X11	
TO DISMANTLE & REINSTALL REAR PETROL TANK FOR FACILITATE REPAIR	\$ 250.00	80 X11 X	
TO DISMANTLE & REINSTALL REAR WINDSCREEN PERFORM	\$ 150.00	120 ✓	
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE COMPONENT TO PERFORM FACILITATE REPAIRS	\$ 260.00	X nn	
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	\$ 80.00	60 ✓	
TO DISMANTLE & REPLACED REAR BOOT LID REVERSE CAMERA WITH SETTING	\$ 80.00	40 ✓	
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 280.00	60 ✓	
TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 80.00	30 ✓	

TOTAL

\$ 5,010.00

ESTIMATE REPORT

TOTAL PARTS COST	:	\$	11,636.58
TOTAL LABOUR COST	:	\$	5,010.00
TOTAL REPAIR COST	:	\$	16,646.58

APPROVED DETAILS

EXCESS :
NO. OF REPAIR DAYS : 13 days
RE-SURVEY :
P / P OR L / S : P / P

DATE / TIME OF SURVEY : 13/03/15 @ 1620
SURVEYED BY / FROM : RASUL CLKK7
CONTACT NUMBER : 90010068
FAX NUMBER :
EMAIL ADDRESS : ~~HPA~~

Resy bp paint

LKK Auto Consultants hence notify the Repairer of the following:

- In resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19004577/R1td3e2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 17-06-2019



ATTN : ERIC TANG

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJQ 1078L	Veh. Inspected	SLL 507A
Policy No.		Coverage (\$)	0.00
Claim No.	MT-1035579-001	Excess (\$)	0.00
Assign From	DANIEL KOH	Assign Date	13/03/2019

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI ELANTRA 1.6	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KMHD841CMHU333029	Colour	GREY
Odometer	6293 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	KUMHO	6 mm
L/H Front Tyre	205/55 R16	KUMHO	6 mm
R/H Rear Tyre	205/55 R16	KUMHO	6 mm
L/H Rear Tyre	205/55 R16	KUMHO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	09/03/2019	Inspect Date / Time	13/03/2019 (03:51 PM)
Survey held at	BP AUTO 48 TOH GUAN RD EAST # 01-121		
Repairer	-		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	13 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 507A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BOOT LID	BENT	1,690.67	1,620.00
1	REAR BOOT LID LOGO EMBLEM	NECESSARY	82.14	50.00
1	REAR BOOT LID ELITE EMBLEM	NECESSARY	65.32	50.00
1	REAR BOOT LID ELANTRA EMBLEM	NECESSARY	78.42	68.00
1	REAR BOOT LID REFLECTOR LED LAMP LH	SCRATCHED	664.90	664.90
1	REAR BOOT LID OUTER LOCK HANDLE SWITCH WITH REVERSE CAMERA	SERVICEABLE	652.97	-
1	REAR BOOT LID NUMBER PLATE LAMP LH	SERVICEABLE	55.65	-
2	REAR BOOT LID HINGES LH / RH @\$145.42	SERVICEABLE	290.84	-
1	REAR BOOT LID INNER UPHOLSTERY TRIM	SERVICEABLE	358.31	-
1	REAR BOOT LID INNER HANDLE	SERVICEABLE	112.10	-
2	REAR BOOT LID RUBBER GUIDE STOPPER LH / RH @\$40.29	NECESSARY	80.58	80.58
1	REAR BOOT LID MECHANISM LOCK	SERVICEABLE	208.70	-
1	REAR BOOT LID WEATHER STRIP	NECESSARY	92.50	92.50
1	REAR BUMPER	TORN	489.24	489.24
1	REAR BUMPER REFLECTOR LH	BROKEN	31.90	31.90
2	REAR BUMPER SIDE RETAINER LH / RH @\$44.30	N/S NECESSARY / O/S SERVICEABLE	88.60	44.30
1	REAR BUMPER INNER SIDE SHIELD RH	SERVICEABLE	145.65	-
1	REAR BUMPER LOWER UNDER COVER LH	SERVICEABLE	151.32	-
2	REAR BUMPER TOP BRACKET LH / RH @\$25.71	N/S NECESSARY / O/S SERVICEABLE	51.42	25.71
1	REAR BUMPER REINFORCEMENT	BENT	548.42	328.00
1	REAR BUMPER INNER BOOT LID ANTENA SENSOR	SERVICEABLE	325.61	-
1	REAR BUMPER MADFLAP LH	SCRATCHED	62.30	62.30
1	REAR BUMPER INNER BOOT LID ANTENA SENSOR WIRE HARNESS	CUT	198.27	100.00
1	REAR TAILLAMP LED LH	CRACKED	876.90	876.90
1	REAR TAILLAMP INNER PANEL LH	BENT	358.78	250.00
1	REAR END PANEL	BENT	480.72	480.72
1	REAR END PANEL INNER TOP GARNISH	CRACKED	159.80	105.00

Report Ref No. CS/INC19004577/R1td3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR END PANEL INNER BOOT LID ANTENA SENSOR	SERVICEABLE	325.61	-
1	REAR END PANEL LOCK STRIKER	SERVICEABLE	43.70	-
1	SPARE TYRE PANEL	BUCKLED	789.48	775.00
1	SPARE TYRE PANEL INNER TOP UPHOLSTERY BOARD	SERVICEABLE	219.10	-
1	SPARE TYRE RETAINER LOCK	NECESSARY	10.90	10.90
1	SPARE TYRE SIDE PANEL LH	TO REPAIR SEE LABOUR	245.62	-
1	REAR SUB CHASSIS FRAME TOP PANEL LH	TO REPAIR SEE LABOUR	813.14	-
1	REAR FENDER LH	BUCKLED	1,769.12	1,560.00
1	REAR FENDER INNER UPHOLSTERY TRIM LH	CUT	207.90	207.90
1	REAR FENDER INNER SHIELD LH	CRACKED	112.30	112.30
1	REAR FENDER STONE PROTECTIVE STICKER LH	NOT NECESSARY	27.02	-
1	REAR WINDSCREEN MOULDING	NECESSARY	129.80	129.80
1	REAR BLIND SPOT DETECTION LH (ADDITIONAL) }	CRACKED	1,660.10	1,487.00
1	REAR BLIND SPOT DETECTION SENSOR BRACKET LH (ADDITIONAL) }		186.20	-
1	REAR BLIND SPOT DETECTION SENSOR WIRE HARNESS LH (ADDITIONAL) }		219.40	-
1	REAR BLIND SPOT DETECTION SENSOR ABSORBER LH (ADDITIONAL) }		97.10	-
	LESS 20% DISCOUNT		-3,051.70	-1,940.59
			12,206.82	7,762.36
	<u>SPECIAL NETT ITEMS</u>			
2	SET REAR BOOT LID REFLECTOR CLIPS LH / RH @\$10.00 (SN)	NECESSARY	20.00	10.00
1	SET REAR BOOT LID INNER UPHOLSTERY TRIM CLIPS (SN)	NECESSARY	50.00	50.00
1	REAR BOOT LID NUMBER PLATE WITH CASING (SN)	NECESSARY	50.00	35.00
1	REAR BOOT LID NUMBER PLATE WEEK END SEAL (SN)	NECESSARY	50.00	50.00
1	REAR BOOT LID SEALANT (SN)	NECESSARY	60.00	40.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	NOT WORKING	280.00	220.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	60.00	40.00
2	SET REAR TAILLAMP CLIPS LH / RH @\$20.00 (SN)	N/S NECESSARY / O/S NOT NECESSARY	40.00	20.00

Report Ref No. CS/INC19004577/R1td3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TAILLAMP INNER PANEL SEALANT LH (SN)	NECESSARY	30.00	30.00
1	SET REAR END PANEL INNER TOP GARNISH CLIPS (SN)	NECESSARY	30.00	30.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	80.00	40.00
1	SPARE TYRE PANEL SEALANT (SN)	NECESSARY	100.00	60.00
1	REAR FENDER SEALANT LH (SN)	NECESSARY	100.00	100.00
1	SET REAR FENDER INNER UPHOLSTERY TRIM CLIPS LH (SN)	NECESSARY	50.00	30.00
1	SET REAR FENDER INNER SHIELD CLIPS LH (SN)	NECESSARY	40.00	20.00
1	REAR WINDSCREEN SEALANT WITH PRIMER (SN)	NECESSARY	120.00	40.00
			1,160.00	815.00
	LABOUR			
	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION. INCLUSIVE OF THE REPAIR OF SPARE TYRE SIDE PANEL LH AND REAR SUB CHASSIS FRAME TOP PANEL LH.		1,800.00	1,400.00
	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA.		1,400.00	1,000.00
	TO APPLY ANTI-RUST & TUFF KOTE.		160.00	100.00
	TO PERFORM LIGHTING & WIRING CHECK.		90.00	60.00
	TO CALIBRATE CHASSIS & CAR BODY BACK TO MANUFACTURING SPECIFICATION.	NOT NECESSARY	380.00	-
	TO DISMANTLE & REINSTALL REAR PETROL TANK FOR FACILITATE REPAIR.	NOT NECESSARY	250.00	-
	TO DISMANTLE & REINSTALL REAR WINDSCREEN PERFORM.		150.00	120.00
	TO DISMANTLE & REPLACED REAR UNDER CARRIAGE COMPONENT TO PERFORM FACILITATE REPAIRS.	NOT NECESSARY	260.00	-
	TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING.		80.00	60.00
	TO DISMANTLE & REPLACED REAR BOOT LID REVERSE CAMERA WITH SETTING.		80.00	40.00
	TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR.		280.00	60.00
	TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION.		80.00	30.00
			5,010.00	2,870.00

Report Ref No. CS/INC19004577/R1td3e2



GRAND TOTAL		18,376.82	11,447.36
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			9,150.00

Report Ref No. CS/INC19004577/R1td3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.