

KIAN TEONG AUTO CENTRE

Blk 176 Sin Ming Drive #01-08

Sin Ming AutoCare Singapore 575721

Tel No. : 64556268 Fax No. : 64555166

E-Mail : info@ktauto.com.sg

Website : www.ktauto.com.sg

Tax Reg. No. : 52991859E Buss. Reg. No. : 52991859E

FWD INSURANCE

Attention : Motor Claim Department

Estimate : ES000482

Date : 13/03/2019

Vehicle Num. : SKJ 2266 D

Make/Model : PORSCHE MACAN

Chassis/Eng# :

Accident Date : 13/03/2019

Claim No. :

Reference :

Policy No. :

S/N Quantity Particular Unit Price Amount S\$

- LIST ITEMS :
1. 1 REAR BUMPER
 2. 1 REAR BUMPER LOWER SPOILER
 3. 1 REAR BUMPER NUMBER PLATE PANEL CENTRE
 4. 1 REAR BUMPER REINFORCEMENT
 5. 2 REAR BUMPER BRACKET
 6. 1 SET REAR BUMPER CLIPS
 7. 1 SET REAR REVERSE SENSOR

List Total S\$:

- NETT ITEMS :
1. 1 REAR NUMBER PLATE
 2. 1 REAR BUMPER DECAL - 3M MATTE DARK GREY

Nett Total S\$:

LABOUR :
LABOUR FEES:
TO PUTTY APPLY PRIMER & SPRAY PAINT THE AFFECTED AREAS
TO KNOCK AND RE-ALIGN ALL DAMAGED PARTS
TO CHECK AND REPAIR ELECTRICAL WIRING
TO CHECK REVERSE SENSOR

Labour Total S\$:

Bul/Pl 1,460.00 ✓
Pl 455.00 ✓
Pl 420.00 ✓
Pl 395.00 X
Pl 190.00 X
Pl 85.00 ✓

3,005.00

CM 58.00 45Jn
Bill 680.00 350Jn
738.00

600.00 400d
960.00 400d
260.00 100d

1,820.00

E. & O.E.

Total S\$: 5,563.00

=====

for KIAN TEONG AUTO CENTRE

Please do not hesitate to contact us at the above number if there is any other further quire.
We thank you for your kind attention. Your prompt reply is greatly appreciated.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: