

COMING

ASS. REC. IY:

REF: CS/ASM 19004582/ R19d319 Special Instruction:

Surveyor: Rosul ASSIGNMENT (Office)

From (Person): Kitty Teo of ASM(CAxA) Date/Time: 12/3/2019

Estimated Cost: _____ Bill to: _____

OD TP WS TP RES OD RES EVA INV MYTC5

To Inspect Vehicle No: SGV 446Z Insured: _____

at Workshop no: Ethoz Tel: 9624 8656

of 30 Blk Bufok Crescent

Policy No: _____ Claim No: S9M01G H8

Sum Insured: _____ Excess: \$500-00

Make of Veh: _____ D.O.A: 8/3/2019
(Client's Record)

CA / REX / REP. / REV 24 HRS H.O.D. Endorsement: _____

Date/Time: 11:20am @ 12/3/19 Person Contacted: Shah Vehicle IN OTR

Date/Time	Action/Instruction (✓) Estimate
	SGV 446Z - CS/1458090/3236/AGY1
14/3/19 @	12:07pm revert to Kitty Teo via Smart Claim
14/3/19 @	5:47pm Kitty Teo informed CA via Smart Claim.
15/3/19 @	9:13am Informed Lee Chen via LPA to ex: \$500 by email.
15/4/19 @	4:27pm Informed Kitty Teo that we have received supp. \$13.20 from repairer & its consistent and economical for repair via Smart Claim.

Signature: *[Handwritten Signature]*

REF: ASM(AxA) CS/ASM1900458411903

15070
LOG NOIRY: MAY/2022

ASSIGNMENT

From: _____ Date: 13/03/2019

Veh No: SGV446Z Yr Regn: 2007 / Jun

Estimated Cost: _____

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

TP / WS / TP RES / OD RES / EVA / INV / MY

Make: Toyota COROLLA ALTIS 1.6A c.c 1598

To Inspect Vehicle No: SGV 446Z

Colour: GREEN A/C: Insured / Std / NI / NA

at Workshop m/s: ETHOZ
of: 30 Blk Bataok Crescent.

Sp. Reading: 130061 T/Radio: Insured / Std / NI / NA

Insured: _____

Eng/No: _____

Policy No: _____

C/No: MROS353ZE0107145054

Claims No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: _____ Excess: \$500.00

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or


Make of Veh: Get audatex
Lee chee sin

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 185/65R14
R: _____

Remark: The veh had commenced its repair at the time of inspection.



BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Bal. or Market Value: 20K

Front Rear

IDAC Accident Report: Consistent? : Yes or No

R/Bal. 5 mm R/Bal. 5 mm

GIA / PR Seen: Consistent? : Yes or No

L/Bal. 5 mm L/Bal. 5 mm

Est. Repairs: 4 days Res.: Yes or No

D.O.A. 08/03/19 D.O.I. 13/03/19

Lum Sum: % 3 Val: Yes or No

Survey held at ETHOZ

CA REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
13/4/19 @ 2.5pm	confirmed with Chen Sin for final pg. 8/285.35, 4 days. (Red @ 711.80, 36%) no lump sum.

RECEIVED 17 APR 2019

Signature: *[Handwritten Signature]*
17/4/2019

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: 4
Resurvey No. of Trip: 1

Survey Fee:	150
Transportation:	
S + RS:	
Photos:	
Others:	
TOTAL:	150

Date/Time, File Return to? _____
Report Format: Smart claim
Lump Sum / I.B.I: (\$ 1285.35)

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)

◀ Service Request Details

Claim

S9M01GH8

Reference

None 

Loss Date

March 8, 2019

Report Date

Mar 9, 2019 12:00:00 AM

Request Date

March 12, 2019

Due Date

March 19, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SGV446Z

1910001

COROLLA ALTIS 1.6

Service Address

22 Tampines Street 92, . , 528876

Primary Contact/Insured

ABDUL RAHMAN BIN AHMAD DASAH
C/O TAYLOR NELSON SOFRES, Singapore
97884722

Claim Handler

TEO Kitty
6568804602
kitty.teo@axa.com.sg
Additional Instructions
XS \$500

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

TYPE



SENT

3/12/19 5:13 PM

FROM

TEO Kitty

SUBJECT

WP SURVEY @ ETHOZ(TAMPINES)

BODY

Hi Please get audatex.



Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 17 April 2019 2:50 PM
To: Lee Chen Sin; Rasul (LKKAuto)
Cc: SUR
Subject: RE: FINALIZATION REPORT OF SGV-446-Z TOYOTA ALTIS (OD)(AXA)

Dear Chen Sin,

WITHOUT PREJUDICE

Confirm final fig \$1,285.35 before excess \$500.00 & GST and 4 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: shiewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lee Chen Sin <ChenSin.Lee@ethozgroup.com>
Sent: Wednesday, 3 April 2019 10:51 AM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: FINALIZATION REPORT OF SGV-446-Z TOYOTA ALTIS (OD)(AXA)

Hi Rasul,

Attached are the finalization report, supplier invoice and photo before paint of above mention vehicle.

Please send acceptance once the COR is confirm.

COR : \$ 1,285.35 (Part By Part)

Repair days : 4

Excess : \$ 500.00

Kindly revert.

Thank you.

Warmest Regards,
Lee Chen Sin
Motor Claims Operations

ETHOZ
ETHOZ GROUP LTD

30 Bukit Batok Crescent Singapore 658075

DID: 6654 7520 | FAX: 6654 7542 | Mobile: 8822 8339

www.ethozgroup.com



⏪ **Re:2ND IA OF VEHICLE SGV 446Z UPLOADED**

Type

📌 Question

Message

Hi Shiau Chan, Please proceed with the supplementary.

Reply



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

12/4/2019

Survey Details:

Date of loss	8-Mar-19
Date of appointment	12-Mar-19
Date of survey	13-Mar-19
Location of survey	ETHOZ - BUKIT BATOK

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SGV 446Z
Make and Model	TOYOTA COROLLA ALTIS 1.6A
Date of registration	1/6/2007
Excess	\$ 500.00
Market Value	\$ 20,000.00
Parf Rebate	\$ 16,275.00
Nett Loss	\$ 3,725.00

Repair details:

Initial Estimate	\$ 1,997.15	(ESTIMATE \$1,983.95 + SUPPLEMENTARY \$13.20)
------------------	-------------	--

Proposed/Revised repair cost:

Parts	\$ 524.70
Check items (estimate)	\$ -
Labour	\$ 760.65
Total	\$ 1,285.35
Lump Sum(if applicable)	-

Number of days for repair	<u>4</u>
---------------------------	----------



Remarks:

DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. We have received supplementary \$13.20 from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair.

Mandate:

Liability(TP)		%	
Proposed repair cost		\$	
Loss of use		\$	no. of days
Loss of rental		\$	no. of days
Loss of income		\$	no. of days
LTA search fees		\$	
Others		\$	
Proposed Total		#VALUE!	

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 15 March 2019 9:13 AM
To: 'ChenSin.Lee@ethozgroup.com'
Subject: AXA OD VEHICLE SGV 446Z (DOA: 08/03/2019)

Dear Chen Sin,

As instructed by our client , please proceed to repair the **insured vehicle SGV 446Z (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

***Our client reserve their right not to pay if there is no valid approval obtained before repair.**

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

⏪ Please authorise. Thanks.

Type

🔍 Question

Message

*

Reply



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

14/3/2019

Survey Details:

Date of loss	8-Mar-19
Date of appointment	12-Mar-19
Date of survey	13-Mar-19
Location of survey	ETHOZ - BUKIT BATOK

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SGV 446Z
Make and Model	TOYOTA COROLLA ALTIS 1.6A
Date of registration	1/6/2007
Excess	\$ 500.00
Market Value	\$ 20,000.00
Parf Rebate	\$ 16,275.00
Nett Loss	\$ 3,725.00

Repair details:

Initial Estimate	\$ 1,983.95
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 511.50
Check items (estimate)	\$ -
Labour	\$ 1,111.95
Total	\$ 1,623.45
Lump Sum(if applicable)	-

Number of days for repair	<u>4</u>
---------------------------	----------



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

*DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE
HAVE NOT AUTHORISE REPAIR.*

Mandate:

Liability(TP)		%
Proposed repair cost		\$
Loss of use		\$ no. of days
Loss of rental		\$ no. of days
Loss of income		\$ no. of days
LTA search fees		\$
Others		\$
Proposed Total		#VALUE!

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1507D
Vehicle Details	
Vehicle No.:	SGV446Z
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	3ZZ4641472
Chassis No.:	MR053ZEC107145054
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$15,245.00
Original Registration Date:	01 Jun 2007
First Registration Date:	01 Jun 2007
Transfer Count:	4
Actual ARF Paid:	\$16,770.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 May 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$25,333.00
COE Rebate Amount:	\$16,275.00
Total Rebate Amount:	\$16,275.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 14 Mar 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/03/2019 10:13
Date Of Accident	08/03/2019 11:00
Exact Location Of Accident	950 DUNEARN ROAD BASEMENT CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGV446Z
Insured/Policyholder	
Name Of Registered Owner	ABDUL RAHMAN BIN AHMAD DASAH
NRIC No	S1621507D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97884722
Alternative Phone No	OFFICE-97884722

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VA1/GA447662
Cover Note Number	01/03/2019-29/02/2020

Driver

Name of Driver	ABDUL RAHMAN BIN AHMAD DASAH
NRIC No	S1621507D
Date Of Birth	10/02/1963
Occupation	INDOOR
Date Of Driving Pass	24/07/1996
Driving Experience	22 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97884722
Fax Number	
Contact Number	OFFICE-97884722
EMail Address	NOEMAIL

Address	950 DUNEARN ROAD 06-06
Postcode	589474
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:




Driver's Signature
(if driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/IN No.:

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Reversing into parking lot and hit the pillar

<p>Important: You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a FOURTEEN (14) DAYS CLAUSE WHEREBY MUST BE MADE within the stipulated time frame from the day of the occurrence.</p>	<input type="checkbox"/>	- Reporting Only
	<input checked="" type="checkbox"/>	- Claim OD
	<input type="checkbox"/>	- Claim TP
	<input type="checkbox"/>	- Claim OD/ TP at other workshop

DECLARATION

I/WE declare the foregoing particulars are true in every respect.



Policyholder's signature
Date & Time

9/3/19 10.00am



Driver's Signature
(if driver not the policyholder)
Date & Time



Reporting Centre Personnel's Signature
Name:
Nric/Fin No.

IDENTITY CARD NO. S1621507D



ABDUL RAHMAN BIN AHMAD
DASAH

أحمد الرحمن بن أحمد داسه

Ethnicity: JAVANESE

Date of birth: 10-02-1963

Sex: M

Country/Place of birth: SINGAPORE

S1621507D

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: S1621507D

Name: ABDUL RAHMAN BIN AHMAD DASAH

Birth Date: 10 Feb 1963

Issue Date: 06 May 2003

20040512SE

6019047



License No. S1621507D



Date of issue: 00-00-2018

Address: 550 DUNEARN ROAD #06-08 SINGAPORE 599474

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

Class 2B	Motorcycles (all above 300 cc)	21 Feb 1991
Class 2A	Motorcycles (between 201 cc and 400 cc)	21 Feb 1991
Class 3	Motor Cars and Motor Tractors (the weight of which (laden does not exceed 3500 kilograms)	24 Jul 1998

License No. S1621507D

NP 420A



redefining / insurance

AXA Insurance Pte Ltd
 1800 880 4888 (Within Singapore)
 (65) 6880 4888 (International)
 (65) 6880 4740
 customer.care@axa.com.sg
 www.axa.com.sg

account number
 11008

Certificate of Insurance

Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) - Motor Vehicles (Third Party Risks and Compensation) Rules, 1967-Road Transport Act, 1967 (Malaysia)
 Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia)

Policy details

Policyholder name	ABDUL RAHMAN BIN AHMAD DASAH	Certificate number	GA447662 / 1
Cover	Comprehensive	Chassis number	MR0532EC10714505-4
Plan name	Essential	Engine number	3224641472
NCD applicable	0%		
Vehicle registration number	SGV4462		
Period of insurance	from 01/03/2019 to 29/02/2020 (both dates inclusive)		
Finance loan company	MAYBANK		

Persons or classes of persons entitled to drive*

- (a) The Policyholder
 (b) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1967 (Malaysia), are not to be included under these headings.

EXCESS	Basic Own Damage Excess	
	Windscreen Excess	

An Additional Excess is applicable as follows:

1. S\$500 for unnamed *Authorized Driver*
2. S\$500 for declared *Young and Inexperienced Driver*
3. S\$5,000 for undeclared *Young and Inexperienced Drivers*. This additional excess is reduced to S\$2,500 if you have chosen AXA Premium Workshops.

Additional clauses & endorsements to your policy

Nil

(We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1967 (Malaysia).

AXA Insurance Pte Ltd

Authorized signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third Party Risks and Compensation) Act (Cap. 189).
 The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, endorsement etc.

AXA Insurance Pte Ltd (189903512M)
 8 Shenton Way, #24-01, AXA Tower,
 Singapore 068811
 Customer Centre, #B1-01

1 of 3

ETHOZ Automotive Solutions Ltd
30 Bukit Batok Crescent
658075

Claim Reference:
Assessment number: SIN00013
Version: 1810
Date calculated: 03/12/2019 09:07 AM

Full Report
Registration: **SGV446Z**
Printed: 12/03/2019 9:08 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	Ethoz Bukit Batok 02	Currency:	SGD
Claim Reference:		Date of Incident:	2019-03-08
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	COROLLA(ZZE122/30)
Sub Model:	BASE MODEL
Model Sheet Number:	70 93 01
Registration:	SGV446Z
VIN number:	
Odometer:	

Model Specs

PROD CONTRY MALAISIA	TWO COAT METALLIC	PREPARE OFF VEHICLE
----------------------	-------------------	---------------------

ETHOZ Automotive Solutions Ltd
30 Bukit Batok Crescent
658075

Claim Reference:
 Assessment number: SIN00013
 Version: 1810
 Date calculated: 03/12/2019 09:07 AM

Full Report
 Registration: SGV446Z
 Printed: 12/03/2019 9:08 AM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
 Date of Inspection:

Damage Areas

All
 Underbody



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	WU Price SGD
B290	RENEW REAR END PANEL (BUMPER REMOVED) INCLUDES: BOTH REAR LAMPS, FLOOR MAT BOOT COMPARTMENT AND ALL TRIMS IN REPAIR AREA REMOVE AND REFIT		33.0	148.50
NO NUMBER	R + R BOOTLID TRIM		1.0	4.50
640201)	R + R BOOT LID LOCK		2.0	9.00
750171	RENEW BADGE "TOYOTA"		2.0	9.00
750171	RENEW BADGE "TOYOTA"		2.0	9.00
750171	RENEW BADGE "COROLLA"		2.0	9.00
B420)	RENEW REAR BUMPER (REMOVED)		1.0	4.50
B410	R + R REAR BUMPER		6.0	27.00
2621	L/END PANEL TRIM REPAIR		5.0*	22.50
2622	R/END PANEL TRIM REPAIR		5.0*	22.50
2931	BOOTLID REPAIR		10.0*	45.00
3481	L/R SIDE PANEL REPAIR		5.0*	22.50

ETHOZ Automotive Solutions Ltd
30 Bukit Batok Crescent
658075

Claim Reference:
 Assessment number: SIN00013
 Version: 1810
 Date calculated: 03/12/2019 09:07 AM

Full Report
 Registration: SGV446Z
 Printed: 12/03/2019 9:08 AM

Code	Description	WU	Price SGD
3482	R/R SIDE PANEL REPAIR	5.0* X ^h	22.50
3901	REAR FLOOR PANEL REPAIR	10.0* X ^h	45.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		8.90	89.0
Total of Labour			400.50

Paint

Code	Description - TWO COAT METALLIC	WU	Price SGD
Paint Work SYSTEM AZT Time Basis 10WU/h			
	REAR PANEL NEW PART PAINTING	20.0	
	REAR BUMPER NEW PART PAINT K1R	11.0	
	L/END PANEL TRIM REPAIR PAINT PLASTIC	9.0	
	R/END PANEL TRIM REPAIR PAINT PLASTIC	9.0	
	BOOTLID REPAIR PAINTING <50%	17.0	
	L/R SIDE PANEL REPAIR PAINTING <50%	15.0	
	R/R SIDE PANEL REPAIR PAINTING <50%	15.0	
	REAR FLOOR PANEL SURFACE PAINT	9.0	

Paint Material Per Part

Code	Description	Price SGD
2711	REAR PANEL NEW PART PAINTING	24.20
2581	REAR BUMPER NEW PART PAINT K1R	51.66
2621	L/END PANEL TRIM REPAIR PAINT PLASTIC	1.62
2622	R/END PANEL TRIM REPAIR PAINT PLASTIC	1.62
2931	BOOTLID REPAIR PAINTING <50%	30.69
3481	L/R SIDE PANEL REPAIR PAINTING <50%	24.23
3482	R/R SIDE PANEL REPAIR PAINTING <50%	24.23
3901	REAR FLOOR PANEL SURFACE PAINT	25.90

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor			45.00 SGD/h
Time Paint		105.0	
Preparation Main Work Metal	2.50	25.0	112.50
Preparation Comp. Work Plastic	0.80	8.0	36.00
Total	13.80	138.0	621.00

ETHOZ Automotive Solutions Ltd
30 Bukit Batok Crescent
658075

Claim Reference:
 Assessment number: **SIN00013**
 Version: 1810
 Date calculated: **03/12/2019 09:07 AM**

Full Report
 Registration: **SGV446Z**
 Printed: **12/03/2019 9:08 AM**

Material Cost - Paint	Price SGD
New Part Painting	24.20
New Part Painting - Plastic K1R	51.66
Repair Painting	79.15
Repair Painting Plastic	3.24
Surface-/Blend Paint	25.90
Material-constant Metal Preparation	28.60
Material-constant Plastic	12.70
Total	225.45

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	Price SGD	
2581	REAR BUMPER	52159 02904	DE /		140.00 /	
2619	L/R BUMPER BRACKET	52156 02030	RE /		8.00 /	
2620	R/R BUMPER BRACKET	52155 02040	RE /		8.00 /	
2625	L/R CTR BUMPER BRKT	52181 02030	RE /		10.00 /	
2626	R/R CTR BUMPER BRKT	52181 02030	RE /		10.00 /	
2650	RR BUMPER CLAMP KIT	90467 09093	nbc /		15.00 /	
2711	REAR PANEL	58307 1A620	PA /		150.00 /	
2944	BOOTLID SEAL	64461 02060	TUC /		22.00 /	
2977	BOOT/TAILGATE LOCK	64610 02050	TA /		15.00 /	
3013	MANUFACTURER BADGE	75441 02090	RE /		10.00 /	
3014	BADGE	75485 12380	RE /		12.00 /	
3016	BADGE	75443 1A840	RE /		18.00 /	
3017	BADGE MODEL	75442 02130	RE /		12.00 /	
3019	TYPE BADGE	75444 02110	RE /		15.00 /	
3281	L/R OUTER LAMP	81560 02230	X 3 SUC		85.00	
3282	R/R OUTER LAMP	81550 02230	X 3		85.00	
4978	LUGG COMPART CARPET	64771 02120C0	X NA		35.00	
4985	END PANEL TRIM	58387 02030B0	DE /		20.00 /	
f: OEM Parts					Savings	0.00
n: Non-OEM Parts					Subtotal	670.00
u: Used parts					Addition(+10.00%)	67.00
Total					737.00	

ETHOZ Automotive Solutions Ltd
30 Bukit Batok Crescent
658075

Claim Reference:
 Assessment number: SIN00013
 Version: 1810
 Date calculated: 03/12/2019 09:07 AM

Full Report
 Registration: SGV446Z
 Printed: 12/03/2019 9:08 AM

Final Calculation

	SGD	SGD
Parts	670.00	
Addition(+10.00%)	67.00	
Total Parts		737.00
Labour Time Base 10 WU/h		
Total 89.0 WU X 45.00 SGD/h	400.50	365.50
Total of Labour		400.50
Paint Work Time Base 10 WU/h		
Labour Cost 138.0 WU X 45.00 SGD/h	621.00	351
Material Cost	225.45	104.15
Total Paint Including Material		846.45
Repair Cost Excludes GST		1,983.95
GST (+7.00%)		138.88
Repair Cost Included GST		2,122.83

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

Passer
15/3/19
Hp 90010068
4 days
P/P
13/03/19 @ 1525
EXCESS: 500
REVERT
Resurvey before paint
1997.15

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice"
 • No illegal modification(s) is allowed
 • Supplementary work(s) must be resurveyed & subject to final approval from insurance
 Acknowledged by Repairer
 Signature:
 Date:

ETHOZ Automotive Solutions Ltd
30 Bukit Batok Crescent
658075

Claim Reference:
 Assessment number: SIN00013
 Version: 1810
 Date calculated: 04/03/2019 10:23 AM

Full Report
 Registration: SGV446Z
 Printed: 03/04/2019 10:24 AM

Final Calculation

	SGD	SGD
Parts	477.00	
Addition(+10.00%)	47.70	
Total Parts		524.70
Labour Time Base 10 WU/h		
Total 59.0 WU X 45.00 SGD/h	265.50	
Total of Labour		265.50
Paint Work Time Base 10 WU/h		
Labour Cost 78.0 WU X 45.00 SGD/h	351.00	
Material Cost	144.15	
Total Paint Including Material		495.15
Repair Cost Excludes GST		1,285.35
GST (+7.00%)		89.97
Repair Cost Included GST		1,375.32
Deductions (Excludes GST)		
Total Of Deductions (Excludes GST)		-500.00
Grand Total Excludes GST		785.35
GST (+7.00%)		54.97
Grand Total Included GST		840.32

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

COR: \$ 1,285.35 (PART BY PART)

1 DAYS REPAIR

EXCESS: \$ 500.00

PARTS - \$ 477.00 + 10%

- \$ 524.70

LABOUR - \$ 760.65

\$ 1,285.35

ETHOZ Automotive Solutions Ltd
30 Bukit Batok Crescent
658075

Claim Reference:
 Assessment number: SIN00013
 Version: 1810
 Date calculated: 04/03/2019 10:23 AM

Full Report
 Registration: SGV446Z
 Printed: 03/04/2019 10:24 AM

Code	Description	Part Number	Supplier	Price SGD	
2620	R/R BUMPER BRACKET	52155 02040		8.00	
2625	L/R CTR BUMPER BRKT	52181 02030		10.00	
2626	R/R CTR BUMPER BRKT	52181 02030		10.00	
2650	RR BUMPER CLAMP KIT	90467 09093		15.00	
2711	REAR PANEL	58307 1A620		150.00	
2944	BOOTLID SEAL	64461 02060		22.00	
2977	BOOT/TAILGATE LOCK	64610 02050		15.00	
3013	MANUFACTURER BADGE	75441 02090		10.00	
3014	BADGE	75485 12380		12.00	
3016	BADGE	75443 1A840		18.00	
3017	BADGE MODEL	75442 02130		12.00	
3019	TYPE BADGE	75444 02110		15.00	
4985	END PANEL TRIM	58387 02030B0		20.00	
1000	Rivet	Lamp Panel	Supplementary Item	12.00	
f: OEM Parts				Savings	0.00
n: Non-OEM Parts				Subtotal	477.00
u: Used parts				Addition(+10.00%)	47.70
Total				524.70	

ETHOZ Automotive Solutions Ltd
30 Bukit Batok Crescent
658075

FINALIZATION REPORT

Claim Reference:
Assessment number: SIN00013
Version: 1810
Date calculated: 04/03/2019 10:23 AM

Full Report
Registration: SGV446Z
Printed: 03/04/2019 10:24 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	Ethoz Bukit Batok 02	Currency:	SGD
Claim Reference:		Date of Incident:	2019-03-08
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	COROLLA(ZZE122/30)
Sub Model:	BASE MODEL
Model Sheet Number:	70 93 01
Registration:	SGV446Z
VIN number:	
Odometer:	

Model Specs

PROD CONTRY MALAISIA	TWO COAT METALLIC	PREPARE OFF VEHICLE
----------------------	-------------------	---------------------

ETHOZ Automotive Solutions Ltd
30 Bukit Batok Crescent
658075

Claim Reference:
 Assessment number: SIN00013
 Version: 1810
 Date calculated: 04/03/2019 10:23 AM


Full Report
 Registration: SGV446Z
 Printed: 03/04/2019 10:24 AM

Vehicle Condition

Vehicle Status
 Pre-Accident Damage:
 Date of Inspection:

Damage Areas

All
 Underbody



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
B290	RENEW REAR END PANEL (BUMPER REMOVED) INCLUDES: BOTH REAR LAMPS, FLOOR MAT BOOT COMPARTMENT AND ALL TRIMS IN REPAIR AREA REMOVE AND REFIT		33.0	148.50
NO NUMBER	R + R BOOTLID TRIM		1.0	4.50
640201)	R + R BOOT LID LOCK		2.0	9.00
750171	RENEW BADGE "TOYOTA"		2.0	9.00
750171	RENEW BADGE "TOYOTA"		2.0	9.00
750171	RENEW BADGE "COROLLA"		2.0	9.00
B420)	RENEW REAR BUMPER (REMOVED)		1.0	4.50
B410	R + R REAR BUMPER		6.0	27.00
2931	BOOTLID REPAIR		10.0*	45.00

ETHOZ Automotive Solutions Ltd
30 Bukit Batok Crescent
658075

Claim Reference:
 Assessment number: SIN00013
 Version: 1810
 Date calculated: 04/03/2019 10:23 AM

Full Report
 Registration: SGV446Z
 Printed: 03/04/2019 10:24 AM

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	5.90	59.0	265.50
Total of Labour			265.50

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	REAR PANEL NEW PART PAINTING	20.0
	REAR BUMPER NEW PART PAINT K1R	11.0
	BOOTLID REPAIR PAINTING <50%	17.0

Paint Material Per Part

Code	Description	Price SGD
2711	REAR PANEL NEW PART PAINTING	24.20
2581	REAR BUMPER NEW PART PAINT K1R	51.66
2931	BOOTLID REPAIR PAINTING <50%	30.69

Labour Cost - Paint	Hrs	WU	Price SGD
Factor	45.00 SGD/h		
Time Paint		48.0	
Preparation Main Work Metal	2.50	25.0	112.50
Preparation Comp. Work Plastic	0.50	5.0	22.50
Total	10 WU/h	78.0	351.00

Material Cost - Paint	Price SGD
New Part Painting	24.20
New Part Painting - Plastic K1R	51.66
Repair Painting	30.69
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	144.15

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01
				Price SGD
2581	REAR BUMPER	52159 02904		140.00
2619	L/R BUMPER BRACKET	52156 02030		8.00




日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

ETHOZ PROTECT PTE LTD
50 GUL CRESCENT

SINGAPORE
ATTN : BRYAN

TAX INVOICE : AR201903-07945
DATE : 15/03/2019
CUSTOMER ID : ORI004
VEH REG. NO. : SGV446Z
TERMS : 30 days
PO NO. : 170404
PAGE NO. : Page 1 of 1
CURR : S\$

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	T90269-06013 AE111	RIVET (FUEL LID)	CC CC12-N-03B9	8	1.50	12.00

SUB-TOTAL : 12.00
ADD GST 7.00 % 0.84

E. & O.E TOTAL AMOUNT S\$: 12.84

[P] 15/03/2019 5:48:12PM
Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 15/03/2019 5:47:27PM

JAE Auto Pte. Ltd.
Sales Executive: LAI



Goods Received in Good Order

This is computer generated document.
No signature is required.

Lee Chen Sin Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729872
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

INDEPENDENT SALES GROUP
Dept Direct: 6417 9791 / 6745 9803



Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

ETHOZ PROTECT PTE LTD
50 GUL CRESCENT

SINGAPORE

ATTN : BRYAN

TAX INVOICE : AR201903-07430
DATE : 15/03/2019
CUSTOMER ID : ORI004
VEH REG. NO. : SGV446Z
TERMS : 30 days
PO NO. : 170404
PAGE NO. : Page 1 of 2
CURR : S\$

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	T75442-02040/1 ZZE121 ALTIS	RR BOOT "COROLLA" EMBLEM	PA PL2-J1-08L	1	10.00	10.00
2	T75443-06151 ALL MODEL	VVTI EMBLEM	PA PL2-J1-08F	1	12.00	12.00
3	T75447-12070 ZZE121	RR BOOT "1.6" EMBLEM	PA PL2-K1-05J	1	18.00	18.00
4	T75444-02090/1 ZZE121 ALTIS	RR BOOT "ALTIS" EMBLEM	PA PL2-J1-08F	1	12.00	12.00
5	T75444-02140/1 ACV31/TH	RR BOOT "E" EMBLEM	PA PL2-K1-06L	1	15.00	15.00
6	T52159-02904 ALTIS-ZZE121	RR BUMPER	PA PL4-D1-22	1	140.00	140.00
7	T52161-16010 ROC ALL MODEL	BUMPER CLIP	PA PL2-N1-04A	10	1.50	15.00

CONTINUE NEXT PAGE

[P] 15/03/2019 10:18:16AM

[E] 15/03/2019 10:06:50AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL



Lee Chen Sin



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

Dept Direct: 6417 9781 / 6415 9833



Dept Direct: 6305 9010

Dept Direct: 6305 9011


Dept Direct: 6417 9770




Dept Direct: 6417 9794



Dept Direct: 6417 9795



Dept Direct: 6417 9796



Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blade), Stripper (Made in Korea),

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

ETHOZ PROTECT PTE LTD
50 GUL CRESCENT

SINGAPORE

ATTN : BRYAN

TAX INVOICE : AR201903-07430
DATE : 15/03/2019
CUSTOMER ID : ORI004
VEH REG. NO. : SGV446Z
TERMS : 30 days
PO NO. : 170404
PAGE NO. : Page 2 of 2
CURR : S\$

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
8	T58307-1A560/620/570 ALTIS-ZZE121	END PANEL (LA570)	PA PL2-P1-02B	1	150.00	150.00
9	T64461-02060 ZZE121	RR BOOT RUBBER **GT-326**	PA NEW	1	22.00	22.00
10	T64610-02050/12350 ZZE121 ALTIS	RR BOOT INNER LOCK **GT-326**	PA NEW	1	15.00	15.00
11	T52155-02040 ALTIS-ZZE121	RR BUMPER S/RETAINER RH **GT-326**	PA NEW	1	8.00	8.00
12	T52156-02030 ALTIS-ZZE121	RR BUMPER S/RETAINER LH **GT-326**	PA NEW	1	8.00	8.00
13	T52181-02030 ALTIS-ZZE121	RR BUMPER BRACKET L/R **GT-326**	PA NEW	2	10.00	20.00
14	T58387-02030BQ ALTIS-ZZE121	END PANEL TRIM **GT-326**	PA NEW	1	20.00	20.00

SUB-TOTAL : 465.00
ADD GST 7.00 % 32.55

E & O E TOTAL AMOUNT S\$: 497.55

[P] 15/03/2019 10:18:16AM

[E] 15/03/2019 10:06:50AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: LAI

This is computer generated document.

No signature is required.



Lee Chen Sin

ORIGINAL

Goods Received in Good Order



[Handwritten Signature]

Signature / Co Stamp / Date

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
Assessment number: SIN00013
Version: 1810
Date calculated: 04/12/2019 04:20 PM

Full Report
Registration: SGV446Z
Printed: 12/04/2019 4:20 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:		Date of Incident:	2019-03-08
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	COROLLA(ZZE122/30)
Sub Model:	BASE MODEL
Model Sheet Number:	70 93 01
Registration:	SGV446Z
VIN number:	
Odometer:	

Model Specs

PROD CONTRY MALAISIA	TWO COAT METALLIC	PREPARE OFF VEHICLE
----------------------	-------------------	---------------------

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
 Assessment number: SIN00013
 Version: 1810
 Date calculated: 04/12/2019 04:20 PM

Full Report
 Registration: SGV446Z
 Printed: 12/04/2019 4:20 PM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
 Date of Inspection:

Damage Areas

All
 Underbody



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
B290	RENEW REAR END PANEL (BUMPER REMOVED) INCLUDES: BOTH REAR LAMPS, FLOOR MAT BOOT COMPARTMENT AND ALL TRIMS IN REPAIR AREA REMOVE AND REFIT		33.0	148.50
NO NUMBER	R + R BOOTLID TRIM		1.0	4.50
640201)	R + R BOOT LID LOCK		2.0	9.00
750171	RENEW BADGE "TOYOTA"		2.0	9.00
750171	RENEW BADGE "TOYOTA"		2.0	9.00
750171	RENEW BADGE "COROLLA"		2.0	9.00
B420)	RENEW REAR BUMPER (REMOVED)		1.0	4.50
B410	R + R REAR BUMPER		6.0	27.00
2931	BOOTLID REPAIR		10.0*	45.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
 Assessment number: SIN00013
 Version: 1810
 Date calculated: 04/12/2019 04:20 PM

Full Report
 Registration: SGV446Z
 Printed: 12/04/2019 4:20 PM

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	5.90	59.0	265.50
Total of Labour			265.50

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	REAR PANEL NEW PART PAINTING	20.0
	REAR BUMPER NEW PART PAINT K1R	11.0
	BOOTLID REPAIR PAINTING <50%	17.0

Paint Material Per Part

Code	Description	Price SGD
2711	REAR PANEL NEW PART PAINTING	24.20
2581	REAR BUMPER NEW PART PAINT K1R	51.66
2931	BOOTLID REPAIR PAINTING <50%	30.69

Labour Cost - Paint	Hrs	WU	Price SGD
Factor			45.00 SGD/h
Time Paint		48.0	
Preparation Main Work Metal	2.50	25.0	112.50
Preparation Comp. Work Plastic	0.50	5.0	22.50
Total		7.80	78.0
			351.00

Material Cost - Paint	Price SGD
New Part Painting	24.20
New Part Painting - Plastic K1R	51.66
Repair Painting	30.69
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	144.15

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	Price SGD
2581	REAR BUMPER	52159 02904			140.00
2619	L/R BUMPER BRACKET	52156 02030			8.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
 Assessment number: SIN00013
 Version: 1810
 Date calculated: 04/12/2019 04:20 PM

Full Report
 Registration: SGV446Z
 Printed: 12/04/2019 4:20 PM

Code	Description	Part Number	Supplier	Price SGD
2620	R/R BUMPER BRACKET	52155 02040		8.00
2625	L/R CTR BUMPER BRKT	52181 02030		10.00
2626	R/R CTR BUMPER BRKT	52181 02030		10.00
2650	RR BUMPER CLAMP KIT	90467 09093		15.00
2711	REAR PANEL	58307 1A620		150.00
2944	BOOTLID SEAL	64461 02060		22.00
2977	BOOT/TAILGATE LOCK	64610 02050		15.00
3013	MANUFACTURER BADGE	75441 02090		10.00
3014	BADGE	75485 12380		12.00
3016	BADGE	75443 1A840		18.00
3017	BADGE MODEL	75442 02130		12.00
3019	TYPE BADGE	75444 02110		15.00
4985	END PANEL TRIM	58387 02030B0		20.00
1000	Rivet	Lamp Panel		12.00

f: OEM Parts
 n: Non-OEM Parts
 u: Used parts

Savings	0.00
Subtotal	477.00
Addition(+10.00%)	47.70
Total	524.70

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
 Assessment number: SIN00013
 Version: 1810
 Date calculated: 04/12/2019 04:20 PM

Full Report
 Registration: SGV446Z
 Printed: 12/04/2019 4:20 PM

Final Calculation

	SGD	SGD
Parts	477.00	
Addition(+10.00%)	47.70	
Total Parts		524.70
Labour Time Base 10 WU/h		
Total 59.0 WU X 45.00 SGD/h	265.50	
Total of Labour		265.50
Paint Work Time Base 10 WU/h		
Labour Cost 78.0 WU X 45.00 SGD/h	351.00	
Material Cost	144.15	
Total Paint Including Material		495.15
Repair Cost Excludes GST		1,285.35
GST (+7.00%)		89.97
Repair Cost Included GST		1,375.32
Deductions (Excludes GST)		
Total Of Deductions (Excludes GST)		-500.00
Grand Total Excludes GST		785.35
GST (+7.00%)		54.97
Grand Total Included GST		840.32

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS