

INS. CASE OWNER:

CC 6, C11 1900 4583, P 302

LAX: IDAC

Surveyor:

RSC

DOI:

11/3/19

Date / Time:

11/3/19

Registered in Merit:

Pre-assign / CCU / FTE



Insured Vehicle No. : PC 4171 H

Claim No. : \_\_\_\_\_

Name of Insured : LONLUM PLC

Policy No. : \_\_\_\_\_

Insured Tel No. : \_\_\_\_\_ HP: \_\_\_\_\_

Make / Model : \_\_\_\_\_

Excess Sec II :SS \_\_\_\_\_ D.O.A: 8/3/19

Place of Accident : \_\_\_\_\_

Is driver the owner? ( YES / NO ) Nature of Accident : \_\_\_\_\_

If NO, Driver Name / Age : \_\_\_\_\_

OI GIA REPORT YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : \_\_\_\_\_ (V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SJW 32440



INSRS: WSP: *Waikae*  
Tel: \_\_\_\_\_  
Liability: \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS: WSP: \_\_\_\_\_  
Tel: \_\_\_\_\_  
Liability: \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS: WSP: \_\_\_\_\_  
Tel: \_\_\_\_\_  
Liability: \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS: WSP: \_\_\_\_\_  
Tel: \_\_\_\_\_  
Liability: \_\_\_\_\_  
RMKS: \_\_\_\_\_

Date/Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI: <i>EMAIL 28.06.19</i>	
	After call ltr to OI:	
	<b>Documentation Check List:</b>	<b>Handler</b> <b>Typist</b>
	Notification ltr (if non-pickup)	<input type="checkbox"/> <input type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Authorization To Act:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/> <input type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/> <input type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/> <input type="checkbox"/>
	PIR:	<input type="checkbox"/> <input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	LOD:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
	Others:	<input type="checkbox"/> <input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: \_\_\_\_\_ Sent By: \_\_\_\_\_

FINALIZATION Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Confirm by: *KSC*

Repair Cost: *45* \$S 4,100 ( 6 days) Reduction: 31 % Email  Call

FINAL SETTLEMENT Date/Time: 09.11.19 Confirm with: *KAREN* Email  Call

Final Liability: % *100* (Agreed / Assessed) BOLA S/N No. : *21* If NO or B 28, Ass. Lia : \_\_\_\_\_

Repair Cost: *1160* \$S 5,109.40 *NO FARE ENDED TP*

Loss of Rental (LOR): \$S - ( days) **COPY SENT 26/11/19**

Loss of Use (LOU): \$S 4500 (\$10 x 3 days)

Loss of Income (LOI): \$S - (\$ x days)

LOR only  LOU only  LOR + LOU  LOR + LOI  [Tick only one]

GIA/LTA Search \$S 1.45 Medical: \$S - Disbursement: \$S - (e.g. Tow/ Independent) Legal Cost: \$S - Total: \$S 5,516.45 Global Sum \$S: \_\_\_\_\_

FINAL PAYMENT Date/Time: 12.11.19 Confirm with: *KAREN* Email  Call

Payee 1: \$S 5,516.45 Name 1: *WAI LEE MOTOR WORKS*

Payee 2: (Strike if N.A.) \$S Name 2: \_\_\_\_\_

Payee 3: (Strike if N.A.) \$S Name 3: \_\_\_\_\_





Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA  
Our ref: CC6/CTI19004583/Kpa3

Date: 15/03/2019

The Motor Claims Department  
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SJW 3244D**


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 11/03/2019 at the premises of M/s Wei Lee Motor Works - Sin Ming and have the following to report:-

Workshop Estimate Amount	: S\$	<u>7,430.36</u>
Revised Estimate Amount	: S\$	<u>4,700.00</u>
"Check" Items Amount	: S\$	<u>-</u>
Total (Including Check Items)	: S\$	<u>4,700.00</u>
Market Value	: S\$	<u>- (est.)</u>
LTA Reimbursement Value	: S\$	<u>- (est.)</u>
Nett Value	: S\$	<u>- (est.)</u>

**Description of Damage:**

The vehicle sustained damages at the  
Rear N/S Portion



**Comments/Present Status:**

Damages Consistent

Estimated normal period for repairs: 6 days

Yours faithfully,

**KENNETH KONG**  
**Licensed Appraiser**

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1813C
Vehicle Details	
Vehicle No.:	5JW3244D
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2010
Engine No.:	3Z24986629
Chassis No.:	MR053ZEE106171738
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,716.00
Original Registration Date:	18 Mar 2010
First Registration Date:	18 Mar 2010
Transfer Count:	2
Actual ARF Paid:	\$16,716.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Mar 2020
PARF Rebate Amount:	\$9,193.00
Intended COE Rebate Details	
COE Expiry Date:	17 Mar 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$20,802.00
COE Rebate Amount:	\$2,108.00
<b>Total Rebate Amount:</b>	<b>\$11,301.00</b>

The information contained herein is correct as at 12 Mar 2019

OK

# 威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,  
SINGAPORE 575644.  
TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com  
Business Regn No: 269438/00J

11, MAR 2019

China Taiping Insurance (S) PL  
105 Cecil Street #18-00  
The Octagon S 069534

Attn: motor claim dept-3<sup>rd</sup> party claim  
Claiming against your insured vehicle no: PC4171H  
Accident involving vehicle no: SJW3244D/Pc4171H  
DOA: 08/03/2019 AT Telok Blangah Road twds Kampong Bahru Road

Not Authorized  
11 Sep @ 4700h  
Resurvey After Paint  
8 days

Dear officer incharge  
Re: Estimate cost of repair for vehicle no: SJW3244D

To supply—

Description	Qty	Amount	
Rear bumper	1 <i>RH</i>	482.00	✓
Rear bumper enforcement/sponge	1	<i>CPM</i> 123.50	—
Rear bumper clip		<i>RM</i> 38.00	—
Rear bumper retainer @69.80	2 <i>NISOT</i>	139.60	✓
Rear bumper foglamp @37.20	2	<i>RM</i> 74.40	X
End panel	1	<i>RH</i> 580.60	✓
End panel top garnish	1	<i>RM</i> 202.70	✓
Lid	1	<i>RH</i> 618.50	✓
Lid outer handle	1	<i>Wagon</i> 136.20	✓
Lid hinge @47.70	2	<i>R</i> 95.40	X
Lid-lock	1	<i>RM</i> 35.80	✓
Lid-1.6 emblem	1	<i>RM</i> 32.40	—
Lid-Altis emblem	1	<i>RM</i> 25.70	—
Lid-corolla emblem	1	<i>RM</i> 24.10	—
Lid-TOYOTA logo	1	<i>RM</i> 66.20	—
Boot weather strip	1	<i>DIT/GR</i> 63.10	301h
Lid-reflector @171.60	2 <i>NISCOM</i>	343.20	✓
Taillamp @409.90	2 <i>NISCOM</i> <i>ORISAU</i>	819.80	✓
Lid doorboard	1	<i>RM</i> 159.10	X
Doorboard cover @32.60	2	<i>RM</i> 65.20	X
Spare tyre panel	1	<i>R</i> 757.00	X
Raer fender,Lh	1	<i>Bur</i> 918.00	✓
Parts		5,800.50	
Parts less 25%		1,450.13	
		4,350.36	

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

Tow fee	80.00	501
Reverse sensor	220.00	2005A
Rear bumper sticker (advertisement)	120.00	605A
To remove/refit rear windscreen glass	160.00	1201
To remove damaged parts and attachments.		
Cut n weld damaged panel.		
Straighten rear chassis where necessary.		
Repair/reshape dented/damaged areas.		
Replace/align all parts	1,300.00	12001
To spray paint.	1,200.00	10001
	<hr/>	
	7,430.36	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI19004583/Kea3n2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 27-11-2019	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	PC 4171H	Veh. Inspected	SJW 3244D
Policy No.	DMB1SN1745431802	Coverage (\$)	0.00
Claim No.	SNM19D201108	Excess (\$)	0.00
Assign From		Assign Date	11/03/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA ALTIS (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	MR053ZEE106171738	Colour	METALLIC GREEN
Odometer	197572	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	3 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	3 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	8 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	08/03/2019	Inspection Date	11/03/2019
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>6 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJW 3244D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	BENT	482.00	482.00
1	REAR BUMPER ENFORCEMENT/SPONGE	CRACKED	123.50	123.50
1	REAR BUMPER CLIP	NECESSARY	38.00	38.00
2	REAR BUMPER RETAINER @\$69.80	N/S DISTORTED	139.60	69.80
2	REAR BUMPER FOGLAMP @\$37.20	SERVICEABLE	74.40	-
1	END PANEL	BENT	580.60	580.60
1	END PANEL TOP GARNISH	DENTED	202.70	202.70
1	LID	BENT	618.50	618.50
1	LID OUTER HANDLE	WARPED	136.20	136.20
2	LID HINGE @\$47.70	TO REPAIR SEE LABOUR	95.40	-
1	LID-LOCK	DENTED	35.80	35.80
1	LID-1.6 EMBLEM	NECESSARY	32.40	32.40
1	LID-ALTIS EMBLEM	NECESSARY	25.70	25.70
1	LID-COROLLA EMBLEM	NECESSARY	24.10	24.10
1	LID-TOYOTA LOGO	NECESSARY	66.20	66.20
2	LID-REFLECTOR @\$171.60	N/S CRACKED	343.20	171.60
2	TAILLAMP @\$409.90	N/S CRACKED / O/S DENTED	819.80	819.80
1	LID DASHBOARD	SERVICEABLE	159.10	-
2	DOORBOARD COVER @\$32.60	SERVICEABLE	65.20	-
1	SPARE TRYE PANEL	TO REPAIR SEE LABOUR	757.00	-
1	REAR FENDER,LH	BUCKLED	918.00	918.00
	LESS 25% DISCOUNT		-1,434.35	-1,086.23
			4,303.05	3,258.67
1	BOOT WEATHER STRIP (50%)(SN)	DISTORTED / CUT	63.10	31.55
	LESS 25% DISCOUNT		-15.78	-
			47.32	31.55



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>SPECIAL NETT ITEMS</b>			
1	REVERSE SENSOR (SN)	TORN	220.00	200.00
1	REAR BUMPER STICKER (ADVERTISEMENT)(SN)	NECESSARY	120.00	60.00
			340.00	260.00
	<b>LABOUR</b>			
	TOW FEE.		80.00	50.00
	TO REMOVE/REFIT REAR WINDSCREEN GLASS.		160.00	120.00
	TO SPRAY PAINT.		1,200.00	1,000.00
	TO REMOVE DAMAGED PARTS AND ATTACHMENTS.CUT N WELD DAMAGED PANEL.STRAIGHTEN REAR CHASSIS WHERE NECESSARY,REPAIR/RESHAPE DENTED/DAMAGED AREAS.REPLACE/ALIGN ALL PARTS.INCLUSIVE OF THE REPAIR OF LID HINGE AND SPARE TRYE PANEL.		1,300.00	1,200.00
			2,740.00	2,370.00
	<b>GRAND TOTAL</b>		<b>7,430.37</b>	<b>5,920.22</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>4,700.00</b>

Report Ref No. CC6/CT119004583/Kea3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.