

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

11, MAR 2019

China Taiping Insurance (S) PL
105 Cecil Street #18-00
The Octagon S 069534

Attn: motor claim dept-3rd party claim

Claiming against your insured vehicle no: PC4171H

Accident involving vehicle no: SJW3244D/Pc4171H

DOA: 08/03/2019 AT Telok Blangah Road twds Kampong Bahru Road

Not Authorized
L1 Rep & 4700k
Resurvey After Paint
8 days

Dear officer incharge

Re: Estimate cost of repair for vehicle no: SJW3244D

To supply—

Description	Qty	Amount	
Rear bumper	1 <i>Rn</i>	482.00	✓
Rear bumper enforcement/sponge	1 <i>CPA</i>	123.50	—
Rear bumper clip		<i>na</i> 38.00	—
Rear bumper retainer @69.80	2 <i>NIJOT</i>	139.60	✓
Rear bumper foglamp @37.20	2	<i>na</i> 74.40	X
End panel	1 <i>Rn</i>	580.60	✓
End panel top garnish	1 <i>Rd</i>	202.70	✓
Lid	1 <i>Rn</i>	618.50	✓
Lid outer handle	1 <i>warp</i>	136.20	✓
Lid hinge @47.70	2 <i>R</i>	95.40	X
Lid-lock	1 <i>Rd</i>	35.80	—
Lid-1.6 emblem	1 <i>na</i>	32.40	—
Lid-Altis emblem	1 <i>na</i>	25.70	—
Lid-corolla emblem	1 <i>na</i>	24.10	—
Lid-TOYOTA logo	1 <i>na</i>	66.20	—
Boot weather strip	1 <i>D.7/6m</i>	63.10	30% ✓
Lid-reflector @171.60	2 <i>NIJOT</i>	343.20	✓
Taillamp @409.90	2 <i>NIJOT of 100</i>	819.80	✓
Lid doorboard	1 <i>na</i>	159.10	X
Doorboard cover @32.60	2 <i>na</i>	65.20	X
Spare tyre panel	1 <i>R</i>	757.00	X
Raer fender,Lh	1 <i>Bar</i>	918.00	✓
Parts		5,800.50	
Parts less 25%		1,450.13	
		4,350.36	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tow fee	80.00	500
Reverse sensor	220.00	2000
Rear bumper sticker (advertisement)	120.00	6000
To remove/refit rear windscreen glass	160.00	1200
To remove damaged parts and attachments.		
Cut n weld damaged panel.		
Straighten rear chassis where necessary.		
Repair/reshape dented/damaged areas.		
Replace/align all parts	1,300.00	12000
To spray paint.	1,200.00	10000
	<hr/>	
	7,430.36	