



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VECHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

GBH 3672 A
TOYOTA DYNA

ATTN:		
NO.	DESCRIPTION - PARTS	QTY PRICE
	FUEL TANK ASSY 945.10 10/300	\$ 1,458.00
	FUEL TANK BRACKET - FRONT 11	\$ 215.00
	FUEL TANK BRACKET - REAR 11	\$ 215.00
	SUBTOTAL	\$ 1,888.00
	LESS 25%	\$ 472.00
	PARTS TOTAL	\$ 1,416.00
	SPECIAL NETT	QTY PRICE
	REAR CABIN SIDE PANEL 12	\$ 2,000.00
	REAR CABIN SIDE RALLING - UPPER 11	\$ 2,000.00
	REAR CABIN SIDE RALLING ROLLER - LOWER Bent	\$ 2,500.00
	REAR CABIN SIDE GATE FRONT 10/300	\$ 4,000.00
	REAR CABIN SIDE PANEL SEAL 11	\$ 400.00
	REAR CABIN SIDE PANEL SEALANT 11	\$ 200.00
	SPECIAL NETT TOTAL	\$ 11,100.00
	LABOUR	QTY PRICE
	TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN 500	\$ 1,800.00
	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA 300	\$ 1,600.00
	TO RUST PROOF ACCIDENT AFFECTED AREA 11 X	\$ 160.00
	TO RNR REAR CABIN TO ASSIST WORK LOAD 11 X	\$ 2,800.00
	TO RNR UNDERCARRAIGE SYSTEM 12 X	\$ 600.00
	TO CHECK WHEEL ALIGNMENT 11 X	\$ 200.00
	TO RNR FUEL TANK TO ASSIST WORK LOAD 60	\$ 600.00
	LABOUR TOTAL	\$ 7,760.00
	GRAND TOTAL COST	\$ 20,276.00
KK Auto Consultants hence notify		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-708-82
S.N 2000-00
60km - 860.00
3568.82
202
2855.05

Not Authorised
LKK
2/5 \$2850/2
4 day
13/3/19
take photo of the work