

INS. CASE OWNER:

CC 4, ALA 1900

4584, Khasy, K

IDAC:

Surveyor:

CSL

DOI:

ASSIGNMENT

13/3/19

Date / Time:

13/3/19

Registered in Merimen:

13/3/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SBX 7775

Name of Insured:

Lay Seng Ann

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

8/3/19

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final? Yes / No

SBX 7775

SLA 916K

SJE 3270Y



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorization To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: R/P

SS

13,048.30

(11 days)

Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Final Liability:

%

100

(Assessed)

BOLA S/N No.:

28

If NO or B 28, Ass. Lia:

100%

Repair Cost: C/L (G70)

SS

14,005.50

Loss of Rental (LOR):

SS

1,500.00

(15 days)

x \$100.00

Loss of Use (LOU):

SS

-

(\$ x days)

Loss of Income (LOI):

SS

-

(\$ x days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

2.00

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

Total:

SS

16,105.50

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS

16,105.50

Name 1:

Accord Auto Services Pte Ltd

Payee 2: (Strike if N.A.)

SS

-

Name 2:

Payee 3: (Strike if N.A.)

SS

-

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$320

COPY SENT
16/3/19

ASS. REC. BY:

REF:

A161

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

11

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1

File pass to

P/P + 13.648.13

Cred: P

11 days + 2 sundays + 3 PPS = 16 days

Date/Time, File Pass to?

☐

: Preil. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Veh No:

SLA 916K

Yr Regn:

01, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volkswagen

Tetra cc

1390

Colour:

Red

A/C: Insured / Std / NI / NA

Sp. Reading

38833

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WVW 888188GM 007019

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

205/55R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU (PIR) SUMI / TOYO / YOKO or

Front

R/Bal.

P

mm

Rear

R/Bal.

P

mm

L/Bal.

P

mm

L/Bal.

P

mm

D.O.A.

8/13/19

D.O.I.

13/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

8/19

The U/C / Chassis frame / Body Structure affected due to collision.

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way,
AIG Building #09-16
Singapore 079120
Attn: Motor Claims Department

Date: 12/03/2019
Vehicle No: SLA916K
Veh Make/Model: Volk. Jetta GP 1.4 TSI
YOM: 2015
Chassis No: WVWZZZ16ZGM007019
Date of Accident: 08/03/2019

Not Authorised

11 Day 87

Reserve After Repair

11 days
@ 13,648.13

No	Qty	Description	Amount S
		List Items:-	
1	1	Bonnet	\$ R 1,097.50
2	1	Front grille assy	\$ Sun 545.00
3	1	RH headlamp *	\$ CM 2,380.00
4	1	LH headlamp *	\$ Sun 2,380.00
5	1	Front bumper	\$ Bu 1,017.00
6	1	Front bumper grille	\$ CM 257.50
7	2	Front bumper side retainer	\$ 61.20
8	1	Bootlid	\$ R 2,250.00
9	1	Bootlid logo	\$ M 137.50
10	1	Bootlid "JETTA" emblem	\$ M 72.00
11	1	Bootlid "TSI" emblem	\$ M 54.00
12	1	Bootlid number plate lamp	\$ R 126.00
13	1	Bootlid reflector (LH)	\$ CM 337.50
14	1	Bootlid reflector (RH)	\$ CM 337.50
15	1	Bootlid lock	\$ B 162.50
16	1	Bootlid weatherstrip	\$ D/L 264.00
17	1	Bootlid inner trim board	\$ R 250.00
18	1	LH tail lamp	\$ R 408.00
19	1	RH tail lamp	\$ CM 408.00
20	1	Rear fender (LH)	\$ R 1,504.00
21	1	Rear fender (RH)	\$ R 1,504.00
22	1	Rear bumper	\$ Bu 992.80
23	1	Rear bumper reflector (LH)	\$ R 65.00
24	1	Rear bumper reflector (RH)	\$ CM 65.00
25	1	Rear bumper lower cover	\$ R 451.20
26	1	Rear bumper centre bracket	\$ CM 72.00
27	2	Rear bumper side retainer	\$ D/L 188.00
28	2	Rear bumper side bracket	\$ R 188.00
29	1	Rear bumper reinforcement	\$ R 582.50
30	1	End panel	\$ R 876.10
		Balance b/f	\$ 19,033.80

LES Auto Consultants hence notify the Insured of the following:
 • To (insuree) before (to) repair (to) repair
 • To display (damaged parts) (to) repair (to) repair
 • Parts prices are subject to (to) repair (to) repair
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be (to) repair (to) repair
 is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

Date : 12/03/2019
Vehicle No : SLA916K
Veh Make/Model : Volk. Jetta GP 1.4 TSI
YOM : 2015
Chassis No : WVWZZZ16ZGM007019
Date of Accident : 08/03/2019

Page 2/3

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way,
AIG Building #09-16
Singapore 079120
Attn: Motor Claims Department

Date : 12/03/2019
Vehicle No : SLA916K
Veh Make/Model : Volk. Jetta GP 1.4 TSI
YOM : 2015
Chassis No : WVWZZZ16ZGM007019
Date of Accident : 08/03/2019

[illegible]

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

SUPPLEMENTARY

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way,
AIG Building #09-16
Singapore 079120
Attn: Motor Claims Department

Date : 14/03/2019
Vehicle No : SLA916K
Veh Make/Model : Volk. Jetta GP 1.4 TSI
YOM : 2015
Chassis No : WVVZZZ16ZGM007019
Date of Accident : 08/03/2019

[illegible]

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

Not Authorised

ESTIMATE

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way,
AIG Building #09-16
Singapore 079120
Attn: Motor Claims Department

U/Sy B?
Resuming After Paint
11 days

Date: 12/03/2019
Vehicle No: SLA916K
Veh Make/Model: Volk. Jetta GP 1.4 TSI
YOM: 2015
Chassis No: WVWZZZ16ZGM007019
Date of Accident: 08/03/2019

No	Qty	Description	Amount S
List Items:-			
1	1	Bonnet	\$ <i>R</i> 1,097.50
2	1	Front grille assy	\$ <i>Sm</i> 545.00
3	1	RH headlamp *	\$ <i>CM</i> 2,380.00
4	1	LH headlamp *	\$ 2,380.00
5	1	Front bumper	\$ <i>Bu</i> 1,017.00
6	1	Front bumper grille	\$ <i>CM</i> 257.50
7	2	Front bumper side retainer <i>O/S DIT</i>	\$ 61.20
8	1	Bootlid	\$ <i>R</i> 2,250.00
9	1	Bootlid logo	\$ <i>Sm</i> 137.50
10	1	Bootlid "JETTA" emblem	\$ <i>Sm</i> 72.00
11	1	Bootlid "TSI" emblem	\$ <i>Sm</i> 54.00
12	1	Bootlid number plate lamp	\$ <i>R</i> 126.00
13	1	Bootlid reflector (LH)	\$ <i>CM</i> 337.50
14	1	Bootlid reflector (RH)	\$ <i>CM</i> 337.50
15	1	Bootlid lock	\$ <i>O/S</i> 162.50
16	1	Bootlid weatherstrip	\$ <i>DIT/Let</i> 264.00
17	1	Bootlid inner trim board	\$ 250.00
18	1	LH tail lamp	\$ 408.00
19	1	RH tail lamp	\$ <i>CM</i> 408.00
20	1	Rear fender (LH)	\$ <i>R</i> 1,504.00
21	1	Rear fender (RH)	\$ <i>R</i> 1,504.00
22	1	Rear bumper	\$ <i>Bu</i> 992.80
23	1	Rear bumper reflector (LH)	\$ <i>Sm</i> 65.00
24	1	Rear bumper reflector (RH)	\$ <i>CM</i> 65.00
25	1	Rear bumper lower cover	\$ <i>R</i> 451.20
26	1	Rear bumper centre bracket	\$ 72.00
27	2	Rear bumper side retainer	\$ <i>DIT</i> 188.00
28	2	Rear bumper side bracket	\$ 188.00
29	1	Rear bumper reinforcement	\$ <i>R</i> 582.50
30	1	End panel	\$ <i>R</i> 876.10
Balance b/f			\$ 19,033.80

L&K Auto Consultants hence notify the Repairer of the following:

- To temporary inform the repairer of the following
- To display damaged part(s) during insurance
- Parts prices are subject to change
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary costs must be reimbursed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way,
AIG Building #09-16
Singapore 079120
Attn: Motor Claims Department

Date : 12/03/2019
Vehicle No : SLA916K
Veh Make/Model : Volk. Jetta GP 1.4 TSI
YOM : 2015
Chassis No : WVVZZZ16ZGM007019
Date of Accident : 08/03/2019

[illegible]

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way,
AIG Building #09-16
Singapore 079120
Attn: Motor Claims Department

Date : 12/03/2019
Vehicle No : SLA916K
Veh Make/Model : Volk. Jetta GP 1.4 TSI
YOM : 2015
Chassis No : WVWZZZ16ZGM007019
Date of Accident : 08/03/2019

No	Qty	Description	Amount \$
		Balance c/f	\$ 20,231.92
		<u>Labour Charges:-</u>	
1		Spray painting on all affected area.	\$ 2,200.00
2		Labour remove/refix accident damages parts to knock, jack, cut weld and realign accident affected area.	\$ 2,400.00
3		To apply anti rust treatment.	\$ 150.00
4		To check wiring system & light.	\$ 120.00
5		To remove and replace front bumper sensor.	\$ 120.00
6		To remove and replace reverse sensor.	\$ 120.00
7		To adjust chassis alignment on car 'O' liner.	\$ 350.00
8		To transfer bootlid inner compartment, mechanism and accessories.	\$ 200.00
9		To check and test rear bootlid water leaking.	\$ 80.00
10		To adjust and remain exhaust silencer system.	\$ 200.00
11		Upholstery details cleaning.	\$ 220.00
12		Computer diagnostic after repair.	\$ 300.00
		Total - L/C	\$ 6,460.00
		Sub-Total	\$ 26,691.92
		7% GST	\$ 1,868.43
		Total	\$ 28,560.35

[Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle No.:	SLA916K
Vehicle Type:	P10 - Passenger Motor Car
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	JETTA GP 1.4 TSI 90 A/T HL HID 1634G5
Chassis No.:	WVWZZZ16ZGM007019
Propellant:	Petrol
Engine No.:	CAXF82973
Engine Capacity:	1390 cc
Maximum Power Output:	90.0 kW (120 bhp)
Maximum Laden Weight:	1870 kg
Unladen Weight:	1417 kg
Year Of Manufacture:	2015
Original Registration Date:	29 Jan 2016
Lifespan Expiry Date:	-
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
Quota Premium:	\$51,301.00
COE Expiry Date:	28 Jan 2026
Road Tax Expiry Date:	28 Jul 2019
PARF Eligibility Expiry Date:	28 Jan 2026
Inspection Due Date:	28 Jan 2021
Intended Transfer Date:	11 Mar 2019
CO2 Emission:	138.00 (g/km)
CEV/VES Rebate Utilised Amount:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

You may print this page for reference.

OK

Print

Pre-Repair Inspection Request – SLA916K vs SBX777S (OI) on D.O.A.: 08/03/2019

From: Hor, Yinrul
To: Admin A (admin-a@lkkauto.com), 'assignments@lkkauto.com'
Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur
Sent: 12/3/2019 10:22:03 AM
Attachments:  SLA916K vs SBX777S.PDF

Hi,

Please refer to the enclosed request from **Accord Auto Services Pte Ltd**.

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know

Kindly assist to assign **Kenneth Kong** as Single Joint Expert as requested.

Thanks & Regards,

Yin Rul, Hor (Viviane)
AIG
Claim Adjuster II, Singapore FNOI, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

Yinrul.Hor@aig.com | www.aig.ae

From: claims@mycarworkshop.com.sg [mailto:claims@mycarworkshop.com.sg]
Sent: Tuesday, March 12, 2019 9:46 AM
To: Hor, Yinrul
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; claims@mycarworkshop.com.sg
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SBX777S AND SLA916K ON 08/03/2019

Hi,

We would be appointing Kenneth Kong (LKK Auto Consultants Pte Ltd) to conduct PRS.

Thank you.

Kind regards,
Jessy Soe

Accord Auto Services Pte Ltd
10 Ang Mo Kio Ind Park 2A
#03-11 Ang Mo Kio Auto Point
Singapore 568047

Mobile : (65) 9740 0999
Tel : (65) 6481 9517
Fax : (65) 6481 9516

This email is confidential and privileged. If you are not the intended recipient, you must not view, disseminate, use or copy this email. Kindly notify the sender immediately, and delete this email from your system. Thank you.

From: Hor, Yinrul
Sent: Mon, 11 Mar 2019 07:42:19 +0000
To: 'claims@mycarworkshop.com.sg'
Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SBX777S AND SLA916K ON 08/03/2019

Without Prejudice

11:00am 13/3/19
vehicle in
jessie
sue @ kenneth

Your Reference : SLA916K
Our Reference : SBX777S

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Yin Rui, Hor (Viviane)

AIG

Claim Adjuster II, Singapore FNOI, Claims Operations - Auto
Shared Services - Malaysia | Global Business Services

YinRui.Hor@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Monday, 16 September 2019 3:51 PM
To: Accord Claims(AV)
Cc: Admin A
Subject: OFFER - Accident involving SLA 916K & SBX 777S (OI- AIG) on 08/03/2019

Tracking:	Recipient	Delivery
	Accord Claims(AV)	
	Admin A	
	Meikwan@lkkauto.com	Delivered: 16/9/2019 3:51 PM
	shupei@lkkauto.com	Delivered: 16/9/2019 3:51 PM
	olivialau@lkkauto.com	Delivered: 16/9/2019 3:51 PM

Your Ref: SLA 916K
Our Ref: CC4/AIG19004589/Kka3

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement at global sum of **\$16,000.00(all in)** on this matter.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Print Received Message

This mail is associated with :

***SLA916K (8042424737SG)
[SBX777S]**

TP

WANG YI JUAN

Mar 8 2019 11:00PM

[TAY SIONG CHIN]

Accord Auto Services Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 10/09/2019 15:38 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$16005.50) - SLA916K - Claim Handler: Chan, Kian-Meng

Approved:16005.50:to ensure docs in order. To propose lump sum repair with TP workshop first.

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Thursday, 26 September 2019 3:10 PM
To: Chan, Kian-Meng
Cc: Admin A
Subject: RE: RE: SEEK MANDATE - AIG REF: TP / 8042424737SG [ACCIDENT INVOLVING SBX777S (OI) AND SLA916K (TP) ON 08/03/2019]

Tracking:	Recipient	Delivery
	Chan, Kian-Meng	
	Admin A	
	Meikwan@lkkauto.com	Delivered: 26/9/2019 3:11 PM
	shupei@lkkauto.com	Delivered: 26/9/2019 3:11 PM
	olivialau@lkkauto.com	Delivered: 26/9/2019 3:11 PM

Dear Mr. Chan Kian Meng,

The above matter and e-mail below refers.

Please be informed that Third party rejected our offer for LOR and counter propose LOR repair days for 17 days.

For amicable settlement purposes, we propose :

** 11 days recommendation for repair + 2 Sundays + 2 PRS = ¹⁵16 days.

Appreciate your mandate/instruction via Merimen.

Thank you.

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Khanchna (LKK Auto)

Sent: Tuesday, 3 September 2019 11:02 AM

To: Chan, Kian-Meng <Kianmeng.Chan1@aig.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: FW: RE: SEEK MANDATE - AIG REF: TP / 8042424737SG [ACCIDENT INVOLVING SBX777S (OI) AND SLA916K (TP) ON 08/03/2019]

AIG Ref: TP / 8042424737SG

LKK Ref: CC4/AIG19004589/Kka3

Dear Sir,

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Monday, 23 September 2019 3:38 PM
To: Accord Claims(AV)
Cc: Admin A
Subject: RE: OFFER - Accident involving SLA 916K & SBX 777S (OI- AIG) on 08/03/2019

Your Ref: SLA 916K
Our Ref: CC4/AIG19004589/Kka3

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement at global sum of **\$16,005.00(all in)** on this matter.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Accord Claims(AV) <avclaims@mycarworkshop.com.sg>
Sent: Monday, 16 September 2019 5:32 PM
To: Khanchna (LKK Auto) <khanchna@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: Re: OFFER - Accident involving SLA 916K & SBX 777S (OI- AIG) on 08/03/2019

Dear Khanchna,

We refer to your email.

We regret to inform you that not agree on the loss of rental. We counter proposal \$16,500.00(all in),

Kindly advise.

Thank you.

Khanchna (LKK Auto)

From: Accord Claims(AV) <avclaims@mycarworkshop.com.sg>
Sent: Tuesday, 8 October 2019 9:44 AM
To: Khanchna (LKK Auto)
Cc: Admin A
Subject: Re: OFFER - Accident involving SLA 916K & SBX 777S (OI- AIG) on 08/03/2019

Dear Khanchna,

Accept your offer.

Kindly let us have your discharge voucher.

Thank you.

Kind regards,
Celia Lai

Accord Auto Services Pte Ltd
Blk 1009 Bukit Merah Lane 3
#01-80
Singapore 159723

Mobile: (65) 9274 0999
Tel : (65) 6271 7433
Fax : (65) 6274 5715

This email is confidential and privileged. If you are not the intended recipient, you must not view, disseminate, use or copy this email. Kindly notify the sender immediately, and delete this email from your system. Thank you.

On Mon, Oct 7, 2019 at 5:03 PM Khanchna (LKK Auto) <khanchna@lkkauto.com> wrote:

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement as follows as the same is reasonable: -

1. Cost of Repair (w/GST)	\$ 14,603.50
2. Loss of Rental (15 days x \$100.00)	\$ 1,500.00
3. LTA Search Fee	\$ 2.00
TOTAL	\$ 16,105.50

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Monday, 7 October 2019 5:03 PM
To: Accord Claims(AV)
Cc: Admin A
Subject: RE: OFFER - Accident involving SLA 916K & SBX 777S (OI- AIG) on 08/03/2019

Tracking:	Recipient	Delivery
	Accord Claims(AV)	
	Admin A	
	Meikwan@lkkauto.com	Delivered: 7/10/2019 5:03 PM
	shupeil@lkkauto.com	Delivered: 7/10/2019 5:03 PM
	oliviafau@lkkauto.com	Delivered: 7/10/2019 5:03 PM

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement as follows as the same is reasonable: -

1. Cost of Repair (w/GST)	\$ 14,603.50
2. Loss of Rental (15 days x \$100.00)	\$ 1,500.00
3. LTA Search Fee	\$ 2.00
TOTAL	\$ 16,105.50

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Accord Claims(AV) <avclaims@mycarworkshop.com.sg>
Sent: Tuesday, 24 September 2019 4:07 PM
To: Khanchna (LKK Auto) <khanchna@lkkauto.com>

Print Received Message

This mail is associated with :

***SLA916K (8042424737SG)**
[SBX777S]

TP

WANG YI JUAN

Mar 8 2019 11:00PM

[TAY SIONG CHIN]

Accord Auto Services Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 02/10/2019 14:21 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$16105.50) - SLA916K - Claim Handler: Chan, Kian-Meng

Approved:16105.50.

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Thursday, 12 December 2019 9:31 AM
To: jenny.lim@laihuat.com.sg
Cc: Admin A
Subject: Seeking assistance - [Accident between SLA 916K & SBX 777S & others on 08/03/2019]

Our Ref: CC4/AIG19004589/Kka3

Dear Jenny,


The above matter refers.

We are acting for our mutual client (**TAY SIONG CHIN/ SBX777S**).

We seek your assistance to contact him to amend the GIA report on the third party vehicle number as it should be "SLA916K" (as per sketch plan from third party below – SLA916K).

MLHM19032752 / Lai Huat (Meng Kee) Motor Pte Ltd - Sin Ming
ENTRY DATE & TIME: 11/03/2019 17:21
SUBMITTED BY: Jenny Lim Lai Foong

Sketch Plan Pg. 1



pending
addendum

Kindly also let us have a copy of the amended GIA.

Thank you a lot.

"Best Wishes for Merry Christmas & Happy New Year 2020"

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Mar 2019 Edit Reg		12 Mar 2019 00:00 Edit Adj Rpt	S\$13,648.13 Edit Estimates	S\$13,648.13 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	TAY SIONG CHIN , ID: S1114105F								
Main Claimant:	WANG YI JUAN , ID: S8737876D								
Vehicle Reg. No.:	SLA916K	Date of Loss:	08/03/2019 23:00 - :59 [37 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 8042424737SG	Policy/Cover Note No.:	2100482082 (Comprehensive)						
Vehicle Reg. No. (Insured):	SBX777S	Policy No. (Claimant):	VB009388						
		Excess:							
Repairer:	Accord Auto Services Pte Ltd (HQ) 10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point, 568047 Ang Mo Kio - Tel: 64819517/85715140								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com								
Claimant's Insurer:	Great American Insurance Company (HQ) - Tel: 6804 6047								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 22/03/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (02/10/2019): Alert - Adj Mandate Approved (S\$16105.50) - SLA916K - Claim Handler: Chan, Kian-... - AIG_SG_EXPRESS (10/09/2019): Alert - Adj Mandate Approved (S\$16005.50) - SLA916K - Claim Handler: Chan, Kian-... - AIG_SG_EXPRESS (10/09/2019): Alert - Adj Mandate Approved (S\$16005.50) - SLA916K - Claim Handler: Chan, Kian-...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLA916K (8042424737SG)
[SBX777S]

TP

WANG YI JUAN

Mar 8 2019 11:00PM

[TAY SIONG CHIN]

Accord Auto Services Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser	
----------------------------------	--	-------------------------------	------------------------------------	------------------------------	------------------------------	--	--

Letters/Correspondences					1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit		

Photos/Images					3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	23/05/19 13:17	Chassis Number		Load JPG	☒	
2	23/05/19 13:17	Odometer Reading		Load JPG	☒	
3	23/05/19 13:18	General View		Load JPG	☒	
4	23/05/19 13:18	General View		Load JPG	☒	
5	23/05/19 13:18	General View		Load JPG	☒	
6	23/05/19 13:18	General View		Load JPG	☒	
7	23/05/19 13:18	General View		Load JPG	☒	
8	23/05/19 13:18	General View		Load JPG	☒	
9	23/05/19 13:18	General View		Load JPG	☒	
10	23/05/19 13:18	General View		Load JPG	☒	
11	23/05/19 13:18	General View		Load JPG	☒	
12	23/05/19 13:18	General View		Load JPG	☒	
13	23/05/19 13:18	General View		Load JPG	☒	
14	23/05/19 13:18	General View		Load JPG	☒	
15	23/05/19 13:18	General View		Load JPG	☒	
16	23/05/19 13:18	General View		Load JPG	☒	
17	23/05/19 13:18	General View		Load JPG	☒	
18	23/05/19 13:18	General View		Load JPG	☒	
19	23/05/19 13:18	General View		Load JPG	☒	
20	23/05/19 13:18	General View		Load JPG	☒	
21	23/05/19 13:18	General View		Load JPG	☒	
22	23/05/19 13:18	General View		Load JPG	☒	
23	23/05/19 13:18	General View		Load JPG	☒	
24	23/05/19 13:18	General View		Load JPG	☒	
25	23/05/19 13:18	General View		Load JPG	☒	
26	23/05/19 13:18	General View		Load JPG	☒	
27	23/05/19 13:18	General View		Load JPG	☒	
28	23/05/19 13:18	General View		Load JPG	☒	
29	23/05/19 13:18	General View		Load JPG	☒	
30	23/05/19 13:18	General View		Load JPG	☒	
31	23/05/19 13:18	General View		Load JPG	☒	
32	23/05/19 13:18	General View		Load JPG	☒	
33	23/05/19 13:18	General View		Load JPG	☒	
34	23/05/19 13:18	General View		Load JPG	☒	
35	23/05/19 13:18	General View		Load JPG	☒	
36	23/05/19 13:18	General View		Load JPG	☒	
37	23/05/19 13:21	Reinspection Photo		Load JPG	☒	
38	23/05/19 13:21	Reinspection Photo		Load JPG	☒	
39	23/05/19 13:21	Reinspection Photo		Load JPG	☒	
40	23/05/19 13:21	Reinspection Photo		Load JPG	☒	

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
41	23/05/19 13:21	Reinspection Photo		☒
42	23/05/19 13:21	Reinspection Photo		☒
43	23/05/19 13:21	Reinspection Photo		☒
44	23/05/19 13:21	Reinspection Photo		☒
45	23/05/19 13:21	Reinspection Photo		☒
46	23/05/19 13:21	Reinspection Photo		☒
47	23/05/19 13:21	Reinspection Photo		☒
48	23/05/19 13:21	Reinspection Photo		☒
49	23/05/19 13:21	Reinspection Photo		☒
50	23/05/19 13:21	Reinspection Photo		☒
51	23/05/19 13:21	Reinspection Photo		☒
52	23/05/19 13:21	Reinspection Photo		☒
53	23/05/19 13:21	Reinspection Photo		☒
54	23/05/19 13:21	Reinspection Photo		☒
55	23/05/19 13:21	Reinspection Photo		☒
56	23/05/19 13:21	Reinspection Photo		☒
57	23/05/19 13:21	Reinspection Photo		☒
58	23/05/19 13:21	Reinspection Photo		☒
59	23/05/19 13:21	Reinspection Photo		☒
60	23/05/19 13:21	Reinspection Photo		☒
61	23/05/19 13:21	Reinspection Photo		☒
62	23/05/19 13:21	Reinspection Photo		☒
63	23/05/19 13:21	Reinspection Photo		☒
64	23/05/19 13:21	Reinspection Photo		☒
65	23/05/19 13:21	Reinspection Photo		☒
66	23/05/19 13:21	Reinspection Photo		☒
67	23/05/19 13:21	Reinspection Photo		☒
68	23/05/19 13:21	Reinspection Photo		☒
69	23/05/19 13:21	Reinspection Photo		☒
70	23/05/19 13:21	Reinspection Photo		☒
71	23/05/19 13:21	Reinspection Photo		☒
72	23/05/19 13:21	Reinspection Photo		☒
73	23/05/19 13:21	Reinspection Photo		☒
74	23/05/19 13:21	Reinspection Photo		☒
75	23/05/19 13:21	Reinspection Photo		☒
76	23/05/19 13:21	Reinspection Photo		☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/03/19 16:57	ACKNOWLEDGEMENT EMAIL TO aig dd 13.03.2019		☐
2	13/03/19 16:57	EMAIL FROM AIG DD 12.03.2019		☐
3	13/03/19 16:57	NOTIFICATION FROM WORKSHOP + TP GIA REPORT		☐
4	23/03/19 17:05	TP ESTIMATE - MARKED		☐
5	10/04/19 17:01	LETTER TO OI		☐
6	14/06/19 11:34	GIA SEARCH		☐
7	14/06/19 11:34	RENTAL RECEIPT		☐
8	26/09/19 15:11	TP LOD		☐
9	12/12/19 11:54	EMAIL TO OI REPORTING CENTRE		☐
10	13/12/19 11:32	OI AMENDED GIA		☐
11	18/12/19 09:20	WORKSHOP INVOICE		☐
12	18/12/19 09:20	AUTHORISATION TO ACT FORM		☐
13	18/12/19 09:20	Release Voucher		☐
14	18/12/19 09:20	LOD		☐
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	14/03/19 14:13	OI GIA REPORT		☐

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^

v

Show Remarks To: ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SBX777S (Insd veh)	Model:	VOLKSWAGEN JETTA GP
	SLA916K (TP veh)		1.4 TSI 90 A/T (A)
Date of Accident:	08/03/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	28,560.35
Final Repair Cost	:	\$	14,603.50
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	1,500.00 15 days
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	16,105.50

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____100____(%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____(%) Assessed Liability (*): ____100____(%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Accord Auto Services Pte Ltd	:	\$ 16,105.50
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

18 Dec
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19004589/KHA3Q2

Date: 18/12/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100482082
 Claimant: SLA916K Insured Vehicle No: SBX777S
 Vehicle No: SLA916K
 Date of Loss: 08/03/2019 Nature of Claim: TP Claim No: 8042424737SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLA916K
 Make & Model: VOLKSWAGEN JETTA GP, 1.4 TSI 90 A/T (A) Engine No: CAXF82973
 Reg. Date: 29/01/2016 (Man. Year: 2015) Chassis No: WWWZZZ16ZGM007019
 Colour: Red Odometer: 38833 km
 Engine Capacity: 1390 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Pirelli 8 mm Rear Left Side: Pirelli 8 mm
 Front Right Side: Pirelli 8 mm Rear Right Side: Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,231.92	10,488.13	9,743.79	48.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,460.00	3,160.00	3,300.00	51.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	26,691.92	13,648.13	13,043.79	48.87
+ GST 7.00/7.00% (\$\$)	1,868.43	955.37	913.06	48.87
Nett Amount (\$\$)	28,560.35	14,603.50	13,956.85	48.87
+ Car Rental (15.0 x S\$100.00/day) (\$\$)		1,500.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		16,105.50		

INSPECTION

Date of Assignment: 12/03/2019
 Date Inspected: 13/03/2019 Inspected At: Accord Auto Services Pte Ltd (HQ)
 10 Ang Mo Kio Ind Park 2A #03-11,
 AMK Auto Point
 Singapore 568047
 Estimated Period of Repair: 11.0 days

Adjuster: KENNETH KONG

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	1,097.50 FL	*- FL
2	1		*FRONT GRILLE ASSY	Scratched	545.00 FL	*545.00 FL
3	1		*RH HEADLAMP	Cracked	2,380.00 FL	*2,380.00 FL
4	1		*LH HEADLAMP	Serviceable	2,380.00 FL	*- FL
5	1		*FRONT BUMPER	Buckled	1,017.00 FL	*1,017.00 FL
6	1		*FRONT BUMPER GRILLE	Cracked	257.50 FL	*257.50 FL
7	1		*FRONT BUMPER SIDE RETAINER	O/S Distorted	61.20 FL	*30.60 FL
8	1		*BOOTLID	Bent	2,250.00 FL	*1,450.00 FL
9	1		*BOOTLID LOGO	Necessary	137.50 FL	*137.50 FL
10	1		*BOOTLID JETTA EMBLEM	Necessary	72.00 FL	*72.00 FL
11	1		*BOOTLID TSI EMBLEM	Necessary	54.00 FL	*54.00 FL
12	1		*BOOTLID NUMBER PLATE LAMP	Serviceable	126.00 FL	*- FL
13	1		*BOOTLID REFLECTOR (LH)	Cut	337.50 FL	*337.50 FL
14	1		*BOOTLID REFLECTOR (RH)	Cracked	337.50 FL	*337.50 FL
15	1		*BOOTLID LOCK	Distorted	162.50 FL	*162.50 FL
16	1		*BOOTLID WEATHERSTRIP	Distorted / Cut	264.00 FL	*264.00 FL
17	1		*BOOTLID INNER TRIM BOARD	Serviceable	250.00 FL	*- FL
18	1		*LH TAIL LAMP	Serviceable	408.00 FL	*- FL
19	1		*RH TAIL LAMP	Cracked	408.00 FL	*408.00 FL
20	1		*REAR FENDER (LH)	Repair	1,504.00 FL	*- FL
21	1		*REAR FENDER (RH)	Repair	1,504.00 FL	*- FL
22	1		*REAR BUMPER	Buckled	992.80 FL	*992.80 FL
23	1		*REAR BUMPER REFLECTOR (LH)	Serviceable	65.00 FL	*- FL
24	1		*REAR BUMPER REFLECTOR (RH)	Cracked	65.00 FL	*65.00 FL
25	1		*REAR BUMPER LOWER COVER	Bent	451.20 FL	*451.20 FL
26	1		*REAR BUMPER CENTRE BRACKET	Cracked	72.00 FL	*72.00 FL
27	2		*REAR BUMPER SIDE RETAINER	Distorted	188.00 FL	*188.00 FL
28	2		*REAR BUMPER SIDE BRACKET	Serviceable	188.00 FL	*- FL
29	1		*REAR BUMPER REINFORCEMENT	Bent	582.50 FL	*582.50 FL
30	1		*END PANEL	Bent	876.10 FL	*876.10 FL
31	1		*END PANEL TOP TRIM	Distorted	175.00 FL	*175.00 FL
32	1		*FLOOR PANEL	Repair	1,341.60 FL	*- FL
33	1		*FLOOR PANEL BOARD	Serviceable	412.80 FL	*- FL
34	3		*EXHAUST SILENCER MOUNTING	Serviceable	225.60 FL	*- FL
35	1		*FRONT NUMBER PLATE WITH HOLDER	Dented	55.00 FS	*45.00 FS
36	1		*REAR NUMBER PLATE WITH HOLDER	Bent	55.00 FS	*45.00 FS
37	2		*FRONT BUMPER SENSOR (CENTRE)	Serviceable	274.00 FS	*- FS
38	4		*REAR REVERSE SENSOR	Missing / Shorted	448.00 FS	*448.00 FS
39	10		*FRONT BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
40	10		*BOOTLID INNER TRIM BOARD CLIP	Necessary	50.00 FS	*50.00 FS
41	10		*REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
42	6		*END PANEL TOP TRIM CLIP	Necessary	30.00 FS	*30.00 FS
43	1		*REAR BOOTLID COMPARTMENT WETERPROOF SEALANT	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	22,350.80	11,573.70
- List Item Discount on L Items 10.00/10.00% (S\$)	2,118.88	1,085.57
Total Parts (S\$)	20,231.92	10,488.13

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING ON ALL AFFECTED AREA	New	2,200.00	1,400.00
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGES PARTS TO KNOCK ,JACK,CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	2,400.00	1,400.00
3	TO APPLY ANTI RUST TRATMENT	New	150.00	60.00
4	TO CHECK WIRING SYSTEM & LIGHT	New	120.00	40.00
5	TO REMOVE AND REPLACE FRONT BUMPER SENSOR	New	120.00	60.00
6	TO REMOVE AND REPLACE REVERSE SENSOR	New	120.00	60.00
7	TO ADJUST CHASSIS ALIGNMENT ON CAR O LINER	New	350.00	0.00
8	TO TRANSFER BOOTLID INNER COMPARTMENT ,MECHANISM AND ACCESSORIES	New	200.00	60.00
9	TO CHECK AND TEST REAR BOOTLID WATER LEAKING	New	80.00	20.00
10	TO ADJUST AND REMAIN EXHAUST SILENCER SYSTEM	New	200.00	60.00
11	UPHOLSTERY DETAILS CLEANING	New	220.00	0.00
12	COMPUTER DIAGNOSTIC AFTER REPAIR	New	300.00	0.00
Gross Labour Cost (\$\$)			6,460.00	3,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >