

2/03/2007

ASS. REC. BY:

REP:

es/smo19004595/And3n2

Special Instruction:

Surveyor
merimen

Adrian

ASSIGNMENT (Office)

From (Person): Hwang Shiang Yi

of

SMO

Date/Time: 12/3/19 @ 4:06pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

JPQ 1697

Insured:

FBJ 32991

at Workshop m/z

Hua Meng

Tel:

67465519

of

11caki Bkt Ave 6# 01-61

Policy No:

D18M1MC0100774

Claim No:

CMTD1901118

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/02/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

2:31pm @ 13/3/19

Person Contacted:

June

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

14/3/19

Informed Shiang Yi - pending workshop est by merimen

30/4/19

Adrian confirmed LS \$ 1200 (Red 3026, 729)

30/4/19

Send preli revised via merimen

REF: SMO

ASSIGNMENT

From: Date: 13/3/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: JPQ 1697
at Workshop m/s Hua Meng Sprng
of No. 1 Kaki Bkt Ave 6 # 01-61

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'up'

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: JPQ 1697, Yr Regn: 2013 / Sept.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha 135CC c.c. 135

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: PMYK6054000133889.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 70/90R17

R: 80/90R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Brightstone

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. mm L/Bal. mm

D.O.A. D.O.I. 13/03/15

Survey held at Hua meng

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
TP Somp.MV: 4K (Ringitt) ≈ 1.3K (Sing Dollar)
PV: 300 (Ringitt) ≈ 100.
Nett: 1.2K (Sing Dollar)

RECEIVED 30 APR 2019

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 30/4 - typist

Report Format: merimen

Lump Sum / I.B.I.: (\$) 1200/-

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation: 250

Photos: 10

Others:

TOTAL 260

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To:	Sompo Insurance Singapore Pte. Ltd. 50 Raffles Place #05-01/06, Singapore Land Tower Singapore 048623	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Hwang Shiang Yi	Date:	30 Apr 2019

Preliminary Advice

Insured Vehicle No	: FBJ3299J	Accident Date	: 26/02/2019
TP Vehicle No	: JPQ1697	Assignment Date	: 12/03/2019
Make	: YAMAHA 135LC	Est. Duration of Repair	: 4
Date of Inspection	: 13/3/2019		
Inspection At	: HUA MENG SPRAY PAINTING WORKSHOP		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,226.00
Revised Amount	:S\$	1,200.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : The above survey was conducted on a 'Without Prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Feb 2019		12 Mar 2019 16:06 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LEE TECK YU, ID: S9146687B, Tel: +6596971125, Email: leeteckyu1991@gmail.com		
Main Claimant:	WONG KIM TIAM		
Vehicle Reg. No.:	JPQ1697	Date of Loss:	26/02/2019 07:00 - :59
Claim Type:	TP / CMTD1901118	Policy/Cover Note No.:	D18MTMC01007744 (Comprehensive)
Vehicle Reg. No. (Insured):	FBJ3299J	Policy No. (Claimant):	
		Excess:	
Repairer:	Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67478064, 67465519		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/03/2019]		
Driver/Custodian (Insured):	LEE TECK YU (27 / Male) , NRIC: S9146687B, Tel: +6596971125 Email: leeteckyu1991@gmail.com		
Adj Asg. Remarks:	-NO TP PR SUBMITTED		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

***JPQ1697 (CMTD1901118)**
[FBJ3299J]

TP

WONG KIM TIAM

Feb 26 2019 7:00AM

[LEE TECK YU]

Hua Meng Spray Painting Workshop

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **14/03/2019 12:20 PM.**
To shiangyi.hwang@sompo.com.sg
Subject TP SURVEY JPQ 1697

Dear Shiang Yi,

Please be informed that we have inspected the vehicle JPQ 1697 on 13/3/2019.

We are pending estimate from repairer.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.

JABATAN PENGANGKUTAN JALAN MALAYSIA

PERAKUAN PENDAFTARAN KENDERAAN



NO. PENDAFTARAN: JKG1697

No. Siri B 5283506

Nama Pemunya Berdaftar : WONG KIM TIAM

700720085573
[MAL]

Alamat : 04-02 BLOK C TAMAN TAN SRI YAACOB
81300 JOHOR BAHRU JOHOR D.T.

No. Enjin : G388EE133888
No. Casis : PMYKG054000133888
Buatan : YAMAHA
Nama Model : YAMAHA 135LC
Keupayaan Enjin : 135 S.P
Bahan Bakar : PETROL
Warna : MERAH
Kelas Kegunaan : MOTORISIKAL
Jenis Badan : MOTORISIKAL
Tahun Dibuat : 2013
Tarikh Pendaftaran : 12/09/2013
Status Pemunya : PERSENDIRIAN
Muatan Tempak :
Duduk : 2
Kadar Lesen :
Kenderaan Motor : 6 bulan 12 bulan

B.D.M/B.G.K
B.T.T.
Berat Kerb
B.T.M.
B.G.1
B.G.2
B.G.3
B.G.4
B.G.5
B.G.6
B.G.7
B.G.8
B.G.9
B.G.10
B.G.11
B.G.12

HL

RM2.00

RM2.00

Tandatangan Pemunya Berdaftar

Perakuan Pendaftaran ini dikeluarkan

oleh Pengerah JPJ Negeri KOMPLEKS JPJ, NEGERI JOHOR III

PENASANGAN TEMPATAN

UNTUK KEGUNAAN PEJABAT

1.
2.
3.
4.
5.
6.
7.
8.
9.
10.
11.
12.
13.

5000

NOTA PENTING

- Simpan perakuan ini di tempat yang selamat. Jika perakuan ini hilang, anda dikehendaki melaporkan kepada balai polis dengan segera dan memohon salinan perakuan pendaftaran daripada Pengerah Jabatan Pengangkutan Jalan (JPJ).
- Semak butir-butir kenderaan di muka ini dan laporkan dengan segera kepada Pengerah JPJ jika terdapat sebarang perubahan.
- Lesen kenderaan motor yang sah hendaklah sentiasa dipamerkan. Anda boleh membaharui lesen 60 hari sebelum tempohnya tamat.
- Anda dikehendaki melaporkan secara bertulis dengan segera kepada Pengerah JPJ sekiranya kenderaan anda tidak berlesen.
- Jika anda menjual kenderaan, serahkan perakuan pendaftaran ini kepada pembeli. Anda dan pembeli dikehendaki mengisi dan mengemukakan borang JPJK3/JPJK3A kepada Pengerah JPJ dalam tempoh tujuh hari dari tarikh penjualan itu.
- Pemunya berdaftar kenderaan adalah bertanggungjawab di atas segala urusan berkaitan dengan kenderaan sehingga pertukaran milikan telah disempurnakan dan kenderaan telah didaftarkan dengan nama pemilik baru.
- Jika alamat anda bertukar, kemukakan perakuan pendaftaran ini kepada Pengerah JPJ dalam tempoh tujuh hari dari tarikh pertukaran itu.

BAYARAN-BAYARAN

1- 109013 12092013 15:47:47 031000 N 40-51386 RMASTURA 03078 PG 0 03078 JPQ1697 11/08/2013 2201000RM*****5.00 RM*****5.00	11
2 109013 12092013 15:48:28 035600 N 40-51387 RMASTURA 03088 PG 0 03088 JPQ1697 11/08/2014 2201000RM*****2.00 RM*****2.00	12
3 0101011 06/09/2015 11:28:54 VEL02010 N ROSLI 011102 1 0 JPQ1697 11/09/2016 2201000RM*****2.00 RM*****2.00	13
4 0101011 03/09/2014 15:35:20 VEL02010 N MASLIZA 066836 1 0 JPQ1697 11/09/2015 2201000RM*****2.00 RM*****2.00	14
5	15
6	16
7	17
8	18
9	19
10	20

PERTUKARAN-PERTUKARAN MILIKAN DAN ALAMAT

1	No. K.P./Def. Niaga/Sykt	Tandatangan Pemunya Berdaftar
2	No. K.P./Def. Niaga/Sykt	Tandatangan Pemunya Berdaftar
3	No. K.P./Def. Niaga/Sykt	Tandatangan Pemunya Berdaftar
4	No. K.P./Def. Niaga/Sykt	Tandatangan Pemunya Berdaftar
5	No. K.P./Def. Niaga/Sykt	Tandatangan Pemunya Berdaftar

REKOD-REKOD PEMERIKSAAN

1	5	9
2	6	10
3	7	11
4	8	12



PACIFIC & ORIENT INSURANCE CO. BERHAD (12557-W)

A Member Of The Pacific & Orient Group
GST Reg. No/No CBP - 001055457280

11th Floor, Wisma Bumi Raya, No. 10, Jalan Raja Laut, 50350 Kuala Lumpur.
P.O. Box 10953, 50730 Kuala Lumpur. Internet: www.pacific-orient.com / <https://www.pno-ins.com>
Telephone: 03 - 2698 5033 Fax: 03 - 2693 8145 Auto Assist Toll Free: 1 800 88 2121



ORIGINAL

立新

MOTORCYCLE POLICY SCHEDULE / JADUAL POLISI

Agent Name / Address / Tel No. / Nama Ejen / Alamat / No. Tel JP MOTOR ENTERPRISES NO. 4 JALAN SERI ORKID 1 TAMAN SERI ORKID 07-5114027	Agent Code / Kod Ejen 37951-01-C Batch No. / No. Kumpulan 09*MT-936905 New Policy No. / No. Policy Baru 01-70-18-JEL-005208
The Insured / Address / Pihak Diinsuranskan / Alamat WONG KIM TIAM 04-02, BLOK C, JALAN PERSIARAN PERDANA, TAMAN TAN SRI YACOB, 81300 SKUDAI JOHOR	Old Policy No. / No. Policy Lama 01-70-17-JEL-005425 Date / Time of Issue / Tarikh / Masa Dikeluarkan 05-09-2018 10:35pm

Geographical Area / **Kawasan Geografi**: Malaysia, Republic of Singapore and Negara Brunei Darussalam

The Policy Premium (RM) / **Premium Polisi (RM)**

Business / Profession / Perniagaan / Pekerjaan	LX	Sum Insured / Jumlah Diinsuranskan	4,000.00
New IC No. / Business Registration No. / No. KP Baru / No. Pendaftaran Perniagaan	700720-08-5573	Trailer Sum Insured / Jumlah Diinsuranskan Bagi Treler	
Old IC No. / No. Kad Pengenalan Lama		Excess Applicable / Lebih Yang Dikenakan	100.00
Gender / Jantina	MALE	Cover Granted / Jenis Perlindungan Yang Diberi	COMPREHENSIVE
Marital Status / Taraf Perkahwinan	MARRIED		
Type of Usage / Jenis Kegunaan	MOTORCYCLE	Basic Premium / Premium Asas	248.47
Period of Insurance / Tempoh Insurans From/Dari 12-09-2018 12:01am To/Hingga 11-09-2019 Midnight/Tgh Malam 12:00am		Inclusive Of / Termasuk All Riders (M/cycle) / Semua Penunggang (M/sikal)	
Class of Vehicle / Kelas Kenderaan	MOTOR CYCLE - ALL RIDER		
Hire Purchase / Sewa Beli		NCD / DTT (25.00%)	62.12
Regn. Card No./Trailer Regn. Card No. / No. Perakuan Pendaftaran Kenderaan/Treler		NCD Effective Date (12-09-2018) / Tarikh Berkuatkuasa DTT	
Vehicle Registration No. / No. Pendaftaran Kenderaan	JPQ1697	Extra Benefits / Perlindungan Tambahan :-	
Trailer Registration No./No Pendaftaran Treler			
Make & Type of Body / Buatan & Jenis Badan	YAMAHA 135LC		
Cubic Capacity / Keupayaan Enjin	135.00 CC		
Year of Manufacture / Tahun Diperbuat	2013		
Seating Capacity (including driver) / Muatan Tempat Duduk (Termasuk Pemandu)	2	Gross Premium / Premium Kasar	186.35
Engine No. / No. Enjin	G399EE133889		
Chassis No. / No. Casis	PMYKG0540D0133889	Service Tax / Cukai Perkhidmatan	11.18
Trailer Chassis No. / No. Casis Treler		GST / GST	0.00
GST Registration No. / No. Pendaftaran GST		Stamp Duty / Duti Setem	10.00
Named Driver(s) / Pemandu yang Diberi Kuasa		Total Premium / Jumlah Premium	207.53
		Amount Payable (Rounded) / Jumlah Perlu Dibayar (Digenapkan)	207.55
		Act Premium / Premium Akta	94.48

Limitation as to use: As per Certificate of Insurance attached / **Had Penggunaan: Seperti Sijil Insuran yang disertakan**
Subject to following clauses printed herein or attached hereto / **Tertakluk kepada fasal-fasal dicetak atau dikepit disini**

Endorsement / **Pengendorsan** include Endt No :

LEGISLATION / **PERUNDANGAN**

Road Transport Act, 1967 (Malaysia) Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore Motor Vehicles (Third Party Risk and Compensation) Rules (Republic of Singapore) Motor Vehicles Insurance (Third Party Risks) Act (Cap 190) Negara Brunei Darussalam (the reference to legislation under the heading "Avoidance of Certain Terms and Right of Recovery is limited to Section 94, 95 and 96 of the Road Transport Act 1967 (Malaysia) Section 7.8 and 9 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore and Section 7 of the Motor Vehicles Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam.

Important Notice: For environmental conservation, we no longer print the policy wording/fact sheet/pocket sized card/directory of panel workshop/importers notice/notice to all policyholders. You may view the documents/terms/conditions of the above stated policy number at www.pacific-orient.com. A print out of your Policy can be obtained from our branch office located nationwide or from your servicing agents.

Keterangan Penting: Untuk pemeliharaan alam sekitar, kami tidak lagi mencetak butir-butir polisi/lembaran fakta/kad saiz poket/panduan bengkel panel membabitkan kenderaan/motor/murah/motik kepada pemegang polisi. Anda boleh membaca dokumen-dokumen tertera/ syarat untuk dokumen polisi bermaksud di atas di www.pacific-orient.com Catatan polisi untuk boleh diperolehi daripada pejabat cawangan kami di seluruh negara ataupun agen Pacific & Orient anda.

You are required to read the Notice in regard to your Personal Data or Sensitive Personal Data. This notice is in Our Website. Please go to www.pacific-orient.com.

*Anda diarahkan untuk membaca Notis berkenaan Data Peribadi atau Data Peribadi Sensitif anda. Notis tersebut boleh didapati di Laman Sesawang kami. Sila lawati www.pacific-orient.com.

THIS IS A COMPUTER GENERATED DOCUMENT AND IT DOES NOT REQUIRE SIGNATURE THIS DOCUMENT SHALL NOT BE INVALIDATED SOLELY ON THE GROUND THAT IT IS NOT SIGNED.

ADALAH DOKUMEN YANG DIKELUARKAN OLEH KOMPUTER DAN TANDATANGAN TIDAK DIPERLUKAN DOKUMEN INI TIDAK HARUS DITAKSAHKAN SEMATA-MATA ATAS ALASAN IA TIDAK DITANDATANGAN.

MOTOR POLICY SCHEDULE.....(1 of 2)

REPRINTED 05-09-2018 10:34pm: 2 P5 AGENT ORC



Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 11/03/2019 12:48		Vide Report No.: F/20190226/0040		Station Diary No.:	
Informant's Particulars					
Name of Informant: WONG KIM TIAM			Address: NO 32 JALAN INDAH 22/5 TAMAN BUKIT INDA 81200 JOHOR BAHRU		
ID Type / ID No.: NEW MALAYSIAN IC / 700720085573			Contact No.: Home/Office: Mobile: 98129333		
Nationality:			Email:		
Sex: Male	Age: 48	Date of Birth: 20/07/1970	Type of Informant: Rider		
Race:		Language:	Institution / School Name:		
Occupation: OTHERS		Driving Licence Information: Class: 2B,3 Date of Expiry:			

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 26/02/2019 07:05	Type of Location: Flyover
Location: Along Road 1 BUKIT TIMAH EXPRESSWAY BKE(PIE) 4 KM				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBJ3299J	Motorcycle					0
JPQ1697	Motorcycle					0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190311/2065

2 of 3

Police Station Of Origin:

Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

Report No. T/20190311/2065

CONTINUATION OF REPORT

Rider			
Name	WONG KIM TIAM	ID No.	700720085573
Related Vehicle	JPQ1697 (Motorcycle)	Contact No.	98129333
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	26/02/2019	Date Discharge	26/02/2019
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

ON THE ABOVE MENTIONED TIME,DATE AND LOCATION.

I WAS RIDING ALONG THE MIDDLE ON LANE 1 AND 2 OUT OF 4 LANES. AS I WAS RIDING, THE SINGAPORE BIKE MENTIONED ABOVE COLLIDED INTO ME FROM BEHIND. I FELL OFF MY BIKE AS A RESULT AND WAS INJURED. I WAS CONVEYED TO NG TENG FONG GENERAL HOSPITAL AS I SUFFERED ABRASIONS ON MY FACE , HANDS AND LEGS.



SINGAPORE
POLICE FORCE



T/20190311/2065

3 of 3

Report No. T/20190311/2065

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:
TP /
KHALED AMR HASSAN MOHSSEN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /
Staff Sgt SUFIYAN BIN KHAIRI
Contact No.: 65476390

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
11/03/2019 12:48

Classification Of Case:



SINGAPORE
POLICE FORCE

Signature: 

TP Sampo
Veron.

JPQ1697 2013 Sept
Yamaha 135LC. 135cc.
PMYK6054000133889.

Nett: 1AK.

Front wheel Rim.	} NP new	250 (SN) x
Front Brake Disc		150 (SN) x.
Front Fender	lit	65 ✓
Front Fork Assy	NP new	650 x
Front Fork Top Bracket	} NP new	90. x
Front Fork Under Bracket		135 x
Front Fork Oil		30 x
Front Fork Oil Seal		20 x
Headlamp	lit	65 ✓
Headlamp Cowling	lit	110. ✓
Headlamp Cowling Number Plate Sticker.	new	10 (SN) ✓
Front Cowling	lit	95 ✓
Front Cowling Signal Lamp x 02	NP new	58 x 2 = 116 x
Front Wing mirror x 02	cracked	35 x 2 = 70 ✓
Brake Lever	lit	22 ✓
Balances RH.	lit	20 ✓
Side Fairing RH.	cracked	115 ✓

JPQ1697.

Front Footrest RH	lt	30 ✓
Footbrake Pedal.	lt	35 ✓
Rear RH Footrest	nm	30 x
Rear RH Footrest Bracket	crushed	48 ✓
Rear Exhaust	Repair	350 +
Rear Exhaust Heat Shield.	lt	80 ✓
Front Footrest Bracket	Bent	50 ✓
Handle Bar	Bent	135 ✓
Rear Seat Side Garnish RH.	Repair	70 x
Tail Lamp RH.	crushed	85 ✓
Rear Number Plate	Bent	20 (sn) ✓

1025
922.5
sn: 30

Labour

~~405~~ 250

Spray Painting

~~425~~ 250

Wiring

~~55~~ 30.

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary costs must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

To straighten chassis member.

350 x

570

Towing Fees

~~60~~ 40

4226

total: 1522.50

h/s: 12K.

040mp.

1.2K

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19004595/AVD3N2

Date: 28/05/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTMC01007744
Claimant Vehicle No :	JPQ1697	Insured Vehicle No :	FBJ3299J
Date of Loss:	26/02/2019	Nature of Claim:	TP
		Claim No:	CMTD1901118

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	JPQ1697	Engine No:	G399EE133889
Make & Model:	YAMAHA 135LC, 135cc ES	Chassis No:	PMYKG054000133889
Reg. Date:	12/09/2013 (Man. Year: 2013)	Odometer:	0 km
Colour:	Red		
Engine Capacity:	135 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70/90 R17	Rear Tyre Size:	80/90 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,966.00	952.50	2,013.50	67.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,260.00	570.00	690.00	54.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,226.00	1,522.50	2,703.50	63.97
Approved Total (Overridden) (S\$)		1,200.00		
Nett Amount (S\$)	4,226.00	1,200.00	3,026.00	71.60

INSPECTION

Date of Assignment:	12/03/2019	
Date Inspected:	13/03/2019 Inspected At:	Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 28 May 2019)	
Parts:	N/A	YAMAHA 135LC 135cc ES (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for JPQ1697)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT FENDER	Cut	65.00 F	*65.00 FL
2	1	*FRONT FORK ASSY	Not Necessary	650.00 F	*- FL
3	1	*FRONT FORK TOP BRACKET	Not Necessary	90.00 F	*- FL
4	1	*FRONT FORK UNDER BRACKET	Not Necessary	135.00 F	*- FL
5	1	*FRONT FORK OIL	Not Necessary	30.00 F	*- FL
6	1	*FRONT FORK OIL SEAL	Not Necessary	40.00 F	*- FL
7	1	*HEADLAMP	Cut	65.00 F	*65.00 FL
8	1	*HEADLAMP COWLING	Cut	110.00 F	*110.00 FL
9	1	*FRONT COWLING	Cut	95.00 F	*95.00 FL
10	2	*FRONT COWLING SIGNAL LAMP	Not Necessary	116.00 F	*- FL
11	2	*FRONT WING MIRROR	Cracked	70.00 F	*70.00 FL
12	1	*BRAKE LEVER	Cut	22.00 F	*22.00 FL
13	1	*BALANCER RH	Cut	20.00 F	*20.00 FL
14	1	*SIDE FAIRING RH	Cracked	115.00 F	*115.00 FL
15	1	*FRONT FOOTREST RH	Cut	30.00 F	*30.00 FL
16	1	*FOOTBRAKE PEDAL	Cut	35.00 F	*35.00 FL
17	1	*REAR RH FOOTREST	Not Necessary	30.00 F	*- FL
18	1	*REAR RH FOOTREST BRACKET	Cracked	48.00 F	*48.00 FL
19	1	*REAR EXHAUST	Repair	350.00 F	*- FL
20	1	*REAR EXHAUST HEAT SHIELD	Cut	80.00 F	*80.00 FL
21	1	*FRONT FOOTREST BRACKET	Bent	50.00 F	*50.00 FL
22	1	*HANDLE BAR	Bent	135.00 F	*135.00 FL
23	1	*REAR SEAT SIDE GARNISH RH	Repair	70.00 F	*- FL
24	1	*TAILLAMP RH	Cracked	85.00 F	*85.00 FL
25	1	*FRONT WHEEL RIM	Not Necessary	250.00 FS	*- FS
26	1	*FRONT BRAKE DISC	Not Necessary	150.00 FS	*- FS
27	1	*HEADLAMP COWLING NUMBER PLATE STICKER	Necessary	10.00 FS	*10.00 FS
28	1	*REAR NUMBER PLATE	Bent	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,966.00	1,055.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	102.50
Total Parts (\$\$)	2,966.00	952.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	400.00	250.00
2	SPRAY PAINTING	New	400.00	250.00
3	WIRING	New	50.00	30.00
4	TO STRAIGHTEN CHASSIS MEMBER	New	350.00	0.00
5	TOWING FEES	New	60.00	40.00
Gross Labour Cost (\$\$)			1,260.00	570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >