

13002001

ASS. REC. BY:

REF: CS/FWD19004600/R13d3³

Special Instruction:

Swi Vesyoy

From (Person):

Ramy
Lionel Tan

ASSIGNMENT (Office)

of

pup

Bill to:

Date/Time:

13/3/19 @ 10.33am

Estimated Cost:

① FTP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

91H 99ST

Insured:

Tel: 9645 2243

at Workshop m/s

of

30 Bkt Bukit Crescent

Claim No:

1201900006308

Policy No:

PNP2018-00009913

Excess:

\$600.00

Sum Insured:

D.O.A

7/13/2019

Make of Vch
(Client's Record)

H.O.D. Endorsement:

CA / REV / REF. / REV 24 HRS

Date/Time:

01.11pm @ 13/3/19

Person Contacted:

shah

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

14/03/19 @ 13:54 p.m. revised IA to Lionel Tan via
memo.

14/03/19 @ 13:55 p.m. mandate requested authorize repair
to Lionel Tan via memo
...date approved by Lionel Tan

Jan

REF

CS/FWD19004600/Rld3

16TH 2023
COE XPIRY: 2024/July

ANALYST

From: _____ Date: _____
Estimated Cost: _____
Type: ☒ TP / WS / TP / RES / OD / RES / VA / MV / MV
To Inspected Vehicle No: **SJH 995T**
At Workshop No: **ETH02**
of _____
Insured: **FWD**
Policy No: _____
Claims No: _____
Sum Insured: **600**
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value: **\$32K**
HAC: Accident Report: Consistent? Yes or No
GLA / PR: Consistent? Yes or No
Est. Repairs: days: Res: Yes or No
Turn Time: %: 3Val: Yes or No
CA: ☒ REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **SJH 995T** at Regn: **2008 July**
Type: ☒ Car / Cycle / Bus / Van / Lorry / Load / Prime Mover /
Truck / Trailer or
Make: **HONDA STREAM RS2 1.8A** 1799
Colour: **NH BK** AC: Insured / 500 / 100 / 100
Sp Reading: **128019** TC: Insured / 500 / 100 / 100
Eng No: _____
Ch No: **RN61077373**
Gen. Cond: Good ☒ / Poor / Burnt
Steering: ☒ Order / Jammed / Leaked / Burnt or
Brake: ☒ Order / Jammed / Leaked / Burnt or
Mod: ☒ H / STD A/Rin or
Tyre Size: F: **215/45R17**
R: **215/45R17**

BS / DUN / EXHOVA / GY / FS / LZA / MIC / OHSU / PIR / SUMIT
TOYO / YOKO or **NEXEN**

Front	mm	Rear	mm
R/Bal	6	R/Bal	6
L/Bal	6	L/Bal	6
D.O.A.	02/03/19	D.O.A.	13/03/19

Survey held at: **ETH02**
Dec. of Damages: ☒ Front / Rear / O/S / H/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time: **14/03/19 @ 16:56 pm.** Action / Instruction: **must authorize repair to Shahh (owner) via email.**

08/05/19 Confirmed r/p \$5,179.00 @ 6 days with Rasuf (\$1,481.00 Red - 22%)

8/5/2019

RECEIVED 09 MAY 2019

Date/Time, File/Fax No: **09/05/19**
Type: **Typist**
Date/Time, File/Fax No: _____
Type: _____

Days Of Repair: **6**
Resurvey No. of Trip: **1**

Add Fee: ☐ Safe Insp. (1)
☐ Interview (1)
☐ Tech Ins (1)
☐ VV Ins (1)

Survey Fee	200
Transportation	50
	50
	10

Report Format: _____
Lump Sum / L.C.C. **5,179.00 p/p**

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	12 Mar 2019 Sendback Est	13 Mar 2019 09:47 S\$6,567.00	13 Mar 2019 10:33 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	SELINA BOYD, ID: G6301677U		
Vehicle Reg. No.:	SJH995T	Date of Loss:	07/03/2019 19:00 - :59 [127 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1201900006308	Policy/Cover Note No.:	PNPV2018-00009913 (Comprehensive)
		Excess:	S\$600.00
Repairer:	ETHOZ Protect Pte Ltd (Bukit Batok) 30 Bukit Batok Crescent, 658075 Bukit Batok - Tel: 66547750/51		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 22/03/2019]		
Driver/Custodian:	BOYD ROBERT ARCHIBALD MCNEILL (), NRIC: G6296193M, Tel: +6597111139 Email:		
		Vehicle Source:	Tow-in/Call-man

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)
[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 14 March 2019 4:56 PM
To: 'Selamatshahh Zainal'
Cc: 'Lee Chen Sin'; SUR
Subject: SJH 995T OD (FWD) DOA - 07/03/2019

Dear Shahh,

As instructed by our client, please proceed to repair the insured vehicle **SJH 995T (Excess \$ 600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 9 May 2019 2:48 PM
To: 'Selamatshahh Zainal'
Cc: Rasul (LKKAuto); SUR
Subject: RE: Finalization for SJH995T

Hi Selamatshahh Zainal,

Confirmed final fig \$5,179.00 (part by part) @ 6 days of repairs before excess \$ 600/- & GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Selamatshahh Zainal [mailto:Selamatshahh.Zainal@ethozgroup.com]
Sent: Thursday, 25 April 2019 11:59 AM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: Finalization for SJH995T
Importance: High

Hi Rasul,

Please assist to confirm final amount at \$5,179.00 6 days

Warmest regards,

Selamatshahh Zainal
Senior Executive
Motor Claims Operations

ETHOZ

ETHOZ GROUP LTD

30 Bukit Batok Crescent Singapore 658075

HP: 9624 8656 | DID: 6654 7519 | Fax: 6654 7542

Website: www.ethozgroup.com



Disclaimer: This message may contain confidential information intended only for the use of the addressee named above. If you are not the intended recipient of this message you are hereby notified that any use, dissemination, distribution or reproduction of this message is prohibited. If you received this message by mistake, please notify the sender by reply email immediately. Please conduct your own virus checks before opening any attachment as ETHOZ Group does not guarantee the integrity of this email or attached files has been maintained nor this communication is free of viruses, interceptions or interference. Any views expressed in this message are those of the individual sender and may not necessarily reflect the views of

ETHOZ Group. ETHOZ Group shall not be responsible nor liable for the improper and incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system.

View Received Message

This mail is associated with :

SJH995T (1201900006308)

OD

Mar 7 2019 7:00PM

[SELINA BOYD]

ETHOZ Protect Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 09/05/2019 10:16 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$5179.00) - SJH995T - Claim Handler: Lionel Tan

Approved:5179.00.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

SJH995T (1201900006308)

OD

Mar 7 2019 7:00PM

[SELINA BOYD]

ETHOZ Protect Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 14/03/2019 14:05 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$5972.00) - SJH995T - Claim Handler: Lionel Tan

Approved:5972.00.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan

Date: 08 May 2019

Preliminary Advice

Vehicle No	: SJH995T	Accident Date	: 07/03/2019
Make	: HONDA STREAM	Policy No.	: PNPV2018-00009913
Assignment Date	: 13/03/2019	Excess	: S\$600.00
Date of Inspection	: 13/03/2019	Est. Duration of Repair	: 6 days
Inspection At	: ETHOZ Protect Pte Ltd (Bukit Batok) 30 Bukit Batok Crescent Singapore 658075		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,660.00 (INCLUSIVE SUPPLEMENTARY)
Revised Amount	:S\$	5,179.00 (INCLUSIVE SUPPLEMENTARY)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,179.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have received supplementary from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair. Supplementary amount is \$93.00.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan

Date: 14 Mar 2019

Preliminary Advice

Vehicle No	: SJH995T	Accident Date	: 07/03/2019
Make	: HONDA STREAM	Policy No.	: PNPV2018-00009913
Assignment Date	: 13/03/2019	Excess	: S\$600.00
Date of Inspection	: 13/03/2019	Est. Duration of Repair	: 6 days
Inspection At	: ETHOZ Protect Pte Ltd (Bukit Batok) 30 Bukit Batok Crescent Singapore 658075		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,567.00
Revised Amount	:S\$	5,021.00
Check Items (Estimated)	:S\$	951.00
Total	:S\$	5,972.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	32,000.00
COE / PARF Rebate	:S\$	16,083.00
Salvage Value	:S\$	
Margin for Repair	:S\$	15,917.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/03/2019 16:27
Date Of Accident	07/03/2019 19:00
Exact Location Of Accident	ALONG NICOLL HIGHWAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJH995T
Insured/Policyholder	
Name Of Registered Owner	SELINA BOYD
Passport No/FIN	G6301677U
Email Address	ROBERT.BOYD@CONTROLRISKS.COM
Mobile Phone No	(LOCAL) +65-97111139
Alternative Phone No	OTHERS-97111139

Vehicle Particulars

Manufacturer	HONDA
Model	STREAM RSZ 1.8 A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2018-00009913
Cover Note Number	N.A

Driver

Name of Driver	BOYD ROBERT ARCHIBALD MCNEILL
Passport No/FIN	G6296193M
Date Of Birth	22/05/1972
Occupation	INDOOR
Date Of Driving Pass	29/06/2010
Driving Experience	8 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97111139
Fax Number	
Contact Number	
Email Address	ROBERT.BOYD@CONTROLRISKS.COM

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I SJH995T was driving along Nicoll highway on the most left lane with a slow moving due to the heavy traffic. As I was following the traffic ahead, suddenly the 3rd party SKJ2266D make sudden brake due to the traffic ahead, I immediately applied my brake to avoid the collision with the 3rd party but my foot slip off from the paddle and couldn't stop on time and collided onto the 3rd party rear vehicle. I manage to exchange some particulars details with the 3rd party, no injuries was involved at the scene.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKJ2266D
Vehicle Make/Model/Colour	PORSCHE MACAN S PDK E6 / GREY
Details Of Properties	NIL
Vehicle Category	PRIVATE CAR
Name of Driver	GENEVIEVE WAN
NRIC/Passport Number	
Contact Number	96508085
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

1. This report contains the details of the accident as given by the police officers.
2. The report must be completed by the Police Officer and the Automobile Enquiry
3. Form provided must be truthful and accurate. Any willful misrepresentation or withholding of material facts may
4. give insurance companies to repudiate policy liability.
5. The above and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies
6. Any false report may be referred to the Police for investigation.
7. The report will be forwarded by the insurers to the GIM Records Management Centre established by the General Insurance Association
8. of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
9. By the lodgement of this report to the insurers, you hereby consent to the storing of this report at the centre and to copies of the report
10. being made available as aforesaid.

(1) I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in the form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurance(s) who have insured my vehicle involved in this accident (all insurance(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"). In the case of my lawyer/firm, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police, for the purposes of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/emails); and

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

collectively the "Purposes".

(b) I understand that the Personal Data Protection Act ("PDPA")

(c) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan

A hand-drawn diagram on graph paper. The diagram features a vertical line labeled "NEW TOWER" in the center. To the left of this line, there are two labels: "A SJH 995T" and "B SKJ 226D". To the right of the line, there are two labels: "C SKJ 226D" and "D SJH 995T". The labels are arranged in a grid-like fashion, with "A" and "B" on the left, and "C" and "D" on the right. The vertical line is labeled "NEW TOWER" at the top. The labels "A SJH 995T" and "B SKJ 226D" are on the left side, and "C SKJ 226D" and "D SJH 995T" are on the right side. The diagram is drawn on a grid of small squares.

ACCIDENT STATEMENT (2000 characters)

I SJH995T was driving along Nicoll highway on the most left lane with a slow moving due to the heavy traffic. As I was following the traffic ahead suddenly the 3rd party SKJ2266D make sudden brake due to the traffic ahead. I immediately applied my brake to avoid the collision with the 3rd party but my foot slip off from the paddle and couldn't stop on time and collided onto the 3rd party rear vehicle. I manage to exchange some particulars details with the 3rd party, no injuries was involved at the scene.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MUHAMMAD SUMARDI BIN MOHD AFFANDI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

9 March 2019 at 1:01 PM

Date/Time:

9 March 2019 at 1:01 PM

> Back to OneMotoring

4-4.5

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Foreign Identification Number
Owner ID:	1677U
Vehicle Details	
Vehicle No.:	SJH995T
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Mar 2019
Vehicle Make:	HONDA
Vehicle Model:	STREAM RSZ 1.8 A
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	R18A1786058
Chassis No.:	RN61077373
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$19,485.00
Original Registration Date:	25 Jul 2008
First Registration Date:	25 Jul 2008
Transfer Count:	4
Actual ARF Paid:	\$17,848.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 Jul 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$18,444.00
COE Rebate Amount:	\$16,083.00
Total Rebate Amount:	\$16,083.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 14 Mar 2019

OK

Avg dep. 7,200/yr

MV 31K - 32K

14/3/19

EMPLOYMENT PASS
Employment of Foreign Manpower Act (Chapter 91A)
Republic of Singapore

Employer:
CONTROL RISKS GROUP (S) PTE LTD



Name:
BOYD ROBERT ARCHIBALD MCNEILL
Occupation:
CHIEF EXECUTIVE OFFICER

FIN:
G6296193M

Date of Issuance:
27-11-2017
Date of Issue:
13-12-2017
Date of Expiry:
13-12-2019



L8508724



Licence Number: G6296193M

Name:

BOYD ROBERT ARCHIBALD
MCNEILL

Birth Date: 22 May 1972

Issue Date: 11 Jun 2015


Valid Till: 28/06/2020



VISIT PASS
Immigration Regulations

Name:

BOYD ROBERT ARCHIBALD MCNEILL



Date of Birth	Sex	Nationality
22-05-1972	M	BRITISH
FIN	Date of Issue	Date of Expiry
G6296193M	13-12-2017	13-12-2019

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED
OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars =< 3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg 29 Jun 2010

NP 428A



REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: G6301677U

Name:

BOYD SELINA MARY

Birth Date: 27 May 1972

Issue Date: 11 Jun 2015

Valid Till: 28-06-2020



REPUBLIC OF SINGAPORE

FIN G6301677U



Name
BOYD SELINA MARY

Date of Birth
27-05-1972

Sex
F

Nationality
BRITISH



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 2B	Motorcycles <= 200 cc	18 Jun 2014
Class 3	Motor Cars <= 3000kg with <=7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg	29 Jun 2010



Licence No: G6301677U

NP 428A

GA0002512

02-04-2018

DEPENDANT'S PASS
Immigration Regulations



Download SCWork&Pass
App to check status



FIN G6301677U



YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.

CERTIFICATE OF INSURANCE

Please call **65-6820 8888** for FWD Emergency Assistance
if Your Car breaks down or is involved in an accident.

All accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

POLICY NUMBER: PNPV2018-00009913 (Comprehensive - Classic Plan)

Car plate number: SJH995T

Your name (As the policyholder): BOYD SELINA MARY

Coverage start date: 30/07/2018

Coverage end date: 29/07/2019

Covered geographical area: Singapore, West Malaysia and Southern Thailand

Who is insured to drive:

(a) You; and

(b) Anyone with a valid driving license who You give permission to drive Your Car.

Important things to know:

Your Policy comprises this Certificate of Insurance, the Contract, the Car Insurance Summary and any Endorsements attached by Us. These documents should be read together as one. You must make sure that any person You give permission to drive Your Car understands Your duties under this Policy and complies with its conditions.

Your Policy is only valid if Your Car is being used for non-commercial activities in accordance with Your contract.

We confirm that this Policy complies with the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).

Issued on: 30/07/2018



Abhishek Bhatia
Chief Executive Officer
FWD Singapore Pte Ltd

Please immediately inform us at **+65-6820 8888**
or email us at **contact@fwd.com** if any details
in this Certificate of Insurance need to be changed.



INSURER: **FWD Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNPV2018-00009913	Date of Loss:	07/03/2019
Vehicle Reg. No.:	SJH995T	Driveable?	
Driver Age/Info:		Party At Fault:	DRIVER
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SELINA BOYD		
Driver:	BOYD ROBERT ARCHIBALD MCNEILL		

Make/Model:	HONDA STREAM, 1.8 RSZ (A)	Vehicle Reg. Date:	25/07/2008
Vehicle Colour:	WHITE		
Engine No:	R18A1786058	Chassis No:	RN61077373
Odometer:	128019 KM		

Paint Type:

Total Loss? **NO**

Est. Duration of Repair (day) **5**

Present Location: **ETHOZ PROTECT PTE LTD (BUKIT BATOK)**

COST OF CLAIMS

	Amount
Parts	4,352.00
Miscellaneous Items	65.00
Labour	2,150.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	6,617.00
+ GST 7.00% (S\$)	459.69
Nett Amount (S\$)	7,076.69

This claim is handled by: KENNETH CORNELIUS / SHAH

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Mar 2019)

Parts: M1-MPV HONDA STREAM 1.8 RSZ (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ETHOZ Protect Pte Ltd/SJH995T/13/03/2019 09:47

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER CRA /	0.00	0.00	*380.00 F
2	2		*FRONT BUMPER RETAINER ne /	0.00	0.00	*36.00 F
3	10		*FRONT BUMPER CLIPS ne /	0.00	0.00	*20.00 F
4	1		*FRONT BUMPER LOWER GRILLE HA /	0.00	0.00	*65.00 F
5	1		*FRONT BUMPER REINFORCEMENT PA /	0.00	0.00	*195.00 F
6	1		*FRONT GRILLE CRA /	0.00	0.00	*195.00 F
7	1		*FRONT GRILLE CHROME MOULDING CRA /	0.00	0.00	*195.00 F
8	1		*FRONT GRILLE LOGO ne /	0.00	0.00	*20.00 F
9	10		*FRONT GRILLE CLIPS ne /	0.00	0.00	*20.00 F
10	2		*HEADLAMP RH/LH CRA /	0.00	0.00	*1,040.00 F
11	2		*HEADLAMP LOWER BRACKET LH-CRA/RH-? X SUC	0.00	0.00	35 *70.00 F
12	1		*BONNET PA /	0.00	0.00	*450.00 F
13	1		*BONNET LOCK PA /	0.00	0.00	*75.00 F
14	1		*BONNET FRONT RUBBER SEAL ne /	0.00	0.00	*25.00 F
15	1		*BONNET INSULATOR X SUC	0.00	0.00	*75.00 F
16	10		*BONNET INSULATOR CLIPS ne /	0.00	0.00	*30.00 F
17	2		*BONNET HINGE ? X SUC	0.00	0.00	*76.00 F
18	1		*SUPPORT PANEL ASSY PA /	0.00	0.00	*350.00 F
19	1		*AIRCON CONDENSER PA /	0.00	0.00	*195.00 F
20	1		*AIRCON FAN BLADE ? X	0.00	0.00	*45.00 F
21	1		*AIRCON FAN MOTOR ? X	0.00	0.00	*115.00 F
22	1		*AIRCON FAN COWLING ? X SUC	0.00	0.00	*80.00 F
23	1		*RADIATOR ? X	0.00	0.00	*300.00 F
24	1		*RADIATOR FAN COWLING ? X	0.00	0.00	*95.00 F
25	1		*RADIATOR FAN MOTOR ? X	0.00	0.00	*150.00 F
26	1		*RADIATOR FAN BLADE ? X	0.00	0.00	*55.00 F
27	1		*FRONT FENDER RH/LH X	0.00	0.00	-
			REPAIR			

F=Franchise part.

Total Parts (\$\$)

4,352.00

ETHOZ Protect Pte Ltd/SJH995T/13/03/2019 09:47. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	COOLANT <i>rec</i>	30.00
2	1	FRONT NUMBER PLATE <i>X sn</i>	35.00
Sub Total (S\$)			65.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	LABOUR TO FACILITATE REPAIR	New <i>800</i>	1,000.00
2	TO RESPRAY AFFECTED AREAS	New <i>800</i> 800	1,000.00
3	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	30.00
4	TO TOP UP AIRCON GAS	New <i>100</i>	120.00
Gross Labour Cost (S\$)			2,150.00

ETHOZ Protect Pte Ltd/SJH995T/13/03/2019 09:47. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

ETHOZ PROTECT PTE LTD

Company Registration No. 199005791M

30 Bukit Batok Crescent, SINGAPORE 658075 . Website : <http://www.orix.com.sg>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resue
Hp 90010068
6 days
4\$ p/p
13/03/19 @ 1500
EXCESS: 600
REVERT
Remov 54 paint
18/3/19



(SUPPLEMENTARY)

INSURER: FWD Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	PNPV2018-00009913	Date of Loss:	07/03/2019
Vehicle Reg. No.:	SJH995T	Driveable?	
Driver Age/Info:		Party At Fault:	DRIVER
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SELINA BOYD		
Driver:	BOYD ROBERT ARCHIBALD MCNEILL		
Make/Model:	HONDA STREAM, 1.8 RSZ (A)	Vehicle Reg. Date:	25/07/2008
Vehicle Colour:	White		
Engine No:	R18A1786058	Chassis No:	RN61077373
Odometer:	128019 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	ETHOZ PROTECT PTE LTD (BUKIT BATOK)		

COST OF CLAIMS	Amount
Parts	93.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00

Gross Total (S\$)	93.00
+ GST 7.00% (S\$)	6.51
Nett Amount (S\$)	99.51
+ Previous Estimates (S\$)	7,026.69
Claim Total (S\$)	7,126.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Generated using Merimen e-Claims Internet Estimation & Adjusting System

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519
FAX :

Date : 25/04/2019
To : FWD SINGAPORE PTE. LTD.

SUPPLEMENTARY

Attn : Motor Claim Department

FAX :

Owner : SELINA BOYD
: FWD SINGAPORE PTE. LTD.

Certificate No : PNPV2018-00009913

Accident Date : 07/03/2019

Vehicle No : SJH- 995-T

Make & Model : HONDA STREAM RSZ 1.8 (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 600.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
<u>List Item</u>			
1	FRONT BUMPER UPPER BEAM	35.00	A Gt ✓
1	BONNET LOCK COVER GARNISH	18.00	A SV ✓
2	FRONT BUMPER SIDE COVER RH/LH	40.00	A CRA ✓
	Sub Total	93.00	
	Add 0% On Parts	0.00	

Remarks:

SUB TOTAL 93.00
GST 7.0 % 6.51
TOTAL 99.51

Surveyor's name: _____

Principal's name: SELINA BOYD

Survey Date & Time: _____

PAGE :

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 25 Apr 2019)
Parts: M1-MPV **HONDA STREAM 1.8 RSZ (A)** (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: ETHOZ Protect Pte Ltd/SJH995T/25/04/2019 11:41
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER UPPER BEAM A B+	0.00	0.00	*35.00 F
2	1		*BONNET LOCK COVER GARNISH A SCR	0.00	0.00	*18.00 F
3	2		*FRONT BUMPER SIDE COVER RH/LH A CRA	0.00	0.00	*40.00 F
Total Parts (S\$)						93.00

F=Franchise part.

ETHOZ Protect Pte Ltd/SJH995T/25/04/2019 11:41. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

ETHOZ Protect Pte Ltd/SJH995T/25/04/2019 11:41. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

ETHOZ PROTECT PTE LTD

Company Registration No. 199005791M

30 Bukit Batok Crescent, SINGAPORE 658075 . Website : <http://www.orix.com.sg>



Date : 25/04/2019
To : FWD SINGAPORE PTE. LTD.

Attn : Motor Claim Department

FAX :

Owner : SELINA BOYD

Insured By : FWD SINGAPORE PTE. LTD.

Certificate No : PNPV2018-00009913 Accident Date : 07/03/2019

Vehicle No : SJH- 995-T Make & Model : HONDA STREAM RSZ 1.8 (A)

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 600.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
List Item			
1	FRONT BUMPER UPPER BEAM	35.00	35.00
1	BONNET LOCK COVER GARNISH	18.00	18.00
2	FRONT BUMPER SIDE COVER RH/LH	40.00	40.00
1	FRONT BUMPER	380.00	380.00
2	FRONT BUMPER RETAINER	36.00	36.00
10	FRONT BUMPER CLIPS	20.00	20.00
1	FRONT BUMPER LOWER GRILLE	65.00	65.00
1	FRONT BUMPER REINFORCEMENT	195.00	195.00
1	FRONT GRILLE	195.00	195.00
1	FRONT GRILLE CHROME MOULDING	195.00	195.00
1	FRONT GRILLE LOGO	20.00	20.00
10	FRONT GRILLE CLIPS	20.00	20.00
2	HEADLAMP RH/LH	1040.00	1040.00
2	HEADLAMP LOWER BRACKET	70.00	35.00

PAGE: 1



Date : 25/04/2019
To : FWD SINGAPORE PTE. LTD.

Attn : Motor Claim Department

FAX :

Owner : SELINA BOYD

Insured By : FWD SINGAPORE PTE. LTD.

Certificate No : PNPV2018-00009913 Accident Date : 07/03/2019

Vehicle No : SJH- 995-T Make & Model : HONDA STREAM RSZ 1.8 (A)

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 600.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
1	BONNET	450.00	450.00
1	BONNET LOCK	75.00	75.00
1	BONNET FRONT RUBBER SEAL	25.00	25.00
1	BONNET INSULATOR	75.00	0.00
10	BONNET INSULATOR CLIPS	30.00	30.00
2	BONNET HINGE	76.00	0.00
1	SUPPORT PANEL ASSY	350.00	350.00
1	AIRCON CONDENSER	195.00	195.00
1	AIRCON FAN BLADE	45.00	0.00
1	AIRCON FAN MOTOR	115.00	0.00
1	AIRCON FAN COWLING	80.00	0.00
1	RADIATOR	300.00	0.00
2	FRONT FENDER RH/LH	RESTORE 0.00	0.00

PAGE: 2



Date : 25/04/2019
To : FWD SINGAPORE PTE. LTD.

Attn : Motor Claim Department

FAX :

Owner : SELINA BOYD

Insured By : FWD SINGAPORE PTE. LTD.

Certificate No : PNPV2018-00009913 Accident Date : 07/03/2019

Vehicle No : SJH- 995-T Make & Model : HONDA STREAM RSZ 1.8 (A)

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 600.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	Sub Total	4145.00	3419.00
	Add 0% On Parts	0.00	0.00
Special Nett Item			
1	FRONT NUMBER PLATE	35.00	0.00
1	COOLANT	30.00	30.00
	Sub Total	65.00	30.00
Labour & Misc			
	LABOUR TO FACILITATE REPAIR	1000.00	800.00
	TO RESPRAY AFFECTED AREAS	1000.00	800.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	30.00	30.00
	TO TOP UP AIRCON GAS	120.00	100.00

PAGE : 3



Date : 25/04/2019
To : FWD SINGAPORE PTE. LTD.

Attn : Motor Claim Department

FAX :

Owner : SELINA BOYD

Insured By : FWD SINGAPORE PTE. LTD.

Certificate No : PNPV2018-00009913 Accident Date : 07/03/2019

Vehicle No : SJH- 995-T Make & Model : HONDA STREAM RSZ 1.8 (A)

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 600.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	Sub Total	2150.00	1730.00
	Sub Total	6,360.00	5,179.00
	GST 7.0 %	445.20	362.53
	Total	6,805.20	5,541.53

Surveyor Name : RASUL - LKK

Date & Time : 14/03/2019 2:00:00 PM

Selamatshahh

PAGE : 4

CLAIM DEPARTMENT

DID : 66547519

FAX :

FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
Tel: 67494998, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
Aain Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949632
Fax: 62992158, 62942354, 62935021
Email: ftrpnet@mbx3.singnet.com.sg
ICB Reg No.: 198301435R

ETHOZ PROTECT PTE LTD
UKIT BATOK CRESCENT
APORE 658075
SJH-995 T P/O:170461
50 GUL CRESCENT

GST Reg. No.: M2-0059747-8

NISSAN TOYOTA OPEL OEM PARTS
TEL: 67426889 62949832 67479292
67426878 62985333 67455824

MITSUBISHI/PROTON

TEL: 62954551
67496954

HONDA/HYUNDAI DIV

TEL: 62970688 64542285
67493588

MAZDA/FORD DIV

TEL: 62935722
67420368

AIRCON/W/S GLASS

TEL: 62952336
67495997

NISSAN
Genuine Parts

OPEL
GENUINE PARTS

MAZDA
Genuine Parts

GENUINE PARTS

Ford

HYUNDAI

TAX INVOICE

TAX INVOICE NO.: CL395156

INVOICE DATE : 15/03/2019

CREDIT TERMS : 30 DAYS

SALES ORDER NO.:

SALESMAN : NSJ

PAGE(S) : 1

	DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	
				(SIN)	(SIN)
711-SMA-000ZZ	FACE, FR, BUMPER		1 ✓	380.000	380.00 ✓
193-SMA-003	SPACER, R, FR, BUMPER		1 PCS ✓	18.000	18.00 ✓
198-SMA-003	SPARCE LH FRT BUMPER		1 PCS ✓	18.000	18.00 ✓
503-SZ5-003	CLIP, BUMPER		20 PCS ✓	2.000	40.00 ✓
130-SMA-000ZZ	BEAM COMP, FR, BUMPER		1 ✓	195.000	195.00 ✓
121-SMA-003	BASE, FR, GRILLE		1 ✓	195.000	195.00 ✓
122-SMA-003	MLDG, FR, GRILLE		1 ✓	195.000	195.00 ✓
700-S5B-003	EMBLEM, FR		1 PCS ✓	20.000	20.00 ✓
151-SMA-003	HEADLIGHT UNIT, LH		1 PCS ✓	420.000	420.00 ✓
190-SMC-000	BEAM, L, FR, BUMPER, UPPER		1 PCS ✓	35.000	35.00 ✓
100-SMA-000ZZ	HOOD, COMP		1 ✓	450.000	450.00 ✓

MOTOR CO. PTE. LTD.

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

SIGNATURE

SIGNATURE

FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
Tel: 67494998, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
Aain Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949632
Fax: 62992158, 62942354, 62935021
Email: ftrpnet@mbx3.singnet.com.sg
ICB Reg No.: 198301435R

ETHOZ PROTECT PTE LTD
UKIT BATOK CRESCENT
APORE 658075
SJH-995 T P/O:170461
50 GUL CRESCENT

GST Reg. No.: M2-0059747-8

NISSAN TOYOTA OPEL OEM PARTS
TEL: 67426889 62949832 67479292
67426878 62985333 67455824

MITSUBISHI/PROTON

TEL: 62954551
67496954

HONDA/HYUNDAI DIV

TEL: 62970688 64542285
67493588

MAZDA/FORD DIV

TEL: 62935722
67420368

AIRCON/W/S GLASS

TEL: 62952336
67495997

NISSAN
Genuine Parts

TOYOTA
GENUINE PARTS

OPEL
GENUINE PARTS

W

MAZDA
Genuine Parts

GENUINE PARTS

Ford

HYUNDAI

TAX INVOICE

TAX INVOICE NO.: CL395156

INVOICE DATE : 15/03/2019

CREDIT TERMS : 30 DAYS

SALES ORDER NO.:

SALESMAN : NSJ

PAGE(S) : 2

	DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	
				(SIN)	(SIN)
120-SMA-003	LOCK ASSY, HOOD		1 ✓	75.000	75.00 ✓
144-SMA-000	SEAL, HOOD RUBBER		1 PCS ✓	25.000	25.00 ✓
501-S1K-003	CLIP, HOOD INSULATOR		4 ✓	3.000	12.00 ✓
501-S1K-003	CLIP, HOOD INSULATOR		6 PCS ✓	3.000	18.00 ✓
400-SMA-300ZZ	BULKHEAD COMP, FRT		1 ✓	350.000	350.00 ✓
110-SMA-003 J	CONDENSOR, COMP		1 PCS ✓	195.000	195.00 ✓

MOTOR CO. PTE. LTD.

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

豐達汽車私人有限公司

FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
Tel: 67494998, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949832
Fax: 62992158, 62942354, 62935021
Email: ftgpnnet@mbox3.singnet.com.sg
ICB Reg No.: 198301435R

ETHOZ PROTECT PTE LTD
UKIT BATOK CRESCENT
APORE 658075
SJH-995 T P/O:170461
50 GUL CRESCENT

GST Reg. No.: M2-0059747-8

NISSAN TOYOTA OPEL OEM PARTS

TEL: 67426889 62949832 67479292
67426878 62985333 67455824

MAZDA/FORD DIV

TEL: 62954551
67496954

HONDA/HYUNDAI DIV

TEL: 62970698 64542285
67493588


MAZDA/FORD DIV

TEL: 62935722
67420368

AIRCON/W/S GLASS

TEL: 62952336
67495997

AUTHORISED STOCKISTS:



TAX INVOICE

TAX INVOICE NO.: CL395156
INVOICE DATE : 15/03/2019
CREDIT TERMS : 30 DAYS
SALES ORDER NO.:
SALESMAN : NSJ
PAGE(S) : 3



DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	
			(SIN)	(SIN)
			GST Excl Amount :	2641.00
			Special Discount :	
			GST @ 7 % :	184.87

MOTOR CO. PTE. LTD. GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

PRINT BY :
NSJ 15/03/2019 09:11:13

SIGNATURE

[Signature]
SIGNATURE

TOTAL 2825.87

豐達汽車私人有限公司

FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
Tel: 67494998, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949832
Fax: 62992158, 62942354, 62935021
Email: ftgpnat@mbx3.singnet.com.sg
ICB Reg No.: 198301435R

ETHOZ PROTECT PTE LTD
UKIT BATOK CRESCENT
APORE 658075
3JH-995 T P/O:170461 MR:SHAH
50 GUL CRESCENT

GST Reg. No.: M2-0059747-8

NISSAN TOYOTA OPEL OEM PARTS

TEL: 67426889 62949832 67479292
67426878 62985333 67455824

MAZDA/FORD DIV

TEL: 62935722
67420388

AIRCON/W/S GLASS

TEL: 62952336
67495997

NISSAN
Genuine Parts

TOYOTA
GENUINE PARTS

OPEL
GENUINE PARTS

MAZDA
Genuine Parts

FORD
GENUINE PARTS

HYUNDAI

HYUNDAI

TAX INVOICE

TAX INVOICE NO.: CL395186

INVOICE DATE : 15/03/2019

CREDIT TERMS : 30 DAYS

SALES ORDER NO.:

SALESMAN : NSJ

PAGE(S) : 1

	DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	
151-SMA-J11	HEADLIGHT UNIT, LH		1 ✓	(SIN) 520.00	(SIN) 520.00 ✓
101-SMA-J11	HEADLIGHT UNIT, RH		1 ✓	520.00	520.00 ✓
140-SMC-000	BEAM, R, FRT BUMPER UPPER		1 PCS ✓	35.00	35.00 ✓
125-SMA-000	COVER, HOOD LOCK		1 PCS ✓	18.00	18.00 ✓
				GST Excl Amount :	1093.00
				Special Discount :	
				GST @ 7 % :	76.51

MOTOR CO. PTE. LTD. GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

PRINT BY :
NSJ 15/03/2019 14:22:52

TOTAL 1169.51

SIGNATURE

SIGNATURE

豐達汽車私人有限公司

FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
Tel: 67494998, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949832
Fax: 62992158, 62942354, 62935021
Email: ftgpnat@mbx3.singnet.com.sg
ICB Reg No.: 198301435R

ETHOZ PROTECT PTE LTD
UKIT BATOK CRESCENT
APORE 658075
3JH-995 T P/O:170461 MR:SHAH
50 GUL CRESCENT

GST Reg. No.: M2-0059747-8

NISSAN TOYOTA OPEL OEM PARTS

TEL: 67426889 62949832 67479292
67426878 62985333 67455824

MAZDA/FORD DIV

TEL: 62935722
67420388

AIRCON/W/S GLASS

TEL: 62952336
67495997

NISSAN
Genuine Parts

TOYOTA
GENUINE PARTS

OPEL
GENUINE PARTS

MAZDA
Genuine Parts

FORD
GENUINE PARTS

HYUNDAI

HYUNDAI

TAX INVOICE

TAX INVOICE NO.: CL395188

INVOICE DATE : 15/03/2019

CREDIT TERMS : 30 DAYS

SALES ORDER NO.:

SALESMAN : NSJ

PAGE(S) : 1

	DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	
102-SMA-000	GRILLE FRT BUMPER LOWER		1 ✓	(SIN) 65.00	(SIN) 65.00 ✓
103-SMA-000	COVER RH FRT BUMPER		1 ✓	20.00	20.00 ✓
108-SMA-000	COVER LH FRT BUMPER		1 ✓	20.00	20.00 ✓
				GST Excl Amount :	105.00
				Special Discount :	
				GST @ 7 % :	7.35

MOTOR CO. PTE. LTD. GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

PRINT BY :
NSJ 15/03/2019 14:37:00

TOTAL 112.35

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Mar 2019 Sendback Est	13 Mar 2019 09:47 S\$6,567.00	13 Mar 2019 10:33 Edit Adj Rpt	S\$5,179.00 Edit Estimates	S\$5,179.00 View Rpt		Pending for Survey Report Cancel Case
Supp #1	25 Apr 2019 11:40	25 Apr 2019 11:41 S\$93.00	25 Apr 2019 11:41			(Combined)	Combined with Main Uncombine Suppl.

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	SELINA BOYD, ID: G6301677U		
Vehicle Reg. No.:	SJH995T	Date of Loss:	07/03/2019 19:00 - :59 [127 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1201900006308	Policy/Cover Note No.:	PNPV2018-00009913 (Comprehensive)
		Excess:	S\$600.00
Repairer:	ETHOZ Protect Pte Ltd (Bukit Batok) 30 Bukit Batok Crescent, 658075 Bukit Batok - Tel: 66547750/51		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 22/03/2019]		
Driver/Custodian:	BOYD ROBERT ARCHIBALD MCNEILL (), NRIC: G6296193M, Tel: +6597111139 Email:		
		Vehicle Source:	Tow-in/Call-man

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- FWD_SG (09/05/2019): Alert - Adj Mandate Approved (S\$5179.00) - SJH995T - Claim Handler: Lionel Tan
- FWD_SG (14/03/2019): Alert - Adj Mandate Approved (S\$5972.00) - SJH995T - Claim Handler: Lionel Tan

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

SJH995T (1201900006308)

OD

Mar 7 2019 7:00PM

[SELINA BOYD]

ETHOZ Protect Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#) ▼

Assessment Reports

1 per page ▼ ☒

No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)		Thumbnail	Print
1	13/03/19 09:47	Repairer Estimates	1	Load HTM	
2	25/04/19 11:41	Repairer Estimates Suppl. #1	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	14/03/19 13:54	Adjuster Immediate Advice	1	Load HTM	
2	08/05/19 11:34	Adjuster Immediate Advice	1	Load HTM	

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/03/19 13:42	Odometer Reading	1	Load JPG	☒
2	15/03/19 13:42	Chassis Number	1	Load JPG	☒
3	15/03/19 13:42	General View	1	Load JPG	☒
4	15/03/19 13:42	General View	1	Load JPG	☒
5	15/03/19 13:42	General View	1	Load JPG	☒
6	15/03/19 13:42	General View	1	Load JPG	☒
7	15/03/19 13:42	General View	1	Load JPG	☒
8	15/03/19 13:42	General View	1	Load JPG	☒
9	15/03/19 13:42	General View	1	Load JPG	☒
10	15/03/19 13:42	General View	1	Load JPG	☒
11	15/03/19 13:42	General View	1	Load JPG	☒
12	15/03/19 13:42	General View	1	Load JPG	☒
13	15/03/19 13:42	General View	1	Load JPG	☒
14	15/03/19 13:42	General View	1	Load JPG	☒
15	15/03/19 13:42	General View	1	Load JPG	☒
16	15/03/19 13:42	General View	1	Load JPG	☒
17	15/03/19 13:42	General View	1	Load JPG	☒
18	15/03/19 13:42	General View	1	Load JPG	☒
19	15/03/19 13:42	General View	1	Load JPG	☒
20	15/03/19 13:42	General View	1	Load JPG	☒
21	15/03/19 13:42	General View	1	Load JPG	☒
22	15/03/19 13:42	General View	1	Load JPG	☒
23	15/03/19 13:42	General View	1	Load JPG	☒
24	15/03/19 13:42	General View	1	Load JPG	☒
25	15/03/19 13:42	General View	1	Load JPG	☒
26	15/03/19 13:42	General View	1	Load JPG	☒
27	15/03/19 13:42	General View	1	Load JPG	☒
28	15/03/19 13:42	General View	1	Load JPG	☒
29	15/03/19 13:42	General View	1	Load JPG	☒
30	15/03/19 13:42	General View	1	Load JPG	☒

Assessment Reports			1 per page ▼	☒
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
31	15/03/19 13:42	General View	 Load JPG	☒
32	15/03/19 13:42	General View	 Load JPG	☒
33	15/03/19 13:42	General View	 Load JPG	☒
34	15/03/19 13:42	General View	 Load JPG	☒
35	15/03/19 13:42	General View	 Load JPG	☒
36	15/03/19 13:42	General View	 Load JPG	☒
37	15/03/19 13:42	General View	 Load JPG	☒
38	15/03/19 13:42	General View	 Load JPG	☒
39	15/03/19 13:42	General View	 Load JPG	☒
40	15/03/19 13:42	General View	 Load JPG	☒
41	15/03/19 13:42	General View	 Load JPG	☒
42	15/03/19 13:42	General View	 Load JPG	☒
43	15/03/19 13:42	General View	 Load JPG	☒
44	15/03/19 13:42	General View	 Load JPG	☒
45	15/03/19 13:42	General View	 Load JPG	☒
46	15/03/19 13:42	General View	 Load JPG	☒
47	15/03/19 13:42	General View	 Load JPG	☒
48	15/03/19 13:42	General View	 Load JPG	☒
49	15/03/19 13:42	General View	 Load JPG	☒
50	15/03/19 13:42	General View	 Load JPG	☒
51	15/03/19 13:42	General View	 Load JPG	☒
52	15/03/19 13:42	General View	 Load JPG	☒
53	08/05/19 11:36	Reinspection Photo	 Load JPG	☒
54	08/05/19 11:36	Reinspection Photo	 Load JPG	☒
55	08/05/19 11:36	Reinspection Photo	 Load JPG	☒
56	08/05/19 11:36	Reinspection Photo	 Load JPG	☒
57	08/05/19 11:36	Reinspection Photo	 Load JPG	☒
58	08/05/19 11:36	Reinspection Photo	 Load JPG	☒
59	08/05/19 11:36	Reinspection Photo	 Load JPG	☒
60	08/05/19 11:36	Reinspection Photo	 Load JPG	☒
61	08/05/19 11:36	Reinspection Photo	 Load JPG	☒
Documentation			1 per page ▼	☒
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	12/03/19 08:35	E-filed GIA report	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/03/19 13:16	ESTIMATE .pdf	 Load PDF	
2	08/05/19 11:36	ESTIMATE & SUPPLEMENTARY MARKED.pdf	 Load PDF	
3	15/05/19 10:35	PARTS INVOICE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS/FWD19004600/R1SD3S2

Date: 15/05/2019

REFERENCE

Insured/Claimant:	SELINA BOYD	Policy No:	PNPV2018-00009913	
Date of Loss:	07/03/2019	Nature of Claim:	OD	Claim No: 1201900006308

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJH995T		
Make & Model:	HONDA STREAM, 1.8 RSZ (A)	Engine No:	R18A1786058
Reg. Date:	25/07/2008 (Man. Year: 2008)	Chassis No:	RN61077373
Colour:	White	Odometer:	128019 km
Engine Capacity:	1799 cc		
Market Value/New Car Price:	S\$32,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/45R17	Rear Tyre Size:	215/45R17
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,445.00	3,419.00	1,026.00	23.08
Miscellaneous Items	65.00	30.00	35.00	53.85
Labour	2,150.00	1,730.00	420.00	19.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,660.00	5,179.00	1,481.00	22.24
- Excess (S\$)	0.00	600.00	-600.00	
(S\$)	6,660.00	4,579.00	2,081.00	31.25
+ GST 7.00/7.00% (S\$)	466.20	320.53	145.67	31.25
Nett Amount (S\$)	7,126.20	4,899.53	2,226.67	31.25

INSPECTION

Date of Assignment:	13/03/2019	Present Location:	ETHOZ Protect Pte Ltd (Bukit Batok)
Date Inspected:	13/03/2019	Inspected At:	ETHOZ Protect Pte Ltd (Bukit Batok) 30 Bukit Batok Crescent Singapore 658075
Estimated Period of Repair:	6.0 days		

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 May 2019)
Parts:	M1-MPV	HONDA STREAM 1.8 RSZ (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJH995T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	380.00 F	*380.00 F
2	2		*FRONT BUMPER RETAINER	Necessary	36.00 F	*36.00 F
3	10		*FRONT BUMPER CLIPS	Necessary	20.00 F	*20.00 F
4	1		*FRONT BUMPER LOWER GRILLE	Bent	65.00 F	*65.00 F
5	1		*FRONT BUMPER REINFORCEMENT	Bent	195.00 F	*195.00 F
6	1		*FRONT GRILLE	Cracked	195.00 F	*195.00 F
7	1		*FRONT GRILLE CHROME MOULDING	Cracked	195.00 F	*195.00 F
8	1		*FRONT GRILLE LOGO	Necessary	20.00 F	*20.00 F
9	10		*FRONT GRILLE CLIPS	Necessary	20.00 F	*20.00 F
10	2		*HEADLAMP RH/LH	Cracked	1,040.00 F	*1,040.00 F
11	1		*HEADLAMP LOWER BRACKET	N/s Cracked / O/s Serviceable	70.00 F	*35.00 F
12	1		*BONNET	Bent	450.00 F	*450.00 F
13	1		*BONNET LOCK	Bent	75.00 F	*75.00 F
14	1		*BONNET FRONT RUBBER SEAL	Necessary	25.00 F	*25.00 F
15	1		*BONNET INSULATOR	Serviceable	75.00 F	*- F
16	10		*BONNET INSULATOR CLIPS	Necessary	30.00 F	*30.00 F
17	2		*BONNET HINGE	Serviceable	76.00 F	*- F
18	1		*SUPPORT PANEL ASSY	Bent	350.00 F	*350.00 F
19	1		*AIRCON CONDENSER	Bent	195.00 F	*195.00 F
20	1		*AIRCON FAN BLADE	Serviceable	45.00 F	*- F
21	1		*AIRCON FAN MOTOR	Serviceable	115.00 F	*- F
22	1		*AIRCON FAN COWLING	Serviceable	80.00 F	*- F
23	1		*RADIATOR	Serviceable	300.00 F	*- F
24	1		*RADIATOR FAN COWLING	Serviceable	95.00 F	*- F
25	1		*RADIATOR FAN MOTOR	Serviceable	150.00 F	*- F
26	1		*RADIATOR FAN BLADE	Serviceable	55.00 F	*- F
27	1		*FRONT FENDER RH/LH (NPA)	Serviceable	-	*- F
Supplementary #1						
28	1		*FRONT BUMPER UPPER BEAM	Bent	35.00 F	*35.00 F
29	1		*BONNET LOCK COVER GARNISH	Scratched	18.00 F	*18.00 F
30	2		*FRONT BUMPER SIDE COVER RH/LH	Cracked	40.00 F	*40.00 F

F=Franchise part.

Total Parts (S\$)	4,445.00	3,419.00
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	COOLANT (NECESSARY)	30.00	30.00
2	1	FRONT NUMBER PLATE (SERVICEABLE)	35.00	0.00
Sub Total (\$\$)			65.00	30.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO FACILITATE REPAIR	New	1,000.00	800.00
2	TO RESPRAY AFFECTED AREAS	New	1,000.00	800.00
3	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	30.00	30.00
4	TO TOP UP AIRCON GAS	New	120.00	100.00
Gross Labour Cost (\$\$)			2,150.00	1,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >