

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan

Date: 08 May 2019

Preliminary Advice

Vehicle No	: SJH995T	Accident Date	: 07/03/2019
Make	: HONDA STREAM	Policy No.	: PNPF2018-00009913
Assignment Date	: 13/03/2019	Excess	: S\$600.00
Date of Inspection	: 13/03/2019	Est. Duration of Repair	: 6 days
Inspection At	: ETHOZ Protect Pte Ltd (Bukit Batok) 30 Bukit Batok Crescent Singapore 658075		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	: \$	6,660.00 (INCLUSIVE SUPPLEMENTARY)
Revised Amount	: \$	5,179.00 (INCLUSIVE SUPPLEMENTARY)
Check Items (Estimated)	: \$	0.00
Total	: \$	5,179.00
Lump Sum Repair	: \$	

Total Loss Consideration

New for Old Value	: \$
Pre-Accident Value	: \$
COE / PARF Rebate	: \$
Salvage Value	: \$
Margin for Repair	: \$

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : We have received supplementary from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair. Supplementary amount is \$93.00.