


poh kin



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
Registration No : SMH4770M
Chassis No : MRHGM6660KT000509
Model : CITY 1.5SV CVT 2019 (EURO 6)
Owner's Name : KHOO SUAT LIM, LYNETTE
Ins Policy No. :
Date of Accident : 9/11/2019

Document No. : SQT19001330
Date : 25. Mar 2019
Customer No. : WZI007
Svc Advisor : JACK NG
Engine No : L15Z16205580
Date | Time : 25. Mar 2019 7:56:59 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:KHOO SUAT LIM, LYNETTE OWNER INSURER:AXA INSURANCE ACC DATE:09/03/2019 SURVEYED BY: DATE: REF NO: TP INSURER:III TP VEH:SH 8271 P						
67010-T9A-T10ZZ	PANEL COMPR.FR.DOOR 1 X 11	1	675.90	25	506.92	35.48	542.40
67326-T9A-T01	TAPER.FR.DOOR SASH CENTER 1 X 11	1	18.50	25	13.87	0.97	14.84
72327-T7A-J01	SUB SEALR.FR.DOOR CENTER 1 X 11	1	47.00	25	35.25	2.47	37.72
67510-T9A-T00ZZ	PANEL COMPR.RR.DOOR 1 X 11	1	652.10	25	489.07	34.23	523.30
67825-T9A-T01	TAPER.RR.DOOR SASH CENTER 1 X 11	1	15.40	25	11.55	0.81	12.36
72826-T9A-T01	SEALRR.DOOR LOWER 1 X 11	1	6.50	25	4.87	0.34	5.21
	Sum Item				1061.53	74.30	1,135.83
BOSUN	SUNDRIES	1	100.00	50	100.00	7.00	107.00
BKDR21R	REMOVE & TRANSFER ITEMS TO NEW RR L DR. ADJUST	1	450.00	380	450.00	31.50	481.50
BKDR12R	REMOVE & TRANSFER ITEMS TO NEW FR R DR. ADJUST	1	450.00	X 11	450.00	31.50	481.50
BOMISC1	RESET & CALLIBRATE SMART ENTRY SYSTEM(N)	1	450.00		450.00	31.50	481.50
BOMISC1	REMOVE & RENEW RHS FRONT & RR DOOR.	1	2000.00	560	2000.00	140.00	2140.00
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P)	1	1500.00	450	1500.00	105.00	1605.00
	Sum Labor				4950.00	346.50	5,296.50

Survey By

Printed on 25/3/2019 8:21:44 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZ1007 / INDIA INTERNATIONAL
Chassis No: MRHGM6660KT000509
License No: SMH4770M
Mileage: 1296
Engine No: L15Z16205580

Document No: SVO19019114
Printed By: JACKNG
Order Date: 25. March 2019
Order Time: 3:20:41 PM
Service Advisor: JACK NG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Incl GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:KHOO SUAT LIM, LYNETTE OWNER INSURER:AXA INSURANCE ACC DATE:09/03/2019 SURVEYED BY: DATE: REF NO: TP INSURER:III TP VEH:SH 8271 P						
67510-T9A-T00ZZ	PANEL COMPR.RR.DOOR	1	652.10	25	489.07	34.23	523.30
67825-T9A-T01	TAPER.RR.DOOR SASH CENTER	1	15.40	25	11.55	0.81	12.36
	SUM PARTS:				500.62	35.04	535.66
BOSUN	SUNDRIES	1	50.00		50.00	3.50	53.50
BKDR21R	0669 REMOVE & TRANSFER ITEMS TO NEW RR L DR. ADJUST & ALIGN RR L DR.(N)	1	380.00		380.00	26.60	406.60
BOMISC1	RESET & CALLIBRATE SMART ENTRY SYSTEM(N)	1	450.00		450.00	31.50	481.50
BOMISC1	0669 REMOVE & RENEW RHS FRONT & RR DOOR.	1	560.00		560.00	39.20	599.20
BP03R	1610 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(3P)	1	450.00		450.00	31.50	481.50
	SUM LABOUR:				1,890.00	132.30	2,022.30
	TOTAL SGD				2,390.62	167.34	2,557.96
	Total Payable (SGD)						2,557.96

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: INDIA INTERNATIONAL INSURANCE PTE	Document No.	: SQT19001330	Page	2
	64 CECIL STREET	Date	: 25. Mar 2019		
	#04-00 & #05-00 IOB BUILDING	Customer No.	: WZI007		
	SINGAPORE 049711	Svc Advisor	: JACK NG		
Registration No	: SMH4770M	Engine No	: L15Z16205580		
Chassis No	: MRHGM6660KT000509	Date Time	: 25. Mar 2019 7:56:59 AM		
Model	: CITY 1.5SV CVT 2019 (EURO 6)	Surveyor Name	:		
Owner's Name	: KHOO SUAT LIM, LYNETTE	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 9/11/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
Date & Time	25/03/19 @ 1420						
Excess							
Status							
Signature							
Total Amount					6,011.53	420.80	6,432.33
Total (Inclusive of GST)							6,432.33

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Printed on 25/3/2019 8:21:44 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.