

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
AXA INSURANCE PTE LTD			Ref : CC4/ASM19004612/Dga3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KIAN CHUAN			Date: 27-05-2020 Code: ASM		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJC 9212L	Veh. Inspected	FBL 6302C	
	Policy No.	GA360975/1	Coverage (\$)	0.00	
	Claim No.	S9M01GMO	Excess (\$)	0.00	
	Assign From		Assign Date	14/03/2019	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA PCX150	c.c	153	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	MLHKF2085G5332812	Colour	GREY	
	Odometer	33100	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	90/90 R14	DUNLOP	2 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	100/90 R14	DUNLOP	2 mm	
	L/H Rear Tyre			mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND N/S BODY.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	10/03/2019	Inspection Date	14/03/2019	
	Survey held at SG 98 MOTOR PTE LTD				
		BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				