

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 15 March 2019

To : LKK

By Fax: 6256-4315

Attn : Bryan Ang

Tel: 97237799

VEHICLE NO : FBL 6302C

Honda PCX 150-Auto

ACCIDENT DATE: 10 March 2019

Description	Qty	Quotation \$
1 Handle Bar MM MM	1	250.00 MM X
2 Visor Swatchel	1	350.00 ✓
3 Front LH Side Panel Crack	1	160.00 ✓
4 Front RH Side Panel 2 crack consistency MM	1	170.00 2 X
5 Fork Tube distorted	1 set	980.00 ✓
6 Dash Cover Panel Front MM cut	1	165.00 MM ✓
7 Meter Cover MM	1	198.00 X
8 Front Panel MM cut	1	200.00 MM ✓
9 Fork Under Bracket MM	1	250.00 X
10 Rear Left Side Fairing monny crack	1	180.00 ✓
11 LH Lower Belly Pan cut	1	150.00 ✓
Sub-Total		3,053.00
Less 10%		305.30
Sub-Total		2,747.70

Suppliers Items

Front Headlamp -

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To resurvey before (part) being resurveyed
- Pass prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

#265-2 monny crack. ✓

2450.00
1070 2205.00

#4026.20

VEHICLE NO : FBL 6302C

Honda PCX 150-Auto

Nett Items

1	Towing fee <i>the</i>	40.00	30/-
2	Remove & replace parts, align & etc	380.00	120/-
3	Remove & replace fork tube, top up fork oil	150.00	80/-
4	Reconnect electrical wiring	80.00	20/-
5	Putty & touch up paint work	250.00	180/-
6	Fork Oil Seal	150.00	50/-
Sub-Total		1,050.00	

Nett Total 3,797.70

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion. Thank you

SG 98 MOTOR PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

14/03/2019 e 1100hrs

Nett Amount

2/5m 4 days

2 klc Auto